
In the Matter of: Tentative Cleanup and Abatement Order No. R9-2011-0001

> November 9, 14, 15, 16 Downey Brand LLP

Overview – SDG&E as Discharger

- Introduction
- Silver Gate Plant Overview
- Sources and Pathways of PCB's/COC's
- Conclusion

Orientation and Operational History



F:\SDG&E\Silvergate\Wasteponds SA\SA report\Draft\Part 1 Aerial Photos


- Plant Housed PCB Containing Equipment
- Plant Wastewater Discharged Through Cooling Water Tunnels
- Plant Wastewater Discharged to Unlined Ponds and Oil-Water Separators


3.4.5 Basement Bilge Water

File Numbe

Basement bilge water consisted of liquids that accumulated in trenches in the plant basement. The WWTP manual (SDG&E, 1978) lists the following waste sources: "turbine drains, boiler drains, condenser drain pump drains, cooling water supply drains, water box drains, service air compressor drains, fire pump drains, relief valve drains, condensate storage and overflow and condensate makeup pump drains." The basement bilge system was divided into two areas, the turbine side and the boiler side. Diagrams from 1965 show that bilge water from the turbine side was piped into the discharge cooling water tunnels, andthe bilge water from the boiler side was pumped, via an 8 inch diameter pipeline, to an "oil-water separating pond" located on Parcel 2, referred to as "Nobles Lake", which was used for evaporation and settling.

ENV.			ENY 🛪	12 F3SDG&EISHwrgatelaedimentaliO report, 7-0417	Report for R9-2004-0026 Silver Gate July 14, 2004 chrical Report 14Jul2004 doc
S	AR193272				SAR193289
	122	1111111			





- Tidelands Housed Unlined Ponds
- Tidelands Housed Oil-Water Separators
- Untreated Wastewater Discharged to Ponds
- Ponds Overflowed
- Ponds Discharged Directly to Bay

May 1, 1950


SILVER GATE STATION


Mr. M. Halmerson, Supt. Construction


ς.


In a recent survey of Unit /3 construction, the following

1. It is noted that our water disposed lars on the tide lands has been overflowing, and a dised has been our to the water's class. This cannot be mentabled, been our oil would the repy be admitted to the bay and our cuspany would be subject to a neavy fine by the fish and dama Commission. It may be measurer to three up a dise around the lake for the time being or to bake a class shell and dig out additional space for the water is discharges










SAR193577



INTERNA	L CORRESPONDENCE	· · · · · · · · · · · · · · · · · · ·	R. Kary			
FORM 118-6143			(A ^{, v}			
FROM	A. W. Hovland	DATE September	10, 1974			
то	M. J. Horna	FILE NUMBER EPE	000			
SUBJECT	Proposed Bilge System Re	vision for Oil Spill Preventio	n			
at Silver Gate						
he nature of this	memo is to review both of the above comments					
		he brim and is at least	ll feet			
Nobles	Lake is filled to the	······································				
		·				
		and earth. It is no lo	nger an			
deep w	ith a mixture of oil	and earth. It is no lo	-			
deep w	ith a mixture of oil	·	-			

- Switchyard Housed PCB Containing Equipment
- Equipment Leaked
- Switchyard Stormwater Discharged to MS4

FEB 000 1 SAN DIEGO GAS & ELECTRIC MPANY 8-8.2 INTERNAL CORRESPONDENCE (IMP - 5G) DATE May 14, 1981 On April 7, 1981, Electric Construction and Maintenance (ECM) were notified by Brian Heramb, Safety Representative, that PCB fluid was leaking from . transformers located at Silver Gate Power Plant. An ECM crew, consisting of Don Swinney and others, soon met with Heramb and Don Darbonne, Silver Gate Foreman. The transformer leaks were pointed out to the ECM crew at this time, but to date no action has been taken by ECM to clean up the spill and recommend necessary repairs.

> GHConnelly MAY 14 198] .. SDG&E020718

DATE 2/11/83
DAILY PCB INSPECTION REPORT
PCB EQUIPMENT: #/ S. Load trans. LOCATION: Silver Gate West. 2978783 DATE OF INSPECTION: 2/11/83 DATE OF LEAK DISCOVERY: 11/22/82 NAME OF INSPECTOR: R. Manes ESTIMATE OF FLUID LEAKED: Medium leak at sample value and
swall leak at the small drain valve DATE OF CLEAN-UP(S), CONTAINMENT, OR REPAIR PERFORMED: No action taken
DESCRIPTION OF CLEAN-UP, CONTAINMENT, OR REPAIR PERFORMED: None
results of any containment and daily inspection for uncorrected active leaks: No action taken

INSPECTION REPORT U.S. ENVIRONMENTAL PROTECTION AGENCY REGION 9 TOXICS AND WASTE MANAGEMENT DIVISION FIFLD OPERATIONS BRANCH

Purpose: TSCA §6 PCB Investigation


Facility: San Diego Gas & Electric Silvergate Power Plant 1348 Sampson Street San Diego, CA 92113

FPA ID Number: CAT000618934

Report Number: T(87)F043

Dates of Investigation: 5 February 1987

SDG&E027986



Summary and Conclusion

- 40 Plus Year Operational History
- Multiple COC (PCB) Sources
- Multiple Pathways to the Bay
- Substantial Evidence
- SDG&E Properly Named as Discharger

In the Matter of: Tentative Cleanup and Abatement Order No. R9-2011-0001

> November 9, 14 – 16 Downey Brand LLP