



Photo 1. Red Ink Main Mine Portal.



Photo 4. Looking west at the berm of waste dump #2. Middle Fork of the American River visible on left.



Photo 2. Portal area looking west.



Photo 5. Portal area looking towards waste dump #1.



Photo 3. Portal area looking east.



Photo 6. Waste dump #3, looking west.



Photo 7. Looking east at waste dump #1.



Photo 10. Looking west at the access road to waste dump #5.



Photo 8. Looking east at waste dump #4.



Photo 11. Waste dump #5 looking west.



Photo 9. Looking at slump failure on waste dump #4.



Photo 12. Waste dump #5 showing end dumped mining waste.



Photo 13. Waste dump #5 showing end dumped mining waste.



Photo 16. Showing natural segregation of end dumped materials.



Photo 14. Showing fine grained materials in waste dump #5.



Photo 17. Looking up from the debris barrier to waste dump #5.




Photo 16. Close up of previous photo.



Photo 18. Near the toe of waste dump #5, looking downgradient at the debris barrier



Photo 19. Debris barrier downgradient of the toe of waste dump #5



Photo 20. Close-up view of previous photo.



Photo 21. Photo taken from Mosquito Ridge Road overlook 1 mile east of mine site. Photo shows slope failures at the toes of waste dump #2 and #4.