

ATTACHMENT D

16 September 2015 Inspection Report

CENTRAL VALLEY REGIONAL WATER QUALITY CONTROL BOARD

Irrigated Lands Regulatory Program Inspection Report

Ownership Information:

Owner(s):	Gilbert & Enedina Marroquin	Coalition:	KBWQA	County:	Tulare
Parcel Number:	119-110-012	Acres:	39.6	I.D. #	P1

Inspection Findings:

Date Inspected:	9/16/2015
Inspected By:	PAB/RKW
Type of Inspection:	Field
Results:	Commercially Irrigated Agriculture
Crop type:	Pistachios
Irrigation Method:	Drip
Other/Notes:	Parcel is generally lower than the road. Canal that runs along east and south side of parcel has elevated bank 2-3 feet above field level. No drainage pipes or other features that would facilitate discharge into canal. No signs of discharge.

Inspection Photo:



CENTRAL VALLEY REGIONAL WATER QUALITY CONTROL BOARD

Irrigated Lands Regulatory Program Inspection Report

Ownership Information:

Owner(s):	Gilbert & Enedina Marroquin	Coalition:	KBWQA	County:	Tulare
Parcel Number:	119-110-013	Acres:	39.6	I.D. #	P2

Inspection Findings:

Date Inspected:	9/16/2015
Inspected By:	PAB/RKW
Type of Inspection:	Field
Results:	Commercially Irrigated Agriculture
Crop type:	Pistachios
Irrigation Method:	Drip
Other/Notes:	Parcel appears to be lower than road that runs along the eastern edge of the property. Canal that runs along northern edge of parcel has an elevated bank of 2-3 feet. No visible drainage pipes or features that would facilitate discharge into canal. No visible signs of discharge.

Inspection Photo:

