

## **Attachment 10**

This attachment includes photos from several construction sites inspected on April 9-10, 2014. Sites include private development, capital improvement projects (CIPs), including two linear undergrounding projects (LUPs).

Notes include deficiencies noted by San Diego Water Board inspectors but not noted by City inspectors.




















Photos from Audit Field Days  
Location: Bankers Hill (LUP Job 945)

Date: April 9, 2014



Inadequate Storm Drain  
Inlet Protection



Rusty pipe should be contained and not in contact with ground.



In the event of rain, City must have BMP plan for the excavated soil.



Storm drain inlet BMPs need maintenance



Stockpile not properly contained and heavy equipment can disperse material into the street and offsite.





