

Attachment 3

Environmental Setting Photos 2 complete sets

**For Application to
Appropriate Water for**
Applicants Harry and Karen Bosworth

Environmental Setting



West facing view of 8.55 acre-foot capacity reservoir.



East facing view of reservoir from dam wall.



South facing view of reservoir from dam wall.

All photos taken 2/7/10



Close up of culvert spillway.



South facing view of dam wall.



Downstream side of dam wall.



Continuation of culvert to unnamed stream.



Culvert and unnamed stream.



Overflow culvert to unnamed stream.

All photos taken 2/7/10




West facing view of culvert and unnamed stream.



Stream channel downstream of POD.



North facing view of east shore of reservoir where drainage enters.



West ~~view~~ facing view from upstream of reservoir.




East ~~view~~ facing view of drainage immediately upstream of reservoir.



North facing view of agriculture groundwater well.



Groundwater well supply to reservoir.



Vineyard irrigation system.

All photos taken 2/7/10