


THOMAS BICKELL
INSPECTION PICTURES: 11/8/2011
RESERVOIR ID Nos. 1946, 1952, and Unlisted



Reservoir 1946 – Front-side of dam for reservoir. (Facing northwest.)




Reservoir 1946 – Looking across reservoir facing northwest.




Reservoir 1946 – Looking at rear of the reservoir, and at the upstream channel in the background. (Facing northwest.)



Reservoir 1946 – Looking across reservoir towards stream channel in southwestern corner of reservoir. (Facing southwest.)



Reservoir 1946 – Stream-channel in southwestern corner of reservoir. (Facing southwest.)



Reservoir 1952 – Looking west across reservoir.



Reservoir 1952 – Floating dock is in center of frame and part of dam is to the right. (Facing north.)



Reservoir 1952 – View of back-side of dam from the floating dock while facing south.




Reservoir 1952 – View of front-side of dam while facing northeast.



Reservoir 1952 – View of spillway facing northwest.




Reservoir 1952 – View of spillway from pond. (Facing east.)



Reservoir 1952 – View of pond from spillway. (Facing southwest.)



Reservoir 1952 – View of discharge pipe on backside of dam from spillway. (Facing east.)



Reservoir 1952 – Looking northwest towards upstream end of pond.



Reservoir 1952 –Near the upstream side of pond.




Unlisted Reservoir – Looking southwest across reservoir. Water-level in reservoir appears drawn-down.



Unlisted Reservoir – Looking at reservoir, facing south, from stream-channel on north side of reservoir.



Unlisted Reservoir – Looking east across reservoir.



Unlisted Reservoir – View of reservoir in background from streambed in upstream channel. (Facing east.)



Unlisted Reservoir – Looking upstream (west) in unnamed stream channel.