



Photo 1: Area 1-looking south at washout.



Area 2- looking south at washout (slumping has buried pipeline in left of photo).



Photo 3: Example of an existing FCR structure in an ephemeral channel of California.
(photograph courtesy of Ercon)