

Attachment B

Owner/ Operator	Field Name	County	Sump Name/Description	Sump Location		(LxWxD) Sump Vol. BBLs	When sump excavated	Years it was active	Total amount of fluid discharged in BBLs	Composition of Fluids	Was sump filled with soil or other materials(Yes/No)	When was the sump filled	What material was used to fill the sump	Was there solidified waste	If yes, what was the composition of these solids
				Lat	Long										
DCOR,LLC	Rincon	Ventura	Produced Water Steel Tank	34.36611	-119.43277	5000	NA	NA	NA	Produced Water	NA	NA	NA	No	
DCOR,LLC	Rincon	Ventura	480sqft concrete sump	34.36611	-119.43277	12'x40'	NA	NA	NA	Process Drains- water & Crude Oil	NA	NA	NA	No	
DCOR,LLC	Rincon	Ventura	1320sqft concrete sump		-119.43277	12'x110'	NA	NA	NA	Storm Water	NA	NA	NA	No	
DCOR,LLC	Rincon	Ventura	36sqft concrete sump	34.36611	-119.43277	6'x6'	NA	NA	NA	Lower level process drains-water & crude	NA	NA	NA	No	
DCOR,LLC	Rincon	Ventura	108sqft Horseshoe concrete sump	34.36611	-119.43277	12'x12'	NA	NA	NA	Pig receivers drain- water and crude	NA	NA	NA	No	
DCOR,LLC	Rincon	Ventura	25sqft concrete sump	34.36611	-119.43277	5'x5'	NA	NA	NA	Lower level process drains-water & crude	NA	NA	NA	No	
DCOR,LLC	Rincon	Ventura	15sqft concrete sump	34.36611	-119.43277	3'x5'	NA	NA	NA	Drains fromLACT tanks-Crude	NA	NA	NA	No	
DCOR,LLC	MOSF	Ventura	25sqft concrete sump	34.20611	-119.25000	5'x5'	NA		NA	Water	NA	NA	NA	No	
DCOR,LLC	MOSF	Ventura	9sqft concrete sump	34.20611	-119.25000	3'x3'			NA	Water	NA	NA	NA	No	
DCOR,LLC	Hopper	Ventura	Two 64sqft concrete sumps	34.43444	-118.83027	8'x8'	Not known	5	NA	Water and oil	NA	NA	NA	No	
DCOR,LLC	Temescal	Ventura	steel sump	34.46888	-118.76083	30"x72"	NA	1	NA	Water	NA	NA	NA	No	