

EDMUND G. BROWN JR.
GOVERNOR

MATTHEW RODRIGUEZ
SECRETARY FOR
ENVIRONMENTAL PROTECTION

San Diego Regional Water Quality Control Board

July 14, 2016

Mr. Bryan Forward
City of Oceanside, Public Works Department
300 North Coast Highway
Oceanside, CA 92054

In reply refer to / attn:
240929:RMitchell

Subject: Mission Avenue Inspection Summary

Mr. Forward:

This letter provides you with a summary of inspection observations for compliance with Order No. 88-053, *Waste Discharge Requirements for the Mission Avenue Landfill in the City of Oceanside, San Diego County* (Order). California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) staff conducted an inspection of the Mission Avenue Landfill (Facility) on July 14, 2016. This letter addresses only observations made by San Diego Water Board staff, regarding compliance with the Order. The San Diego Water Board has the following comments:

1. **Observed Violations:** During the inspection of the Facility, San Diego Water Board staff did not observe any violations against the requirements specified in the Order.
2. **Areas of Concern:** During the inspection of the Facility, San Diego Water Board staff did not observe any areas of concern against the requirements specified in the Order.
3. **Next Monitoring Report:** The next monitoring report required to be submitted is the January-June 2016 semiannual monitoring report, which is due by July 30, 2016.
4. **Future Responses and Correspondence:** Please submit all future correspondence to the San Diego Water Board by email.¹ The email submittals must include a signed transmittal letter (with the facility name, facility contact information, and reference codes as indicated above), and be sent to sandiego@waterboards.ca.gov. Information required by the Order should be emailed to sandiego@waterboards.ca.gov. Routine email correspondence may be sent to individual San Diego Water Board staff members. If you have any specific questions about email submittal procedures please contact Ms. Cleo Munoz in our Mission Support Unit, at 619-521-3384 or cleo.munoz@waterboards.ca.gov.

In the subject line of any response, please include the reference code **240929:AGrove**. Please contact Ms. Amy Grove at 619-521-3920, or at Amy.Grove@waterboards.ca.gov if you have any questions.


¹ See public notification on electronic reporting on-line at:
http://www.waterboards.ca.gov/sandiego/docs/Electronic_Reporting_Sept2014.pdf

Mr. Forward

- 2 -

July 14, 2016

Respectfully,



Roger N. Mitchell
Engineering Geologist
Groundwater Protection Branch

RNM:rnm

Enclosure: (1) Facility Inspection Report for Inspection ID: 24732046
(2) Facility Inspection Photographs

Tech Staff Info & Use	
Reg. Measure ID	142064
Place ID	240929
Party ID	32483; 56729
Inspection ID	24732046

Mission Avenue Landfill Inspection Summary
Enclosure (1): Inspection Report No. 24732046

Inspection ID: 24732046

Date Printed: 07/14/2016

FACILITIES INSPECTION REPORT

Region/Office: 9	Status: Performed	Reg. Measure ID: 142064
Program Type: LFNONOPER	WDID: 9 000000342	Order Number: 88-053
Scheduled Insp. Date: 07/12/2016	Actual Insp. Date: 07/14/2016	

Discharger Information

Party ID: 32483	Discharger Organization Name: Oceanside City	
Address: 300 North Coast Highway		City, State, Zip: Oceanside, CA 92054
Discharger Contact Person:	Bryan Forward	Discharger Contact Phone: 760-435-5278

Facility Information

Place ID: 240929	Facility Name: Mission Avenue Landfill	
Address: Mission Avenue		City, State, Zip: Oceanside, CA 92058
County: San Diego	Latitude: 33.20763	Longitude: -117.36491 Method:

Lead Inspector Information

Lead Inspector Party ID: 534450	Lead Inspector Name: Roger Mitchell			
Inspector Type:	<input checked="" type="checkbox"/> State	<input type="checkbox"/> State Contractor	<input type="checkbox"/> EPA Contractor	<input type="checkbox"/> EPA (Regional)
	<input type="checkbox"/> EPA and State (EPA Lead)	<input type="checkbox"/> EPA and State (State Lead)		

INSPECTION TYPE (Check One)

- "A" type compliance - Comprehensive inspection in which samples are usually taken (EPA Type S)
- AGT SPCC - An inspection of an above ground tank site and review of the site's spill prevention control and counter measure plant.
- "B" type compliance - A routine inspection (EPA Type C) that typically does not include collecting samples
- Complaint - Inspection made in response to a complaint
- Field Oversight - Inspection or site visit to confirm clean-up work is being performed
- Follow-up (enforcement) - Included inspections specifically made to verify compliance with enforcement mandates
- Follow-up (non-compliance) - Includes inspections specifically made to verify corrections of non-compliance where no enforcement has been initiated
- Pre-requirement - Inspection made to gather information relative to preparing, modifying, or rescinding requirements
- Pretreatment Compliance Audit - An audit that includes review of that program authority, records, and industrial facility field inspections
- Pretreatment Compliance Inspection - An inspection of a pretreatment program that includes records review and industrial facility field inspections
- MS4 Audit - An evaluation of an MS4 program or program component that could possibly lead to enforcement. It must include a site visit.
- NOT - Inspection performed in response to the submittal of a Notice of Termination coverage under a general order
- Miscellaneous - Any inspection type not mentioned above

Mission Avenue Landfill Inspection Summary
Enclosure (1): Inspection Report No. 24732046

Inspection ID: 24732046

Date Printed: 07/14/2016

VIOLATIONS

Were Violations noted during this inspection? Yes No

Violation ID	Violation Type	Occurrence Date	Rank	Description

INSPECTION SUMMARY (REQUIRED) (500 character limit)

No observed violations, or areas of concern.

GENERAL NOTES (OPTIONAL) (2000 character limit)

Landfill property is being properly managed.

For Internal Use (Optional)

Reviewed By: (1)	(2)	(3)
CIWQS Entry Date:	Regional Board File Number:	CIWQS Inspection ID:

Mission Avenue Landfill Inspection Summary
Enclosure (2): Facility Inspection Photographs



Photograph 1: Storm Water BMPs.



Photograph 2: Landfill face, and owl box



Photograph 3: Landfill signage.



Photograph 4: Landfill cover.