

Appendix 3. Waterbody field notes and/or photographs.

Live Oak Creek (HSA 3.12)

Live Oak Creek (HSA 3.12) San Diego Thomas Brothers page 998 D7. The spillway at Red Mountain reservoir leads to Live Oak Creek (HSA 3.12) drainage. Stream dry. Visited area on July 5, 2005.

Live Oak Creek (HSA 3.12) North Ridge Drive, at Live Oak Park Road located at N33.38360, W117.20037, elevation 669 feet. San Diego Thomas Brothers page 1028 C2. No photographs. Riparian habitat consists of oak woodland and sycamore. Live Oak Creek is about 2 feet wide and 1 inch depth. There is erosion and undercutting of the stream bank within Live Oak Creek. Driving south from the North Ridge Drive crossing along Live Oak Park Road, one can view washouts where some of the road crossings have failed due to storm flows within Live Oak Creek. Stream flow approximately 1/10 cfs on July 5, 2005 at 1533hrs.

Live Oak Creek (HSA 3.12) Live Oak County Park located at N33.36347, W117.20397, elevation 557 feet. San Diego Thomas Brothers page 1028 C5. No photographs. There is an oak woodland with sycamores on upland areas near the channel. Stream is channelized and full of algae. Stream flow approximately 1 cfs on July 5, 2005 at 1505hrs.