



Figure 1. Slope stabilization adjacent to extended detention basin under Otay River Bridge



Figure 2. Extended detention basin under Otay River Bridge



Figure 3. Recently graded bio-swale south of Operations Center building.



Figure 4. Extended detention basin between Otay River and Otay Mesa Rd.



Figure 5. Extended detention basin South of Birch Rd.



Figure 6. Bio-swale at Birch Rd. (East side)



Figure 7. Bio-swale at Birch Rd. (West side)



Figure 8. Median bio-swale North of E. H St.