



California Regional Water Quality Control Board, San Diego Region

July 20, 2012

In reply refer to: L10009404819:AGrove

City of Oceanside Department of Public Works Landfill Management Attn: Bryan Forward 300 North Coast Highway Oceanside, CA 92054

Mr. Forward:

Subject: Landfill Cover Areas of Concern, Mission Avenue Landfill, City of Oceanside, San Diego County, California

On June 26, 2012, the California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) staff conducted a compliance inspection at the Mission Avenue Landfill located north of Mission Avenue and south of the San Luis Rey River in the City of Oceanside.

During the inspection, numerous rodent holes and mounds were observed northeast of the main waste area in the final landfill cover; refer to attached landfill inspection report. These landfill cover conditions are areas of concern warrant corrective action in a timely manner, but no later than October 31, 2012. Once addressed, please submit a letter report describing the date(s), nature and location of the actions implemented to correct the areas of concern.

In the subject line of any response, please include the requested "In reply refer to:" information located in the heading of this letter. For questions pertaining to this letter, please contact Ms. Amy Grove by phone at (858) 637-7136 or by email at <u>AGrove@waterboards.ca.gov</u>.

Sincerely,

Seature Sinffer

Beatrice Griffey, M.Sc., PG Northern Cleanup Unit

Enclosure:

June 26, 2012 Inspection Report including pictures

GRANT DESTACHE, CHAIR | DAVID GIBSON, EXECUTIVE OFFICER

9174 Sky Park Court, Suite 100, San Diego, CA 92123-4353 | (858) 467-2952 | www.waterboards.ca.gov/sandiego

Recycled Paper

Tech Staff Info & Use		
Order No. Party (GT/CIWQS) ID File No. WDID	88-053 L10009404819/32483 06-0342	
NPDES No. Reg. Measure ID		
Place ID	240929	
Person ID Inspection ID	8855697	

GRANT DESTACHE, CHAIR | DAVID GIBSON, EXECUTIVE OFFICER

9174 Sky Park Court, Suite 100, San Diego, CA 92123-4353 | (858) 467-2952 | www.waterboards.ca.gov/sandiego

Recycled Paper



Landfill Inspection Report



	Name of Facility:	Mission Avenue Landfill	Date:	6/26/2012
	Owner:	City of Oceanside	WDR No.:	88-053
	Operator:	City of Oceanside	Inspection Type:	В
	Facility Address:	Mission Avenue, Oceanside	Mgr./Sup. Of Site:	Bryan Forward
	RB Inspector:	Beatrice Griffey		Colin (Chip) Brust
_	<u>المعالم المعالم المعالم</u>][

	RB Inspector: Beatrice Griffey	
Checked? (Yes/No)	Description	Comments
	WDR/File Review	
Yes	RB File Review	Technical/Correspondence
Yes	WDR Status	Closure
	Permitted Waste: Hazardous, Nonhazardous,	
	Designated, Inert, Sewage Sludge, Ash, Auto	· · · ·
Yes	Shredder, Liquids, Condensate, Other	
No	Are Self Monitoring Reports Submitted On Time?	Unknown
Yes	Have Past Violations Been Corrected?*	Yes
	*If no, identify violation(s):	
	Field Inspection	
Yes	Site Activity	Closed
Yes	WDR Reflects Current Discharge?*	Yes
	*If no, identify: WDR Not Current, Type or Rate	
	Changed, Monitoring Reporting Program	
	Changed, Inadequate Load Checking, Other	
	Cover Material, Site Conditions/Maintenance	
Yes	Type of Cover	Final Cover
Yes	Does Cover Provide Adequate Protection?*	Yes
	*If no, identify: Exposed Waste, Litter Off-site,	
	Seeps, Leachate, Ponding, Poor Drainage, Odors,	
	Other Nuisance Condition	
	Precipitation/Drainage Controls	
Yes	Is Drainage System Adequate?*	Yes
	*If no, identify: Erosion, Downcutting, Flooding, Ponding, Does Not Control Peak Flows	
	Water Quality Monitoring Program	
	Type of Monitoring Program: Surface Water,	· ·
	Groundwater, Unsaturated Zone, Condensate,	
No	Leachate, Other	
No	Is Monitoring Program Adequate?*	Unknown
	*If no, identify: Construction Problem, Broken, Could Not Find, Unknown	
No	Samples Collected? (sample no. & location)	No



Landfill Inspection Report



Additional Comments: identify each violation and/or correction

The RWQCB inspector was not able to locate MW-4 or MW-5 during the inspection, therefore the conditions of these wells are unknown. The surface drainage channels were clear of debris and sediment. With one exception the condition of the landfill cover appeared intact. The one exception was the presence of a few rodent holes in the landfill cover in the northeastern portion of the main waste area of the landfill, refer to attached pictures. These features may serve as preferential downward migration pathways for surface water, are considered to be areas of concern, and need to be addressed prior to the rainy season.

The item listed above is an area of concern for this Landfill.

Please take steps to correct this area of concern as soon as possible, but no later than (

Signed by Regional Board Inspector:

eature Griffing


Received by Manager/Supervisor:

7/20/2012

Date:

Attachments: Pictures taken during landfill inspection.

Mission Avenue Landfill June 26, 2012 Inspection Pictures




Rodent holes and mounds observed in the Landfill cover in the vicinity of the northeastern portion of the main waste area adjacent to the football field.



Rodent holes observed in the Landfill cover in the vicinity of the northeastern portion of the main waste area adjacent to the football field.



Rodent holes observed in the Landfill cover in the vicinity of the northeastern portion of the main waste area adjacent to the football field.



Surface water drainage channel along the northeastern portion of the main waste area of the Landfill.



Surface water drainage channel along the northeastern portion of the main waste area of the Landfill.