



CSRMA and  
Chris Ewers, P.E.  
(Ewers Engineering)

# FORCE MAIN CONDITION: WHAT HAVE YOU GOT?

Serve your customers well. Plan ahead.

## **Recommended reading**

The following articles provide a range of data, including California and national statistical likelihoods of force main failure, California and national sanitary agency use of condition assessment practices, and projections of pressure pipe failure rates and tools for rehabilitation.

They're also available for free.

“Best Management Practices for Sanitary Sewer Overflow Reduction Strategies,” Central Valley Clean Water Agency and Bay Area Clean Water Agency, Dec. 2009

“Buried No Longer: Confronting America’s Infrastructure Challenge,” AWWA, February 2012

2012 CSRMA Member Force Main Risk Management Survey Results, January 2013

*Inspection Guidelines for Ferrous Force Mains*, WERF report 04-CTS-6UR, 2007


State Water Resources Control Board Order No. 2006-0003-DWQ: Statewide General Waste Discharge Requirements for Sanitary Sewer Systems

If you have questions about condition assessment and its application, please contact me:

Chris Ewers, P.E.  
Ewers Engineering  
916.521.9696  
[chris@ewersengineering.com](mailto:chris@ewersengineering.com)

# Risk


The possibility of failure and consequent damage




# Likelihood of failure: 5-year record\*

## Category 1 spills:

**Number**




**Volume**



\*California State Water Resources Control Board SSO database, 1/5/2013

# Likelihood of failure: 5-year record\*

Category 1 spills by year



\*California State Water Resources Control Board SSO database, 1/5/2013

# Consequence of failure: Example 1

Spill

24" Force main rupture,  
3/31/07-4/3/07

Volume

7,300,000 gallons into lagoon



# Consequence of failure: Example 1

## Costs



|                       |                      |
|-----------------------|----------------------|
| Construction          | \$4.4 Million        |
| State fine            | \$1.1 Million        |
| Lagoon                | \$0.5 Million        |
| Staff/admin.          | \$ ?                 |
| Attorneys             | \$ ?                 |
| <i>Partial Total</i>  | <i>\$5.6 Million</i> |
| <i>Est. Pipe Cost</i> | <i>\$3.2 Million</i> |

# Consequence of failure: Example 1

## Time

Cleanup-  
Construction

4/2007-12/2012

*(5 years, 8 months of agency time)*

# Consequence of failure: Example 2

**Spill**

Multiple system failure,  
flooding at WWTP, 1/2008

**Volume**

7,000,000 gallons into Pacific



# Consequence of failure: Example 2

## Costs

|                              |                       |
|------------------------------|-----------------------|
| Construction, repairs (est.) | \$50 Million          |
| State fine                   | \$2.3 Million         |
| Staff/admin.                 | \$ ?                  |
| Attorneys                    | \$ ?                  |
| <i>Partial Total</i>         | <i>\$52.3 Million</i> |

# Consequence of failure: Example 2

## Time

Cleanup-  
Construction

1 / 2008-today

*(5 years and counting of agency time)*

# Goal

**Put you on the path to a healthy,  
well-managed system of force  
mains.**

# Agenda: Condition Assessment

---

1

What we are doing

2

What we can do

3

Guidelines for implementation

# Agenda: Condition Assessment

---

1

What we are doing

2

What we can do

3

Guidelines for implementation

# Force Mains in California\*




- Age
  - ▣ Average: 32 years
- Length per agency
  - ▣ Average: 15 miles

*\*CSRMA survey of member agencies on force mains, 12/2012*


# Condition Assessment in California\*

## Condition assessment techniques




\*CSRMA survey of member agencies on force mains, 12/2012

# Force Mains in the U.S. \*




## Age of force mains



\*WERF Final Report, Inspection Guidelines for Ferrous Force Mains, 2007

# Condition Assessment in the U.S.\*




- Budget: \$4.13/foot (average)
- Spent: \$24.05/foot (average)

(Includes inspection, assessment, repair, and cleanup.)

\*WERF Final Report, Inspection Guidelines for Ferrous Force Mains, 2007

# What we are doing: Conclusions



- Force mains
  - ▣ Small diameter (4"-20")
  - ▣ Ferrous (DIP, CIP, Steel ~60%)
  - ▣ <<50 years old when replaced
- We underestimate repair and cleanup costs from failures.
  - ▣ Condition assessment is not effectively used.

# Agenda: Condition Assessment

---

1

What we are doing

2

What we can do

3


Guidelines for implementation

# Goal of Condition Assessment

---


- Determine likelihood of failure:
  - ▣ Know where and when to repair and maintain
  - ▣ Know how long to maintain until replacement
  - ▣ Use time until replacement to set aside funding

# Goal of Condition Assessment




# Goal of Condition Assessment

Third-party construction emergency!



# Goal of Condition Assessment

## Force main corrosion



A decorative horizontal bar at the top of the slide, consisting of an orange rectangular block on the left and a blue rectangular block on the right.

# Indirect condition assessment tools

# Inventory

**Know  
what you  
have to  
get  
started.**

- Identify and map
  - ▣ Pumping facilities
  - ▣ Force mains and valves
  - ▣ Access points
- Materials, diameters, age of pipe, repair history
  
- Preparation: Minimal
- Cost: Staff time

# Site visit

**Know  
what you  
have to  
get  
started.**

- Verify mapping, diameter, materials
- Evaluate air release/air vacuum valves
- Signs of leakage, construction disturbance
  
- Preparation: Minimal
- Cost: Staff time

# Performance tests

**Know  
what you  
have to  
get  
started.**

- ❑ Lift station: pressure/flow
- ❑ Pressure: Transient max.?
- ❑ Corrosion test stations
  
- ❑ Preparation: Minimal
- ❑ Cost: Staff time, equipment

# Visual inspection: CCTV

**Know  
what you  
have to  
get  
started.**

- ❑ Requires force main out of service for extended duration
- ❑ Access may require construction
- ❑ Dark pipe reduces value
- ❑ Look for seepage into dewatered pipe
  
- ❑ Preparation: Depressurize, dewater, install or use access
- ❑ Cost: Staff time, equipment ~ \$3/foot

# Leak and gas pocket detection

**Know  
what you  
have to  
get  
started.**

- **Technology: Acoustic sensing**
  - **In-line**
    - Tethered: Sahara hydrophone
    - Free-swimming: SmartBall hydrophone
  - **Acoustic field testing**

# Leak and gas pocket detection

Technology: Acoustic sensing (hydrophone)

- Aided by high pressure, high flow ( $Re \geq 1,000$ )
- Sound of wastewater passing gas pockets permits their detection



# Leak and gas pocket detection

Technology: Acoustic sensing (hydrophone)

- Field hydrophones


- ▣ Attach hydrophone to live pipeline

- Sahara

- ▣ Tethered: Refined, repeatable location ( $\geq 0.25$  gpm leaks)

- Smartball

- ▣ Free-swimming: Accommodates long intervals at 3 mph min.



# Leak and gas pocket detection

|                               | In-Line           |                   | Field                        |
|-------------------------------|-------------------|-------------------|------------------------------|
|                               | Sahara            | SmartBall         | Field hydrophones            |
| Technology                    | Acoustic          | Acoustic          | Acoustic                     |
| Material                      | All               | All               | All                          |
| Sizes                         | $\geq 4''$        | $\geq 6''$        | All                          |
| Preparation                   | Access: 2" tap    | Access: 4" port   | Access: Pipe wall or appurt. |
| Cost<br>(mobilization/\$/mi.) | \$35,000/\$35,000 | \$25,000/\$12,000 | Equipment                    |



# Direct condition assessment tools

# Structural integrity assessment


**Combine  
acoustic  
tools to  
assess  
pipe wall  
thickness**

- **Technology: Acoustic sensing**
  - **Acoustic field testing**

# Structural integrity assessment

## Technology: **Acoustic sensing (hydrophone)**

- Hydrophone receives/correlates pipe noise
- Speed of wave reflects rigidity of pipe
- Bulk modulus of sewage needed for pipe thickness



# Structural integrity assessment


|                               | In-Line | Field                            |
|-------------------------------|---------|----------------------------------|
|                               |         | Field hydrophones                |
| Technology                    |         | <b>Acoustic</b>                  |
| Material                      |         | All                              |
| Sizes                         |         | All                              |
| Preparation                   |         | Access: Three 6" pipe wall seats |
| Cost<br>(mobilization/\$/mi.) |         | X/\$30,000                       |

*Not yet commercially available*

# Structural integrity assessment

Tried,  
proven  
tool for  
profiling  
pipe wall

- Technology: **Ultrasonic Testing**
  - Coating removal, cleaning
  - Calibration with pipe wall required
  - Hand-held: B-Scan
  - Circumferential: Guided-Wave (50-500 ft.)



# Structural integrity assessment

Hand-  
scan tool  
for  
detecting  
anomalies  
in ferrous  
pipes

- Technology: **Broadband Electromagnetic Testing**
  - Scans through 2” coating
  - Uses eddy current sensing
  - Data interpreted in Australia
  - Slow process finds relative changes in wall



# Structural integrity assessment

## Field

|                               |   |                              |
|-------------------------------|---|------------------------------|
| Technology                    | Ultrasonic: B-Scan,<br>Guided-Wave          | Broadband<br>Electromagnetic |
| Material                      | Ferrous                                     | Ferrous                      |
| Sizes                         | ≥6"   | ≥6"                          |
| Preparation                   | Access: Full<br>diameter, remove<br>coating | Access: Full<br>diameter     |
| Cost<br>(mobilization/\$/mi.) | \$3,500/read                                | \$3,500/read                 |

# Structural integrity assessment

In-line  
tool with  
the finest  
resolution  
available  
for PCCP  
testing

- Technology: **Magnetic Flux Leakage**
  - In-line, sized to match pipe
  - Scans through mortar coating
  - Requires full-diameter access
  - Characterizes PCCP strand damage, small pits in ferrous walls
  - Cracks are often not detected



# Structural integrity assessment

Live-pipe,  
free-  
swimming  
test of  
PCCP pipe  
walls

- Technology: **Remote Field Transformer Coupling (Pipe Diver)**
  - In-line, scans through mortar coating
  - Launch in live force main
  - Characterizes PCCP strand damage, ferrous pipe wall damage
  - Navigates bends, valves



# Structural integrity assessment

Flooded-  
pipe  
platform  
that can  
test PCCP  
pipe walls

- Technology: **SONAR, P-wave electro magnetics, CCTV, laser profiling, (robotic platform)**
  - In-line, tethered
  - Crawl 40 feet/min.,  $\leq 8,000$  feet
  - Float  $\leq 16,000$  feet
  - Characterizes PCCP strand damage, profiles, visual assessment



# Structural integrity assessment

|                               |                              | In-line                           |                              |
|-------------------------------|------------------------------|-----------------------------------|------------------------------|
|                               | Magnetic Flux Leakage Pig    | Pipe Diver (free-swimming)        | Robotic (tethered)           |
| Technology                    | Magnetic Flux Leakage        | Remote Field Transformer Coupling | P-Wave EM, laser, CCTV, etc. |
| Material                      | PCCP, BWP                    | PCCP, BWP                         | PCCP, BWP                    |
| Sizes                         | 8"-78"                       | 24"-96"                           | 18"-72"                      |
| Preparation                   | Access: Full inter. diameter | Access: 12" ports                 | Access: 14"x16"              |
| Cost<br>(mobilization/\$/mi.) | \$40,000/\$40,000            | \$40,000/\$40,000                 | \$40,000/\$40,000            |

# Agenda: Condition Assessment

---

1

What we are doing

2

What we can do

3

Guidelines for implementation

# Guidelines for implementation

---

- Watch out for big data.
- Pick the technology that fits your force main and budget.
- Start simple, invest more as you know more.
- Prioritize your efforts.



# Questions?

Chris Ewers, P.E.  
Ewers Engineering  
*chris@ewersengineering.com*  
916.521.9696