

Arroyo Sequit Fish Barrier Photograph Description

Photographer:

Kevin Jontz, Restoration and Monitoring Specialist- Heal the Bay Stream Team

Rationale:

Endangered Steelhead Trout face multiple barriers to upstream migration in Arroyo Sequit Creek at Leo Carrillo State Park. These photos were taken to provide further evidence that fish barriers are present in Arroyo Sequit Creek.

Photo Description:

Date, Time, Latitude and Longitude of photographs are imbedded in each image. Details of the camera and camera settings are in photo properties (right click image file, click properties, see tab titled "Details")



ARROYO 1-Looking upstream from slight angle at Barrier 1



ARROYO 2-Looking off to side of Barrier 1



ARROYO 3-Looking upstream Arroyo Sequit at Barrier 2



ARROYO 4-Looking downstream Arroyo Sequit at Barrier 2

Spatial Representation:





