


SOURCE: Tuolumne County, 2004; and ESA, 2006

**Figure 5-1**  
Surface Water Monitoring Locations





SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-9**  
GV-1 Monitoring Location






Development of an algal bloom below Lime Kiln Road on Curtis Creek.



Livestock observed within a contributing drainage to Curtis Creek. Livestock waste was observed along channel banks and, in some locations, within the actual channel.




SOURCE: CDEC, 2006; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-2**  
Daily Rainfall at Sonora





SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-3**  
MM-1 Monitoring Location






SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-4**  
WD-1 Monitoring Location





SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-5**  
SV-1 Monitoring Location






SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-6**  
SV-2 Monitoring Location





SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-7**  
CT-1 Monitoring Location





SOURCE: USGS, 2002; and ESA, 2006

Tuolumne County Foothill Watershed Assessment . 204254

**Figure 5-8**  
TB-1 Monitoring Location