



Below are brief descriptions of the photographs, Exhibit 5.

[Picture 002](#)- Toz inspecting the Stanshaw Creek refugia pool after during a fish kill at the site in July 2009.

[Picture 003](#)- A picture of the refugia pool after a fish kill was reported in July 2009. It appears to be refilling after being recently dewatered.

[Picture 004](#)- A photo of a dead juvenile Coho found floating on the surface of the refugia pool after the resident landowner reported a fish kill at the site in July 2009.

[Picture 006](#)- A photo of a dead juvenile floating on the water surface of the refugia pool after a reported fish kill in July 2009.

[Picture 008](#)- A photo of the staff gauge located in the Stanshaw Creek refugia pool.

[Picture 010](#)- A photo of the inflow channel to the Stanshaw Creek refugia pool during a reported fish kill in 2009. The channel appears to have recently head cut which is an indication the pool was drawn down rapidly. The sand bar bench was the pool surface water elevation prior to being dewatered.

/s/Toz Soto

October 6, 2017