Exhibit 19

Prosecution Team Evidence List Exhibits for:

Rocklin Crossings

Photo 1. Lincoln Bypass Project, 12 October 2010. Seed, straw and tack applied to disturbed soil areas as permanent erosion controls.

Photo 2. Lincoln Bypass Project, 25 October 2010. Seed, straw and tack applied to disturbed soil areas near Orchard Creek as permanent erosion controls.

Photo 3. Rocklin Commons, 24 December 2012. Hydro-mulch applied to disturbed soil areas as temporary erosion controls.

Photo 4. Rocklin Commons, 24 December 2012. Hydro-mulch applied to disturbed soil areas as temporary erosion controls.

Photo 5. Lincoln Bypass Project, 13 October 2009. Rock check dam installed within a roadside drainage ditch.

Photo 6. Lincoln Bypass Project, 16 December 2009. Temporary straw bale berm covered with plastic installed in a roadside drainage ditch.

Photo 7. Lincoln Bypass Project, 25 October 2010. Temporary straw bale berm covered with plastic installed in a roadside drainage ditch.

Photo 8. Lincoln Bypass Project, 20 January 2010. Temporary straw bale and sand bag berm covered with plastic installed in a roadside drainage ditch. The outflow channel was also protected with plastic.

Photo 9. Lincoln Bypass Project, 25 October 2010. Temporary straw bale berm covered with plastic installed in a roadside drainage ditch.

Photo 10. Rocklin Commons, 24 December 2012. Temporary earth berm covered with plastic and weighted with sand bags. This area was used as a temporary detention basin during the December 21st through the 25th, 2012 rain event.