

## PT EXHIBIT 3

### Proposed Revocation Hearing

Millview County Water District

License 5763 (Application 15679)

### WRITTEN TESTIMONY OF LAUREN MULLOY, ENVIRONMENTAL SCIENTIST

My name is Lauren Mulloy. I am currently an Environmental Scientist with the California Department of Fish and Wildlife (Department). Prior to working with the Department, I was an Environmental Scientist assigned to the Inland Stream Unit of the Permitting Section, Division of Water Rights (Division), State Water Resources Control Board (State Water Board). I have a B.A. in Biological Sciences from the California State University of Sacramento. I was employed with the Division from 2007 to 2009. I have been employed by the Department since 2009. A copy of my resume is attached as Prosecution Team (PT) Exhibit 4.

When I was with the Division I was responsible for processing water right applications, change petitions, permits and licenses, as well as voluntary and statutory revocations of water right permits and licenses. I would review all pertinent information associated with pending water right applications and change petitions. As the Water Rights Coordinator for the Department's North Central Region Water Program, I am responsible for determining whether there is potential to cause adverse impacts on fish, wildlife and public trust resources from the proposed water right applications and change petitions and.

#### April 27<sup>th</sup>, 2008 Site Inspection

On April 27<sup>th</sup> 2008, I met with the Millview County Water District (Millview) General Manager, Tim Bradley, to conduct a site inspection of the Masonite plant and well sites. The purpose of the site inspection was to document the condition of the authorized place of use and points of diversion for License 5763. The photographs referenced in this testimony and included in the Field Investigation Report I prepared for the April 27, 2008 investigation are true and correct copies of photographs I took of the site during the investigation.

Upon arrival at the Masonite site it was apparent the Masonite Plant had been shut down and dismantled. Only an empty warehouse remained. There were three wells located on the property, Well No. 3, Well No. 4 and Well No. 5. Well No. 4 was abandoned and filled in with sand. Well Nos. 3 and 5 appeared to not have been in use for some time. There was vegetation growing around the well structures and the electrical boxes were in disrepair. Photographs showing the condition of the wells are included in the Field Inspection Report. (PT Exhibit 20.) I

observed and documented that the electrical wire and the power lines supplying the wells were missing.

After leaving the Masonite Plant, I visited the Millview Well Field located on the East side of the River. The Millview Well Field was not listed as an authorized point of diversion under License 5763. The Millview Well Field was a proposed point of diversion that Millview requested the Division of Water Rights add to License 5763. (PT Exhibit 19.) At the conclusion of the site inspection I prepared a site inspection report documenting conditions at the site. (PT Exhibit 20.)

Based on information obtained during the site investigation and supporting information in the file for License 5763 my conclusion is that water had not been diverted under License 5763 for at least five years prior to the site inspection.