CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD CENTRAL COAST REGION 895 Aerovista Place, Suite 101 San Luis Obispo, CA 93401-7906

ADMINISTRATIVE CIVIL LIABILITY ORDER NO. R3-2005-0025

Issued to:

Haig Kelegian San Luis Obispo County

The California Regional Water Quality Control Board, Central Coast Region, finds:

- 1. Haig Kelegian (hereafter Discharger) is the owner of 412 acres of land in the Creston area of San Luis Obispo County. The specific location is Section 31, Township 28 South, Range 14 East, Mount Diablo Base, and Meridian (35° 27′- Latitude, 120° 25′- Longitude). The property has on occasion been referred to as Kelegian Ranch, and Kelegian Creston Ranch. During the summer of 2002, the Discharger cleared and grubbed most of the vegetation from approximately 200 of the 412 acres. The 200-acre area will hereafter be referred to as the Site.
- 2. The Site drains to an unnamed "blue line" stream that is tributary to Huerhuero Creek, both of which are waters of the state. Huerhuero Creek is tributary to the Salinas River. The Water Quality Control Plan, Central Coast Region (Basin Plan) designates protection of both recreation and aquatic life as beneficial uses of the unnamed "blue line" stream, and municipal and domestic water supply, agricultural supply, ground water recharge, water contact recreation, non-contact water recreation, wildlife habitat, warm freshwater habitat, rare, threatened, or endangered species, and commercial and sport fishing as beneficial uses of Huerhuero Creek.
- 3. By removing most of the vegetation from the Site during August 2002, without ever implementing effective Best Management Practices (BMPs) to control erosion and sediments, the Discharger discharged or threatened to discharge soil to waters of the

- state. The threatened discharged was present for at least 185 days, from September 1, 2002, when vegetation removal was completed, until at least March 4, 2003, when Water Board staff documented the soils were not adequately stabilized. The precise time the soils stabilized is unknown; after March 4, 2003, soils were still eroding and being discharged to state waters. Water Board staff inspected the Site next on September 19, 2003; at that time the soils appeared to be mostly stable.
- 4. On November 8, 2002, Water Board staff first witnessed and documented eroded soil sediments being discharged from the Site to waters of the state.
- 5. The Basin Plan contains several Land Disturbance Prohibitions in Chapter 4. Implementation Plan, page IV-70. The Discharger violated the following prohibition:

VIII.E.1. LAND DISTURBANCE PROHIBITIONS

The discharge or threatened discharge of soil, silt, bark, slash, sawdust, or other organic and earthen materials into any stream in the basin in violation of best management practices for timber harvesting construction, and other soil disturbance activities and in quantities deleterious to fish, wildlife, and other beneficial uses is prohibited.

6. The Discharger discharged and threatened discharge of soil, silt, and other organic and

Item No. 19 Attachment No. 19 July 7-8, 2005 Meeting Haig Kelegian ACL earthen materials into the blue line stream and Huerhuero Creek in violation of best management practices for soil disturbance activities and in quantities deleterious to fish, wildlife, and other beneficial uses. The Discharger violated this prohibition by removing most of the existing vegetation from the Site without implementing BMPs to eliminate or minimize erosion and sediment discharges. The Site qualifies as a severe erosion hazard as established by the Resource Conservation District.

- 7. Pursuant to California Water Code Sections 13350(e)(1), the Water Board may impose civil liability up to \$5,000 per day for each day a violation occurs. The Discharger violated a Basin Plan prohibition for a total of at least 185 days each. The maximum liability that may be imposed is \$925,000 (nine hundred twenty-five thousand dollars).
- 8. As required by California Water Code Section 13327, the Regional Board considered:
 - a. nature, circumstances, extent, and gravity of the violations
 - b. discharge susceptibility to cleanup or abatement
 - c. discharge toxicity
 - d. ability to pay and the effect on ability to continue in business
 - e. voluntary cleanup efforts undertaken
 - f. violation history
 - g. degree of culpability
 - h. economic benefit or savings (if any), and
 - i. other matters as justice may require.

Nature, circumstances, extent, and gravity of the violation or violations

The Discharger removed most of the existing vegetation from the Site during the summer of 2002, without implementing any form of erosion controls, and with sediment controls that were ineffective.

On October 1, 2002, Water Board staff inspected the Site. The Discharger's representative proposed to seed the site as a means of erosion control. The Discharger did not propose any other BMP. Water Board staff sent a letter dated October 8, 2002 addressing best management practices:

"...applying seed alone is not a sufficient erosion control measure. Established vegetation is a means of erosion control; thus, the seed must be nurtured into vegetation before runoff occurs to be effective erosion control."

During the fall of 2002, Water Board staff sent letters dated October 8, November 12, and November 25, 2002, urging the Discharger to provide effective erosion and sedimentation controls for the Site. These efforts also included an Administrative Civil Liability Complaint dated November 21, 2002. Although the Discharger made some efforts to prevent erosion and the discharge of sediments, he failed to use best management practices. Although the Water Board staff made repeated efforts to convince the Discharger that effective BMPs were essential to prevent erosion and the discharge of sediment, the Discharger's effort's remained ineffective. The Discharger's efforts in part consisted of spreading loose straw on the Site. However, the Discharger did not apply a tackifier to make the straw cohesive or crimp the straw into the soil to prevent it from being mobilized by rain and wind, thus rendering the straw ineffective. Fiber rolls or straw wattles were placed on some slopes, but the distance between them was too great to reduce runoff velocities and eliminate erosion or trap sediments. Hay bales were used in some areas, in an apparent attempt to trap sediments, but were installed improperly; flush with the ground surface rather than recessed below the surface, and with up-gradient drainage areas too great for the bales to be effective. The piles of cleared vegetation that were left at the base of some slopes were purported by the Discharger's consultant to be functioning as sediment controls or barriers, however they were largely ineffective because the vegetation consisted mostly of lightweight brush that was lying loosely on the ground surface. The steep grades and large up-gradient areas resulted in storm water runoff volumes and velocities that rendered the brush ineffective. Existing erosion rills compounded the ineffectiveness of these efforts. No attempt was made to eliminate the rills, either prior to the installation of the BMPs, or later following rain events, and as a result, the rills became more pronounced as the rainy season progressed.

From the beginning of the project, the Discharger violated the prohibition by threatening the

discharge in violation of best management practices. In addition, sediment discharges occurred periodically throughout the entire rainy season of 2002-2003, and receiving water beneficial uses were adversely affected. Thus, the discharge constituted a condition of pollution as defined by the California Water Code section 13050(1).

Because the Discharger removed most of the vegetation from the 200-acre Site, there was a major threat of larger discharges that would have more severely impaired beneficial uses. Larger quantities of sediment would have been discharged from the Site if storms had been more intense or more frequent.

Because the vast majority of all eroded sediments were discharged to the blue line stream and Huerhuero Creek, and the sediments were not recovered, the receiving waters bore the full impact of the illicit discharges. Soil sediments are known to be deleterious to fish, wildlife and other beneficial uses of surface waters. The following excerpt is from the US Environmental Protection Agency document titled "Protocol For Developing Sediment TMDLs, First Edition:

"IMPACTS OF SEDIMENTS ON DESIGNATED USES

Aquatic life and fisheries

Excessive sediments deposited on streams and lake bottoms can choke spawning gravels (reducing survival and growth rates), impair fish food sources, fill in rearing pools (reducing cover from prey and thermal refuge), and reduce habitat complexity in stream channels. Excessive suspended sediments can make it more difficult for fish to find prey and at high levels can cause direct physical harm, such as clogged gills, In some waters, hydrologic modifications (e.g., dams) can cause sediment deficits that result in stream channel scour and destruction of habitat structure."

A report prepared by the RCD concerning soil conditions on adjacent acreage discussed the damage soil erosion that other landowners had done to the Huerhuero Creek watershed. The RCD Report states:

"Consequently it is critical, at this time, that proper erosion and sediment control be exercised throughout the water sheds draining into Huerhuero Creek to preclude further damage to or elimination of remaining vegetation in the creek. This would include all work done on the applicant's property. Similar measures should be underwritten for other development being proposed in this region of the county."

The sediment discharges adversely affected beneficial uses and, because the Discharger removed most of the vegetation from a 200-acre site, threatened subsequent discharges were in amounts deleterious to fish, wildlife and other beneficial uses. The Discharger violated the Discharge Prohibition for the entire rainy season of 2002-2003. Also, because such a large area of high erosion hazard soil was cleared, there was a significant threat of larger discharges. Finally, Water Board staff communicated numerous times regarding its concerns and BMP requirements. To a large degree, the Discharger ignored these communications. As a result, a significant amount of liability is justified. Maximum liability is not justified however, because the violations were not toxic, the most harmful nor the most extensive violations covered by Water Code section 13350.

Consideration of this factor justifies assessment of civil liability that is significant, but less than the maximum

Whether the discharge is susceptible to cleanup or abatement

Although it is possible that at least some of the discharged sediments could have been cleaned up, it was probably not prudent to do so because doing so can often be more damaging than if the sediments are left in place. As a result, a significant amount of liability is justified. Maximum liability is not justified, however, because the violations were not toxic, the most harmful nor the most extensive violations covered by Water Code section 13350.

Consideration of this factor justifies assessment of civil liability that is significant but less than the maximum.

The degree of toxicity of the discharge

There is no reason to believe that the discharged sediments were toxic.

Consideration of this factor justifies assessment of civil liability that is less than maximum.

With respect to the violator, the ability to pay, the effect on ability to continue in business

The Water Board has no evidence regarding the Discharger's financial resources or the ability to stay in business.

Consideration of this factor does not affect the amount of liability assessed.

Any voluntary cleanup efforts undertaken

The Discharger never proposed or initiated any efforts to remove the discharged sediments from waters of the state. However, Water Board staff would probably have discouraged such efforts as being impractical because efforts to remove the sediments in this case could have been more damaging than if they were left in place.

Consideration of this factor justifies assessment of civil liability that is significant but less than the maximum.

Any prior history of violations

The Water Board has no evidence of any prior violations of environmental laws by the Discharger.

Consideration of this factor justifies assessment of civil liability less than the maximum.

The degree of culpability

The Discharger removed most of the vegetation from an area known for severe erosion hazard soils without initiating effective BMPs, and as a result the soils eroded and discharged and threatened discharge of soil and silt in amounts deleterious to fish, wildlife and beneficial uses of the blue line stream and Huerhuero Creek. Even after Regional Board staff instructed the Discharger that, to be an effective BMP, seeding must include nurturing seed into vegetation as a means of erosion control, the Discharger did little to prevent the seed from being washed away by storm water runoff. The Discharger failed to implement this best management practice throughout most of the Site for the entire rainy season of 2002-2003. The Discharger failed to implement effective best management practices despite repeated visits, discussions and warnings from Regional Board staff. The Site extensively stabilized and the prohibition violations essentially ceased after the 2002-2003 rainy season.

The Discharger's failure to comply over an entire rainy season despite knowledge of the environmental consequences and opportunities to come into compliance indicates a high degree of culpability. Consideration of this factor justifies assessment of a significant portion of the maximum liability.

Economic benefit or savings, if any, resulting from the violation

Although Regional Board staff does not have specific information to determine the actual amount, the Discharger realized some savings from not providing effective BMPs. Because of the steepness of the terrain and erosive nature of the soil, in order to prevent erosion and allow seeds to mature into vegetation, Central Coast Water Board staff feels that the vast majority of the Site needed to be covered with erosion mats. The steep terrain would have also made installation of the mats labor intensive. The cost of purchasing, installing, and maintaining erosion mats would have substantially increased the Discharger's BMP expenditures.

Consideration of this factor justifies assessment of a significant portion of the maximum.

Other matters that justice may require

The actions and inactions of the Discharger are by themselves deserving of strong, decisive enforcement. Enforcement is also necessary to deter others from doing as the Discharger has done.

During the past three years, Water Board staff has spent an extensive amount of time addressing water quality concerns on the Discharger's property. Using conservative estimates, staff has spent 359 hours on the matter at a cost \$26,925 (Hourly Rate = \$75).

Consideration of this factor justifies assessment of civil liability that is not less than \$26, 925 (twenty six thousand, nine hundred and twenty five dollars).

- 9. Upon consideration of factors as required by California Water Code Section 13327, the Executive Officer recommends civil liability be assessed in the amount of \$100,000 for the Discharger's violations of the Basin Plan Prohibition from September 1, 2002 through March 4, 2003.
- 10. This enforcement action is taken for the protection of the environment and as such is exempt from provisions of the California Environmental Quality Act (Public Resources Code Section 21000, et seq.) in accordance with California Code of Regulations, Title 14, Sections 15307 and 15308.
- 11. A hearing on this matter was held before the Water Board on July 8, 2005, at 895 Aerovista Place, Suite 101, San Luis Obispo, California. The Discharger, and the Discharger's representative(s), had the opportunity to be heard and to contest the allegations in the

- Complaint No. R3-2005-0025, which recommended the imposition of civil liability by the Water Board.
- 12. Following completed testimony on July 8, 2005, the hearing was closed and the Water Board deliberated. This Administrative Civil Liability Order No. R3-2005-0025 is adopted based upon the evidence and arguments presented at the hearing and relevant evidence in the Water Board files and upon consideration of the factors mandated by Water Code section 13327.
- IT IS HEREBY ORDERED, pursuant to California Water Code Section 13350, Haig Kelegian is assessed a total civil liability of \$100,000 (one hundred thousand dollars) to be delivered to the Regional Water Quality Control Board at the letterhead address by August 9, 2005. The check is to be made payable to the State Water Resources Control Board.

I, Roger W. Briggs, Executive Officer,	do hereby certify that the foregoing is a full, true, and correct copy of
an order adopted by the Regional Water	Quality Control Board on July 8, 2005.

Roger W. Briggs, Executive Officer	Date

S:\Storm Water\Construction\San Luis Obispo Co\319350, Kelegian, Crest\ACL - 04\ACL-II\Final\Kelegian Order 6-15-05 FINAL.doc