



GROUNDWATER FLOW DIRECTION Second Quarter 2010 to Third Quarter 2015*



Each shaded area represents data from one groundwater monitoring event

Rose diagram showing groundwater gradient direction from Second Quarter 2010 measured at the Lake Tahoe Laundry Works site through Third Quarter 2015.

*with the exception of First Quarter 2011





Lake Tahoe PCE Summary


Comments on Proposed Cleanup and Abatement Order No. R6T-2015-PROP Lake Tahoe Laundry Works South Lake Tahoe, California

2/16

1021.001.01.00&02100101008 CommdrCAO 1 DRAWING NUMBER

KSF

REVIEWED BY





from Shallow Water-Bearing Zone (2001-2008)

Comments on Proposed Cleanup and Abatement Order No. R6T-2015-PROP Lake Tahoe Laundry Works

South Lake Tahoe, California

PLATE


1021.001.01.008

102100101008 CommdrCAO 2-3

KSF

REVIEWED BY

2/16





from Middle Water-Bearing Zone (2001-2008) Comments on Proposed Cleanup and Abatement Order No. R6T-2015-PROP

Lake Tahoe Laundry Works South Lake Tahoe, California PLATE

1021.001.01.008

102100101008 CommdrCAO 2-3

KSF

REVIEWED BY

2/16