

Technical Report – Ridgeway

Order # R4-2015-0453

1. Both catch basins (Sumps) are unlined in heavy shale rock.
2. Both sumps have been in use for decades.
3. Any discharges have been negligible and were used only as required as emergency safety catch basins.
4. Any discharges into any sumps were clear water only and used minimal over the years.
5. No solid waste have every been discharged into sumps
6. There are no domestic or municipal water wells within 3.5 miles of the sumps.
7. n/a
8. n/a
9. n/a
10. No new wells have been drilled on our property in 40 years nor any plans.
11. Only one water discharged was made in the last 25 years and the sump was dry within an hour.