


117°00'W 116°30'W 115°00'W 115°30'W 115°00'W SAN BERNARDINO CO

117°00'W 116°30'W 115°00'W 115°30'W 115°00'W

117°00'W 116°30'W 115°00'W 115°30'W 115°00'W


117°00'W 116°30'W 115°00'W 115°30'W 115°00'W

117°00'W 116°30'W 115°00'W 115°30'W 115°00'W




Twentynine Palms Sanitary Landfill

- Landfill Site
- Quaternary Faults - CGS



Geologic Map of the Sheep Hole 30'x60' Quadrangle, San Bernardino and Riverside Counties, California - Howard, 2002

COLORADO RIVER REGIONAL WATER QUALITY CONTROL BOARD
 BOARD ORDER R7-2015-0019



EXPLANATION:

- TNP-8
|||
(1526.90)
 - TNP-1
|||||
 - (0.014).
 - (NO)
 - NO DATA AVAILABLE APPROXIMATE
 - LIMIT OF REFUSE APPROXIMATE
 - PROPERTY BOUNDARY
- GROUNDWATER MONITORING '11a.1. LOCATION AND
 GROUNDWATER ELEVATION IN FEET ABOVE MEAN
 SEA LEVEL (USING CORRECTION FACTORS FROM
 GYROSCOPE DIRECTIONAL SURVEY)
- SOIL-PORE GAS MONITORING PROBE LOCATION
- CONTOUR LINE SHOWING GROUNDWATER
 POTENTIOMETRIC SURFACE ELEVATION, DASHED
 WHERE INFERRER (CONTOUR INTERVAL - 2 FEET)
- GROUNDWATER FLOW DIRECTION AND RATE (ft./ft.)

DECEMBER 2005 TOPOGRAPHIC PLAN PROVIDED BY SAN BERNARDINO COUNTY

GRAPHIC SCALE
 100 0 100 200
 (in feet)

2014 GROUNDWATER EQUIPOTENTIAL CONTOURS
 WATER QUALITY MONITORING 2014
 TWENTYNINE PALMS SANITARY LANDFILL.

COUNTY OF SAN BERNARDINO
 TWENTYNINE PALMS LANDFILL

GROUNDWATER CONTOUR MAP/WELL
 LOCATIONS ATTACHMENT C