



California Regional Water Quality Control Board, San Diego Region

June 25, 2012

In reply refer to: CRU: 9 00000400: KSchwall CIWQS Place ID: 215572

Russell A. McCarthy, Jr. Director of Administration Continental Maritime of San Diego 1995 Bay Front Street San Diego, CA 92113

Dear Mr. McCarthy:

Subject:

CORRECTIONS TO LETTER DATED JUNE 19, 2012: REVIEW OF SEPTEMBER 2008 – MARCH 2012 SELF MONITORING REPORTS FOR ORDER NO. R9-2008-0049, AND JULY 2007 – AUGUST 2008 SELF MONITORING REPORTS FOR ORDER NO. R9-2002-0282, NPDES PERMIT NO. CA0109142, CONTINENTAL MARITIME OF SAN DIEGO

The California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) has completed review of the referenced reports for the subject facility. Please note the following comments and violations on the reports received:

Violations for Order No. R9-2002-0282

- 1. On October 4, 2007, approximately 10 gallons of fuel spilled into the bay.
- 2. On March 27, 2008, there was an oil sheen of unknown amount in the bay.

Violations for Order No. R9-2008-0049

- 3. On September 9, 2008, a small amount of soapy water was discharge into the bay.
- 4. On February 20, 2009, there was a diesel oil sheen less than one liter in the bay.
- 5. On March 5, 2009, less than 2 gallons of descaler/hcl were spilled into the bay.
- 6. On March 13, 2009, less than a quarter gallon of diesel oil spilled into the bay.
- 7. On August 24, 2009, about 10 gallons of canola oil spilled into the bay.
- 8. On December 23, 2010, less than 5 gallons of oil spilled into the bay.
- 9. On February 15, 2011, approximately 1.5 lb of abrasive blast dust went into the bay.
- 10. On April 6, 2011, about 1/2 lb of abrasive grit dust spilled into the bay.
- 11. On April 11, 2011, abrasive blasting grit dust leaked into the bay.
- 12. On April 25, 2011, about 1/2 a cup of hydraulic oil leaked into the bay.
- 13. On May 3, 2011, about 1/2 lb of abrasive grit dust spilled into the bay.
- 14. On June 3, 2011, about 4 ounces of fine paint dust spilled into the bay.
- 15. On June 7, 2011, approximately 4 ounces of paint chips and dust spilled into the bay.

The heading portion of this letter includes a San Diego Water Board code number noted after "In reply refer to:" In order to assist us in the processing of your correspondence please include this code number in the heading or subject line portion of all correspondence and reports to the San Diego Water Board pertaining to this matter.

GRANT DESTACHE, CHAIR | DAVID GIBSON, EXECUTIVE OFFICER



Russell A. McCarthy, Jr. Director of Administration

If you have any questions regarding the above, please contact Kristin Schwall at (858) 467-2345 or KSchwall@waterboards.ca.gov.

- 2

Sincerely,

Robert Marrie

Robert W. Morris Senior Water Resource Control Engineer

RWM:ks

RM: 385614

V: 1) 928395, 2) 928396, 3) 928397, 4) 928398, 5) 928399, 6) 928400, 7) 928401, 8) 928402, 9) 928403, 10) 928404, 11) 928405, 12) 928406, 13) 928407, 14) 928408, 15) 928409

| WDID | 9 000000400 | WDID | 9 000000400 |
|-----------------|--------------|-----------------|--------------|
| Order No. | R9-2008-0049 | Order No. | R9-2002-0282 |
| NPDES No. | CA0109142 | NPDES No. | CA0109142 |
| CIWQS Place ID | 215572 | CIWQS Place ID | 215572 |
| Reg Measure No. | 352044 | Reg Measure No. | 131371 |
| Party ID | 9293 | Party ID | 9293 |

GRANT DESTACHE, CHAIR | DAVID GIBSON, EXECUTIVE OFFICER

9174 Sky Park Court, Suite 100, San Diego, CA 92123 | (858) 467-2952 | www.waterboards.ca.gov/sandiego

Recycled Paper