Notice of Termination (NOT) is being prepared since this facility does not operate under any of the covered SIC Codes identified in Attachment A of the IGP."

In addition to, and related to, the SIC Code issue, the site has a lot going on and has an outdoor wash station for washing vehicles and construction equipment (which is the source of a lot of oil and grease, etc... The water from the wash station flows into an inlet that routes the water through a four stage clarifier that discharges to the sanitary sewer, <u>except</u> in the event of heavy/persistent rainfall, in which case it overflows/bypasses the sanitary sewer and discharge to surface waters via the storm drain. The facility has indoor vehicle maintenance, and a fuel island near the facility entrance. As for exposed equipment and materials stored onsite, it varies, the photos speak for themselves. Christina is cc'd because she forwarded the NOT request to me for further evaluation. Tony is cc'd for his input regarding evaluation of photos (site conditions) and SIC Code. Lets discuss at your convenience.

Thank you. Whitney

Ms. Whitney J. Ghoram Sanitary Engineering Associate Storm Water Unit San Diego Regional Water Quality Control Board-Region 9 2375 Northside Drive, Suite 100 San Diego, CA 92108 Phone (619) 521-8040 E-Mail: <u>WGhoram@waterboards.ca.gov</u> Website: <u>www.waterboards.ca.gov/sandiego</u>

From: Kelly Doyle [kdoyle@rickengineering.com]
Sent: Friday, August 07, 2015 2:19 PM
To: Ghoram, Whitney@Waterboards
Cc: Walsh, Laurie@Waterboards; Arias, Christina@Waterboards; Jayne Janda-Timba
Subject: RE: R.E. Hazard: 6465 Marindustry Drive- BMP Violations

Hi Whitney,

Thank you for the photos. I spoke with Bruce Hamilton and Charlie White of Hazard and they are already in the process of correcting these issues.

Looking forward to speaking with you next week.

Thanks and have a great weekend, Kelly

From: Ghoram, Whitney@Waterboards [mailto:Whitney.Ghoram@waterboards.ca.gov]
Sent: Friday, August 07, 2015 1:57 PM
To: Kelly Doyle
Cc: Walsh, Laurie@Waterboards; Arias, Christina@Waterboards
Subject: R.E. Hazard: 6465 Marindustry Drive- BMP Violations

Hi Kelly,

See attached 5 photos of BMP violations that require immediate corrective action. I will get back in touch with you regarding this site and the NOT next week. As I mentioned, I took a lot of photos during the site inspection.

Thank you. Whitney

Ms. Whitney J. Ghoram Sanitary Engineering Associate Storm Water Management Unit San Diego Regional Water Quality Control Board-Region 9 2375 Northside Drive, Suite 100 San Diego, CA 92108 E-MAIL ADDRESS: <u>WGhoram@waterboards.ca.gov</u> Phone: (619) 521-8040 Website: <u>www.waterboards.ca.gov/sandiego</u> Storm Water web page: <u>http://www.waterboards.ca.gov/water_issues/programs/stormwater/industrial.shtml</u>





























NOT Inspection: August 7, 2015 Inspector: W. Ghoram San Diego Water Board

SWPPP

STORMWATER POLLUTION PREVENTION PLAN (SWPPP) FOR INDUSTRIAL ACTIVITIES

OWNER: R.E. Hazard Contracting Company FACILITY: 6465-6485 Marindustry Place San Diego, California 92192 WDID No. 937S004580

June 9, 2004

Prepared for:

R.E. HAZARD CONTRACTING COMPANY 6465-6485 Marindustry Place San Diego, California 92192

Prepared by:



GeoSyntec Consultants 3990 Old Town Avenue, Suite B-101 San Diego, California 92110 (619) 297-1530

GeoSyntec Project No. SW0107.02
























Miller, Loren@Waterboards

From:	Ghoram, Whitney@Waterboards
Sent:	Wednesday, September 23, 2015 12:04 PM
То:	Miller, Loren@Waterboards
Subject:	FW: R.E. Hazard: 6465 Marindustry Drive- BMP Violations
Attachments:	InspectionPics-HazardConstructionNOT-Inspection.docx

Hi Loren, See email below and attachment.

Ms. Whitney J. Ghoram Sanitary Engineering Associate Storm Water Unit San Diego Regional Water Quality Control Board-Region 9 2375 Northside Drive, Suite 100 San Diego, CA 92108 Phone (619) 521-8040 E-Mail: <u>WGhoram@waterboards.ca.gov</u> Website: <u>www.waterboards.ca.gov/sandiego</u>

From: Ghoram, Whitney@Waterboards
Sent: Wednesday, August 12, 2015 1:41 PM
To: Kelly Doyle; bhamilton@hazardcon.com
Cc: Walsh, Laurie@Waterboards; Arias, Christina@Waterboards; Jayne Janda-Timba; Felix, Tony@Waterboards; Khounphet, Sandy@Waterboards
Subject: RE: R.E. Hazard: 6465 Marindustry Drive- BMP Violations

Hi Kelly, (RE: WDID 9 371004580, R.E. Hazard Contracting - Notice of Termination Request)

Attached is a Word document containing all of the photos that I took during my "NOT" inspection of R.E. Hazard Contracting's site located at 6465 Marindustry Drive, San Diego on August 7, 2015. Bruce Hamilton, Shop Superintendent accompanied me and Sandy Khounphet during the inspection. As we previously discussed, the deficient housekeeping BMPs that are obvious in the photos (attached here, and that I previously emailed to you) should be corrected immediately and photo's emailed back to demonstrate corrective actions. Also, as discussed, I need to have my supervisor (Laurie Walsh) review the photos and then discuss with me to make a determination of what correct SIC Code applies to this site, and, if/when the NOT can be approved.

Laurie, (Christina and Tony cc'd)

NOT ID 528254 is in SMARTS and includes a description of the basis for the NOT request as follows:

"This facility has had coverage under the IGP since 1992. This Notice of Termination (NOT) has been prepared because an incorrect SIC Code was originally identified incorrectly requiring this facility to obtain coverage under the California IGP. A SWPPP titled, "Industrial SWPPP for R.E. Hazard Contracting Company," prepared by Kleinfelder, dated October 1, 1992, identified the SIC Code as 1611. The SWPPP was Amended in June 2004 and again in October 2008 that changed the SIC Code to 4214. Based on information supplied by our accounting department, our SIC Codes are 1611, 1622, 1629, 1771, and 1794. SIC Code 4214 is not associated with our business.

Our primary economic activity with R.E. Hazard is general engineering contracting, building interstate freeways, bridges and roadways throughout Southern California. At this R.E. Hazard facility we have our corporate office as well as short term storage of materials to be utilized in our construction projects and short term storage/maintenance of light duty and heavy duty construction equipment. There has been no major change in our business operation since 1992, and it is our understanding that the SIC Codes originally identified in our 1992 SWPPP should not have required us to obtain coverage under the IGP. Our primary economic activity, related to SIC Codes 1611, 1622, 1629, 1771, and 1794, are not codes identified in Attachment A of the IGP as requiring coverage under the IGP. Based on conversations with the SWRCB, this