Final

November 23, 2011

Review of Leaking Underground Storage Tank Cases Not in Cleanup Fund and Open Over 15 Years

Los Angeles Regional Water Quality Control Board (RWQCB) – Region 4 Cases

Prepared as in-kind task as part of Cooperative Agreement LS-97952501-2 between USEPA Region 9 and the California State Water Resources Control Board

Table of Contents

Section	Pag	ge
Executive Summa	ry1	
Apparent Case Sta	ntus – Initial Review and After Discussion with Lead Agency2	
Updated Aging No	on-CUF Case Review Summary Table	
Attachment 1: Dr	aft Report – Including Case Review PowerPoint Slides	
1 2 3 4 5 6 7 8 9 1 1 1 1 1 1 1 1 1 2 2 2 2 2 2 2 2	T060700979 (Dunn-Edwards Paint) T0603704815 (Shell #204-6168-2245) T10000000209 (76 Station #255973) T0603702493 (Jamison Properties) T0603701981 (Chevron #9-2811)	
3	0. T0603701095 (Mobil 18-K1R) 1. T0603701894 (Mobil #18-MPX)	
3	2. T0603702147 (US Postal Service) 3. T0603702307 (Mobil #18-LMQ)	
	4. T0603704809 (Mobil #18-FV6) 5. T0603700555 (Palms Distribution Headquarter)	
	6. T0603702788 (Mobil Former Bulk Plant #04-419)	

- 37. T0603701041 (Atlantic Aviation Former Mercury Services)
- 38. T0603700608 (Mobil 18-LEG)
- 39. T0603701679 (LA Co Facilities Management Department)
- 40. T0603702922 (Shell WIC 204-4190-0204)
- 41. T0603701203 (Shell Station)
- 42. T0603701540 (GI Trucking Co.)
- 43. T0603700594 (Good Samaritan Hospital)
- 44. T0603703277 (Shell #204-1944-0100)
- 45. T0603702878 (Mobil #18-E45 Former #11-E45)
- 46. T0603701109 (Shell)
- 47. T0603701871 (Target Store #T-292)
- 48. T0603702870 (Mobil #18-GP9 Former #11-GP9)
- 49. T0603702884 (Exxon #7-3591 Former)
- 50. T0603703278 (Exxon #7-9477 Former) Charnock Well
- 51. T0603704589 (Mobil 18-GG4)
- 52. T0603705396 (Fast Gas #538/Target T-290)
- 53. T0603701215 (Shell Branded Service Station Former)
- 54. T0603704674 (Mobil #18-MAP) EAOP
- 55. T0603704754 (Mobil Oil Corp SS #18-LKA)
- 56. T0603702399 (76 Products Station #4682)
- 57. T0603702424 (Mobil #11-FXV)
- 58. T0603701110 (TOSCO 76 Station #2021)
- 59. T0603701007 (ARCO #0166)
- 60. T0603702223 (Shell)
- 61. T0603702983 (Mobil #18-KCM)
- 62. T0603700727 (Mobil #11-LM9)
- 63. T0603701878 (Mobil 18-MLT)
- 64. T0603704837 (Chevron #9-6594)
- 65. T0603704802 (Mobil #11-MKK)
- 66. T0603701091 (Southwest Street Maintenance Yard)
- 67. T0603700620 (Mobil #18-LLR)
- 68. T0603700617 (LA DPW Western District HQ)
- 69. T0603701393 (Chevron #9-9266)
- 70. T0603701940 (Petro Diamond Terminal Company)
- 71. T0603702476 (Texaco)
- 72. T0603704600 (TOSCO 76 Station #7426)
- 73. T0603759597 (Therm-X Chemical & Oil Co.)
- 74. T0603700406 (LA City Dept Water & Power)
- 75. T0603702627 (ARCO #3018)
- 76. T0603701506 (TOSCO 76 Station #5096)
- 77. T0603700926 (Texaco)
- 78. T0603701903 (The Southland Corp Chief/Auto)
- 79. T0603702451 (Mobil #11-FCG)
- 80. T0603702479 (ARCO #1361 Former)
- 81. T0603700880 (Mobil #18-FOM Former 11-FOM)
- 82. T0603702685 (Yellow Freight Systems Inc)
- 83. T0603701383 (Argo Realty Property) EAOP

- 84. T0603703087 (Texaco)
- 85. T0603774459 (Bixby Land Company)
- 86. T0603702803 (Prudential Overall Supply)
- 87. T0603703264 (Cerritos Community College)
- 88. T0603700808 (Foua DN Dagher)
- 89. T0603792929 (City of La Verne, City Hall)
- 90. T0603704036 (P&M #936)
- 91. T0603704593 (Temple Sheriff Station)
- 92. T0603701939 (West Coast Choppers)
- 93. T0603701960 (Long Beach City Tow Yard)
- 94. T0603701971 (Public Service Yard)
- 95. T0603721214 (Diamond Oil Company)
- 96. T0603758087 (Downey Glass Co, Inc)
- 97. T0603704696 (Shell #204-0580-0200)
- 98. T0603701918 (Mobil)
- 99. T0603700490 (Gas S/S)
- 100. T0603701919 (George Mitchel)
- 101. T0611100023 (Ventura Marketing Distribution Plant)
- 102. T0603700532 (Fire Station #3)
- 103. T0603703839 (Pacific Valves)
- 104. T0603704996 (Lunada Bay Automotive)
- 105. T0603705023 (Key Centers, Inc)
- 106. T0603701826 (Hende's Station)
- 107. T0603701864 (Long Beach Hot Mix/Asphalt)
- 108. T0603701290 (Stabond Corporation)
- 109. T0603704068 (Pemaco Inc)
- 110. T10000000531 (Ruben Gonzales Garage)
- 111. T0603701707 (Mobil)
- 112. T0603707050 (Oakdale Memorial Park)
- 113. T0603700531 (Parker Center)
- 114. T0603702989 (Essex Chemicals Corp.)
- 115. T0603703168 (Alhambra General Mail Facility)
- 116. T0603702750 (Nu-Way Industries)
- 117. T0603704128 (EC Construction Company)
- 118. T0603704166 (Pic A Part Auto Salvage)
- 119. T0603704294 (ARCO Credit Union)
- 120. T0603772920 (Good Samaritan Hospital 2)
- 121. T0603704357 (Old Five Inc)
- 122. T0603702091 (Rayne Softwater of the Valley)
- 123. T0603703083 (Texaco)
- 124. T0603704904 (LA Co Sheriff Station)
- 125. T0603704108 (Belmont Fibers)
- 126. T0603704432 (Smith's Food & Drugs/Moskowitz)
- 127. T0603760075 (Shell Gas Station)
- 128. T0603700082 (Kratka Ridge Ski Area)
- 129. T0603772692 (MC Nottingham)
- 130. T0603703607 (Arcadia Fire Station #2)

- 131. T0603703983 (Shell Pipeline Company)
- 132. T0603701265 (Rancho Los Amigos Hospital)
- 133. T0603704103 (Paramount Associates)
- 134. T0603704149 (Circus Auto Sales)
- 135. T0603704888 (76 Products Station #3349)
- 136. T0603704431 (Sealy Mattress Co)
- 137. T0603704611 (Eastern Auto Repair)
- 138. T0603704776 (Lost Hills Sheriff's Station)
- 139. T0603704649 (Arrowhead Mountain Spring Water Co)
- 140. T0603702503 (Menasco Aerosystem Division)
- 141. T0603701471 (UCC/Linde Division)
- 142. T0603701962 (Marine Hardware Co)
- 143. T0603701212 Charnock Wells

Executive Summary

The Draft version of this report was submitted on September 03, 2010, with a request for follow-up meetings and input from Los Angeles Regional Water Quality Control Board (RWQCB) – Region 4 into the "Next Steps for Agency" column of the case cleanup status spreadsheet.

Los Angeles RWQCB (Region 4) met with USEPA Region 9 and its contractor, Tetra Tech, Inc., on May 2, 2011, and again on August 5, 2011 with USEPA Region 9, to discuss the draft report and the lead agency's next steps for each case. The meeting was conducted with the case workers and their supervisors. The agency acknowledged several challenges with these cases. A few of the challenges mentioned by Los Angeles RWQCB (Region 4) and conclusions from the meeting are:

- Thirteen (13) cases were closed and twenty four (24) cases appear to be near completion within 1-2 years.
- Four (4) cases were transferred to other lead agencies: Los Angeles County LIA, City of Torrance LIA and Ventura County LOP.
- Five (5) cases were identified as possibly not Federal UST case the agency will determine if these cases are SLIC cases.
- The number of cases appears to be on track doubled to 65 cases most cases were originally not on track (11 cases), stuck (8 cases), and unable to determine (9 cases).
- The number of cases originally appears <u>not</u> on track reduced from 15 cases to none. After discussion with case workers, these cases are now on track (11 cases), near completion (2 cases), stuck (1 case) and closed (1 case).
- The number of cases originally appears to be stuck (23 cases) have moved forward to near completion (5 cases), on track (8 cases) and closed (2 cases), with only 8 cases remained in stuck status.
- The number of cases originally unable to determine (insufficient information in GeoTracker) reduced from 43 cases to 3 cases. These cases moved forward to stuck (23 cases), on track (9 cases), transferred (3 cases), near completion (2 cases), might not be federal case (2 cases) and closed (1 case).
- The 34 cases appears to be stuck are due to the following reasons:
 - ✓ Low priority (Priority D) sites
 - ✓ Transferred from other lead agencies without case files or information
 - ✓ RP issues: (1) non-responsive/recalcitrant, (2) funding issues to conduct assessment/cleanup, and (3) unidentified/unable to determine RP
 - ✓ Part of a larger investigation Charnock Site which has strict closure

Los Angeles Regional Water Quality Control Board (RWQCB)-Region 4 Apparent Case Status – Initial Review and After Discussion with Agency

TOTAL NUMBER OF CASES REVIEWED = 143


NUMBER OF ACTIVE LUST CASE ON JUNE 1, 2010 = 1,460 CASES


DRAFT REVIEW REPORT PREPARED AND SENT TO AGENCY ON SEPTEMBER 03, 2010

HAD MEETINGS WITH THE AGENCY TO DISCUSS CASES REVIEWED ON MAY 02 AND AUGUST 05, 2011

APPARENT STATUS OF CASES REVIEWED - INITIAL REVIEW AND AFTER MEETING TO DISCUSS CASES

Apparent Case Status	Initial Assessment Number of Cases (09-03-2010)	Post Meeting Assessment Number of Cases (05-02-2011)
CASE CLOSED	0	12
Appears close to completion	3	0
Appears near completion within 1-year	24	19
Appears to be on track	31	65
Appears NOT to be on track	15	0
Appears to be stuck	23	34
Unable to determine (Insufficient information in GeoTracker)	43	4
NOT A FEDERAL UST CASE	4	5
OTHERS – Transferred to other agencies	0	4





ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and	SITE NAIME (CASE LEAD AGENCY: WAGELES RWQCB - REGION 4)	σηγ	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Appears close to completion	Appears near completion within 1-year	DUNN-EDWARDS PAINTS	VERNON	<u>T0603700979</u>	Nhan Bao	11/18/1983	26	- Likely to close case within 1-year	Complete closure process in 1-year (includes well decommission)
Appears close to completion	Appears near completion within 1-year	SHELL #204-6168-2245	POMONA	<u>T0603704815</u>	Noman Chowdhury	6/21/1989	21	Remediation done (additional assessment)Approved confirmation (letter 2010)More likely to close case within 1-year	Complete closure process in 1-year (includes well decommission)
Appears close to completion	CLOSED (09/21/2010)	76 STATION #255973	WOODLAND HILLS	<u>T10000000209</u>	David M. Bjostad	1/15/1991	19	- Case closed (09/21/2010)	CASE CLOSED (09/21/2010)
Appears near completion within 1-year	CLOSED (01/16/2011)	JAMISON PROPERTIES	ENCINO	<u>T0603702493</u>	Arman Toumari	3/13/1985	25	- Case closed (01/16/2010)	CASE CLOSED (01/16/2010)
Appears near completion within 1-year	Appears near completion within 1-year	CHEVRON #9-2811	LONG BEACH	<u>T0603701981</u>	Ha D. Nguyen	10/25/1985	24	8/5 - Almost completed; 2 more monitorings (benzene and MTBE in 1 well); 1 year or less to closure	Complete closure process in 1-year (includes well decommission)
Appears near completion within 1-year	CLOSED (09/01/2010)	TOSCO - 76 STATION #3645 (Case in EAOP)	SHERMAN OAKS	<u>T0603702417</u>	Maryam Taidy	9/10/1986	24	- Case closed (09/01/2010)	CASE CLOSED (09/01/2010)
Appears near completion within 1-year	Appears to be on track	MOBIL #18-HYQ	LOS ANGELES	<u>T0603700474</u>	Daniel Pirotton	5/13/1988	22	 On-going SVE (dual phase extraction) Site ready for closure but has 5-ft free product across the street Might have separate source (need to do additional work) Has other sites located across and downgradient 	Push for new/additional remedial investigation (RI)/risk assessment
Appears near completion within 1-year	Appears to be stuck	LAC/USC MEDICAL CENTER	LOS ANGELES	<u>T0603700846</u>	Magdy Baiady	11/7/1988	22	 - Priority D site (low) - Difficult to handle because it is located next to emergency room - Problem locating wells - Caseworker will look into finding the wells 	Push for new/additional remedial investigation (RI)/risk assessment
Appears near completion within 1-year	CLOSED (08/16/2010)	GAVIOTA HEIGHTS	LONG BEACH	<u>T0603701963</u>	Jay Huang	6/14/1989	21	- Case closed (08/16/2010)	CASE CLOSED (08/16/2010)
Appears near completion within 1-year	Appears to be on track	FORMER TEXACO	WOODLAND HILLS	<u>T0603702372</u>	Jay Huang	9/21/1989	21	Co-mingled plume siteHas contamination from upgradient sourcesSubmitted closure request; LA-RWQCB rejected closure	Continue remediation until low-risk criteria is met
Appears near completion within 1-year	CLOSED (11/18/2010)	MOBIL #18-FYM (FORMER #11-FYM)	RANCHO PARK	T0603701166	Chandra Cansler	7/16/1990	20	- Case closed (11/18/2010)	CASE CLOSED (11/18/2010)
Appears near completion within 1-year	Appears to be on track	SANTA MONICA MUNICIPAL BUS LINES MAINTENANCE FACIL	SANTA MONICA	T0603701364	Jay Huang	7/16/1990	20	- City of Santa Monica site- Previously an ARCO- Can close site but has diesel sheen in groundwater	Continue remediation until low-risk criteria is met

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP (BASED ON MEETINE? ON 05-02-2011 and	SITE NAME LOS ANGELES RWQCB - REGION 4)	σην	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM METING/GEOTRACKER (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Appears near completion within 1-year	Appears to be on track	TOSCO - 76 STATION #5195 (FORMER)	WHITTIER	<u>T0603703719</u>	Noman Chowdhury	2/28/1990	20	- Priority D case - In remediation (still hot)	Continue remediation until low-risk criteria is met
Appears near completion within 1-year	Appears to be on track	BARRY J. NIDOR JUVENILE HALL	SYLMAR	<u>T0603702268</u>	Arman Toumari	3/20/1992	18	- Began closure, then discover free product	Push for new/additional remedial investigation (RI)/risk assessment
Appears near completion within 1-year	CLOSED (09/16/2010)	76 STATION #254488 (EAOP)	CANOGA PARK	T10000000494	David M. Bjostad	12/10/1991	18	- Case closed (09/16/2010)	CASE CLOSED (09/16/2010)
Appears near completion within 1-year	Appears near completion within 1-year	CONOCO INC (Charnock Well)	CULVER CITY	<u>T0603704152</u>	WeiXing Tong	9/4/1992	18	- City is holding up closure because of need for more data	Complete closure process in 1-year (includes well decommission)
Appears near completion within 1-year	1.1	MOBIL #18-E67 (FORMER #11-E67) (Site in EAOP)	DIAMOND BAR	<u>T0603704511</u>	Noman Chowdhury	9/10/1992	18	- Will close site (remediation and confirmation boring done)	Complete closure process in 1-year (includes well decommission)
Appears near completion within 1-year	Appears near completion within 1-year	TOSCO - 76 STATION #3900	LOS ANGELES	<u>T0603700641</u>	Daniel Pirotton	4/23/1993	17	- Site is ready for closure (within 1-year) - EAOP site	Complete closure process in 1-year (includes well decommission)
Appears near completion within 1-year	Appears to be on track	CHEVRON #9-8701	SAN PEDRO	<u>T0603701638</u>	Arman Toumari	3/25/1993	17	High detections in offsite wellsSome new downgradient wellsMNA or active monitoring	Push for new/additional remedial investigation (RI)/risk assessment
Appears near completion within 1-year	Appears near completion within 1-year	CUDDLY TOYS MFG	LOS ANGELES	<u>T0603704442</u>	Magdy Baiady	10/21/1992	17	Closure requested by RPNot familiar with this case; no data?Will look into closing this site	Complete closure process in 1-year (includes well decommission)
Appears near completion within 1-year Appears near	Appears to be on track	TERMINAL ISLAND PRISON	TERMINAL ISLAND	<u>T060370027</u>	Jimmie Woo	5/23/1995	15	- Has funding issue (Federal funding)- Agency requested work	Continue remediation until low-risk criteria is met
completion within 1-		76 STATION #254359	DOWNEY	<u>T0603704998</u>	Noman Chowdhury	7/27/1995	15	- Potential closure candidate (within 1-year)	Complete closure process in 1-year (includes well decommission)
Appears near completion within 1-year	ปก่ลิฮิโe to determine (Insufficient information in	VIRCO MANUFACTURING CORP.	LOS ANGELES	T0603728230	Maryam Taidy	3/16/1995	15	8/5 - No idea?	Verify if the case is warranted (i.e., is a Federal UST case)
Appears near completion within 1-year	Appears to be on track	76 STATION #2705706	LOS ANGELES	<u>T10000000206</u>	Mercedes Hsu	6/14/1995	15	- Under remediation - EAOP site	Continue remediation until low-risk criteria is met
Appears near completion within 1-year	CLOSED (10/28/2010)	AT&T B1245 FACILITY	AGOURA HILLS	T0603704688	David M. Bjostad	7/12/1995	15	- Case closed (10/28/2010)	CASE CLOSED (10/28/2010)
Appears near completion within 1-year	completion within	DON BOSCO TECHNICAL SCHOOL	ROSEMEAD	<u>T0603704468</u>	Ahmad J Lamma	11/30/1994	15	- Site is closeable (within 1-year)	Complete closure process in 1-year (includes well decommission)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and 0.	SITE NAME LOS ANGELES RWQCB - REGION 4)	CITY	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM METING/GEOTRACKER (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Appears near completion within 1- year	CLOSED (03/28/2011)	FIRE STATION #127	CARSON	<u>T0603705133</u>	Magdy Baiady	12/11/1995	15	- Case closed (03/28/2011)	CASE CLOSED (03/28/2011)
Appears to be on track	Appears to be on track	U-HAUL CENTER #713-84	LONG BEACH	<u>T0603701854</u>	Nhan Bao	11/30/1984	26	- Site has on-going SVE that is removing lots of contamination	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL #18-LMR	HOLLYWOOD	<u>T0603700759</u>	Jay Huang	8/1/1986	24	- EAOP site- Just upgraded to remediation (SVE)	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL 18-K1R	LOS ANGELES	<u>T0603701095</u>	Arman Toumari	6/8/1986	24	Was an EAOP siteHas on-going monitoring and vapor extraction	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL #18-MPX	LONG BEACH	<u>T0603701894</u>	Ha D. Nguyen	6/10/1986	24	8/5 - Site developed; commercial building; SVE-GWETS-AS; remediation for awhile longer	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	US POSTAL SERVICE	ENCINO	<u>T0603702147</u>	Chandra Cansler	6/26/1986	24	- Priority D1 site - Remediation Action Plan (April 2010) approved - WDR permit issued (Feb 2010)	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be on track	Appears to be on track	MOBIL #18-LMQ	SANTA CLARITA	<u>T0603702307</u>	Chandra Cansler	2/11/1986	24	 Priority B1 site Had free product in well in 2008 Need to confirm plume is stable (2 more rounds of sampling) Site was in remediation (GW pump and treat); shut down system Site is closeable 	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL #18-FV6	HUNTINGTON PARK	<u>T0603704809</u>	Maryam Taidy	4/14/1986	24	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - On-going GWM: last report (10/8/2010) - Soil Vapor Survey Workplan (10/5/2010)	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	PALMS DISTRIBUTION HEADQUARTER	LOS ANGELES	<u>T0603700555</u>	Daniel Pirotton	5/22/1987	23	- LADWP has 2 sites - SVE - High benzene	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL FORMER BULK PLANT # 04-419	LA PUENTE	<u>T0603702788</u>	Ahmad J Lamma	3/19/1987	23	- Issued WDR - High benzene	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be on track	Appears to be on track	ATLANTIC AVIATION (FORMER MERCURY SERVICES)	WESTCHESTER	<u>T0603701041</u>	David M. Bjostad	2/6/1989	22	- Site had free product; but no free product since last fall - Received soil data summary 2 months ago (March 2011) - Probably close within 1-year	Complete closure process in 1-year (includes well decommission)
Appears to be on track	Appears to be on track	MOBIL 18-LEG	JEFFERSON PARK	T0603700608	David M. Bjostad	11/23/1987	22	- EAOP site (low priority) - Has on-going REMEDIATION - High GW concentration	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	LA CO FACILITIES MGM DEPT	CARSON	<u>T0603701679</u>	Magdy Baiady	8/5/1988	22	- Has on-going GW monitoring	Continue remediation until low-risk criteria is met

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP ON 05-02-2011 3:2	SITE NAME LOS ANGELES RWQCB - REGION 4)	αην	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM METING/GEOTRACKER (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Appears to be on track	Appears to be on track		HACIENDA HEIGHTS	<u>T0603702922</u>	Ha D. Nguyen	7/13/1988	22	8/5 - Remediation removed a lot of petroleum HCs; GW benzene, MTBE, TBA asymptotic; rebound testing	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be stuck	SHELL STATION	LOS ANGELES	<u>10603701203</u>	Jay Huang	5/15/1989	21	 Charnock MTBE Project Site High vapor (running SVES) Can be closed but not because it is a Charnock Site (strict closure) Shell holding up the closure 	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	G I TRUCKING CO.	LA MIRADA	<u>T0603701540</u>	Ha D. Nguyen	11/11/1988	21	8/5 - In remediation; still has free product; more assessment; did health assessment	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be on track	Appears to be on track	GOOD SAMARITAN HOSPITAL	LOS ANGELES	<u>T0603700594</u>	Arman Toumari	5/11/1990	20	- Has on-going GW monitoring	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	SHELL #204-1944-0100	CULVER CITY	<u>T0603703277</u>	WeiXing Tong	7/22/1991	19	- The number 1 Charnock MTBE Project Site - Most money spent in GW remediation in North America	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL #18-E45 (FORMER #11-E45)	WHITTIER	<u>T0603702878</u>	Noman Chowdhury	8/13/1991	19	- Has on-going GW monitoring	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	SHELL	LOS ANGELES	<u>T0603701109</u>	Daniel Pirotton	10/25/1991	18	EAOP SiteDoing plume delineationLikely soil and GW cleanup	Push for additional/alternate remediation (current remediation ineffective)
Appears to be on track	Appears to be on track	TARGET STORE #T-292	SIGNAL HILL	<u>T0603701871</u>	Nhan Bao	11/1/1991	18	- In remediation: dual phase extract (approved June 2010) - Case in compliance	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL #18-GP9 (FORMER #11-GP9)	ARTESIA	<u>T0603702870</u>	Nhan Bao	6/17/1992	18	- Site has on-going pump-and-treat (in compliance)	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	EXXON #7-3591 (FORMER)	ATHENS	<u>T0603702884</u>	Magdy Baiady	10/21/1991	18	Trying to close the caseWaiting for final round of samplingPlume has stabilized, but concentration is still high	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	EXXON #7-9477 (FORMER) (Charnock)	CULVER CITY	<u>T0603703278</u>	WeiXing Tong	4/8/1992	18	- Charnock MTBE Project Site - Has on-going in-situ treatment	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL 18-GG4	NORWALK	<u>T0603704589</u>	Ha D. Nguyen	7/2/1992	18	8/5 - Lots of remediation; SVE-GWETS since 2006; GW still has TBA; want to do drill borings for effective of remediation	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	FAST GAS #538/TARGET T-290	GARDENA	<u>T0603705396</u>	Chandra Cansler	10/29/1991	18	- Priority D1 Site - WDR issued (April 2010)	Continue remediation until low-risk criteria is met

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and	SITE NAME LOS ANGELES RWQCB - REGION 4)	GΠγ	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Appears to be on track	Appears near	SHELL BRANDED SERVICE STATION (FORMER)	LOS ANGELES	<u>T0603701215</u>	Daniel Pirotton	6/17/1993	17	 EAOP Site Early release (no MTBE) Has nearby gas station (off-site with significant MTBE) Potential case closure; need to proof contaminationis from off-site source 	Complete closure process in 1-year (includes well decommission)
Appears to be on track	Appears to be on track	MOBIL #18-MAP (Case in EAOP)	TORRANCE	<u>T0603704674</u>	Arman Toumari	12/15/1993	17	- EAOP Site - Possible closure in a few years	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL OIL CORP. S.S. #18-LKA	CULVER CITY	<u>T0603704754</u>	Jay Huang	1/19/1994	17	- Has on-going remediation	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	76 PRODUCTS STATION #4682	WOODLAND HILLS	<u>T0603702399</u>	Maryam Taidy	2/7/1995	16	8/5 - RAP requested; low levels; will look at for closure	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	MOBIL #11-FXV	SHERMAN OAKS	<u>T0603702424</u>	Chandra Cansler	6/1/1995	15	- Priority D1 and EAOP site- In remediation- Submitted report	Continue remediation until low-risk criteria is met
Appears to be on track	Appears to be on track	TOSCO - 76 STATION #2021	LOS ANGELES	<u>T0603701110</u>	Chandra Cansler	1/7/1996	15	- Priority C1 Site- Submitted WDR permit (March 15)- Remedial Action Plan (April 2011)	Continue remediation until low-risk criteria is met
Appears NOT to be on track	Appears to be on track	ARCO #0166	LOS ANGELES	<u>T0603701007</u>	Maryam Taidy	11/15/1984	26	8/5 - On-going GWM; last report (01-15-2011) - Remedial Action Plan (10-15-2010)	Continue remediation until low-risk criteria is met
Appears NOT to be on track	Appears to be on track	SHELL	RESEDA	<u>T0603702223</u>	Magdy Baiady	11/19/1985	25	- On-going GWM: last report (1/11/2011)	Push for new/additional remedial investigation (RI)/risk assessment
Appears NOT to be on track	Appears to be on track	MOBIL #18-KCM	SANTA CLARITA	<u>T0603702983</u>	Jay Huang	3/31/1986	24	- Priority D1 site - Has remediation (pump-and-treat)	Continue remediation until low-risk criteria is met
Appears NOT to be on track	Appears to be on track	MOBIL #11-LM9	LOS ANGELES	<u>T0603700727</u>	Maryam Taidy	7/16/1987	23	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - On-going GWM; last report (04-15-2011) - Soil Vapor Assessment Report (12-17-2010)	Continue remediation until low-risk criteria is met
Appears NOT to be on track	Appears to be on track	MOBIL 18-MLT	LONG BEACH	<u>T0603701878</u>	Ha D. Nguyen	9/1/1987	23	8/5 - Site assessment not completed; proposed 3 more wells to complete assessment; system in place	Push for new/additional remedial investigation (RI)/risk assessment
Appears NOT to be on track	Appears to be on track	CHEVRON #9-6594	INGLEWOOD	T0603704837	Jimmie Woo	10/19/1987	23	- Approved additional work on site - Just approved workplan for more wells (additional investigation) - Priority Alisite	Push for new/additional remedial investigation (RI)/risk assessment
Appears NOT to be on track	Appears to be on track	MOBIL #11-MKK	DOWNEY	T0603704802	Noman Chowdhury	11/25/1987	23	- Remediation is NOT on-track - Pilot test, elevated MTBE - Did not submit final remediation plan	Push for additional/alternate remediation (current remediation ineffective)
Appears NOT to be on track	Appears near completion within 1-year	SOUTHWEST STREET MAINT YARD	LOS ANGELES	T0603701091	Daniel Pirotton	9/4/1987	23	- Potential closure within 1-year - Site has recurring product	Complete closure process in 1-year (includes well decommission)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and CLEANUP	SITE NAME (CASE LEAD AGENCY: 105 ANGELES RWQCB - REGION 4)	σιγ	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Appears NOT to be on track		MOBIL #18-LLR	LOS ANGELES	<u>T0603700620</u>	Daniel Pirotton	8/24/1989	21	- Site condition warrant closure- Off-site plume; free product in cluster wells- Air sparging combo; rebound test	Continue remediation until low-risk criteria is met
Appears NOT to be on track	1.7	LA DPW WESTERN DISTRICT-H.Q.	MID CITY	<u>T0603700617</u>	Daniel Pirotton	5/1/1992	18	- Site has on-going cleanup- City of Los Angeles has no funding- There are 3 sites within this area	Continue remediation until low-risk criteria is met
Appears NOT to be on track	CLOSED (10/05/2010)	CHEVRON #9-9266	SANTA MONICA	<u>T0603701393</u>	Jay Huang	3/22/1993	17	- Case closed (10/05/2010)	CASE CLOSED (10/05/2010)
Appears NOT to be on track	Appears to be on track	PETRO DIAMOND TERMINAL COMPANY	LONG BEACH	T0603701940	Mercedes Hsu	11/2/1992	17	- Priority D site- Free product found at the site- Last report dated 12/01/2010	Push for new/additional remedial investigation (RI)/risk assessment
Appears NOT to be on track	Appears to be stuck	TEXACO	SHERMAN OAKS	<u> 70603702476</u>	Chandra Cansler	6/23/1993	17	 - Priority D1 and EAOP site - Possible off-site contamination - ARCO might be contaminating the site - Waiting on UST CUF acceptance letter - Applied OSCA (Nov 2010) - STUCK: waiting on ARCO and funding 	Push for new/additional remedial investigation (RI)/risk assessment
Appears NOT to be on track	completion within	TOSCO - 76 STATION #7426	AGOURA	<u>T0603704600</u>	Daniel Pirotton	4/1/1994	16	EAOP SiteClosure requested, but rejected in the past due to benzeneSite appears closeable within 1-year	Complete closure process in 1-year (includes well decommission)
Appears NOT to be on track		THERM-X CHEMICAL & OIL CO	HUNTINGTON PARK	<u>T0603759597</u>	Maryam Taidy	10/14/1993	16	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - Workplan for Additional Site Assessment (02-22-2010) submitted and agency concurred (03-10-2010)	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears to be on track	LA CITY DEPT WATER & POWER	WATTS	<u>T0603700406</u>	Magdy Baiady	3/23/1984	26	- Approved a Work Plan	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears to be on track	ARCO #3018	EL MONTE	<u>T0603702627</u>	Nhan Bao	1/22/1985	26	- Approved a Work Plan to do additional investigation - Soil only case	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears near completion within 1-vear	TOSCO - 76 STATION #5096	TORRANCE	<u>T0603701506</u>	Arman Toumari	2/25/1986	25	- Ready for closure within 1-year - Adjacent site kept monitoring	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	Appears to be stuck	TEXACO	HOLLYWOOD	<u>T0603700926</u>	Daniel Pirotton	4/4/1986	24	No file; completely missing (will check with LA City Fire Dept)Unidentified RP	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Appears to be stuck	Appears to be on track	THE SOUTHLAND CORP (CHIEF/AUTO)	LONG BEACH	<u>T0603701903</u>	Maryam Taidy	5/12/1986	24	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - On-going GWM; last report (01-26-2011)	Push for new/additional remedial investigation (RI)/risk assessment

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and 0.	SITE NAME LOS ANGELES RWQCB - REGION 4)	CITY	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM METING/GEOTRACKER (05-02-2011 and 08-05-2011)	MEXT STEP FOR AGENCY
Appears to be stuck	CLOSED (01/19/2011)	MOBIL #11-FCG	VAN NUYS	<u>T0603702451</u>	Magdy Baiady	11/10/1986	24	- Case closed (01/19/2011)	CASE CLOSED (01/19/2011)
Appears to be stuck	Appears to be stuck	ARCO #1361 (FORMER)	SHERMAN OAKS	T0603702479	Maryam Taidy	10/14/1986	24	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - One report (Workplan for Site Assessment) dated 10-11-2006 in GT	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears to be on track	MOBIL #18-FOM (FORMER 11-FOM)	LOS ANGELES	<u>T0603700880</u>	Jay Huang	7/10/1987	23	 EAOP Site Unable to close site due to co-mingled plume (free product from upgradient migrated to this site) Mobil tried to close site 	Continue remediation until low-risk criteria is met
Appears to be stuck	Appears near completion within	YELLOW FREIGHT SYSTEMS INC	PICO RIVERA	<u>T0603702685</u>	Ahmad J Lamma	9/24/1987	23	- Will close after July 2011	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	Appears to be on track	ARGO REALTY PROPERTY (EAOP)	SANTA MONICA	T0603701383	Jay Huang	11/2/1987	23	 EAOP Site (Shell in charge of this site) Has a big building on site Off-site migration to Santa Monica City has its own case Passive monitoring 	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears to be stuck	TEXACO	PARAMOUNT	T0603703087	Ahmad J Lamma	3/15/1988	22	- Unable to locate RP - Gave case file to Lynda A (USEPA contractor) to locate RP - "Dead-end case"	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Appears to be stuck	Appears to be on track	BIXBY LAND COMPANY	LONG BEACH	<u>T0603774459</u>	Noman Chowdhury	7/7/1988	22	 No monitoring wells (grab samples only) Has soil-vapor samples Agency need to send directive letter (need to delineate site) Developer wants to redevelop site 	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears to be on track	PRUDENTIAL OVERALL SUPPLY	CERRITOS	<u>T0603702803</u>	Ahmad J Lamma	1/31/1989	22	- Site has free product (cannot close)- Facility is now closed- Doing bailing on-site	Push for new/additional remedial investigation (RI)/risk assessment
Appears to be stuck	Appears near completion within 1-year	CERRITOS COMMUNITY COLLEGE	NORWALK	<u>T0603703264</u>	Ahmad J Lamma	12/5/1988	22	- Will close after July 2011 - Did site inspection in 2010	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	Appears to be stuck	FOUA D N DAGHER	MONTECITO HEIGHTS	T0603700808	Magdy Baiady	6/19/1989	21	- Caseworker will check on this case (last letter issued in 2003) - Transferred in 2003?	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Appears to be stuck	1 1	CITY OF LA VERNE, CITY HALL	LA VERNE	T0603792929	Ahmad J Lamma	5/19/1989	21	No case files (need to find case information); "dead-end case"Referred from LA County	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Appears to be stuck	Appears to be stuck	P&M #936	HACIENDA HEIGHTS	<u>T0603704036</u>	Ha D. Nguyen	3/21/1991	19	8/5 - RP (elderly) funding issue (mom & pop); applied to CUF and awaiting funding	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and 0	SITE NAME LOS ANGELES RUNGCB - REGION 4)	αην	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM METING/GEOTRACKER (05-02-2011 and 08-05-20 ₁₁₎	NEXT STEP FOR AGENCY
Appears to be stuck		TEMPLE SHERIFF STATION	TEMPLE CITY	<u>T0603704593</u>	Ha D. Nguyen	5/23/1991	19	8/5 - In hands of EPA for awhile, gave back; also has PCE-TCE contaminants; EPA determined chlorinates from offsite source; petroleum not bad; close and transfer to SLIC; proposed soil confirmation samples; has case upgradient (dry cleaners)	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	WEST COAST CHOPPERS	LONG BEACH	<u>T0603701939</u>	Jay Huang	5/15/1995	15	- Priority D1 site - RP is unresponsive	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Appears to be stuck	Appears near completion within 1-year	LONG BEACH CITY TOW YARD	LONG BEACH	<u>T0603701960</u>	David M. Bjostad	8/30/1995	15	- Drafted closure package and ready to be closed (6/8/11: Carmen Piro's email)	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	Appears to be stuck	PUBLIC SERVICE YARD	LONG BEACH	<u>T0603701971</u>	Noman Chowdhury	8/4/1995	15	 City of Long Beach (Carmen Piro?) appears to be the RP Lynda A (USEPA contractor) has the case files and will contact Carmen Not claimed in GeoTracker 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Appears to be stuck	completion within	DIAMOND OIL COMPANY	MONTEBELLO	<u>T0603721214</u>	Ha D. Nguyen	11/2/1995	15	8/5 - Referred to LA-RWQCB (10/2009); sent letter, no response; appears closeable, but must locate RP to send letter; letters to RP all returned	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	CLOSED (01/24/2011)	DOWNEY GLASS CO, INC	COMMERCE	T0603758087	Magdy Baiady	10/6/1995	15	- Case closed (01/24/2011)	CASE CLOSED (01/24/2011)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	SHELL #204-0580-0200	BELL GARDENS	<u>T0603704696</u>	Magdy Baiady	4/6/1984	26	 First status report received on 4/15/2011 Tried to coordinate cleanup with other sites Priority B site (will be a high priority for the agency) Transferred from LA County in 2009 	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	MOBIL	LONG BEACH	T0603701918	Daniel Pirotton	10/17/1984	26	 - Priority D site - City of Long Beach (LB Redevelopment) is partly involved - Site is across the street from another site and RPs are finger-pointing - Referred site to Lynda A (USEPA contractor) 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	GAS S/S	LOS ANGELES	<u>T0603700490</u>	Maryam Taidy	3/6/1985	25		Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	GEORGE MITCHEL	LONG BEACH	<u>T0603701919</u>	Jay Huang	11/1/1984	25	- Priority D1 site - Agency sent letter to RP (RP is unresponsive)	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP BPELINE? ON 05-02-2011 and	SITE NAME LOS ANGELES RWQCB - REGION 4)	GΠγ	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	Transferred lead to Ventura County LOP	VENTURA MARKETING DIST PLANT	VENTURA	<u>T0611100023</u>	Yue Rong	3/1/1987	24	- Changed lead agency in GeoTracker to Ventura County LOP	CASE TRANSFERRED TO VENTURA COUNTY LOP
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	FIRE STATION #3	LOS ANGELES	<u>T0603700532</u>	Chandra Cansler	6/16/1986	24	 - Priority D1 site - Remedial Action Plan received on Dec 2010 (not reviewed yet) 	Continue remediation until low-risk criteria is met
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	PACIFIC VALVES	SIGNAL HILL	T0603703839	Nhan Bao	9/12/1986	24	Recalcitrant RPRequested RP submittal to GeoTracker (RP refused);case remains unclaimed	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	Lunada Bay Automotive	Palos Verdes Estates	T0603704996	Daniel Pirotton	3/27/1986	24	 Priority D site Agency sent letter requesting for additional information, but no response from RP Caseworker will follow up with RP 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	KEY CENTERS, INC	HERMOSA BEACH	T0603705023	Mercedes Hsu	4/10/1986	24	- Non-responsive RP - Agency issued first 30-days letter on 03/20/2009	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	HENDE'S STATION	LONG BEACH	<u>T0603701826</u>	Ha D. Nguyen	12/9/1986	23	8/5 - Site is inactive; enforcement actions needed	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	LONG BEACH HOT MIX/ASPHALT	LONG BEACH	T0603701864	Nhan Bao	8/1/1987	23	- Agency sent letter to RP but letter was returned ("dead end case")- Has case files (not in GeoTracker)	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears near completion within 1-year	STABOND CORPORATION	GARDENA	<u>T0603701290</u>	Magdy Baiady	4/19/1988	22	 Prepared closure package (will close within 1-year) Waiting for Gardena City for additional information Site is abandoned (cannot access) 	Complete closure process in 1-year (includes well decommission)
Unable to determine (Insufficient information in GeoTracker)	NOT FEDERAL UST SITE?	PEMACO INC	MAYWOOD	<u>T0603704068</u>	Nhan Bao	7/19/1988	22	- Superfund Site	NOT FEDERAL UST SITE (SUPERFUND)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	RUBEN GONZALES GARAGE	LOS ANGELES	<u>T10000000531</u>	Maryam Taidy	3/10/1988	22	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - Agency letter (06-11-2009) requesting for additional info; no reply - Case transferred from LA County on 04-16-2009	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	MOBIL	LONG BEACH	T0603701707	Mercedes Hsu	1/25/1989	21	- Non-responsive RP - Formal EO letter was issued on 4/14/2011 - One of the pilot sites for I-710 project	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 and	SITE NAIME LOS ANGELES RIVOCB - REGION 4)	CITY	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM METING/GEOTRACKER (05-02-2011 and 08-05-2011)	MEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)		OAKDALE MEMORIAL PARK	GLENDORA	<u>T0603707050</u>	Chandra Cansler	5/17/1989	21	 Caseworker is Noman Chowdhury Agency issued letter to RP in July 2009 requesting for corrective action (no response) 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears near completion within 1-year	PARKER CENTER	LOS ANGELES	<u>T0603700531</u>	Maryam Taidy	7/2/1990	20	8/5 - RP requested for closure (08-10-2010); working on closure	Complete closure process in 1-year (includes well decommission)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	ESSEX CHEMICALS CORP.	COMPTON	<u>T0603702989</u>	Magdy Baiady	3/12/1990	20	- Priority B2 site- Site is in assessment- Agency requested for information in Nov 2010	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	stuck	ALHAMBRA GENERAL MAIL FACILITY	INDUSTRY	<u>T0603703168</u>	Noman Chowdhury	3/30/1990	20	 Non-compliance RP; RP angry at doing assessment Assumed closeable if RP conduct assessment, but detected high concentration after sampled (in 2007) 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Transferred lead to Los Angeles County LIA	NU-WAY INDUSTRIES	IRWINDALE	<u>T0603702750</u>	Yue Rong	8/14/1990	20	- Changed lead agency in GeoTracker to Los Angeles County LIA	CASE TRANSFERRED TO LOS ANGELES COUNTY LIA
Unable to determine (Insufficient information in GeoTracker)	determine (Insufficient	E C. CONSTRUCTION COMPANY	SOUTH EL MONTE	<u>T0603704128</u>	Joe F. Luera	3/6/1990	20	7/11: Case file missing	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)		PIC A PART AUTO SALVAGE	MONROVIA	<u>T0603704166</u>	Joe F. Luera	5/2/1990	20	Agency need to issue work directive 8/5 - RP deceased; very little contamination; some VOC (chlorinated)	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	ARCO CREDIT UNION	CARSON	<u>T0603704294</u>	Maryam Taidy	3/13/1990	20	CW NOT AVAILABLE, BASED ON GEOTRACKER INFO - No data/report/document in GT - Only one letter in GT: Agency requested RP for additional information (04-01-2009); no reply	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	GOOD SAMARITAN HOSPITAL (2)	LOS ANGELES	<u>T0603772920</u>	Arman Toumari	5/11/1990	20	- Might be ready for closure in 1-2 years	Continue remediation until low-risk criteria is met
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	OLD FIVE INC.	BELLFLOWER	T0603704357	Noman Chowdhury	10/17/1990	20	 Recalcitrant RP Limited case information available Agency sent letter in 2008 to RP requesting for corrective action 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)		RAYNE SOFTWATER OF THE VALLEY	CANOGA PARK	T0603702091	Maryam Taidy	2/12/1991	19	- No RP identified (unclaimed)	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP PIPELINE? ON 05-02-2011 = 1.1	SITE NAME LOS ANGELES RWQCB - REGION 4)	Gηγ	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM MEETING/GEOTRACKER (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	TEXACO	COVINA	T0603703083	Ahmad J Lamma	12/20/1991	18	 Recalcitrant RP Agency issued letter on Nov 2009; no response from RP Referred from LA County 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	LA CO SHERIFF STATION	SANTA CLARITA	T0603704904	Jay Huang	3/16/1992	18	In remediation, then shut downApproved revised remediation planRP fired consultant (new consultant)	Push for additional/alternate remediation (current remediation ineffective)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	BELMONT FIBERS	MONTEBELLO	T0603704108	Ahmad J Lamma	3/10/1992	18	- Unresponsive RP- Agency issued letter on April 2009- Need files from LA County (transferred in 2009)	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	SMITH'S FOOD & DRUGS/MOSKOWITZ	LAKEWOOD	T0603704432	Nhan Bao	8/27/1992	18	- Unresponsive/recalcitrant RP	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	SHELL GAS STATION	LOS ANGELES	<u>T0603760075</u>	Arman Toumari	3/31/1992	18	- Priority D1 site- Unresponsive RP (Shell might not be the RP?)- Agency sent multiple letters requesting for information	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Transferred lead to Los Angeles County LIA	KRATKA RIDGE SKI AREA	LA CANADA- FLINTRIDGE	T0603700082	Yue Rong	12/16/1992	18	- Changed lead agency in GeoTracker to Los Angeles County LIA	CASE TRANSFERRED TO LOS ANGELES COUNTY LIA
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	M C NOTTINGHAM	EL MONTE	<u>T0603772692</u>	Ahmad J Lamma	6/23/1993	17	 No case information available (not claimed in GeoTracker) Need files from LA County (transferred) Current caseworker "inherited" case from a retired caseworker 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	ARCADIA FIRE STATION #2	ARCADIA	T0603703607	Nhan Bao	1/4/1994	17	- Removed tank with trace concentration - Likely a low-risk closure	Solicit case closure proposal/request
Unable to determine (Insufficient information in GeoTracker)	NOT FEDERAL UST SITE?	SHELL PIPELINE COMPANY	SIGNAL HILL	<u>T0603703983</u>	Ahmad J Lamma	6/17/1993	17	Possible SLIC case (tank farm)Need files from LA County (transferred)Unresponsive RP	NOT FEDERAL UST SITE (SLIC)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	RANCHO LOS AMIGOS HOSPITAL	DOWNEY	T0603701265	Noman Chowdhury	9/20/1994	16	Recalcitrant RP (caseworker called RP)Case files available?Building under construction	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	PARAMOUNT ASSOCIATES	PARAMOUNT	T0603704103	Ahmad J Lamma	11/29/1993	16	- Trying to locate RP - Lynda A (USEPA contractor) will assist in this case	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE? (09-03-2010)	CHANGE IN STATUS IN THE CLEANUP (BASED ON MEETINGS ON 05-02-2011 and	SITE NAME (CASE LEAD AGENCY: 105 ANGELES RWQCB - REGION 4)	CITY	GLOBAL ID	CASEWORKER	RELEASE DATE	AGE	DISCUSSION NOTES FROM (05-02-2011 and 08-05-2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	CIRCUS AUTO SALES	DOWNEY	<u>T0603704149</u>	Ahmad J Lamma	9/13/1994	16	 No response from RP Agency sent a letter to RP on Nov 2009 requesting additional information Referred from LA County (no data/report/information) Unknown priority 	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	76 PRODUCTS STATION #3349	INGLEWOOD	<u>T0603704888</u>	Jay Huang	1/4/1995	16	- Priority D1 and EAOP Site - Case was referred from LA County in 2010	Continue remediation until low-risk criteria is met
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	SEALY MATTRESS CO	SOUTH GATE	<u>T0603704431</u>	Joe F. Luera	6/14/1995	15	Remediation necessary - sheen detected in groundwater during recent monitoring 8/5 - Property transfer; currently in monitoring	Continue remediation until low-risk criteria is met
Unable to determine (Insufficient information in GeoTracker)	Appears to be stuck	EASTERN AUTO REPAIR	CITY TERRACE	T0603704611	Maryam Taidy	3/20/1995	15	- Priority D1 site- Agency issued letter in June 2009 requesting for additional information; no reply	Ensure RP compliance (includes identify RP, enforcement, EAR account etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	LOST HILLS SHERIFF'S STATION	CALABASAS	<u>T0603704776</u>	David Bjostad	6/13/1995	15	- Draft Workplan received in April 2011 (no signatures) - Case was referred from LA County in 2009	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	CLOSED (02/03/2011)	ARROWHEAD MTN SPRING WATER CO	GARDENA	<u>T0603704649</u>	Jay Huang	1/4/1995	15	- Case closed (02/03/2011)	CASE CLOSED (02/03/2011)
NOT FEDERAL UST CASE (SLIC)	NOT FEDERAL UST SITE?	MENASCO AEROSYSTEM DIVISION	BURBANK	<u>T0603702503</u>	Larry Moore	4/8/1988	22	- Need to confirm if this is a SLIC case	CONFIRM IS CASE A FEDERAL UST CASE OR SLIC?
MIGHT NOT BE FEDERAL UST CASE	Transferred lead to City of	UCC/LINDE DIVISION	TORRANCE	T0603701471	Yue Rong	12/18/1986	23	- Changed lead agency in GeoTracker to City of Torrance	CASE TRANSFERRED TO CITY OF TORRANCE
MIGHT NOT BE FEDERAL UST CASE	NOT FEDERAL UST SITE?	MARINE HARDWARE CO (NOT UST CASE)	LONG BEACH	<u>T0603701962</u>	Jay Huang	10/15/1990	19	Need to confirm if this is a SLIC caseAgency sent letter (unresponsive RP)	CONFIRM IS CASE A FEDERAL UST CASE OR SLIC?
MIGHT NOT BE FEDERAL UST CASE	NOT FEDERAL UST SITE?	CHARNOCK WELLS (NOT UST CASE)	LOS ANGELES	<u>T0603701212</u>	WeiXing Tong	6/1/1995	15	- An areawide regional investigation- No tanks, but case created by the city to track	NOT A FEDERAL UST CASE

Attachment 1

Draft Report (September 03, 2010)

Review of Leaking Underground Storage Tank (LUST) Cases

(Not in Cleanup Fund and Open Over 15 Years)

The contents of this attachment are provided in electronic format only

Draft

September 3, 2010

Review of Leaking Underground Storage Tank (LUST) Cases

(Not in Cleanup Fund and Open Over 15 Years)

Los Angeles Regional Water Quality Control Board (RWQCB) – Region 4 Cases

Prepared as in-kind task as part of
Cooperative Agreement LS-96934701-1
between
USEPA Region 9
and the
California State Water Resources Control Board

Secti	ion	Page
Case	Review Analysis	1
Case	Review Summary Table	4
Case	Location Map	12
Case	e Review Power Point Slides – Site List	
1.	T060700979 (Dunn-Edwards Paint)	14
2.	T0603704815 (Shell #204-6168-2245)	16
3.	T1000000209 (76 Station #255973)	18
4.	T0603702493 (Jamison Properties)	20
5.	T0603701981 (Chevron #9-2811)	22
6.	T0603702417 (TOSCO – 76 Station #3645) – EAOP	24
7.	T0603700474 (Mobil #18-HYQ)	26
8.	T0603700846 (LAC/USC Medical Center)	28
9.	T0603701963 (Gaviota Heights)	30
10.	T0603702372 (Former Texaco)	32
11.	T0603701166 (Mobil #18-FYM (Former #11-FYM)	34
12.	T0603701364 (Santa Monica Municipal Bus Lines Maintenance Facility)	36
13.	T0603703719 (TOSCO – 76 Statopm 5195)	38
14.	T0603702268 (Barry J. Nidor Juvenile Hall)	40
15.	T1000000494 (76 Station #254488) – EAOP	42
16.	T0603704152 (Conoco Inc) – Charnock Well	44
17.	T0603704511 (Mobil #18-E67 – Former #11-E67) – EAOP	46
18.	T0603700641 (TOSCO – 76 Station #3900)	48
19.	T0603701638 (Chevron #9-8701)	50
20.	T0603704442 (Cuddly Toys Manufacturing)	52
21.	T060370027 (Terminal Island Prison)	54
22.	T0603704998 (76 Station #254359)	56
23.	T0603728230 (Virco Manufacturing Corp.)	58
24.	T1000000206 (76 Station #2705706)	60
25.	T0603704688 (AT&T B1245 Facility)	62
26.	T0603704468 (Don Bosco Technical School)	64
27.	T0603705133 (Fire Station #127)	66
28.	T0603701854 (U-Haul Center #713-84)	68
29.	T0603700759 (Mobil #18-LMR)	70

Secti	on	Page
30.	T0603701095 (Mobil 18-K1R)	72
31.	T0603701894 (Mobil #18-MPX)	74
32.	T0603702147 (US Postal Service)	76
33.	T0603702307 (Mobil #18-LMQ)	78
34.	T0603704809 (Mobil #18-FV6)	80
35.	T0603700555 (Palms Distribution Headquarter)	82
36.	T0603702788 (Mobil Former Bulk Plant #04-419)	84
37.	T0603701041 (Atlantic Aviation – Former Mercury Services)	86
38.	T0603700608 (Mobil 18-LEG)	88
39.	T0603701679 (LA Co Facilities Management Department)	90
40.	T0603702922 (Shell WIC 204-4190-0204)	92
41.	T0603701203 (Shell Station)	94
42.	T0603701540 (GI Trucking Co.)	96
43.	T0603700594 (Good Samaritan Hospital)	98
44.	T0603703277 (Shell #204-1944-0100)	100
45.	T0603702878 (Mobil #18-E45 – Former #11-E45)	102
46.	T0603701109 (Shell)	104
47.	T0603701871 (Target Store #T-292)	106
48.	T0603702870 (Mobil #18-GP9 – Former #11-GP9)	108
49.	T0603702884 (Exxon #7-3591 – Former)	110
50.	T0603703278 (Exxon #7-9477 – Former) – Charnock Well	112
51.	T0603704589 (Mobil 18-GG4)	114
52.	T0603705396 (Fast Gas #538/Target T-290)	116
53.	T0603701215 (Shell Branded Service Station – Former)	118
54.	T0603704674 (Mobil #18-MAP) – EAOP	120
55.	T0603704754 (Mobil Oil Corp SS #18-LKA)	122
56.	T0603702399 (76 Products Station #4682)	124
57.	T0603702424 (Mobil #11-FXV)	126
58.	T0603701110 (TOSCO – 76 Station #2021)	128
59.	T0603701007 (ARCO #0166)	130
60.	T0603702223 (Shell)	132
61.	T0603702983 (Mobil #18-KCM)	134
62.	T0603700727 (Mobil #11-LM9)	136

Section	on Control of the Con	Page
63.	T0603701878 (Mobil 18-MLT)	138
64.	T0603704837 (Chevron #9-6594)	140
65.	T0603704802 (Mobil #11-MKK)	142
66.	T0603701091 (Southwest Street Maintenance Yard)	144
67.	T0603700620 (Mobil #18-LLR)	146
68.	T0603700617 (LA DPW Western District – HQ)	148
69.	T0603701393 (Chevron #9-9266)	150
70.	T0603701940 (Petro Diamond Terminal Company)	152
71.	T0603702476 (Texaco)	154
72.	T0603704600 (TOSCO – 76 Station #7426)	156
73.	T0603759597 (Therm-X Chemical & Oil Co.)	158
74.	T0603700406 (LA City Dept Water & Power)	160
75.	T0603702627 (ARCO #3018)	162
76.	T0603701506 (TOSCO – 76 Station #5096)	164
77.	T0603700926 (Texaco)	166
78.	T0603701903 (The Southland Corp – Chief/Auto)	168
79.	T0603702451 (Mobil #11-FCG)	170
80.	T0603702479 (ARCO #1361 – Former)	172
81.	T0603700880 (Mobil #18-FOM – Former 11-FOM)	174
82.	T0603702685 (Yellow Freight Systems Inc)	176
83.	T0603701383 (Argo Realty Property) – EAOP	178
84.	T0603703087 (Texaco)	180
85.	T0603774459 (Bixby Land Company)	182
86.	T0603702803 (Prudential Overall Supply)	184
87.	T0603703264 (Cerritos Community College)	186
88.	T0603700808 (Foua DN Dagher)	188
89.	T0603792929 (City of La Verne, City Hall)	190
90.	T0603704036 (P&M #936)	192
91.	T0603704593 (Temple Sheriff Station)	194
92.	T0603701939 (West Coast Choppers)	196
93.	T0603701960 (Long Beach City Tow Yard)	198
94.	T0603701971 (Public Service Yard)	200
95.	T0603721214 (Diamond Oil Company)	202

Sectio	on Control of the Con	Page
96.	T0603758087 (Downey Glass Co, Inc)	204
97.	T0603704696 (Shell #204-0580-0200)	206
98.	T0603701918 (Mobil)	208
99.	T0603700490 (Gas S/S)	210
100.	T0603701919 (George Mitchel)	212
101.	T0611100023 (Ventura Marketing Distribution Plant)	214
102.	T0603700532 (Fire Station #3)	216
103.	T0603703839 (Pacific Valves)	218
104.	T0603704996 (Lunada Bay Automotive)	220
105.	T0603705023 (Key Centers, Inc)	222
106.	T0603701826 (Hende's Station)	224
107.	T0603701864 (Long Beach Hot Mix/Asphalt)	226
108.	T0603701290 (Stabond Corporation)	228
109.	T0603704068 (Pemaco Inc)	230
110.	T1000000531 (Ruben Gonzales Garage)	232
111.	T0603701707 (Mobil)	234
112.	T0603707050 (Oakdale Memorial Park)	236
113.	T0603700531 (Parker Center)	238
114.	T0603702989 (Essex Chemicals Corp.)	240
115.	T0603703168 (Alhambra General Mail Facility)	242
116.	T0603702750 (Nu-Way Industries)	244
117.	T0603704128 (EC Construction Company)	246
118.	T0603704166 (Pic A Part Auto Salvage)	248
119.	T0603704294 (ARCO Credit Union)	250
120.	T0603772920 (Good Samaritan Hospital 2)	252
121.	T0603704357 (Old Five Inc)	254
122.	T0603702091 (Rayne Softwater of the Valley)	256
123.	T0603703083 (Texaco)	258
124.	T0603704904 (LA Co Sheriff Station)	260
125.	T0603704108 (Belmont Fibers)	262
126.	T0603704432 (Smith's Food & Drugs/Moskowitz)	264
127.	T0603760075 (Shell Gas Station)	266
128.	T0603700082 (Kratka Ridge Ski Area)	268
129.	T0603772692 (MC Nottingham)	270

Sectio	n	Page
130.	T0603703607 (Arcadia Fire Station #2)	272
131.	T0603703983 (Shell Pipeline Company)	274
132.	T0603701265 (Rancho Los Amigos Hospital)	276
133.	T0603704103 (Paramount Associates)	278
134.	T0603704149 (Circus Auto Sales)	280
135.	T0603704888 (76 Products Station #3349)	282
136.	T0603704431 (Sealy Mattress Co)	284
137.	T0603704611 (Eastern Auto Repair)	286
138.	T0603704776 (Lost Hills Sheriff's Station)	288
139.	T0603704649 (Arrowhead Mountain Spring Water Co)	290
140.	T0603702503 (Menasco Aerosystem Division)	292
141.	T0603701471 (UCC/Linde Division)	294
142.	T0603701962 (Marine Hardware Co)	296
143.	T0603701212 – Charnock Wells	298


LOS ANGELES REGIONAL WATER QUALITY CONTROL BOARD (RWQCB) – REGION 4 OPEN LEAKING UST: NON-CUF, OLDER (OPEN>15 YEARS), AND DEEMED "NOT READY FOR CLOSURE – FINAL" CASES IN GEOTRACKER (DATA IN GEOTRACKER, AUGUST 2010)

SUMMARY OF CASE REVIEW


TOTAL NUMBER OF CASES REVIEWED = 143 CASES (4 CASES DO NOT APPEAR TO MEET FEDERAL UST TANK DEFINITION)

NUMBER OF ACTIVE LUST CASE ON AUGUST 1, 2010 = 2,211 CASES

1) APPARENT STATUS OF CASES REVIEWED (BASED ON THE 139 FEDERAL UST CASES)



2) RESPONSIBLE PARTY TYPES





3) APPARENT MAIN BARRIERS (ENVIRONMENTAL AND NON-ENVIRONMENTAL) TO CLOSURE

RANK	ENVIRONMENTAL BARRIER	NUM OF CASE	% OF CASE REVIEWED
1	NO/INCOMPLETE ASSESSMENT	62	47%
2	CA POLICY (WATER QUALITY OBJECTIVES NOT MET)	32	23%
3	OTHER	21	15%
4	REMEDIAL CONFIRMATION	20	14%
5	AWAITING WELL ABADONMENT	1	1%


RANK	NON-ENVIRONMENTAL BARRIER	NUM OF CASE	% OF CASE REVIEWED
1	UNKNOWN	61	44%
2	NO DATA IN GEOTRACKER	53	38%
3	NON-RESPONSIVE RP	9	6%
4	NONE	8	6%
5	OTHER	7	5%
6	FINANCIAL HARDSHIP	1	1%

4) DATA IN GEOTRACKER






5) CASE ACTIVITIES IN GEOTRACKER (2004-2009)



6) AGE OF CASES



ESTIMATED STATUS IN THE CLEANUP PIPELINE?	(CASE LEAD AGENCY: LOS ANGELES RWQCB - REGION 4)	СПУ	GLOBAL ID	LOCAL CASE ID (REGION 2 CASE NII	CASEWORKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMENTAL BARRIER TO	APPARENT NON-ENVIRONMENTAL RACE	PRIMARY COC (In. C.	APPARENT TYPE OF RP	DOES SITE APPEARS TO HAVE BEEN P.	DOES SITE APPEARS TO HAVE CURREN	CLAIMED IN GEOTRACKED.	GROUNDWATER MONITORING (LAST 5-YEAR-6-1	INVESTIGATION (LASTS-YEARS)	REMEDIATION (LAST 5-YEARS)	LAST REGULATORY DIRECTIVE LETTER	PERCEPTION OF WEED.	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Appears close to completion	DUNN-EDWARDS PAINTS	VERNON	<u>T0603700979</u>	900400061	Nhan Bao	Open - Site Assessment	O - Other	O - Other	Solvent	S - Small Private Busine	ss No	Unknown	Yes	Yes	No	No	No	Yes	Incomplete (GWM only)	11/18/1983	26		
Appears close to completion	SHELL #204-6168-2245	POMONA	<u>T0603704815</u>	R-26417	Noman Chowdhury	Open - Remediation	O - Other	U - Unknown	Diesel	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Partially Complete (Missing some data)	6/21/1989	21		
Appears close to completion	76 STATION #255973	WOODLAND HILLS	<u>T10000000209</u>	913670361A	David M. Bjostad	Open - Site Assessment	O - Other	N - None	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	No	Yes	No	Limited	1/15/1991	19		
Appears near completion within 1-year	JAMISON PROPERTIES	ENCINO	<u>T0603702493</u>	914360225		Open - Remediation	O - Other	O - Other	Gasoline	Z - Major Oil Company	Yes	No	No	Unknown	Unknown	Yes	No	Yes	Limited	3/13/1985	25		
Appears near completion within 1-year	CHEVRON #9-2811	LONG BEACH	<u>T0603701981</u>	908150052	Ha D. Nguyer	Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Limited	10/25/1985	24		
Appears near completion within 1-year	TOSCO - 76 STATION #3645 (Case in EAOP)	SHERMAN OAKS	<u>T0603702417</u>	914030025	Maryam Taidy	Open - Remediation	O - Other	N - None	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Partially Complete (Missing some data)	9/10/1986	24		
Appears near completion within 1-year	MOBIL #18-HYQ	LOS ANGELES	<u>T0603700474</u>	900060052	Daniel Pirotton	Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	N - None	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	5/13/1988	22		
Appears near completion within 1-year	LAC/USC MEDICAL CENTER	LOS ANGELES	<u>T0603700846</u>	900330270	Magdy Baiady	Open - Remediation	O - Other	U - Unknown	Gasoline	G - Government Entity (include School, Hospita	al, No	Unknown	Yes	Yes	No	No	No	Yes	Incomplete (GWM only)	11/7/1988	22		
Appears near completion within 1-year	GAVIOTA HEIGHTS	LONG BEACH	<u>T0603701963</u>	908130516	Jay Huang	Open - Site Assessment	O - Other	U - Unknown	Gasoline	S - Small Private Busine	ss Unknown	No	Yes	Yes	Yes	No	Yes	Yes	Limited	6/14/1989	21		
Appears near completion within 1-year	FORMER TEXACO	WOODLAND HILLS	<u>T0603702372</u>	913640452	Jay Huang	Open - Site Assessment	O - Other	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes	Unknown	No	Yes	Yes	Limited	9/21/1989	21		
Appears near completion within 1-year	MOBIL #18-FYM (FORMER #11-FYM)	RANCHO PARK	<u>T0603701166</u>	900640070	Chandra Cansler	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	7/16/1990	20		
Appears near completion within 1-year	SANTA MONICA MUNICIPAL BUS LINES MAINTENANCE FACIL		T0603701364	904010043	Jay Huang	Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	ND - No Data in GeoTracker	Diesel	G - Government Entity (include School, Hospita Utility)	al, Yes	No	Yes	Yes	No	Unknown	Yes	Yes	None	7/16/1990	20		
Appears near completion within 1-year	TOSCO - 76 STATION #5195 (FORMER)	WHITTIER	<u>T0603703719</u>	I-11042		Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes	Yes	Yes	Yes	No	Partially Complete (Missing some data)	2/28/1990	20		
Appears near completion within 1-year	BARRY J. NIDOR JUVENILE HALL	SYLMAR	<u>T0603702268</u>	913421561		Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	ND - No Data in GeoTracker	Diesel	G - Government Entity (include School, Hospita Utility)	al, Unknown	Unknown	No	Yes	Yes	No	Yes	Yes	None	3/20/1992	18		
Appears near completion within 1-year	76 STATION #254488 (EAOP)	CANOGA PARK	<u>T10000000494</u>	913060225A	David M. Bjostad	Open - Verification Monitoring	O - Other	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	No	Yes	No	Limited	12/10/1991	18		
Appears near completion within 1-year	CONOCO INC (Charnock Well)	CULVER CITY	<u>T0603704152</u>	I-14314	WeiXing Tong	Open -	CP - CA Policy (Water Quality Objectives Not Met)	ND - No Data in GeoTracker	Gasoline	Z - Major Oil Company	Yes	Unknown	Yes	Yes	Yes	Yes	No	Yes	Limited	9/4/1992	18		
Appears near completion within 1-year	MOBIL #18-E67 (FORMER #11-E67) (Site in EAOP)	DIAMOND BAR	<u>T0603704511</u>	R-00090		Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Unknown	Yes	Yes	Yes	Incomplete (GWM only)	9/10/1992	18		
Appears near completion within 1-year	TOSCO - 76 STATION #3900	LOS ANGELES	<u>T0603700641</u>	900200143	Daniel Pirotton	Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	No	No	Yes	Partially Complete (Missing some data)	4/23/1993	17		
Appears near completion within 1-year	CHEVRON #9-8701	SAN PEDRO	<u>T0603701638</u>	907310325		Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	No	No	No	Yes	Limited	3/25/1993	17		

ESTIMATED STATUS IN THE CLEANUP PIPETIME.	CASE LEAD AGENCY: LOS ANGELES RWQCB - REGION 4)	СПУ	GLOBAL ID	LOCAL CASE ID (REGION 2 CASE M	CASEWORKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMENTAL BARRIER TO	/ 8	FINARY COC 11.	APPARENT TIPE OF RP	DOES SITE APPEARS TO HAVE BEEN PET	DOES SITE APPEARS TO HAVE CURREAL	CAINED IN GEOTRACKED.	GROUNDWATER MONITORING	INVESTIGATION (LAST S-KEARS)	REWEDIATION (LAST SYEARS)	LAST REGULATORY DIRECTIVE LETT.	PERCEPTION OF NEED	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Appears near completion within 1-year	CUDDLY TOYS MFG	LOS ANGELES	<u>T0603704442</u>	I-17062	Magdy Baiady	Open - Site Assessment	O - Other	ND - No Data in GeoTracker	Diesel	S - Small Private Business	Unknown	Unknown	Yes	Unknown	No	No	Yes	Yes	None	10/21/1992	17		
Appears near completion within 1-year	TERMINAL ISLAND PRISON	TERMINAL ISLAND	<u>T060370027</u>	907310307	Jimmie Woo	Open - Site Assessment	I - Incomplete Assessment	U - Unknown	Diesel	G - Government Entity (include School, Hospital, Utility)	No	Unknown	Yes	Yes	Yes	No	Yes	Yes	Limited	5/23/1995	15		
Appears near completion within 1-year	76 STATION #254359	DOWNEY	<u>T0603704998</u>	R-11008	Noman Chowdhury	Open - Referred	O - Other	RP - Non- Responsive RP	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	No	Yes	No	Partially Complete (Missing some data)	7/27/1995	15		
Appears near completion within 1-year	VIRCO MANUFACTURING CORP.	LOS ANGELES	<u>T0603728230</u>	902470134		Open - Remediation	O - Other	RP - Non- Responsive RP	Solvent	I - Industry (Railroad, Steel etc)	Yes	Unknown	Yes	Yes	Unknown	Unknown	Yes	Yes	None	3/16/1995	15		
Appears near completion within 1-year	76 STATION #2705706	LOS ANGELES	<u>T10000000206</u>	900040252A		Open - Referred	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	No	Yes	No	Limited	6/14/1995	15		
Appears near completion within 1-year	AT&T B1245 FACILITY	AGOURA HILLS	<u>T0603704688</u>	R-05671	David M. Bjostad	Open - Verification Monitoring	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Diesel	S - Small Private Business	No	Unknown	Yes	Unknown	Yes	No	Yes	No	Limited	7/12/1995	15		
Appears near completion within 1-year	DON BOSCO TECHNICAL SCHOOL	ROSEMEAD	<u>T0603704468</u>	I-21159		Open - Remediation	O - Other	ND - No Data in GeoTracker	Solvent	S - Small Private Business	Unknown	Unknown	Yes	Unknown	Unknown	No	Yes	Yes	None	11/30/1994	15		
Appears near completion within 1-year	FIRE STATION #127	CARSON	<u>T0603705133</u>	R-12498	Magdy Baiady	Open - Verification Monitoring	R - Remedial Confirmation	U - Unknown	Solvent	G - Government Entity (include School, Hospital, Utility)	No	Unknown	Yes	Yes	Yes	Yes	No	Yes	Partially Complete (Missing some data)	12/11/1995	15		
Appears to be on track	U-HAUL CENTER #713-84	LONG BEACH	<u>T0603701854</u>	908070025	Nhan Bao	Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	S - Small Private Business	Yes	Unknown	Yes	Yes	No	Yes	Yes	Yes	Partially Complete (Missing some data)	11/30/1984	26		
Appears to be on track	MOBIL #18-LMR	HOLLYWOOD	<u>T0603700759</u>	900280107	Jay Huang	Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Multiple	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	8/1/1986	24		
Appears to be on track	MOBIL 18-K1R	LOS ANGELES	<u>T0603701095</u>	900470107		Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)		Multiple	Z - Major Oil Company	Yes	No	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	6/8/1986	24		
Appears to be on track	MOBIL #18-MPX	LONG BEACH	<u>T0603701894</u>	908080143	Ha D. Nguyen	Open - Remediation	R - Remedial Confirmation	O - Other	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes	Yes	Yes	No	No	Limited	6/10/1986	24		
Appears to be on track	US POSTAL SERVICE	ENCINO	<u>T0603702147</u>	913160225		Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	G - Government Entity (include School, Hospital, Utility)	No	No	Yes	Yes	No	No	No	Yes	Limited	6/26/1986	24		
Appears to be on track	MOBIL #18-LMQ	SANTA CLARITA	<u>T0603702307</u>	913500043	Chandra Cansler	Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	Yes	Limited	2/11/1986	24		
Appears to be on track	MOBIL #18-FV6	HUNTINGTON PARK	<u>T0603704809</u>	R-09382	Maryam Taidy	Open - Site Assessment	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	Partially Complete (Missing some data)	4/14/1986	24		
Appears to be on track	PALMS DISTRIBUTION HEADQUARTER	LOS ANGELES	<u>T0603700555</u>	900160034	Daniel Pirotton	Open - Remediation	R - Remedial Confirmation	O - Other	Diesel	G - Government Entity (include School, Hospital, Utility)	Unknown	Unknown	Yes	Yes	Yes	Yes	No	Yes	Incomplete (GWM only)	5/22/1987	23		
Appears to be on track	MOBIL FORMER BULK PLANT # 04-419	LA PUENTE	<u>T0603702788</u>	I-01520		Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes	Yes	Yes	No	Yes	Partially Complete (Missing some data)	3/19/1987	23		
Appears to be on track	ATLANTIC AVIATION (FORMER MERCURY SERVICES)	WESTCHESTER	T0603701041	900450152	David M. Bjostad	Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Diesel	G - Government Entity (include School, Hospital, Utility)	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Limited	2/6/1989	22		

	ESTIMATED STATUS IN THE CLEANUP PIPELINE?	ICASE LEAD AGENCY. LOS ANGELES RWQCB - REGION 4)	Cfty	OI THEOTIS	LOCAL CASE ID (REGION 2 CASE	САЅЕWОRKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMENTAL BARRIER TO	APPARENT NON-ENVIRONMENTAL P.	PRIMARY CO.	APPARENT TYPE OF RP	DOES SITE APPEARS TO HAVE BEEN PER	DOES SITE APPEARS TO HAVE CURRENT	CLAIMED IN GEOTRACE.	GROUNDWATER MONITORING (LAST 5-YEARS)	INVESTIGATION (LAST 5-YEARS)	REMEDIATION (LAST 5-YEARS)	LAST REGULATORY DIRECTIVE	PERCEPTION OF NOT	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Арр	pears to be on track	MOBIL 18-LEG	JEFFERSON PARK	<u>T0603700608</u>	900180098		Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	11/23/1987	22		
App	pears to be on track	LA CO FACILITIES MGM DEPT	CARSON	<u>T0603701679</u>	907450034		Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	G - Government Entity (include School, Hospital, Utility)	No	Unknown	Yes	Yes	Yes	Yes	No	Yes	Partially Complete (Missing some data)	8/5/1988	22		
Арр	pears to be on track	SHELL WIC 204-4190-0204	HACIENDA HEIGHTS	<u>T0603702922</u>	I-03526	Ha D. Nguyen	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	Unknown	Unknown	Yes	Yes	Yes	Yes	Yes	Yes	Partially Complete (Missing some data)	7/13/1988	22		
Арр	pears to be on track	SHELL STATION	LOS ANGELES	<u>T0603701203</u>	900660052	Jay Huang	Open - Remediation	R - Remedial Confirmation	N - None	Gasoline	S - Small Private Business	No	Yes	Yes	Yes	Yes	Yes	No	Yes	Limited	5/15/1989	21		
Арр	pears to be on track	G I TRUCKING CO.	LA MIRADA	<u>T0603701540</u>			Open - Remediation		U - Unknown	Gasoline	I - Industry (Railroad, Steel etc)	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Limited	11/11/1988	21		
Арр	pears to be on track	GOOD SAMARITAN HOSPITAL	LOS ANGELES	<u>T0603700594</u>	900170143	Arman Toumari	Open - Verification Monitoring	R - Remedial Confirmation	U - Unknown	Solvent	G - Government Entity (include School, Hospital, Utility)	Yes	Unknown	Yes	Yes	Yes	Yes	Yes	No	Limited	5/11/1990	20		
Арр	pears to be on track	SHELL #204-1944-0100	CULVER CITY	<u>T0603703277</u>	I-07099	WeiXing Tong	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Partially Complete (Missing some data)	7/22/1991	19		
Арр	pears to be on track	MOBIL #18-E45 (FORMER #11-E45)	WHITTIER	<u>T0603702878</u>	I-02988		Open - Remediation	O - Other	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Unknown	No	Yes	Partially Complete (Missing some data)	8/13/1991	19		
Арр	pears to be on track	SHELL	LOS ANGELES	<u>T0603701109</u>	900480098		Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	No	No	Yes	No	Limited	10/25/1991	18		
Арр	pears to be on track	TARGET STORE #T-292	SIGNAL HILL	<u>T0603701871</u>	I-11132	Nhan Bao	Open - Site Assessment	I - Incomplete Assessment	U - Unknown	Gasoline	S - Small Private Business	No	Unknown	Yes	Yes	Yes	Yes	Yes	No	Limited	11/1/1991	18		
Арр	pears to be on track	MOBIL #18-GP9 (FORMER #11-GP9)	ARTESIA	<u>T0603702870</u>	I-02871	Nhan Bao	Open - Site Assessment	R - Remedial Confirmation	U - Unknown	Solvent	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	6/17/1992	18		
Арр	pears to be on track	EXXON #7-3591 (FORMER)	ATHENS	<u>T0603702884</u>	I-03027		Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes	Yes	Yes	No	No	Partially Complete (Missing some data)	10/21/1991	18		
Арр	pears to be on track	EXXON #7-9477 (FORMER) (Charnock)	CULVER CITY	<u>T0603703278</u>	I-07100	WeiXing Tong	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	Yes	Unknow	Partially Complete (Missing some data)	4/8/1992	18		
Арр	pears to be on track	MOBIL 18-GG4	NORWALK	<u>T0603704589</u>	R-02210	Ha D. Nguyen	Open - Remediation	R - Remedial Confirmation	U - Unknown	Other	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	No	Yes	Partially Complete (Missing some data)	7/2/1992	18		
Арр	pears to be on track	FAST GAS #538/TARGET T- 290	GARDENA	<u>T0603705396</u>	R-23243	Chandra Cansler	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Unknown	Yes	Yes	Yes	Yes	Limited	10/29/1991	18		
Арр	pears to be on track	SHELL BRANDED SERVICE STATION (FORMER)	LOS ANGELES	<u>T0603701215</u>	900680016	Daniel Pirotton	Open - Remediation	R - Remedial Confirmation	N - None	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes	No	Yes	No	Yes	Partially Complete (Missing some data)	6/17/1993	17		
Арр	pears to be on track	MOBIL #18-MAP (Case in EAOP)	TORRANCE	<u>T0603704674</u>	R-05290		Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	N - None	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes	Yes	Yes	Yes	No	Partially Complete (Missing some data)	12/15/1993	17		

ESTINATED STATUS IN THE CLEANUP PIPELINE?	ICASE LEAD AGENCY: LOS ANGELES RWQCB - REGION 4)	СПУ	GLOBAL ID	LOCAL CASE ID (REGION 2 CASE NIII	CASEWORKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMENTAL BARRES -	APPARENT NON-ENVIRONMENTAL	PRIMARY COC (In Geore	APPARENT TIPE OF RP	DOESSITE APPEARS TO HAVE BEEN REDEVEN	DOES SITE APPEARS TO HAVE CURRENT	CLAIMED IN GEOTFACKER?	GROUNDWATER MONITORING (LAST 5-YEARS)	(LAST SYEARS) REMEDIATION	IMSS E-VEARS) MST REGULATORY DIRECTIVE LETTER ANY ISSUED SINCE 2004?)	DATA IN GEOTRACKER	RELEASE DATE	AGE NEXT STEP FOR AGENCY	
Appears to be on track	MOBIL OIL CORP. S.S. #18-LKA	CULVER CITY	<u>T0603704754</u>	R-07139	Jay Huang	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es Yes	Yes N	Partially Complete (Missing some data)	1/19/1994 1	7	
Appears to be on track	76 PRODUCTS STATION #4682	WOODLAND HILLS	<u>T0603702399</u>	913670634		Open - Site Assessment	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es No	No N	Partially Complete (Missing some data)	2/7/1995	16	
Appears to be on track	MOBIL #11-FXV	SHERMAN OAKS	<u>T0603702424</u>	914030316	Chandra Cansler	Open - Remediation	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es Yes	No Y	s Limited	6/1/1995	.5	
Appears to be on track	TOSCO - 76 STATION #2021	LOS ANGELES	<u>T0603701110</u>	900480107		Open - Site Assessment	I - Incomplete Assessment	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es No	No N	Partially Complete (Missing some data)	1/7/1996	1.5	
Appears NOT to be on track	ARCO #0166	LOS ANGELES	<u>T0603701007</u>	900420089	Maryam Taidy	Open - Remediation	I - Incomplete Assessment	O - Other	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Unki	nown Yes	No Y	s Limited	11/15/1984 2	:6	
Appears NOT to be on track	SHELL	RESEDA	<u>10603702223</u>	913350716		Open - Site Assessment	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	Z - Major Oil Company	Yes	Unknown	Yes	Yes N	lo Yes	No Y	s Limited	11/19/1985 2	5	
Appears NOT to be on track	MOBIL #18-KCM	SANTA CLARITA	<u>T0603702983</u>	I-04508	Jay Huang	Open - Remediation	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	z - Major Oil Company	No	Yes	Yes	Yes Y	es Yes	No N	Partially Complete (Missing some data)	3/31/1986	4	
Appears NOT to be on track	MOBIL #11-LM9	LOS ANGELES	<u>T0603700727</u>	900260243		Open - Site Assessment	I - Incomplete Assessment	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es Yes	No Y	Partially Complete (Missing some data)	7/16/1987 2	.3	
Appears NOT to be on track	MOBIL 18-MLT	LONG BEACH	T0603701878	908070307	Ha D. Nguyen	Open - Remediation	I - Incomplete Assessment	N - None	Multiple	Z - Major Oil Company	No	Yes	Yes	Yes Y	es No	No Y	Partially Complete (Missing some data)	9/1/1987 2	23	
Appears NOT to be on track	CHEVRON #9-6594	INGLEWOOD	<u>T0603704837</u>	R-09600	Jimmie Woo	Open - Site Assessment	I - Incomplete Assessment	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes Y	es No	No Y	s Limited	10/19/1987 2	.3	
Appears NOT to be on track	MOBIL #11-MKK	DOWNEY	<u>T0603704802</u>	R-09348	Noman Chowdhury	Open - Remediation	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es Yes	No Y	Partially Complete (Missing some data)	11/25/1987	3	
Appears NOT to be on track	SOUTHWEST STREET MAINT YARD	LOS ANGELES	T0603701091	900470061	Daniel Pirotton	Open - Remediation	CP - CA Policy (Water Quality Objectives No Met)		Other	G - Government Entity (include School, Hospital, Utility)	No	Unknown	Yes	Yes N	lo Yes	No Y	s Partially Complete (Missing some data)	9/4/1987 2	23	
Appears NOT to be on track	MOBIL #18-LLR	LOS ANGELES	<u>T0603700620</u>	900190107	Daniel Pirotton	Open - Remediation	O - Other	U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes N	lo Yes	No Y	s Limited	8/24/1989 2	1	
Appears NOT to be on track	LA DPW WESTERN DISTRICT H.Q.	MID CITY	<u>10603700617</u>	900190070	Daniel Pirotton	Open - Remediation	R - Remedial Confirmation	U - Unknown	Gasoline	G - Government Entity (include School, Hospital, Utility)	No	No	Yes	Yes Y	es Yes	No Y	Incomplete (GWM only)	5/1/1992 1	1.8	
Appears NOT to be on track	CHEVRON #9-9266	SANTA MONICA	T0603701393	904040125A	Jay Huang	Open - Remediation	I - Incomplete Assessment	U - Unknown	Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Unki	nown No	No Y	Partially Complete (Missing some data)	3/22/1993 1	7	
Appears NOT to be on track	PETRO DIAMOND TERMINAL COMPANY	LONG BEACH	<u>T0603701940</u>	908130261	Mercedes Hsu	Open - Remediation	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	I - Industry (Railroad, Steel etc)	No	Yes	Yes	Yes N	lo Yes	Yes Y	s Limited	11/2/1992 1	7	
Appears NOT to be on track	TEXACO	SHERMAN OAKS	<u>T0603702476</u>	914230207		Open - Site Assessment	CP - CA Policy (Water Quality Objectives No Met)	t U - Unknown	Gasoline	Z - Major Oil Company	Yes	No	Yes	Yes Unki	nown Yes	No Y	Incomplete (GWM only)	6/23/1993 1	7	
Appears NOT to be on track	TOSCO - 76 STATION #7426	AGOURA	<u>T0603704600</u>	R-02634	Daniel Pirotton	Open - Remediation	CP - CA Policy (Water Quality Objectives No Met)		Gasoline	Z - Major Oil Company	No	Yes	Yes	Yes Y	es Unkno	wn Yes N	Partially Complete (Missing some data)	4/1/1994 1	1.6	


	ESTIMATED STATUS IN THE CLEANUP PIPELINE?	ICASELEAD AGENCY: LOS ANGELES RWQCB · REGION 4)	СПУ	GiOBAL ID	LOCAL CASE ID (REGION 2 CASE NII	CASEWORKER	CURRENT CASE STATUS	APARENT PRIMARY ENVIRONMENTAL BARRIER TO	APPARENT NON-ENVIRONMENTAL P.	PRIMARY COC. 1.	'I'I Geofracker)	MPARENT TYPE OF RP	DOES SITE APPEARS TO HAVE BEEN REVIEW	DOES SITE APPEARS TO HAVE CURPE.	USAGE? THENT PETROLEUM CLAIMED IN GEOTRACKER?	GROUNDWATER MONITORING (LAST 5-YEA B-C-)	INVESTIGATION (LAST 5-YEARS)	REMEDIATION (LAST.S-YEARS)	LAST REGULATORY DIRECTIVE LETTED	PERCEPTION OF NEED FOR INCO.	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Appears NOT to	o be on track	THERM-X CHEMICAL & OIL	HUNTINGTON PARK	<u>T0603759597</u>	R-21186		Open - Site Assessment	A - Awaiting Well Abadonment	ND - No Data in GeoTracker	Other	I - Industry (R Steel etc)	Railroad,	No	Unknown	No	No	No	No	Yes	Yes	None	10/14/1993	16		
Appears to be s	stuck	LA CITY DEPT WATER & POWER	WATTS	T0603700406	900020016		Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	ND - No Data in GeoTracker	Gasoline	G - Governme (include Scho		Unknown	Unknown	Yes	Yes	Yes	No	No	Yes	None	3/23/1984	26		
Appears to be s	stuck	ARCO #3018	EL MONTE	<u>T0603702627</u>	R-09016 9221-09016	Nhan Bao	Open - Site Assessment	I - Incomplete Assessment	U - Unknown	Gasoline	Z - Major Oil	Company	No	Yes	Yes	Yes	Yes	No	No	Yes	Partially Complete (Missing some data)	1/22/1985	26		
Appears to be s	stuck	TOSCO - 76 STATION #5096	TORRANCE	<u>T0603701506</u>	905050061		Open - Remediation	I - Incomplete Assessment	U - Unknown	Gasoline	Z - Major Oil	Company	No	Yes	Yes	Yes	Yes	No	Yes	No P	Partially Complete (Missing some data)	2/25/1986	25		
Appears to be s	stuck	TEXACO	HOLLYWOOD	<u>T0603700926</u>	900380152	Daniel Pirotton	Open - Site Assessment	O - Other	ND - No Data in GeoTracker	Gasoline	U - Unknown		Yes	Yes	No	No	No	Yes	No	Yes	None	4/4/1986	24		
Appears to be s	stuck	THE SOUTHLAND CORP (CHIEF/AUTO)	LONG BEACH	<u>T0603701903</u>	908100061		Open - Remediation	I - Incomplete Assessment	U - Unknown	Gasoline	S - Small Priva	ate Business	Yes	No	Yes	Yes	No	No	No	Yes	Limited	5/12/1986	24		
Appears to be s	stuck	MOBIL #11-FCG	VAN NUYS	<u>T0603702451</u>	914061743	Magdy Baiady	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	Z - Major Oil	Company	No	Yes	Yes	No	No	No	Yes	Yes	Limited	11/10/1986	24		
Appears to be s	stuck	ARCO #1361 (FORMER)	SHERMAN OAKS	<u>T0603702479</u>	914230307		Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Priv	ate Business	Unknown	Unknown	Yes	No	No	No	No	Yes	None	10/14/1986	24		
Appears to be s	stuck	MOBIL #18-FOM (FORMER 11-FOM)	LOS ANGELES	<u>T0603700880</u>	900350098	Jay Huang	Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)		Gasoline	Z - Major Oil	Company	No	Yes	Yes	Yes	Yes	Unknown	No	Yes	Limited	7/10/1987	23		
Appears to be s	stuck	YELLOW FREIGHT SYSTEMS INC	PICO RIVERA	T0603702685	I-00185	Ahmad J Lamma	Open - Remediation	I - Incomplete Assessment	RP - Non- Responsive RP	Other	S - Small Priva	ate Business	Yes	No	Yes	Unknown	Unknown	No	No	Yes	None	9/24/1987	23		
Appears to be s	stuck	ARGO REALTY PROPERTY (EAOP)	SANTA MONICA	<u>T0603701383</u>	904040034	Jay Huang	Open - Site Assessment	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil	Company	Yes	No	Yes	Yes	Yes	No	No	Yes	Incomplete (GWM only)	11/2/1987	23		
Appears to be s	stuck	TEXACO	PARAMOUNT	<u>T0603703087</u>	1-05588			I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	U - Unknown		No	Yes	No	No	No	No	Yes	Yes	None	3/15/1988	22		
Appears to be s	stuck	BIXBY LAND COMPANY	LONG BEACH	<u>T0603774459</u>	908150307			I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Priv	ate Business	Unknown	Unknown	Yes	No	Yes	No	Yes	Yes	None	7/7/1988	22		
Appears to be s	stuck	PRUDENTIAL OVERALL SUPPLY	CERRITOS	<u>T0603702803</u>	I-01827			I - Incomplete Assessment	U - Unknown	Solvent	S - Small Priva	ate Business	No	Unknown	Yes	Yes	No	No	No	Yes	Incomplete (GWM only)	1/31/1989	22		
Appears to be s	stuck	CERRITOS COMMUNITY COLLEGE	NORWALK	<u>T0603703264</u>	1-06888			I - Incomplete Assessment	U - Unknown	Multiple	G - Governme (include Scho Utility)		No	Unknown	Yes	Yes	Yes	Yes	Yes	Yes	Partially Complete (Missing some data)	12/5/1988	22		
Appears to be s	stuck	FOUA D N DAGHER	MONTECITO HEIGHTS	<u>T0603700808</u>	900310270	Magdy Baiady	Open - Remediation	CP - CA Policy (Water Quality Objectives Not Met)	U - Unknown	Gasoline	Z - Major Oil	Company	No	Yes	Yes	Yes	Yes	Yes	No	Yes	Partially Complete (Missing some data)	6/19/1989	21		
Appears to be s	stuck	CITY OF LA VERNE, CITY HALL	LA VERNE	<u>T0603792929</u>	I-13153		Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	G - Governm (include Scho Utility)	ent Entity ool, Hospital,	Unknown	No	No	No	No	No	Yes	Yes	None	5/19/1989	21		
Appears to be s	stuck	P&M #936	HACIENDA HEIGHTS	<u>T0603704036</u>	I-13117	Ha D. Nguyen	Open - Site Assessment	I - Incomplete Assessment	F - Financial Hardship	Gasoline	S - Small Privi	ate Business	Unknown	Unknown	Yes	No	Yes	No	Yes	Yes	Limited	3/21/1991	19		

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	(CASE LEAD AGENCY: LOS ANGELES RWQCB - REGION 4)	CITY	GLOBAL ID	LOCAL CASE ID (REGION 2 CASE NU	CASEWORKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMAE	egulatory Agency NENTAL BARRIER	PRIMARY COC (In Geor	APPARENT TIPE OF RP	DOES SITE APPEARS TO HAVE BEEN P.	DOES SITE APPEARS TO HAVE CLIBER.	USAGE? THEN PETROLEUM CLAIMED IN GEOTRACE.	GROUNDWATER MONITORING	WESTGATION (LAST 5-YEARS)	REWEDIATION (LAST.5-YEARS)	LAST REGULATORY DIRECTIVE LETTER (ANY ISSUED SINCE 2007)	PERCEPTION OF NEED FOR INCREASE.	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Appears to be stuck	TEMPLE SHERIFF STATION	TEMPLE CITY	<u>T0603704593</u>	R-02444	Ha D. Nguyen	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	No	Unknown	No	Unknown	Unknown	Unknown	Yes	Yes	None	5/23/1991	19		
Appears to be stuck	WEST COAST CHOPPERS	LONG BEACH	<u>T0603701939</u>	908130252	Jay Huang	Open - Site Assessment	I - Incomplete Assessment	RP - Non- Responsive RP	Other	S - Small Private Business	No	Unknown	No	No	No	No	Yes	Yes	None	5/15/1995	15		
Appears to be stuck	LONG BEACH CITY TOW YARD	LONG BEACH	T0603701960	908130498	David M. Bjostad	Open - Verification Monitoring	I - Incomplete Assessment	U - Unknown	Gasoline	G - Government Entity (include School, Hospital, Utility)	Unknown	Unknown	Yes	Unknown	Unknown	No	Yes	Yes	Limited	8/30/1995	15		
Appears to be stuck	PUBLIC SERVICE YARD	LONG BEACH	T0603701971	908130607	Noman Chowdhury	Open -	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	Uńknown	Unknown	No	No	No	No	No	Yes	None	8/4/1995	15		
Appears to be stuck	DIAMOND OIL COMPANY	MONTEBELLO	T0603721214	R-12651	Ha D. Nguyen	Open - Referred	I - Incomplete Assessment	RP - Non- Responsive RP	Gasoline	Z - Major Oil Company	Yes	No	No	Unknown	Unknown	Unknown	Yes	Yes	None	11/2/1995	15		
Appears to be stuck	DOWNEY GLASS CO, INC	COMMERCE	T0603758087	900220025A	Magdy Baiady	Open - Referred	O - Other	RP - Non- Responsive RP	Gasoline	S - Small Private Business	No	Unknown	No	Unknown	Unknown	Unknown	Yes	Yes	None	10/6/1995	15		
Unable to determine (Insufficient information in GeoTracker)	SHELL #204-0580-0200	BELL GARDENS	<u>T0603704696</u>	R-05769	Magdy Baiady	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	Yes	No	No	No	No	No	No	Yes	None	4/6/1984	26		
Unable to determine (Insufficient information in GeoTracker)	MOBIL	LONG BEACH	<u>T0603701918</u>	908130034		Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	Yes	Unknown	Yes	Unknown	Unknown	No	No	Yes	None	10/17/1984	26		
Unable to determine (Insufficient information in GeoTracker)	GAS S/S	LOS ANGELES	<u>T0603700490</u>	900110016		Open - Site Assessment	O - Other	ND - No Data in GeoTracker	Gasoline	U - Unknown	Unknown	Unknown	No	No	No	No	Yes	Yes	None	3/6/1985	25		
Unable to determine (Insufficient information in GeoTracker)	GEORGE MITCHEL	LONG BEACH	<u>T0603701919</u>	908130043	Jay Huang	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	Unknown	Unknown	Yes	Unknown	Unknown	No	No	Yes	None	11/1/1984	25		
Unable to determine (Insufficient information in GeoTracker)	VENTURA MARKETING DIST	VENTURA	<u>T0611100023</u>	930010343	Yue Rong	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	U - Unknown	Yes	No	No	No	No	No	No	Yes	None	3/1/1987	24		
Unable to determine (Insufficient information in GeoTracker)	FIRE STATION #3	LOS ANGELES	<u>T0603700532</u>	900120361	Chandra Cansler	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	Unknown	No	Yes	Yes	Unknown	No	No	Yes	None	6/16/1986	24		
Unable to determine (Insufficient information in GeoTracker)	PACIFIC VALVES	SIGNAL HILL	<u>T0603703839</u>	I-11716	Nhan Bao	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Solvent	S - Small Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	9/12/1986	24		
Unable to determine (Insufficient information in GeoTracker)	Lunada Bay Automotive	Palos Verdes Estates	<u>T0603704996</u>	R-11004	Daniel Pirotton	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel	Z - Major Oil Company	Yes	Unknown	No	No	No	No	Yes	Yes	None	3/27/1986	24		
Unable to determine (Insufficient information in GeoTracker)	KEY CENTERS, INC	HERMOSA BEACH	<u>T0603705023</u>	R-11141		Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	4/10/1986	24		
Unable to determine (Insufficient information in GeoTracker)	HENDE'S STATION	LONG BEACH	<u>T0603701826</u>	908060070	Ha D. Nguyen	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	No	Yes	No	No	No	No	Yes	Yes	None	12/9/1986	23		
Unable to determine (Insufficient information in GeoTracker)	LONG BEACH HOT MIX/ASPHALT	LONG BEACH	<u>T0603701864</u>	908070152	Nhan Bao	Open - Remediation	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel	S - Small Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	8/1/1987	23		
Unable to determine (Insufficient information in GeoTracker)	STABOND CORPORATION	GARDENA	<u>T0603701290</u>	902490152	Magdy Baiady	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Other	S - Small Private Business	Unknown	Unknown	No	Unknown	Unknown	No	Yes	Yes	None	4/19/1988	22		

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	ICASELEAD AGENCY: LOS ANGELES RWQCB - REGION 4)	City	от ривоть	LOCAL CASE ID (REGION 2 CASE NUMBERS)	CASEWORKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMENTAL BARRED -	APPARENT NON-ENVIRONMENTAL BARRIER T	PRIMARY COC II.	" (in Geoffacker)	APPARENT TYPE OF RP	DOES SITE APPEARS TO HAVE BEEN DO.	DOES SITE APPEARS TO HAVE CLIDATE.	USAGE? OURENT PETROLEUM CLAIMED IN GEOTRACE.	GROUNDWATER MONITORING	INVESTIGATION (LAST 5-YEARS)	REWEDIATION (LAST 5.YEARS)	LAST REGULATORY DIRECTIVE LETTED	PERCEPTION OF NEED FOR INCREASER.	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Unable to determine (Insufficient information in GeoTracker)	PEMACO INC	MAYWOOD	<u>T0603704068</u>	I-13417	Nhan Bao	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Solvent	S - Small I	Private Business	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Yes	None	7/19/1988	22		
Unable to determine (Insufficient information in GeoTracker)	RUBEN GONZALES GARAGE	LOS ANGELES	<u>T10000000531</u>	R-01912	Maryam Taidy	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Multiple	S - Small I	Private Business	No	Unknown	No	No	No	No	Yes	Yes	None	3/10/1988	22		
Unable to determine (Insufficient information in GeoTracker)	MOBIL	LONG BEACH	<u>T0603701707</u>	908020234	Mercedes Hsu	Open - Remediation	I - Incomplete Assessment	RP - Non- Responsive RP	Gasoline	S - Small I	Private Business	Yes	No	No	No	No	No	Yes	Yes	None	1/25/1989	21		[
Unable to determine (Insufficient information in GeoTracker)	OAKDALE MEMORIAL PARK	GLENDORA	<u>T0603707050</u>	R-23243	Chandra Cansler	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small I	Private Business	No	No	No	No	No	No	Yes	Yes	None	5/17/1989	21		
Unable to determine (Insufficient information in GeoTracker)	PARKER CENTER	LOS ANGELES	<u>T0603700531</u>	900120352	Maryam Taidy	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel		nment Entity chool, Hospital,	Unknown	No	No	Unknown	Unknown	Unknown	Yes	Yes	None	7/2/1990	20		
Unable to determine (Insufficient information in GeoTracker)	ESSEX CHEMICALS CORP.	COMPTON	<u>T0603702989</u>	I-04560	Magdy Baiady	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Other	I - Industr Steel etc)	y (Railroad,	No	Unknown	No	No	No	No	Yes	Yes	None	3/12/1990	20		
Unable to determine (Insufficient information in GeoTracker)	ALHAMBRA GENERAL MAIL FACILITY	INDUSTRY	<u>T0603703168</u>	I-06116		Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline		nment Entity chool, Hospital,	No	Unknown	No	Unknown	Unknown	No	Yes	Yes	None	3/30/1990	20		
Unable to determine (Insufficient information in GeoTracker)	NU-WAY INDUSTRIES	IRWINDALE	<u>T0603702750</u>	I-01077	Yue Rong	Open - Site Assessment	I - Incomplete Assessment	RP - Non- Responsive RP	Gasoline	I - Industr Steel etc)	y (Railroad,	No	Unknown	No	No	No	No	No	Yes	None	8/14/1990	20		
Unable to determine (Insufficient information in GeoTracker)	E C. CONSTRUCTION COMPANY	SOUTH EL MONTE	T0603704128	I-14000A	Joe F. Luera	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	U - Unkno	own	Unknown	Unknown	No	No	No	No	No	Yes	None	3/6/1990	20		
Unable to determine (Insufficient information in GeoTracker)	PIC A PART AUTO SALVAGE	MONROVIA	<u>T0603704166</u>	I-14428	Joe F. Luera	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small I	Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	5/2/1990	20		
Unable to determine (Insufficient information in GeoTracker)	ARCO CREDIT UNION	CARSON	T0603704294	I-15338	Maryam Taidy	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline		Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	3/13/1990	20		
Unable to determine (Insufficient information in GeoTracker)	GOOD SAMARITAN HOSPITAL (2)	LOS ANGELES	<u>T0603772920</u>	900170216	Arman Toumari	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Solvent		nment Entity chool, Hospital,	Unknown	Unknown	No	Yes	No	No	Yes	Yes	None	5/11/1990	20		1
Unable to determine (Insufficient information in GeoTracker)	OLD FIVE INC.	BELLFLOWER	<u>T0603704357</u>	I-15840		Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small I	Private Business	Yes	No	No	No	No	No	Yes	Yes	None	10/17/1990	20		I
Unable to determine (Insufficient information in GeoTracker)	RAYNE SOFTWATER OF THE VALLEY	CANOGA PARK	<u>T0603702091</u>	913030852	Maryam Taidy	Open - Site Assessment	O - Other	ND - No Data in GeoTracker	Solvent	S - Small I	Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	2/12/1991	19]
Unable to determine (Insufficient information in GeoTracker)	TEXACO	COVINA	<u>T0603703083</u>	I-05556	Ahmad J Lamma	Open - Referred	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	Z - Major	Oil Company	No	Yes	No	No	No	No	Yes	Yes	None	12/20/1991	18		1
Unable to determine (Insufficient information in GeoTracker)	LA CO SHERIFF STATION	SANTA CLARITA	<u>T0603704904</u>	R-10092	Jay Huang	Open - Remediation	O - Other	U - Unknown	Gasoline		nment Entity chool, Hospital,	Unknown	Unknown	Yes	Yes	Unknown	Unknown	No	Yes	Limited	3/16/1992	18		
Unable to determine (Insufficient information in GeoTracker)	BELMONT FIBERS	MONTEBELLO	<u>T0603704108</u>	I-13835	Ahmad J Lamma	Open - Site Assessment	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel	S - Small I	Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	3/10/1992	18		
Unable to determine (Insufficient information in GeoTracker)	SMITH'S FOOD & DRUGS/MOSKOWITZ	LAKEWOOD	<u>T0603704432</u>	I-16734	Nhan Bao	Open - Remediation	I - Incomplete Assessment	ND - No Data in GeoTracker	Other	S - Small I	Private Business	Unknown	Yes	No	No	No	No	Yes	Yes	None	8/27/1992	18]

CASE REVIEW SUMMARY TABLE (REGION 4 – LOS ANGELES RWQCB)

ESTINATED STATUS IN THE CLEANUP PIPELINE?	ICASE LEAD AGENCY: LOS ANGELES RWQCB - REGION 4)	CITY	GLOBAL ID	LOCAL CASE ID (REGION 2 CASE NUMAN.	CASEWORKER	CURRENT CASE STATUS	APPARENT PRIMARY ENVIRONMENTAL BARRIER 77	APPARENT NON-ENVIRONMENTAL BARRIER 77	PRIMARY COC (In Geotter)	APPARENT TYPE OF RP	DOES SITE APPEARS TO HAVE BEEN RECO	DOES SITE APPEARS TO HAVE CURPE.	CLAINED IN GEOTRACKED.	GROUNDWATER MONITORING (LAST 5-YEARE)	INVESTIGATION (LAST 5-YEARS)	REMEDIATION (LAST 5-YEARS)	LAST REGULATORY DIRECTIVE LETTED	PERCEPTION OF NEED FOR	DATA IN GEOTRACKER	RELEASE DATE	AGE	NEXT STEP FOR AGENCY	
Unable to determine (Insufficient information in GeoTracker)	SHELL GAS STATION	LOS ANGELES	<u>T0603760075</u>	900420152		- Site I	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	Z - Major Oil Company	No	Yes	No	No	No	No	Yes	Yes	None	3/31/1992	18		
Unable to determine (Insufficient information in GeoTracker)	KRATKA RIDGE SKI AREA	LA CANADA- FLINTRIDGE	<u>T0603700082</u>	907310307	Yue Kong	sment	I - Incomplete Assessment	RP - Non- Responsive RP	Solvent	U - Unknown	No	Unknown	No	Unknown	Unknown	Unknown	No	Yes	None	12/16/1992	18		
Unable to determine (Insufficient information in GeoTracker)	M C NOTTINGHAM	EL MONTE	<u>T0603772692</u>	R-13377	Ahmad J Open Lamma Refer		I - Incomplete Assessment	ND - No Data in GeoTracker	Other	S - Small Private Business	Unknown	Unknown	No	No	No	No	No	Yes	None	6/23/1993	17		
Unable to determine (Insufficient information in GeoTracker)	ARCADIA FIRE STATION #2	ARCADIA	<u>T0603703607</u>	I-10328	Nhan Bao Refer		I - Incomplete Assessment	ND - No Data in GeoTracker		G - Government Entity (include School, Hospital, Utility)	No	Unknown	No	Unknown	Unknown	No	Yes	Yes	None	1/4/1994	17		
Unable to determine (Insufficient information in GeoTracker)	SHELL PIPELINE COMPANY	SIGNAL HILL	<u>T0603703983</u>	I-12597	Ahmad J Open Lamma Refer		I - Incomplete Assessment	ND - No Data in GeoTracker	Solvent	Z - Major Oil Company	No	Yes	Yes	Unknown	Unknown	Unknown	Yes	Yes	None	6/17/1993	17		
Unable to determine (Insufficient information in GeoTracker)	RANCHO LOS AMIGOS HOSPITAL	DOWNEY	<u>T0603701265</u>	902420016	Noman Open Chowdhury Reme	10	O - Other	ND - No Data in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	No	Unknown	Yes	Unknown	Yes	Yes	No	Yes	None	9/20/1994	16		
Unable to determine (Insufficient information in GeoTracker)	PARAMOUNT ASSOCIATES	PARAMOUNT	<u>T0603704103</u>	I-13817	Ahmad J Open Lamma Asses		I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	No	Unknown	No	No	No	No	Yes	Yes	None	11/29/1993	16		
Unable to determine (Insufficient information in GeoTracker)	CIRCUS AUTO SALES	DOWNEY	<u>T0603704149</u>	I-14271	Ahmad J Open Lamma Refer		I - Incomplete Assessment	ND - No Data in GeoTracker	Solvent	S - Small Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	9/13/1994	16		
Unable to determine (Insufficient information in GeoTracker)	76 PRODUCTS STATION #3349	INGLEWOOD	<u>T0603704888</u>	R-09979	Jay Huang Open Refer		I - Incomplete Assessment	O - Other	Multiple	Z - Major Oil Company	Unknown	Unknown	Yes	Yes	Yes	No	Yes	Yes	Limited	1/4/1995	16		
Unable to determine (Insufficient information in GeoTracker)	SEALY MATTRESS CO	SOUTH GATE	<u>T0603704431</u>	I-16710	Joe F. Luera Reme	- 4	I - Incomplete Assessment	ND - No Data in GeoTracker	Diesel	S - Small Private Business	Unknown	Unknown	Yes	Unknown	Unknown	Unknown	Yes	Yes	None	6/14/1995	15		
Unable to determine (Insufficient information in GeoTracker)	EASTERN AUTO REPAIR	CITY TERRACE	<u>T0603704611</u>	R-03463	Maryam Open Taidy Asses		I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	Unknown	Unknown	No	No	No	No	Yes	Yes	None	3/20/1995	15		
Unable to determine (Insufficient information in GeoTracker)	LOST HILLS SHERIFF'S STATION	CALABASAS	<u>T0603704776</u>	R-08531	David Bjostad Refer	IN IN	I - Incomplete Assessment	U - Unknown	Solvent	G - Government Entity (include School, Hospital, Utility)	No	Unknown	Yes	No	Yes	No	Yes	Yes	Limited	6/13/1995	15		
Unable to determine (Insufficient information in GeoTracker)	ARROWHEAD MTN SPRING WATER CO	GARDENA	<u>T0603704649</u>	R-04646	Jav Huang	- Site I	I - Incomplete Assessment	ND - No Data in GeoTracker	Gasoline	S - Small Private Business	Unknown	Unknown	No	Unknown	Unknown	No	Yes	Yes	None	1/4/1995	15		
NOT FEDERAL UST CASE (SLIC)	MENASCO AEROSYSTEM DIVISION	BURBANK	<u>T0603702503</u>	109.0842	Larry Moore	- Site ssment	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	4/8/1988	22		
MIGHT NOT BE FEDERAL UST CASE	UCC/LINDE DIVISION	TORRANCE	<u>T0603701471</u>	905030134	Yue Rong	- Site I	I - Incomplete Assessment	RP - Non- Responsive RP	Other	S - Small Private Business	No	Unknown	No	No	No	No	No	Yes	None	12/18/1986	23		
MIGHT NOT BE FEDERAL UST CASE	MARINE HARDWARE CO (NOT UST CASE)	LONG BEACH	T0603701962	908130516	Jay Huang Open Reme	ediation	O - Other	ND - No Data in GeoTracker	Solvent	S - Small Private Business	No	Unknown	No	Unknown	Unknown	No	Yes	Yes	None	10/15/1990	19		
MIGHT NOT BE FEDERAL UST CASE	CHARNOCK WELLS (NOT UST CASE)	LOS ANGELES	<u>T0603701212</u>	900660143	WeiXing Tong Reme	ediation (O - Other	O - Other	Gasoline	U - Unknown	No	No	No	No	No	No	No	Yes	None	6/1/1995	15		





DUNN-EDWARDS PAINTS (T0603700979)

4885 52ND PL E, VERNON, CA 90040



Possible Reasons Why This Case Is So Old

- Lack of regulatory agency enforcement (Last Enforcement: Notice to Comply letter to RP on Sept 16, 2008)
- Lack of RP involvement
- Missing case files

Case Age: 26 years

RP Identified by Regulator: Andy Gillette

(Dunn Edwards Corporation)
Primary COC: Solvents
Media of Concern: Soil
Current Land Use: Industrial

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900400061 CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED

VERNON, CITY OF

CASEWORKER: LEWIS POZZEBON - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: SH	ow All Activities 💌 🖸	ão .
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
ENFORCEMENT/ORDERS	Staff Letter	3/29/1999	3/29/1999
LEAK ACTION	Leak Reported	11/18/1983	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700979

Assessment last 5 years

2005-2009: GWM

Remediation last 5 years

None

Assessment older than 5 years


• 3/6/2000 – Site Assessment

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603700979

as reported by regulatory agency



Review Conclusions T0603700979

- Review indicates:
 - Missing historical case information
 - Appears to have no/limited site assessment
 - Soil only case
 - On-going GW monitoring (2005-2009)
 - GWM conducted in September 2009 indicated <u>no chemical</u> contamination detected.
- Discussion:
 - Solvent case (paint facility Federal UST site?)
 - Consider closure → GWM results

Potential closure candidate

SHELL #204-6168-2245 (T0603704815) 1518 GAREY AVE N, POMONA, CA 91767



Possible Reasons Why This Case Is So Old

- Limited site activities at the beginning of case
- GW contamination
- Remediation began in 2003, SVE, P&T

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 21 years Primary COC: Diesel

RP Identified by Regulator: Shell Oil Prod US Potential Media Affected: Drinking water

supply Aquifer

Current Land Use: RADC Enterprises Inc/Shell

Gas Station Well Network: 18

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-26417
CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #. 009632-026417

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Soil and Water Investigation Report	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
ENFORCEMENT/ORDERS	Staff Letter	3/2/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - WORKPLANS	Other Workplan	10/15/2009

Activities Conducted to Date Based on GeoTracker Info T0603704815

Assessment last 5 years

- Ongoing: GW monitoring (18 wells)
- On- and offsite wells
- Remedial Action Plan
- Self monitoring

Assessment older than 5 years

- Fourteen soil borings
- 6 monitoring wells
- Site Conceptual Model

Remediation last 5 years

- Interim vacuum events
- SVE pilot study
- SVE system operation
- **GWE** system operation

- Fuel system removal
- Minor soil excavation

as reported by regulatory agency

518 GAREY AVE N DMONA, CA 91767 DS ANGELES COUNTY UST CLEANUP SITE				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RIVOCO (REGION 4) (LEAD) - CASE CASEWORKER: NOMAN CHOWDHURY LOS ANGELES COUNTY - CASE #. 009632-026417 CASEWORKER: JOHN AWUJO			
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE		CASE IS NOT READY	FOR CLOSURE AS C	NE 10/22/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
							VIEW ALL POSSIBLE CLOSURE REVIEW VALUE.
ON OWNER DESIGNATION							VIEW ALE POSSIBLE CLOSURE REVIEW VALUE
IMPEDIMENTS PLUME INSTA	TO CLOSURE BILITY	Complete - <i>A confirmatic</i>					YEW ALE POSSIBLE CLOSURE REVIEW VALUE.
PLUME INSTA • Verifical	TO CLOSURE BILITY						VIEW ALL PUSHBLE CLOSURE REVIEW VALUE
PLUME INSTA Verifical BENEFITS OF	TO CLOSURE BILITY ion Monitoring Not ADDITIONAL WORK	Complete - A confirmatic	on boring is necessary	leted to determine the effe	ectiveness of the remedial	system	YILWALL POSSIBLE CLOSURE, REVIEW VALUE
PLUME INSTA Verifical BENEFITS OF Verify Re	TO CLOSURE BILITY ion Monitoring Not ADDITIONAL WORK medial Action Effec	Complete - A confirmatic	on boring is necessary		ctiveness of the remedial	system	YILWALL POSSIBLE CLOSURE, REVIEW VALUE

Review Conclusions T0603704815

- Review indicates:
 - Site is currently an active gas station.
 - Active investigation and remediation efforts 2003-2009.
 - GeoTracker indicates RWQCB waiting for final monitoring verification and review of system effectiveness (both through a confirmation soil boring) as final tasks prior to considering case closure.
- Discussion:
 - Complete cleanup closure process, looks like closure could be completed soon.

Potential closure candidate

76 STATION #255973 (T10000000209)

20905 VENTURA BLVD, WOODLAND HILLS, CA 91364



Possible Reasons Why This Case Is So Old

- Appears to have limited activity between 1991 and 2008
- LA-RWQCB issued NFA in 1996 (case re-opened due to minor MtBE in soil, remains open)
- Closure again requested in 2010

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 20 years

RP Identified by Regulator: Conoco Phillips Co

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking

water

Current Land Use: Gas Station

Well Network: 4

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913670361A
CASEWORKER: DAVID M. BJOSTAD
LOS ANGELES, CITY OF - CASE #: 234420
CASEWORKER: TERRENCE PALMER



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report > Other	10/13/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - REPORTS	Well Installation Report	3/18/2009
RESPONSE - REPORTS	Status report	1/15/2009
RESPONSE - REPORTS	Other Report / Document	9/20/2008
ENFORCEMENT/ORDERS	Staff Letter	8/21/2008
LEAK ACTION	Leak Reported	1/15/1991
LEAK ACTION	Leak Discovery	1/14/1991

Activities Conducted to Date Based on GeoTracker Info T10000000209

Assessment last 5 years

- 2007 Five (5) soil borings were drilled
- 2008 Due Diligence and Sensitive Receptor Survey
- 2008 Subsurface investigation and advanced four (4) MWs

Assessment older than 5 years

 1991 – Eight (8) soil borings were drilled and five (5) GW MWs installed (abandoned in 1996 after NFA)

Remediation last 5 years


None

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T100000000209

as reported by regulatory agency



Review Conclusions T10000000209

- Review Indicates:
 - Initial site assessment led to NFA in 1996
 - Case transferred to new lead agency and reopened requesting GW evaluation
 - Soil and groundwater investigated recently completed
 - Case closure requested by RP in 2010
- Discussion
 - Site appears to meet low risk groundwater case
 - Closure timeline should be prepared, appears near completion.

Potential Closure Candidate

JAMISON PROPERTIES (T0603702493) 16501 Ventura Blvd, Encino, CA 91436



Case Age: 25 years
Primary COC: Gasoline

RP Identified by Regulator: Lee Hanley (Mobil

Oil Corp)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Commercial Complex **Well Network:** None listed in GeoTracker

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 914360225 CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Comingled plume /2 cases
- Limited reports/data from recent dates
- No historical site information in GeoTracker
- Appears to have limited/no oversight and RP involvement at the beginning of case
- Closure requested in 2008, no reply in GT

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Remedial Progress Report	1/15/2007
RESPONSE - REPORTS	Remedial Progress Report	3/16/2006

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702493

Assessment last 5 years

- Unsure if any investigation occurred on this property?
- See MOBIL #18-FRN
- Few reports in GeoTracker

Remediation last 5 years

- GWP&T from parking garage sump
 - Operated by adjacent site RP

Assessment older than 5 years


- Unsure if any investigation occurred on this property?
- See MOBIL #18-FYM
- Few reports in GeoTracker

Remediation older than 5 years

• Few reports in Geotracker

IMPEDIMENTS TO CLOSURE T0603702493

as reported by regulatory agency



Review Conclusions T0603702493

- Review indicates:
 - Site is associated with the adjacent site (Mobil 18-FRN: In CUF T0603702489) and the files are combined
 - No onsite wells to monitor remedial progress of Mobil's remediation (Pump & Treat) system effectiveness
 - No recent data or report in GeoTracker (last report dated 2008)
 - Comingled plumes?
 - Primary source appears as the adjacent former Mobil station
 - Site history unclear
 - 2008 case closure request → requested for ExxonMobil to be removed as RP for the HVOCs detected in the area
 - Results from 2008 seems to support closure consideration
 - Site has been redeveloped
- Discussion:
 - Cleanup closure consideration (pending recent sampling results)

Potential closure consideration

CHEVRON #9-2811 (T0603701981) 2601 BELLFLOWER BLVD, LONG BEACH, CA 90815



Possible Reasons Why This Case Is So Old

- Several releases, 1985 and 1999
- No active remediation
- Years of gap between oversight and RP involvement

Case Age: 24 years

RP Identified by Regulator: Chevron USA

Primary COC: Gasoline

Media of Concern: Aquifer Used for Drinking

Water Supply

Current Land Use: Gas Station

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908150052

CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	₩ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008
RESPONSE - REPORTS	Soil and Water Investigation Report	9/15/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2008
ENFORCEMENT/ORDERS	Staff Letter	7/1/2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701981

Assessment last 5 years

- On-going: GW monitoring (7 wells)
- 2005: Monitoring well installation

Remediation last 5 years

By 2006: 1,261.57-tons of soil removed

Assessment older than 5 years


- 1997: Site assessment (soil borings and installed GW wells)
- 1999: GW monitoring (URF)
- 2000: Site assessment (URF), Soil and water (well installation) investigation

Remediation older than 5 years

1999: Removed 650-cubic yards of impacted soil

IMPEDIMENTS TO CLOSURE T0603701981

as reported by regulatory agency



Review Conclusions T0603701981

- Review indicates:
 - Several releases occurred, 1985 and 1999
 - Only two wells with elevated concentrations (TPH, benzene)
 - Plume is not completely defined to west (residential) down gradient of source
 - Recent offsite well suggests migration may be limited
- Discussion:
 - Remaining source mass and GW trends
 - Indoor air risk to site workers
 - Consider closure if trends stabilize or decreasing
- Potential Closure Candidate

TOSCO – 76 STATION #3645 (T0603702417) 15410 VENTURA BLVD, SHERMAN OAKS, CA 91403



NOTE: Site is in the EAOP

Case Age: 24 years Primary COC: Gasoline

RP Identified: Tosco/76 Products Current Land Use: Gas Station

Potential Media Effected: Aquifer used for

drinking water supply Well Network: 10

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 914030025 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED LOS ANGELES CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
OTHER REGULATORY ACTIONS	Site Visit / Inspection / Sampling	6/24/2010	6/24/2010
RESPONSE - OTHER	Request for Closure	5/17/2010	5/17/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	4/15/2010	4/13/2010
RESPONSE - REPORTS	Soil and Water Investigation Report	2/11/2010	2/11/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/14/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	8/27/2009
ENFORCEMENT/ORDERS	Staff Letter	6/23/2009	6/23/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/15/2009
RESPONSE - OTHER	Request for Closure	3/20/2009	3/20/2009
DECOUNCE DEPONTS	Manifest Dennet Overheite	1/15/2000	1/16/2000

Possible Reasons Why This Case Is So Old

- Persistent groundwater contamination
- Multiple case closures requested (2006, 2009 and 2010) but were denied
- Effectiveness of remediation

NOTE: Data gueried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603702417)

Assessment last 5 years

- Ongoing: GW monitoring
- 2009-ongoing: NPDES
- 2010: Site assessment

Remediation last 5 years

- 2007: Interim remedial action
- 2005: H2O2 added to enhance remediation

Assessment older than 5 years

- 2003: Soil and water investigation
- 1992-ongoing: GW monitoring
- 1997: 2 GWM wells
- 1993: 17 soil borings
- 1986: 3 GWM wells installed

- 2003: SVE with Other, and DPE system
- 2002: Dual phase extraction
- 1997: Free product removal

IMPEDIMENTS TO CLOSURE (T0603702417)

as reported by regulatory agency

15410 VENTURA BLVD SHERMAN OAKS, CA 91403 LOS ANGELES COUNTY LUST CLEANUP SITE			CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE # CASEWORKER: MARYAM TAIDY LOS ANGELES, CITY OF CASEWORKER: eloy luna				
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community involvement	
CLOSURE	REVIEW - THIS			OF 1/21/2010			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
	SOURCE CONTROL Source Control Not	Performed - groundwate	r remediation not condu	cted			
BENEFITS OF	ADDITIONAL WORK						
• Remove	/ Reduce Source Ma	ass - "hot spot" cleanup re	quired to remediate sig	nificant concentrations of f	uel constituents in the gro	oundwater at well MW-11	
SENSITIVE RE	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAMI	FOR IMPACT				
SENSITIVE REC	EPTOR	TIME	FRAME FOR IMPACT		COMMENTS		

GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY: 10

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

Other - Repsonsible party submitted letter dated August 19, 2009 requesting to continue quarterly groundwater monitoring frequency due to WDR Permit Requirement

Review Conclusions T0603702417

- Review indicates:
 - Case closures requested by RP in 2006, 2009 and May 2010.
 - RWQCB denied 2006 closure and requested additional remedial action to mitigate GW.
 - 2010 Investigation suggests limited impacts near MW-11 → Site
 Assessment Report in Feb 2010 proposed installing 2 GWM wells to replace MW-11 which has become dry.
 - RWQCB's Closure Review indicates "GW remediation not conducted" and "hot spot cleanup required at MW-11."
- Discussion:
 - Review closure request submitted in May 2010 (not in GeoTracker)
 - Site is an active service station (benefits of additional remediation)
 - Cleanup closure timeline should be evaluated in SCM

Potential Closure Candidate within 1 year

MOBIL #18-HYQ (T0603700474) 958 ALVARADO ST S, LOS ANGELES, CA 90006



NOTE: Site is in EAOP

Case Age: 22 years
Primary COC: Gasoline

RP Identified by Regulator: Felicia Jones

(Exxon Mobil Oil Corp)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Mobil Services

Well Network: 20

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900060052


CASEWORKER: <u>DANIEL PIROTTON</u> - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears to have lag in oversight at beginning of the case
- GW contamination still above clean-up goals
- Remediation began recently -- SVE is still ongoing

NOTE: Data queried from GeoTracker and reviewed in August 2010





Activities Conducted to Date Based on GeoTracker Info T0603700474

Assessment last 5 years

- Semi-annual GWM
- Well installation
- Feasibility study
- Few investigation reports in GeoTracker

Remediation last 5 years

- Dual phase extraction
- Soil vapor extraction
 - Current approach
- Few remediation reports in GeoTracker


Assessment older than 5 years

- Initial subsurface investigation
- Well installation
- DPE/SVE pilot tests
- Few investigation reports in GeoTracker

- None
- Few remediation reports in GeoTracker

IMPEDIMENTS TO CLOSURE T0603700474

as reported by regulatory agency



Review Conclusions T0603700474

- Review indicates:
 - Few investigation reports in GeoTracker
 - Site is currently an active gas station
 - RP reportedly plans to advance confirmation borings followed by submitting a case closure request in 2010
 - Ongoing SVE → not yet asymptotic
- Discussion:
 - Cleanup closure timeline

Potential closure candidate pending remediation results, possible closure within 1 year

LAC/USC MEDICAL CENTER (T0603700846) 1200 STATE ST N, LOS ANGELES, CA 90033



Case Age: 22 years
Primary COC: Gasoline

RP Identified by Regulator: John Kelley

(LAC/USC Medical Center)

Potential Media Affected: Aguifer used for

drinking water supply

Current Land Use: Commercial Center

Well Network: 3 wells NOTE: No street view

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900330270

CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Multiple USTs removal and releases over different periods
- No remediation conducted?
- No assessment documents
- Government entity site, lack of funding?

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700846

Assessment last 5 years

- Ongoing: GW monitoring (3 wells)
- No reports entered for 2010

Remediation last 5 years

None


Assessment older than 5 years

- 2003: Soil and Water investigation
- 2001: Subsurface investigation (URF)
- 2001-ongoing: GW monitoring

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603700846

- Review indicates:
 - Limited reports/documents available in GeoTracker (only GW monitoring reports) to review to provide complete assessment.
 - 2005: Request for closure for Site 5 citing the site has 2 separate hydrocarbon plumes that are not commingled.
 - Site is in an area of "non-water bearing" rocks (no or limited GW present).
 - GW Report (April 2009) indicated no free product present, no MTBE detected in Site 4, and overall decreased in TPH-g (below detection limit) and BTEX.
 - Last Activity in GeoTracker dated 2009.
 - Site is a medical center.
- Discussion:
 - Review recent GWM results and trend need for remediation?
 - Consider closure and/or closure timeline

Potential closure candidate (pending recent GWM trend) within 1 year

GAVIOTA HEIGHTS (T0603701963)

1200 GAVIOTA AVE, LONG BEACH, CA 90813



Possible Reasons Why This Case Is So Old

- Appears to lack oversight and RP involvement
- Site investigation began in 2010

Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Zoltan Katinszky

(Classic Property Management)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Residential

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130516
CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED
LONG BEACH/SIGNAL HILL, CITIES OF
CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	5/15/2009
ENFORCEMENT/ORDERS	Staff Letter	3/10/2009
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	12/15/2008
ENFORCEMENT/ORDERS	Staff Letter	10/29/2008
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
ENFORCEMENT/ORDERS	Staff Letter	12/5/2001
ENFORCEMENT/ORDERS	Staff Letter	7/9/2001
LEAK ACTION	Leak Reported	6/14/1989



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

T0603701963 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

 2007, 2008, 2009 and 2010: Limited Soil and groundwater investigations

Remediation last 5 years

None


Assessment older than 5 years

 Some assessment performed when tanks removed in 1989

Remediation older than 5 years

Excavation during tank removal in 1989

IMPEDIMENTS TO CLOSURE T0603701963 as reported by regulatory agency



Review Conclusions T0603701963

- Review indicates:
 - Limited reports/documents available in GeoTracker.
 - Site is currently residential.
 - Limited Site assessment in February 2010 showed ND soil sample results, Groundwater sample results were: TPH-g 7,000-μg/L, toluene 20.9-μg/L, ethylbenzene 708-μg/L and xylenes at 1,078-μg/L respectively. Benzene was non detectable.
 - No Further Action/Closure Recommended by consultant (no record of reply by agency, over 5 months later).

Discussion:

- Agency should respond to closure recommendation
- Need for additional sampling/assessment?
- Potential Closure Candidate? Will agency require additional data? Is there a need for indoor air evaluation?

FORMER TEXACO (T0603702372)

22401 VENTURA BLVD, WOODLAND HILLS, CA 91367



Possible Reasons Why This Case Is So Old

- Several high concentration up-gradient sources
- Onsite benzene and TBA elevated in GW; source(s) unclear
- Site surrounded by active gas stations
- Closure requested March, 2010, no record of response (4 months ago)

NOTE: Data gueried from GeoTracker and reviewed in August 2010

Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Y. M. Tuan (Chevron) **Potential Media Affected:** Drinking water aquifer

Current Land Use: Commercial Center

Well Network: 10

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913640452 CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	ihow All Activities 🔻 Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - OTHER	Request for Closure	3/18/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Remedial Progress Report	9/29/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009
ENFORCEMENT/ORDERS	StaffLetter	6/15/2009



Activities Conducted to Date Based on GeoTracker Info T0603702372

Assessment last 5 years

- Semi-annual GWM
- Additional well installation
- Soil borings 2009

Remediation last 5 years

- MNA is current approach
- No remediation reports in GeoTracker


Assessment older than 5 years

 Apparent initial investigation and monitoring well installations

- UST system removal
- Soil excavation
- No remediation reports in GeoTracker

IMPEDIMENTS TO CLOSURE T0603702372

as reported by regulatory agency



Review Conclusions T0603702372

- Review indicates:
 - Several up- to cross-gradient sites with an order of magnitude higher groundwater concentrations – some of which recently reopened due to increasing concentrations.
 - Site has been redeveloped and is surrounded by residential properties on the north, and active gas stations southeast, southwest and northeast corners of intersection.
 - A 2005 closure request was submitted and denied. Another request for closure was submitted on March 2010, no reply noted in GeoTracker.
 - Available info in GeoTracker strongly suggests that:
 - A) onsite groundwater concentrations do not equate to onsite soil concentrations as the primary source
 - B) a comingled plume(s) possibly exists with offsite source(s) responsible for elevated concentrations observed onsite
- Discussion:
 - Review March 2010 Assessment Report/Closure Request to evaluate closure eligibility
 - Consider combining groundwater monitoring with other offsite RPs, and gaps identified so that adequate trend analysis can be performed

Potential closure consideration pending GW results, closure within 1 year potential

MOBIL #18-FYM (FORMER #11-FYM) (T0603701166) 10863 OLYMPIC BLVD, RANCHO PARK, CA 90064



Case Age: 20 years
Primary COC: Gasoline

RP Identified by Regulator: Lee Hanley

(Exxon Mobil Oil Corp)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Mobil Station

Well Network: 9

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900640070

CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES OFFICE - SUPERVISOR: NONE SPECIFIED

CASEWORKER: elov luna - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Former NAPL site
- Elevated benzene in GW

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go		
ACTION TYPE	ACTION	-	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1000	7/15/2010	7/13/2010
RESPONSE - REPORTS	Remedial Progress Report		7/15/2010	7/13/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly		4/15/2010	4/19/2010
RESPONSE - REPORTS	Soil and Water Investigation Report		3/1/2010	3/1/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually		1/15/2010	12/2/2009
RESPONSE - OTHER	Other Report / Document		10/1/2009	10/1/2009

NOTE: Data gueried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701166

Assessment last 5 years

- Qtrly GWM
- Additional subsurface investigation
- Well installation

Remediation last 5 years

- Active SVE (now shut down in 2009 due to asymptotic results)
- MNA current approach

Assessment older than 5 years

- Site conceptual model
- RAP/CAP-feasibility study
- Well installation
- Initial subsurface investigation

- Active dual-phase extraction
- Active SVE

IMPEDIMENTS TO CLOSURE T0603701166

as reported by regulatory agency

MOBIL #18-FYM (FORMER #11-FYM) (T0603701166) - (MAP) 10863 OLYMPIC BLVD RANCHO PARK, CA 90064 LOS ANGELES COUNTY LUST CLEANUP SITE				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: 90064007 CASEWORKER: MERCEDES HSU LOS ANGELES, CITY OF CASEWORKER: gloy lung			
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE		CASE IS NOT READY	FOR CLOSURE AS C	DF 9/3/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
• Groundw		ve Other Cleanup Goal - E	levated Benzene				
BENEFITS OF	ADDITIONAL WORK						
 Verify Re 	emedial Action Effec	ctiveness - MNA					
SENSITIVE REC	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAMI	E FOR IMPACT				
SENSITIVE REC			TIME FRAME FOR IMPA	σ		COMMENTS Elevated Benzene	
							J

Review Conclusions T0603701166

- Review indicates:
 - Site is currently an active gas station
 - Site is a former NAPL site, i.e. source to groundwater reduced but not stopped
 - Active remediation recently reached asymptotic state, currently in MNA
- Discussion:
 - Post-remediation effectiveness monitoring
 - Cleanup closure timeline should be discussed

Potential Closure Candidate or closure within 1 year

SANTA MONICA MUNICIPAL BUS LINES MAINTENANCE FACILITY (T0603701364)

1620 6TH ST, SANTA MONICA, CA 90401



Possible Reasons Why This Case Is So Old

- No reports/documents in GeoTracker
- Appears to have had long gaps in oversight and RP involvement
- Site might have been redeveloped or is in redeveloping process
- Closure requested and denied

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 20 years
Primary COC: Diesel

RP Identified by Regulator: Dean Kubani (City

of Santa Monica)

Potential Media Affected: Aguifer used for

drinking water supply

Current Land Use: Commercial Building

Wells Network: 28

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. 904010043
CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED
SANTA MONICA, CITY OF
CASEWORKER: RICHARD H. BERMAN - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Well Destruction Report	10/1/2009	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/23/2009	6/23/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/29/2009



Activities Conducted to Date Based on GeoTracker Info T0603701364

Assessment last 5 years

 Ongoing: GW monitoring (28 wells)

Remediation last 5 years

 Remedial action (unsure of the details)

Assessment older than 5 years

- 2001: Soil and water investigation
- 2002-ongoing: GW monitoring

Remediation older than 5 years

- 1997: Remove free product (URF)
- 1999: Groundwater extraction system (according to a letter)
- 2001: Vacuum extraction (URF)

NOTE: Approximately 154-gal free product removed

as reported by regulatory agency

SANTA MO	NICA MUNICIPA	L BUS LINES MAINTE	ENANCE FACIL (T06	03701364) - <u>(MAP)</u>		
1620 006TH S SANTA MONI OS ANGELE LUST CLEAN	CA, CA 90401 S COUNTY			ū	LEANUP OVERSIGHT AGENCIE OS ANGELES RWQCB (REGION CASEWORKER: <u>JAY HUANG</u> ANTA MONICA, CITY OF CASEWORKER: <u>RICHARD H.</u>	14) (LEAD) - CASE #: 904010043
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement
Remaining BENEFITS OF	SOURCE CONTROL ng Source Poses Th ADDITIONAL WORK	reat to Groundwater - fre				
SENSITIVE RE	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAME	FOR IMPACT			
Groundwate		-	IME FRAME FOR IMPACT Already Impacted		COMMENTS since 1997	

Review Conclusions T0603701364

- Review indicates:
 - No reports/documents available in GeoTracker.
 - As of 2009, site has pending site development.
 - On November 2009, closure was requested, but LA-RWQCB rejected closure due to the presence of a sheen of free product (0.03-inch in thickness) in MW-28B.
- Discussion:
 - RP and GeoTracker compliance are issues needing address
 - Case appears close to completion (closure) upon remediation of MW-28B (site redeveloping)

Potential closure candidate

TOSCO – 76 STATION #5195 (FORMER) (T0603703719) 16205 LEFFINGWELL RD E, WHITTIER, CA 90603



Case Age: 20 years **Primary COC:** Gasoline

RP Identified by Regulator: Andrea Wing

(Shell Oil Products US)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Church Parking Lot

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-11042

CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



Possible Reason Why This Case Is So Old

- GW contamination
- Appeared to lack oversight and RP involvement at the beginning of the case
- Site has been redeveloped?

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities Go	
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
RESPONSE - WORKPLANS	Interim Remedial Action Plan	7/15/2009
RESPONSE - WORKPLANS	<u>Corrective Action Plan / Remedial Action Plan - Addendum</u>	7/1/2009

NOTE: Data gueried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603703719

Assessment last 5 years

- Semi-annual GWM
- Additional well installation
- CAP/RAP-addendum

Remediation last 5 years

- Ozone injection
 - Recently changed to oxygen injection
- Dual phase extraction

Assessment older than 5 years

- System replacement
- Initial subsurface investigation
- On- and offsite wells installation
- Air-sparge well installation
- System removal
- CAP/RAP-Feasibility study

- SVE/AS pilot test
- Soil excavation
- Ozone injection

as reported by regulatory agency

TOSCO) - 76 STA	TION #5195 (I	FORMER) (T	0603703719) - ((MAP)		
16205 LEFFINGWELL RD E WHITTIER, CA 90603 LOS ANGELES COUNTY LUST CLEANUP SITE				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RIVOCB (REGION 4) (LEAD) - CASE #: I-110- CASEWORKER: NOMAN CHOWDHURY LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO			
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Invalvement	
							VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
GROUNDWAT Groundw		ve Other Cleanup Goal - E	Elevated levels of HC in (SW			
BENEFITS OF	ADDITIONAL WORK			Salvania de la compania de la compa			
• Other - 0	Continue operation	of ozone sparge system, I	DPE and quarterly monit	oring & sampling			
SENSITIVE RE	CEPTORS LIKELY TO E	BE IMPACTED AND TIME FRAME	E FOR IMPACT				
SENSITIVE REC				ME FOR IMPACT		-	OMMENTS HC in GW

Review Conclusions T0603703719

- Review indicates:
 - Site has ongoing active remediation → oxygen injection combined with DPE
 - RP plans to submit closure request in 2011 → based on conclusion of update RAP to be prepared in 2010
 - NPDES/WDR reports in GeoTracker
 - Site appears to have been redeveloped (gas station to church)?
- Discussion:
 - Review recent remediation sapling results and trend
 - Cleanup closure timeline

Potential closure candidate in 1 year

BARRY J.NIDOR JUVENILE HALL (T0603702268) 16351 FILBERT ST, SYLMAR, CA 91342



Case Age: 18 years **Primary COC:** Diesel

RP Identified by Regulator: Juan Peinado (LA County Probation) - Unclaimed in GeoTracker Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Distribution Building

Wells Network: 3

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913421561 CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- No reports/documents in GeoTracker
- Limited assessment performed
- Limited oversight and RP involvement
- Free product in GW
- Government Entity Site?

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009
RESPONSE - REPORTS	Well Installation Report	8/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/30/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
RESPONSE - REPORTS	Investigation Progress Report	10/15/2007
ENFORCEMENT/ORDERS	Staff Letter	7/20/2007
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	4/15/2006
RESPONSE - REPORTS	Monitoring Report - Quarterly	*10/15/2007
ENFORCEMENT/ORDERS	Staff Letter	2/14/2006
RESPONSE - REPORTS	Additional Information Report	8/15/2002
ENFORCEMENT/ORDERS	Staff Letter	7/10/2002
LEAK ACTION	Leak Reported	3/20/1992

Activities Conducted to Date Based on GeoTracker Info

T0603702268 (NOTE: Based on "Activities Report" and letters in GeoTracker)

Assessment last 5 years

- 2007: Investigation progress report
- 2009: GW monitoring (3 wells)

Remediation last 5 years

None


Assessment older than 5 years

1992: 7 soil borings drilled and 3 converted to MW wells

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603702268 as reported by regulatory agency



Review Conclusions T0603702268

Other - The groundwater has been monitored only twice since 2000. Free product has been detected. More data are needed to characterize the groundwater condition and closure considerations

Review indicates:

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

- No reports/documents/letters available in GeoTracker.
- Activities Report in GeoTracker indicates multiple activities (Investigation and Monitoring etc) between 2002 and 2010.
- In 1992, case was transferred from LAFD to LA-RWQCB.
- Regulators have sent the following letters: (1) Notice of Non-Compliance (Sept 2008), (2) Delinquent Notice (June 2009), and (3) IRAP Requirement (June 2010)
- Regulator letter (June 2010) indicates "prior to consideration of case closure, at least one round of GW monitoring must be conducted...."
- Discussion:
 - RP and GeoTracker compliance → recent reports and results
 - Cleanup closure timeline, is this case near closure within 1 year?

Potential closure candidate

76 STATION #254488 (T10000000494)

20105 Vanowen St, Canoga Park, CA 91306



NOTE: Site is in EAOP

Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Shari London

(Conoco Phillips Co)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Gas Station

Well Network: 5

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913060225A

CASEWORKER: DAVID M. BJOSTAD - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why Is This Case So Old

- Little activity between 1991 and 2008
- NFA by two different agencies in 1996 and 2000, respectively, insufficient oversight
- Site characterization incomplete
- No active remediation

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities ▼ Go ACTION TYPE **ACTION DATE** RESPONSE - REPORTS Monitoring Report - Other 10/15/2009 RESPONSE - REPORTS Monitoring Report - Semi-Annually 7/15/2009 ENFORCEMENT/ORDERS Staff Letter 6/15/2009 RESPONSE - REPORTS Well Installation Report 4/17/2009 RESPONSE - REPORTS Monitoring Report - Quarterly 4/15/2009 RESPONSE - REPORTS Other Report / Document 1/16/2009 RESPONSE - REPORTS 12/20/2008 Other Report / Document ENFORCEMENT/ORDERS Staff Letter 11/21/2008 LEAK ACTION 12/10/1991 Leak Discovery LEAK ACTION Leak Reported 12/10/1991

Activities Conducted to Date Based on GeoTracker Info T10000000494

Assessment last 5 years

- 2007: Seven (7) soil borings
- 2008: Due Diligence
- 2009: Installed five (5) GW MWs

Remediation last 5 years

None


Assessment older than 5 years

 Three (3) GW monitoring wells installed in 1991 and abandoned by 1997 (after LARWQCB determined NFA)

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T10000000494

- Review Indicates:
 - Insufficient oversight led to two separate NFAs being issued
 - Case reopened and initial assessment including installation of monitoring wells recently completed
 - Site requires at least one round of GW monitoring to evaluate conditions
 - RP requested for "Low Risk Case Closure" (March 2010)
 - Site is an active gas station and in EAOP
- Discussion:
 - Closure timeline and approach (remediation or MNA)
 - Evaluate GWM trend

Potential Closure Consideration

CONOCO INC (T0603704152)

1198 WASHINGTON PL, CULVER CITY, CA 90232



Case Age: 18 years Primary COC: Gasoline

RP Identified by Regulator: Mark Aebi

(Conoco Phillips Inc)

Potential Media Affected: Well used for

drinking water supply

Current Land Use: Automotive Service

CLEANUP OVERSIGHT AGENCIES

OS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-14314 CASEWORKER: WEIXING TONG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Part of the Charnock Well Field
- GW contamination MTBE and TBA
- Site might have been redeveloped
- Limited data in GeoTracker

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704152 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

- 2005: Soil and water investigation
- Ongoing: GW monitoring (10 wells quarterly and 4 wells semi-annually)

Assessment older than 5 years


2002-ongoing: GW monitoring

Remediation last 5 years

Ongoing: Remedial (SVE)

- 2001: Excavate and dispose
- 2002: SVE

IMPEDIMENTS TO CLOSURE T0603704152 as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY: 10, SEMI-ANNUALLY: 4

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

- Well Being Sampled During Remedial Action for Progress Assessment SVE system is operating at the site
- Other The site is within Charnock Well Field Investigation area

Review Conclusions T0603704152

- Review indicates:
 - Only one GWM Report (January 2010) available in GeoTracker
 → recommended closure consideration.
 - "Activities Report" in GeoTracker showed multiple activities conducted between 2002 and 2009.
 - Site is part of the Charnock well field.
 - Closure Review indicates "SVE system is operating at the site" and "MTBE and TBA in GW."
- Discussion:
 - RP GeoTracker compliance, need more reports uploaded
 - Consider closure based on recent data

Potential closure consideration

MOBIL #18-E67 (FORMER #11-E67) (T0603704511) 1024 BREA CANYON RD S, DIAMOND BAR, CA 91789



Possible Reasons Why This Case Is So Old

- High TBA concentrations in GW
- Ongoing remediation of oxygenates
- Appears to have years of gaps in site activities

NOTE: Case is in EAOP Case Age: 18 years Primary COC: Gasoline

RP Identified by Regulator: Johnny Medrano

(Exxon Mobil Oil Corp)

Potential Media Affected: Drinking water supply

aquifer

Current Land Use: Sam's Mobil

Well Network: 18

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-00090

CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	10/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704511

Assessment last 5 years

- Semi-annual GWM
- Apparent missing reports?

Remediation last 5 years


- Oxygen emitters
- Apparent missing reports?

Assessment older than 5 years

- Initial investigation
- Well installation
- Interim RAP
- Apparent missing reports?

- Replace UST system
- Soil excavation
- Dual phase extraction
- Apparent missing reports?

IMPEDIMENTS TO CLOSURE T0603704511 as reported by regulatory agency



Review Conclusions T0603704511

- Review indicates:
 - Site is currently an active gas station.
 - Few documents available in GeoTracker for review (mostly GWM Report)
 - Residual TBA main COC according to GeoTracker.
 - Current strategy appears as MNA post DPE → oxygen emitters still in use.
 - Based on Oct 2009 GWM Report:
 - Benzene concentrations have been below lab reporting limits,
 - MTBE concentration decreased to below lab reporting limits in most wells,
 - TBA have decreased throughout the central and western portions of the site (and over the last 3-years), and TBA concentrations have fluctuated at the northeastern portion between 2006 and 2009"
- Discussion:
 - Closure consideration based on GWM trend, could be closable within 1 year.

Potential closure consideration

TOSCO – 76 STATION #3900 (T0603700641) 4000 6TH ST W, LOS ANGELES, CA 90020



Case Age: 17 years

Primary COC: Gasoline/Waste oil

RP Identified by Regulator: Ms. Shari London

(Conoco Philips Company)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Unocal Dealers Services

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900200143

CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Former NAPL site
- No active remediation has been implemented, only passive skimmers
- GW contamination above cleanup goals

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show	All Activities 💌	Go
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/12/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	1/20/2010
RESPONSE - REPORTS	Monitoring Report - Other	10/12/2009	10/12/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/3/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/6/2009



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700641

Assessment last 5 years

- Semi-annual GWM
- Site conceptual model
- Monitoring frequency reduction requested
- No investigation reports in GeoTracker

Assessment older than 5 years

- Initial subsurface investigation
- Well installations
- Interim RAP
- CAP/RAP-Feasibility study
- No investigation reports in GeoTracker

Remediation last 5 years


- SVE/AS pilot test
- No investigation reports in GeoTracker

- UST system up grade
- Passive skimmer to recover NAPL
 - Changed to automated belt skimmer
- No investigation reports in GeoTracker

DRAFT: SEPT 3, 2010

IMPEDIMENTS TO CLOSURE T0603700641

as reported by regulatory agency



Review Conclusions T0603700641

- Review indicates:
 - No investigation reports uploaded in GeoTracker
 - Site has gasoline and waste-oil releases
 - Site is currently an active gas station
 - RP has requested monitoring frequency reduction citing "...site near closure"
 - COC concentrations are low based on 2009 GWM rpt
 - Former NAPL site:
 - Ongoing source to groundwater possible
 - No active remediation has been implemented
- Discussion:
 - Recent sampling results/propose remediation
 - Closure referenced in correspondence from consultant, is it likely?

Potential closure candidate

CHEVRON #9-8701 (T0603701638) 106 GAFFEY ST S, SAN PEDRO, CA 90731



Case Age: 17 years Primary COC: Gasoline

RP Identified by Regulator: Chevron USA Potential Media Affected: Aguifer used for

drinking water supply

Current Land Use: Gas Station

Well Network: 8

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 907310325

CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Several sources over time
- Multiple investigations
- Lack of active remediation
- MNA current approach

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	4/5/2010
RESPONSE - REPORTS	Remedial Progress Report	8/17/2009	8/17/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	6/10/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	2/26/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009	12/2/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008	9/5/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2008	6/10/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2008	3/10/2008
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	1/15/2008	

Activities Conducted to Date Based on GeoTracker Info T0603701638

Assessment last 5 years

Ongoing: GW monitoring (8 wells)

Remediation last 5 years

None


Assessment older than 5 years

- 1998, 2000: Additional GW wells
- 1997-ongoing: GW monitoring
- 1996: GW borings and soil samples
- 1992: 12 hand auger soil borings

Remediation older than 5 years

1995: Excavate (until 9 ft bgs) and dispose (399 tons)

IMPEDIMENTS TO CLOSURE τ0603701638 as reported by regulatory agency



OF WELLS MONITORED - SEMI-ANNUALLY: 8

Review Conclusions T0603701638

- Review indicates:
 - Within the immediate site vicinity, three properties (two up-gradient, Unocal and Texaco, and one down-gradient, World Oil) were open and/or closed environmental cases with RWQCB.
 - GW monitoring in 2009 showed stable detection levels for benzene and MTBE in most wells.
 - RP requested case closure in 2005 on grounds that:
 - 1) no active production wells used for drinking water purposes located near the site
 - 2) MTBE only detected in GW and not in soil samples
 - 3) low detections of petroleum HCs in soil and GW
 - 4) 1995 remedial excavation have removed the source
- Discussion:
 - Case appears to meet or almost meet low risk groundwater criteria.
 - Identify final data gaps to meet closure.
- Potential Closure Candidate

CUDDLY TOYS MFG (T0603704442) 1835 EASTERN AVE N, LOS ANGELES, CA 90032



Possible Reasons Why This Case Is So Old

- Lack of oversight and RP involvement
- Unknown current site condition report indicated that RP requested closure in 2001 due to low or ND concentrations.
- No response/activities from RB since 2008, when they sent notice of non compliance.

Case Age: 18 years Primary COC: Diesel

RP Identified by Regulator: Leo Ramdwar

(Cuddly Toys MFG)

Potential Media Affected: Aguifer used for

drinking water supply Current Land Use: Industrial

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. I-17062

CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COLINEY. LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
LEAK ACTION	Leak Reported	10/21/1992
LEAK ACTION	Leak Discovery	9/11/1992

NOTE: Data gueried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704442

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

2000: GW monitoring (3 wells)

Remediation older than 5 years

None

as reported by regulatory agency

CUDDL	Y TOYS N	IFG (T060370	4442) - <u>(MA</u> F	2)			
LOS ANGE LOS ANGE	ERN AVE N (LES, CA 90032 LES COUNTY ANUP SITE	2					QCB (REGION 4) <i>(LEAD) - CASE #. I-17062</i> <i>: MAGDY BAIADY</i> JNTY
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE		CASE IS NOT READY	FOR CLOSURE AS O	OF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
SITE ASSESSE	MENT INCOMPLETE	Model (CSM) - informatio	n needed				
BENEFITS OF	ADDITIONAL WORK						
Fill-in RI	Data Gaps - <i>inform</i>	ation needed					
SENSITIVE RE	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAMI	FOR IMPACT				
Groundwate			TIME FRAME FO Undetermine			COMMENTS Info. need	ed

Review Conclusions T0603704442

- Review indicates:
 - Limited reports/documents available in GeoTracker.
 - In 2001, RP requested LA-RWQCB to consider case closure on grounds of ND for MTBE and low detections of TPH and benzene.
 - LA-RWQCB sent RP letters (1) Notice of Non-Compliance (Sept 2008) and (2) Reduction of GWM frequency (June 2009).
 - Activities Report indicates Monitoring Report (2009).
 - Closure Review indicates "Incomplete CSM information needed."
- Discussion:
 - Review recent site monitoring information
 - Consider possible case closure

Potential closure candidate

TERMINAL ISLAND PRISON (T060370027)

1299 SEASIDE AVE, TERMINAL ISLAND, CA 90731



Address: 1299 S. Seaside Ave, San Pedro, CA 90731

Case Age: 15 years
Primary COC: Diesel

RP Identified: David Moore (Fed. Bureau of Prisons) **Potential Media Effected:** Aguifer used for drinking

water supply

Current Land Use: Federal Correctional Institute

Well Network: 3 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 907310307

CASEWORKER: JIMMIE WOO - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Possible gaps in oversight and RP involvement.
- Site might still have free product in GW.
- Appears that extent of GW contamination remains undetermined – undefined plume.
- Case appears to be transferred between agencies.

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	₹ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Soil and Water Investigation Report	1/15/2010	
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	3/30/2010
ENFORCEMENT/ORDERS	Staff Letter	10/23/2009	10/23/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	2/15/2007	6/1/2009
ENFORCEMENT/ORDERS	Staff Letter	12/18/2006	12/18/2006
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2004	11/30/2004
RESPONSE - OTHER	Well Destruction Report	*11/15/2003	12/29/2003

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T060370027)

Assessment last 5 years

- Ongoing: GW monitoring
- 2007, 2010: Soil and Water investigation

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years

- 2002-ongoing: GW monitoring
- 2002, 2003: Soil and Water investigation
- 2001: Site assessment
- 1995: Investigation during tank removal

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (TO60370027)

as reported by regulatory agency



Review Conclusions T060370027

- Review indicates:
 - The site is in the process of site characterization and GW assessment report due early 2010 (it is now August 2010).
 - Limited reports/documents available in GeoTracker.
 - Site appears it can be considered for closure in the near future (see GW results below from 2009 Semi-Annual GW Monitoring Report).

Monitoring Well Number	Date	Gasoline-Range Organics (C ₂ - C ₁₂)	Diesel-Range Organics (C ₁₃ - C ₂₂)	Oil-Range Organics (C ₂₃ - C ₄₀)	Extractable Fuel Hydrocarbons (C ₁₃ - C ₄₀)
Uni	ts	μg/L	mg/L	mg/L	mg/L
MW-3	11/12/2009	260	72	< 48	95
MW-4	11/12/2009	< 50	< 0.50	< 0.50	< 0.50
MW-4	11/12/2009	< 50	< 0.50	< 0.50	< 0.50
MW-5	11/12/2009	< 50	< 0.50	< 0.50	< 0.50

Monitoring Well Number	Date	Naphthalene	Benzene	Toluene	Ethylbenzene	Xylene	MTBE	DIPE	ETBE	TAME	TBA	Ethanol
MW-3	11/12/2009	9.5	< 0.50	< 0.50	< 0.50	< 1.0	< 1.0	< 5.0	< 5.0	< 5.0	< 10	< 150
MW-4	11/12/2009	< 1.0	< 0.50	< 0.50	< 0.50	< 1.0	< 1.0	< 5.0	< 5.0	< 5.0	< 10	< 150
MW-4	11/12/2009	< 1.0	< 0.50	< 0.50	< 0.50	< 1.0	< 1.0	< 5.0	< 5.0	< 5.0	< 10	< 150
MW-5	11/12/2009	< 1.0	< 0.50	< 0.50	< 0.50	< 1.0	< 1.0	< 5.0	< 5.0	< 5.0	< 10	< 150

- Discussion:
 - Closure consideration

Potential closure candidate

76 STATION #254359 (T0603704998)

10208 Lakewood Blvd S. Downey, CA 90241



Possible Reasons Why This Case Is So Old

- Little work conducted between 1995 and 2007 (12 years)
- Recalcitrant RP
- Transferred between agencies referred to RWQCB in 2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 15 years
Primary COC: Gasoline

RP Identified: ConocoPhillips Co.

Potential Media Affected: Drinking Water

Supply Aquifer

Current Land Use: Active Service Station

Well Network: 7 wells

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-11008
CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 11021-11008
CASEWORKER: RANI V. IYER - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activit	es 💌 Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Manitoring Report - Semi-Annually	7/15/2010	7/12/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/14/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/13/2009
RESPONSE - OTHER	Request for Closure	9/25/2009	9/25/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/16/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/14/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009	1/16/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008	10/15/2008
RESPONSE - OTHER	Other Report / Document	10/15/2008	10/9/2008
ENFORCEMENT/ORDERS	Staff Letter	8/1/2008	8/1/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2008	7/15/2008
LEAK ACTION	Leak Stopped	7/27/1995	
LEAK ACTION	Leak Discovery	7/27/1995	
LEAK ACTION	Leak Reported	7/27/1995	

Activities Conducted to Date Based on GeoTracker Info T0603704998

Assessment last 5 years

- Multiple phases of soil borings/wells
- Sensitive Receptor Survey

Remediation last 5 years


None

Assessment older than 5 years

- Post over-excavation, confirmation samples indicated impacted soil "effectively" removed
- Case closure request by consultant

- UST System removal (gasoline and waste oil); compliance samples contained elevated concentrations
- Soil over-excavation and disposal

as reported by regulatory agency



Review Conclusions T0603704998

- Review indicates:
 - UST system replaced → site is currently an active gas station
 - Soil over-excavation primary remedial approach
 - Multiple phases of borings and well installation
 - Impacts to soil and groundwater adequately characterized
 - Concentrations in GW appears to have been significantly reduced over time
 - No threatened sensitive receptors
 - RP requested closure in 2009 → appears to meet low risk groundwater criteria for closure
- Discussion:
 - 2009 Case Closure Request submitted, did not see reply by RWQCB
 - Cleanup closure timeline needed, could be closable within 1 year?

Potential closure candidate

VIRCO MANUFACTURING CORP. (T0603728230) 15134 S. Vermont Ave., Los Angeles, CA 90247



Possible Reasons Why This Case Is So Old

- Case managed under UST and SLIC RWQCB programs
- Case is combined with adjacent property
- Case involves multiple source areas and chemicals of potential concern
- 2008 agency letter for non-compliance with GeoTracker requirements
- Closure requested, no record of reply

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 18 years (leak is 45 years old)
Primary COC: VOCs (chlorinated solvents)
RP Identified: APA III, Ltd. c/o Real Property

Resources, Inc.

Potential Media Affected: Drinking Water

Supply Aquifer

Current Land Use: Former manufacturing

Well Network: 3 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 902470134

CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF - CASE #: 442
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2005	
ENFORCEMENT/ORDERS	Staff Letter	7/20/2005	7/20/2005
RESPONSE - OTHER	Additional Information Report	3/12/2004	4/5/2005
ENFORCEMENT/ORDERS	Staff Letter	1/28/2004	1/28/2004
LEAK ACTION	Leak Reported	3/16/1995	
LEAK ACTION	Leak Discovery	7/25/1992	
CLEANUP ACTION	Excavate and Dispose	4/30/1990	
LEAK ACTION	Leak Began	1/1/1965	

Activities Conducted to Date Based on GeoTracker Info T0603728230

Assessment last 5 years

- Large data "gap" investigation at both properties including soil gas, soil, and groundwater sampling including new wells.
- Case closure requested, 2007

Remediation last 5 years

Insufficient data to review

Assessment older than 5 years

Insufficient data to review


Remediation older than 5 years

Insufficient data to review

DRAFT: SEPT 3, 2010

NOT UPDATED

as reported by regulatory agency



Review Conclusions T0603728230

- Review indicates:
 - Large site comprising two large former manufacturing plants. Both sites are reportedly to be combined and undergoing redevelopment.
 - Primary COPCs are chlorinated solvents, with minor TPH and metals.
 - Apparent multiple phase II investigations completed.
 - 2008 agency letter indicates RP is out of compliance with GeoTracker data submittal.
 - 2007 data "gap" investigation completed.
 - Based on 2007 study, case closure was recommended. The study appears to cover RWQCB concerns and data gaps required for closure.
 - No agency response to this investigation was located.
- Discussion:
 - Future redevelopment plans.
 - Closure requested, no reply noted in GeoTracker.

<u>Insufficient information in GeoTracker to determine status - potential closure</u>

76 STATION #2705706 (T10000000206) 304 Vermont Ave N., Los Angeles, CA 90004



Case Age: 15 years
Primary COC: Gasoline

RP Identified: ConocoPhillips
Potential Media Affected: Soil

Current land use: Active Service Station

Well Network: 4 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900040252A

CASEWORKER: MERCEDES HSU - SUPERVISOR: NONE SPECIFIED

LOS ANGELES CITY DE CASE #: 20522

LOS ANGELES, CITY OF - CASE #: 20533
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIE



Possible Reasons Why This Case Is So Old

- Appears to have no activity between 1996 and 2007 following receipt of No Further Action letter by the RWQCB
- No active remediation; MNA approach
- New data reported warrants continued monitoring

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Site Assessment Report	5/10/2010	5/10/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/13/2010
RESPONSE - REPORTS	Site Assessment Report	1/19/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/14/2010
RESPONSE - REPORTS	Monitoring Report - Other	10/13/2009	10/13/2009
RESPONSE - WORKPLANS	Preliminary Site Assessment Workplan	9/8/2009	9/8/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	7/16/2009
RESPONSE - REPORTS	Soil and Water Investigation Report	3/12/2009	3/12/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009	1/16/2009
RESPONSE - OTHER	Other Report / Document	10/15/2008	9/18/2008
ENFORCEMENT/ORDERS	Staff Letter	9/3/2008	9/3/2008
LEAK ACTION	Leak Reported	6/14/1995	
LEAK ACTION	Leak Discovery	6/1/1995	

Activities Conducted to Date Based on GeoTracker Info T1000000206

Assessment last 5 years

- Follow up phase II, eleven years later including new wells
- 2009 additional wells installed
 - Groundwater data still pending

Remediation last 5 years


• None

Assessment older than 5 years

- Compliance sampling associated with UST removals
- Initial phase II investigation, borings and wells
- Risk assessment
- SVE well abandonment

- Fuel USTs removed & soil overexcavated
- Used-oil UST, clarifier, and hoists removed & dispenser islands remodeled
- SVE wells installed; no system op

as reported by regulatory agency



Review Conclusions T10000000206

- Review indicates:
 - SVE wells installed, but then based on the limited data set, SVE was not initiated, and site closure was sought.
 - After 11 years, a new phase investigation took place reporting additional data warranting case groundwater monitoring continuation.
 - A 2009 investigation was performed where elevated hydrocarbons in soil were detected
 - Groundwater data has yet to be reported.
 - Existing data suggests that chemical concentrations in groundwater are primary impediment.
- Discussion:
 - A review of remedial alternatives may be warranted if MNA is not effective prior to closure request.
 - Cleanup closure timeline. Where are sensitive receptors located relative to site?
- Potential closure candidate

AT&T B1245 FACILITY (T0603704688)

29300 Roadside Dr., Agoura Hills, CA 91301



Case Age: 18 years

Primary COC: Diesel and MTBE **RP Identified:** AT&T Services, Inc.

Potential Media Affected: Drinking Water

Supply Aquifer

Current land use: Commercial Structure

Well Network: 5 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-05671

CASEWORKER: <u>DAVID M. BJOSTAD</u> - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY - CASE #: 005470-005671 CASEWORKER: <u>RANI IYER</u> - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Little activity between 1996 and 2008
- Transferred between agencies referred to RWQCB in 2009
- Up-gradient gasoline source (Chevron) appears as main contributor

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Soil and Water Investigation Report	*7/31/2010	
ENFORCEMENT/ORDERS	Staff Letter	3/9/2010	3/9/2010
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	9/15/2009	2/2/2010
RESPONSE - OTHER	Other Report / Document	8/15/2009	8/11/2009
ENFORCEMENT/ORDERS	Staff Letter	7/16/2009	7/16/2009
REFERRAL TO OTHER AGENCY	Referral to Regional Board	6/10/2009	6/10/2009
LEAK ACTION	Leak Reported	7/12/1995	
LEAK ACTION	Leak Discovery	6/29/1992	
LEAK ACTION	Leak Stopped	6/29/1992	



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704688

Assessment last 5 years

- Review of upgradient Chevron well data as potential source
- 2010 Additional Phase II
 Workplan results pending

Remediation last 5 years

 Heating oil UST removal (compliance samples indicate no release)


Assessment older than 5 years

- Initial monitoring well installed downgradient of former diesel UST cavity
- Additional soil borings/wells
- Slug tests

Remediation older than 5 years

 Diesel UST removal (compliance samples indicate hydrocarbon release)

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - OTHER: 5

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

· Assessment Incomplete - Well screen depths are unknown or submerged, so GW grab samples to assess current conditions

Review Conclusions T0603704688

- Review indicates:
 - Former heating oil and diesel storage; only diesel appeared to have leaked.
 - Minor impacts from diesel UST in soil and shallow GW reported in initial phase II investigation.
 - Only MTBE was detected in onsite wells during 1996 GW sampling event suggesting an offsite source (upgradient Chevron Station with known leak).
 - Ongoing review of upgradient Chevron wells appears to support offsite source for gasoline components especially MTBE.
 - Current approved phase II workplan to address gaps and to develop closure plan.
- Discussion:
 - Define extent of soil and groundwater impacts near former diesel UST appears warranted.
 - Depending on investigation results, consider cleanup closure timeline.

Potential closure candidate

DON BOSCO TECHNICAL SCHOOL (T0603704468) 1151 SAN GABRIEL BLVD N, ROSEMEAD, CA 91770



Case Age: 15 years

Primary COC: Other Solvent or Non-Petroleum

RP Identified: Father Michael Gergen (Don

Bosco Technical School)

Current Land Use: Commercial

Potential Media Effected: Aquifer used for

drinking water supply Well Network: 6

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-21159 CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- No report/document upload to GeoTracker
- Limited oversight and RP involvement
- Case transferred between agencies

ACTIVITIES REPORT ACTION DATE RESPONSE - REPORTS Monitoring Report - Semi-Annuall ENFORCEMENT/ORDERS Staff Letter 6/15/2009 RESPONSE - REPORTS RESPONSE - REPORTS Monitoring Report - Quarterly 10/15/2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603704468)

Assessment last 5 years

2002-2009: GW monitoring (?)

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years

2003: MTBE investigation (?)

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (TO603704468)

as reported by regulatory agency

151 SAN GABRIEL BLV	DN			CLEANUP OVERSIGI	HT AGENCIES
OSEMEAD, CA 91770				LOS ANGELES RWQ	ICB (REGION 4) (LEAD) - CASE #: 1-2
OS ANGELES COUNTY					AHMAD J. LAMMA
UST CLEANUP SITE				LOS ANGELES COUI CASEWORKER:	
				CASETTOTALE	SOM PHOSE
Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI) Site Maps / D	Occuments Community Involvement	
CLOSURE REVIEW - THIS					VIEW ALL POSSIBLE CLOSURE REVIEW VA
BENEFITS OF ADDITIONAL WORK					
Other - Need one more rou	ınd of sampling				
SENSITIVE RECEPTORS LIKELY TO	BE IMPACTED AND TIME FRAME	FOR IMPACT			
SENSITIVE RECEPTOR	TIME FRAM	NE FOR IMPACT	COMMENTS		
Municipal Well	Undetern	mined	Need one more r	ound of sampling	
NOTES / COMMENTS					
Need one more round of sampling					
Need one more round of sampling					
Need one more round of sampling Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI) Site Maps / Dr	pruments Community Involvement	
	Cleanup Status History	Regulatory Activities	Environmental Data (ESI) Site Maps / Di		
Summary Closure Review			Environmental Data (ESI) Site Maps / Di		S A SUBMITTAL WAS AUTO-RECEIV
Summary Closure Review	ogs (GEO_MAP and GE	O_BORE)	Environmental Data (ESI) Site Maps / Di	* DENOTE	
Summary Closure Review Site Maps and Boring Lo	ogs (GEO_MAP and GE	O_BORE)	Environmental Data (ESI) Site Maps / Di	* DENOTE SUBMITTED	<u>SIZE</u>
Summary Closure Review Site Maps and Boring Lo	ogs (GEO_MAP and GE	O_BORE)	Environmental Data (ESI) Site Maps / Di	* DENOTE	
Summary Closure Review	ogs (GEO_MAP and GE	O_BORE)	Environmental Data (ESI) Site Maps / Dr	* DENOTE SUBMITTED	<u>SIZE</u>
Summary Closure Review Site Maps and Boring Le TITLE SEO MAP Site Documents	ogs (GEO_MAP and GE	O_BORE) BY IO (AUTH_RP)	Environmental Data (ESI) Site Maps / Dr	* DENOTE SUBMITTED	<u>SIZE</u>
Summary Closure Review Site Maps and Boring Lo	ogs (GEO_MAP and GE SUBMITTED I RICK L. FER	O_BORE) BY IO (AUTH_RP)		* DENOTE SUBMITTED	<u>SIZE</u> 21 KB
Summary Closure Review Site Maps and Boring Le TITLE SEO MAP Site Documents TITLE UNKNOWN	DES (GEO_MAP and GE SUBMITTED I RICK L. FER	O_BORE) BY IO (AUTH_RP)	SUBMITTED BY	* DENOTE SUBMITTED	<u>SIZE</u> 21 KB <u>Date</u> <u>Size</u>
Summary Closure Review Site Maps and Boring Le TITLE SEO MAP Site Documents TITLE VINKNOWN Monitoring Reports	DES (GEO_MAP and GE SUBMITTED I RICK L. FER TYPE STAFF LETTER	O_BORE) BY IO (AUTH_RP)	SUBMITTED BY	* DENOTE SUBMITTED	<u>SIZE</u> 21 KB <u>Date</u> <u>Size</u>
Summary Closure Review Site Maps and Boring Le TITLE SEO MAP Site Documents	DES (GEO_MAP and GE SUBMITTED I RICK L. FER TYPE STAFF LETTER	O_BORE) BY IO (AUTH_RP)	SUBMITTED BY	* DENOTE SUBMITTED	<u>SIZE</u> 21 KB <u>Date</u> <u>Size</u>
Summary Closure Review Site Maps and Boring Le SITLE SEO MAP Site Documents SITLE JINKNOWN Monitoring Reports IO MONITORING REPORT SUBMI	OBS (GEO_MAP and GE SUBMITTED I RICK L. FER TYPE STAFF LETTER TTALS FOUND FOR THIS FACIL	O_BORE) BY O (AUTH_RP)	SUBMITTED BY	* DENOTE SUBMITTED	<u>SIZE</u> 21 KB <u>Date</u> <u>Size</u>
Summary Closure Review Site Maps and Boring Le SEO MAP Site Documents SITLE SINKNOWN Annitoring Reports	OPS (GEO_MAP and GE SUBMITTED I RICK L. FER TYPE STAFF LETTER TTALS FOUND FOR THIS FACIL MONITORING FR	O_BORE) BY O (AUTH_RP)	SUBMITTED BY	* DENOTE SUBMITTED	<u>SIZE</u> 21 KB <u>Date</u> <u>Size</u>

Review Conclusions T0603704468

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one RWQCB letter (June 2009) requesting for reduction in GW monitoring frequency, and a geo map.
 - Activities Report showed "GW monitoring between 2002-2009" and "MTBE investigation in 2003" → no data/information in GeoTracker.
 - Closure Review indicates "need one more round of sampling."
- Discussion:
 - RP and GeoTracker compliance are needed
 - Consider closure → once receive latest sampling data?

Potential closure consideration (pending latest sampling data)

FIRE STATION #127 (T0603705133) 2049 E 223rd Street, Carson, CA 90810



Possible Reasons Why This Case Is So Old

- Appears to have years of gap between work performed in the past
- Government Site, funding issues?
- Groundwater cleanup took time
- Closure request April 2010

Case Age: 15 years

Primary COC: Other solvent, non-petroleum

RP Identified: LA Co Fire Dept.

Potential Media Affected: Drinking Water

Supply Aquifer

Current Land Use: Active Fire Station

Well Network: 4 Wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-12498

CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go		
ACTION TYPE	ACTION		ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - OTHER	Request for Closure		5/4/2010	5/4/2010
RESPONSE - OTHER	Site Conceptual Model		1/15/2010	1/26/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly		1/15/2010	1/26/2010
RESPONSE - OTHER	Site Conceptual Model		7/15/2009	7/31/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually		7/15/2009	7/31/2009
ENFORCEMENT/ORDERS	Staff Letter		6/15/2009	6/15/2009
RESPONSE - REPORTS	Well Installation Report		5/28/2009	5/28/2009
RESPONSE - OTHER	Site Conceptual Model		4/15/2009	5/20/2009
ENFORCEMENT/ORDERS	Waste Discharge Requirements		2/19/2009	2/19/2009



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603705133

Assessment last 5 years

GWM

Remediation last 5 years


- Injection well installed, Fenton's Reagent Injection
- SVE/GWE wells installed
- DPE treatment system with thermal oxidation and carbon adsorption proposed

Assessment older than 5 years

- GWM
- Multiple phase II investigation, borings and monitoring wells

- USTs (gas & diesel) removed
- NAPL bailing

as reported by regulatory agency



Review Conclusions T0603705133

- Review indicates:
 - Leak has been stopped, much of source has been removed
 - Soil and groundwater impacts defined, low levels remain in GW
 - Primary impacts in vadose zone (5 to 35 ft bgs)
 - DPE treatment system appears successful
 - Fenton's reagent injection appears successful
- Discussion:
 - Effectiveness of remediation should be fully evaluated
 - Closure request was based on low levels in GW, what is the risk now of closing the site (where are receptors located?)
 - Only low levels remain in groundwater monitoring wells

Potential closure candidate within 1 year

U-HAUL CENTER #713-84 (T0603701854)4045 CHERRY AVE, LONG BEACH, CA 90807



Case Age: 26 years

RP Identified by Regulator: Amerco Real

Estate Company

Primary COC: Gasoline

Media of Concern: Aguifer used for

drinking water supply

Current Land Use: Industrial

Well Network: 11

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908070025 CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Multiple USTs removed
- Multiple releases over time
- Little work between 1984 and 2002
- NAPL case with active remediation

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	₩ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
CLEANUP ACTION		11/4/2008
RESPONSE - REPORTS	Site Conceptual Model Report	7/15/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2008
RESPONSE - REPORTS	Site Conceptual Model Report	1/15/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2007
RESPONSE - REPORTS	Site Conceptual Model Report	10/15/2007
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2007
RESPONSE - WORKPLANS	Corrective Action Plan / Remedial Action Plan	5/15/2007

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701854

Assessment last 5 years

 Ongoing: GW monitoring (11 wells)

Remediation last 5 years

- 2007-2009: VE and Dual phase extraction (vapor and GW) ~5,370-gal removed from soil and GW
- 2007-2009: Vapor extraction and free product removal

Assessment older than 5 years


- 2002-2008: SCM
- 2004: Soil and GW investigation report

Remediation older than 5 years

2006: Remedial wells installed

IMPEDIMENTS TO CLOSURE TO603701854

as reported by regulatory agency



OF WELLS MONITORED - SEMI-ANNUALLY: 11

Review Conclusions T0603701854

- Review indicates;
 - As a result of the remediation program, free product thickness in wells has been reduced to a sheen as of June 2009.
 - Has two adjacent sites (former Texaco and Union-76) that are environmental cases.
 - According to sampling reports, remediation technique seems effective in reducing contamination in GW.
 - Given the age of release and based on sampling data:
 - * any mobile portion of the release has likely stabilized
 - * any existing potential receptors will already likely impacted
- Discussion:
 - Residual NAPL, indoor air risk, and closure timeline
 - GeoTracker report compliance is needed
- Closure Consideration pending GW remediation, on track

MOBIL #18-LMR (T0603700759) 5700 HOLLYWOOD BLVD, HOLLYWOOD, CA 90028



Possible Reasons Why This Case Is So Old

- Age of case might not be 24-years possible data error in GeoTracker?
- GW contamination over MCL in small area of site
- No record of activity between 1986 and early 2000's

NOTE: Site is in EAOP

Case Age: 24 years (GeoT) -> maybe only 8-years RP Identified by Regulator: Emily Anderson

(Exxon Mobil Refining and Supply)

Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

Media of Concern: Aquifer used for drinking water

Current Land Use: Mobil Gas Station

Wells Network: 9 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900280107 CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF - CASE #: 22403

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	YPE FILTER: Show All Activities V Go		
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE	
RESPONSE - WORKPLANS	Corrective Action Plan / Remedial Action Plan	6/7/2010	6/7/2010	
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	3/29/2010	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	12/21/2009	
RESPONSE - REPORTS	Site Assessment Report	8/3/2009	8/3/2009	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/3/2009	
RESPONSE - OTHER	Other Report / Document	6/22/2009	6/22/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700759

Assessment last 5 years

- 2003-2008: Groundwater monitoring
- 2008: Four vapor extraction wells installed
- 2009: Soil vapor probes installed

Assessment older than 5 years

2003: Groundwater monitoring wells installed

Remediation last 5 years


 2008: SVE removed up to 5,400-ppmv TPH-g, 5.4ppmv benzene and 68ppmv MTBE.

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603700759

as reported by regulatory agency



Review Conclusions T0603700759

- Review indicates:
 - Age of case is may be only approximately 8 –years (release from 2001?), and not 23-years as shown in GeoTracker?
 - Site is currently an active as station.
 - Soil vapor survey performed
 - RP and Lead Agency are conducting assessment and remediation on the site
- Discussion:
 - Check actual age of case
 - Where are sensitive receptors compared with remaining plume at the site?

<u>Site appears to be on track, may be potential Closure Candidate</u> <u>soon</u>

MOBIL #18-K1R (T0603701095)

1406 MANCHESTER AVE W, LOS ANGELES, CA 90047



NOTE: Site was in EAOP, not now

Case Age: 24 years (GeoTracker) -> 10-years

based on report

RP Identified by Regulator: Emily Anderson

(Exxon Mobil Refining and Supply)

Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

Media of Concern: Aquifer used for drinking

water

Current Land Use: Vacant Lot

Well Network: 7 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900470107

CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy/luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Free product and high levels of GW contamination persist
- Nearby municipal well might be impacted
- Actual age of case might be incorrect

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	Go	* 11
ACTION TYPE	АСТІОМ	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/13/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/15/2009
RESPONSE - OTHER	Other Report / Document	7/14/2009	7/14/2009
RESPONSE - REPORTS	Site Assessment Report	6/22/2009	6/22/2009
RESPONSE - REPORTS	Well Destruction Report	6/22/2009	6/22/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701095

Assessment last 5 years

- Ongoing: Quarterly monitoring
- 2007: Site visit/inspection/sampling

Remediation last 5 years

2008: SVE

Assessment older than 5 years


- 1999 ongoing: Quarterly monitoring
- Since 1997: 5 phases of site investigations (22 soil borings drilled and 11 converted to MWs)

Remediation older than 5 years

2001: Remove 33-gallons of free product

IMPEDIMENTS TO CLOSURE T0603701095

as reported by regulatory agency



Review Conclusions T0603701095

- Review indicates:
 - This site is a vacant lot.
 - This site was part of the Expedited Agency Oversight Program (EAOP) for Priority D sites, until meeting in 1st Qtr 2010.
 - Report indicates release from UST removal in 1999 approximately age of case is 10-years, not 23-years as shown in GeoTracker.
 - RP and Lead Agency are currently conducting assessment and remediation on the site.
- Discussion:
 - Check actual age of case
 - Effectiveness of remediation in cleanup should be continuously evaluated

Not a Potential Closure Candidate

MOBIL #18-MPX (T0603701894)

4101 BELLFLOWER BLVD N, LONG BEACH, CA 90808



Case Age: 24 years

RP Identified by Regulator: Emily Anderson

(Exxon Mobil Refining and Supply)

Primary COC: Gasoline

Media of Concern: Drinking water aquifer Current Land Use: Commercial Center -

Restaurants

Well Network: 18



Possible Reasons Why This Case Is So Old

- Residual source present (NAPL) free product
- Potential to impact municipal well located down-gradient of site
- GW contamination exceeds cleanup levels

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908080143
CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED
LONG BEACH/SIGNAL HILL GITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All	Activities <u>•</u> Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - OTHER	Site Conceptual Model	4/15/2010	4/14/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010	1/19/2010
RESPONSE - OTHER	Site Conceptual Model	7/15/2009	7/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	7/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701894

Assessment last 5 years

- Semi-annual GWM
- Site conceptual model
- Remedial action report
- Remedial well installation

Remediation last 5 years

- Active remediation
 - Air sparge
 - Soil-vapor extraction
 - Groundwater pump & treat
- Over-excavation of UST pit


Assessment older than 5 years

- Soil & groundwater investigations
- DPE well installation
- Apparent missing reports

- **Dual-phase extraction**
- NAPL bailing

IMPEDIMENTS TO CLOSURE T0603701894

as reported by regulatory agency



Review Conclusions T0603701894

- Review indicates:
 - Former NAPL site immobile NAPL long term source to groundwater
 - Dissolved benzene concentrations remain elevated
 - Municipal well located down-gradient and 694 feet southeast of site
 - Active remediation ongoing
 - Site has been redeveloped into commercial center
- Discussion:
 - Effectiveness of remediation → free product in GW
 - Cleanup closure timeline

Not a Potential Closure Candidate, site appears on track

US POSTAL SERVICE (T0603702147)5823 WHITE OAK AVE, ENCINO, CA 91316



Possible Reasons Why This Case Is So Old

- Limited assessment and cleanup activities
- Government entity site, budget issues?
- Recently approved RAP (active remediation)
- Elevated fuel constituent concentrations in Groundwater

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 24 years

RP Identified by Regulator: US Postal

Service/Pacific Facility **Primary COC:** Gasoline

Media of Concern: Aquifer used for drinking

water

Current Land Use: US Post Office

Well Network: 8

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913160225

CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy lung - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	₩Go	
ACTION TYPE	ACTION	ACTION DATE	
RESPONSE - REPORTS	Remedial Progress Report	7/15/2011	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2011	
RESPONSE - REPORTS	Monitoring Report - Annually	1/15/2011	
ENFORCEMENT/ORDERS	Staff Letter	5/11/2010	
RESPONSE - WORKPLANS	Corrective Action Plan / Remedial Action Plan	1/15/2010	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	
RESPONSE - OTHER	Fee Title Holder Info.	11/12/2009	
ENFORCEMENT/ORDERS	Staff Letter	10/13/2009	

Activities Conducted to Date Based on GeoTracker Info T0603702147

Assessment last 5 years

 GW monitoring (no reports in GeoTracker) – letter indicated GW monitoring stopped in Dec 2008

Remediation last 5 years

None


Assessment older than 5 years

- 1987-2001: GW MWs installed
- 1997-current: GW monitoring

- 2000-2008: Free product removal (5-gal)
- 2001: Excavate and Dispose (URF)

IMPEDIMENTS TO CLOSURE T0603702147

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY
OF WELLS MONITORED - SEMI-ANNUALLY: 8

Review Conclusions T0603702147

- Review indicates:
 - Some data missing in GeoTracker
 - Site has been adequately assessed
 - Elevated fuel constituents concentrations in groundwater
 - Recent RAP approved
 - Active remediation pending installation and operation of system
- Discussion:
 - Incomplete data/report submittals to GeoTracker
 - Plume definition, indoor air risk, future site use, closure timeline should all be evaluated and a detailed site conceptual model prepared.
- Not a Potential Closure Candidate, but on track now with remedial actions being implemented.

MOBIL #18-LMQ (T0603702307) 16411 DE LONE ST, SANTA CLARITA, CA 91351



Case Age: 24 years

RP Identified by Regulator: Exxon Mobil Oil

Corp

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking

water

Current Land Use: ARCO Gas Station

Well Network: 14

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913500043 CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED

CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Multiple USTs removed over time
- Appears to have limited activity between 1994-2002
- Persistent GW contamination
- Evaluate effectiveness of remediation

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Preliminary Site Assessment Report	6/30/2008
ENFORCEMENT/ORDERS	Staff Letter	4/28/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	*6/30/2008
RESPONSE - REPORTS	Preliminary Site Assessment Report	*6/30/2008
ENFORCEMENT/ORDERS	Staff Letter	10/26/2007
RESPONSE - REPORTS	Additional Information Report	9/5/2006
ENFORCEMENT/ORDERS	Staff Letter	9/5/2006
LEAK ACTION	Leak Discovery	10/14/1986
LEAK ACTION	Leak Reported	10/14/1986

Activities Conducted to Date Based on GeoTracker Info T0603702307

Assessment last 5 years

- Ongoing: GW monitoring (14 wells)
- 2008: Soil borings installation

Remediation last 5 years

- 2009: Pump and Treat
- 2003-2007: GW Pump and Treat (596,013-gal GW)


Assessment older than 5 years

- 1983-1991: Multiple phases of assessment, including installation of GW and extraction wells
- 1988: GW monitoring
- 1986-2003: Soil borings and installation of 16 GW MWs

- 1993-1994, 1997-2005: Vapor extraction (46,312-lbs HCs)
- 1983-1990: Free product recovery (~2,000-gal NAPL)

IMPEDIMENTS TO CLOSURE T0603702307

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY # OF WELLS MONITORED - SEMI-ANNUALLY : 14

Review Conclusions T0603702307

- Review indicates:
 - Maximum benzene and MTBE concentrations present in wells in the vicinity of the USTs
 - As of 2009, maximum concentrations of TPH-g and benzene were 10,000-µg/L and 3,400-µg/L, respectively, and indicative of source material still present (immobile NAPL?)
 - Given the age of release, any mobile portion of the release will likely have stabilized and any existing potential receptors will already likely impacted → Site is currently a gas station
- Discussion:
 - Evaluate remediation effectiveness, forecast trend to meet Clean-Up Goals
 - Sensitive receptor review, other data gaps to be filled in?
 - Closure timeline will be later
- Potential Closure Consideration in a few years, not on fast track, partially due to air permit issues?

DRAFT: SEPT 3, 2010

MOBIL #18-FV6 (T0603704809)

3084 GAGE AVE E, HUNTINGTON PARK, CA 90255



Case Age: 24 years

RP Identified by Regulator: Exxon Mobil Oil

NOT UPDATED

Corp

Primary COC: Gasoline

Media of Concern: Drinking water supply

aquifer

Current Land Use: Gas Station

Well Network: 10

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-09382

CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



Possible Reasons Why This Case So Old

- Little activity between 1986 and 2008
- Case was transferred between agencies (2008)

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show	All Activities	*
ACTION TYPE	ACTION	ACTION DATE	
RESPONSE - REPORTS	Well Installation Report	4/15/2010	
RESPONSE - REPORTS	Remedial Progress Report	1/15/2010	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	
ENFORCEMENT/ORDERS	Staff Letter	12/14/2009	
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	11/16/2009	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	10/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	9/25/2009	
RESPONSE - WORKPLANS	Corrective Action Plan / Remedial Action Plan	7/30/2009	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	
RESPONSE - WORKPLANS	Pilot Study / Treatability Workplan	5/22/2009	

Activities Conducted to Date Based on GeoTracker Info T0603704809

Assessment last 5 years

- 2007-ongoing: GW monitoring (10 wells)
- 2008 soil borings
- 2009 SVE wells
- 2009 Corrective Action Plan

Remediation last 5 years

• 2009 SVE pilot test

Assessment older than 5 years

None

Remediation older than 5 years

None


Review Conclusions T0603704809

- Review indicates:
 - Initial investigation completed 2007-2009
 - Case was transferred from LA County to LA-RWQCB in 2008
 - Recent proposal for SVE will provide active remediation and, based on system effectiveness, a timeline for closure under existing remediation methodology
- Discussion:
 - System installation and operations schedule
 - Other data gaps to be filled in?
 - Closure timeline to be evaluated once system is operational

Not a Potential Closure Candidate, appears to be on track at present.

IMPEDIMENTS TO CLOSURE T0603704809

as reported by regulatory agency



PALMS DISTRIBUTION HEADQUARTER (T0603700555) 2311 FAIRFAX AVE S, LOS ANGELES, CA 90016



Case Age: 23 years
Primary COC: Gasoline

RP Identified by Regulator: Mr. Dat Quach

(LADWP)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Undetermined

Well Network: 32

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900160034

CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears to have history of lack of oversight and RP involvement
- Large NAPL site
- GW contamination issue → Free product RESPONSE REPORT in GW
- Government entity site

NOTE: Data queried from GeoTracker and reviewed in August 2010





Activities Conducted to Date Based on GeoTracker Info T0603700555

Assessment last 5 years

- Semi-annual GWM
- Well installation
- CAP
- SCM
- No investigation reports in GeoTracker

Assessment older than 5 years

- Initial subsurface investigation
- Well installations
- Soil vapor survey
- Pilot study
- Interim RAP
- No investigation reports in GeoTracker


Remediation last 5 years

- SVE/GWP&T
- No investigation reports in GeoTracker

- Product recovery pumping
 - By 1996 over 12,000 gallons of mobile NAPL were removed
 - No investigation reports in GeoTracker

IMPEDIMENTS TO CLOSURE T0603700555

as reported by regulatory agency



Review Conclusions T0603700555

- Review indicates:
 - Large NAPL site → Residual source to groundwater likely extensive, i.e. immobile fraction.
 - Ongoing active remediation \rightarrow SVE/GWP&T.
- Discussion:
 - Effectiveness of remediation to be evaluated
 - RP and GeoTracker compliance
 - Cleanup closure timeline

Not a Potential Closure Candidate, appears to be on track at present.

MOBIL FORMER BULK PLANT #04-419 (T0603702788) 16300 OLD VALLEY BLVD, LA PUENTA, CA 91746



Possible Reasons Why This Case Is So Old

- Large former bulk plant
- Three impacted groundwater zones
- Appears to have elevated TPH-g and benzene in GW

Case Age: 23 years

RP Identified by Regulator: Johnny J. Medrano

(Mobil Oil Corp)

Primary COC: Gasoline

Media of Concern: Drinking water supply

aquifer

Current Land Use: Parking/Vacant Lot

Well Network: 10

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-01520 CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/7/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/12/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010	1/12/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	2/16/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/23/2009
RESPONSE - OTHER	Site Conceptual Model	7/15/2009	8/17/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702788

Assessment last 5 years

- Semi-annual GWM
- Site conceptual model
- No investigation reports in GeoTracker

Remediation last 5 years


- "Rotating" Dual phase extraction
 - Rebound monitoring in between
- Chemical injection proposed for 2010

Assessment older than 5 years

- Initial subsurface investigation
- Monitoring well installations
- Soil-gas survey investigation
- Pump test
- DPE pilot test
- No investigation reports in GeoTracker

- Site/system removal
- Over excavation
- Dual phase extraction

IMPEDIMENTS TO CLOSURE τ0603702788 as reported by regulatory agency



Review Conclusions T0603702788

- Review indicates:
 - Site was a large former bulk plant with wide spread impacts (former NAPL site). Currently a vacant lot.
 - Three groundwater zones impacted.
 - Complicated remediation implementation and monitoring.
 - Site has ongoing active DPE remediation.
 - Chemical oxidation alternative proposed for 2010.
- Discussion:
 - Effectiveness of remediation should be evaluated
 - Cleanup closure timeline (pending GW monitoring trend)

Not a Potential Closure Candidate at this time, appears to be on track

ATLANTIC AVIATION (FORMER MERCURY SERVICES) (T0603701041)

6851 IMPERIAL HWY W, WESTCHESTER, CA 90045



Case Age: 22 years

Primary COC: OTHER SOLVENT OR NON-

PETROLEUM HYDROCARBON

RP Identified by Regulator: Joe West

(Atlantic Aviation)

Potential Media Affected: Aquifer used for

drinking water

Current Land Use: Airlines Cargo

Wells Network: 7

CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900450152 CASEWORKER: DAVID M. BJOSTAD - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF CASEWORKER: gloy lung - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears to have years of gaps in between site activities
- As of Dec. 2009, free product still detected in one MW, and TPH-d and chloroform were also detected.
- Free product removal directed by agency in Feb. 2010
- Listed as "OTHER SOLVENT OR NON-PETROLEUM HYDROCARBON" release in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in August 2010



Activities Conducted to Date Based on GeoTracker Info

T0603701041 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

- Ongoing: GW monitoring (7 wells)
- 2009: Feasibility Study

Remediation last 5 years

- 2004: Interim remedial
- 2008-2009: Remedial

Assessment older than 5 years

- 2000-ongoing: GW monitoring
- 1998: Well installation

- 2003: Interim remedial
- 1999-2008: Free product removal (approx 116-galgal removed from MW-5A)

IMPEDIMENTS TO CLOSURE T0603701041 as reported by regulatory agency

ATLAN	TIC AVIA	TION (FORME	R MERCURY	SERVICES) (T0603701041)	- (MAP)	
WESTCHES LOS ANGE	RIAL HWY W STER, CA 9004 LES COUNTY ANUP SITE	45				CLEANUP OVERSIGHT LOS ANGELES RWQC CASEWORKER: Q LOS ANGELES, CITY C CASEWORKER: Q	B (REGION 4) (LEAD) - CASE #: 900450152 AVID M. BJOSTAD OF
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
				OF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS T	TO CLOSURE						
Feasible : GROUNDWAT	ER IMPACTS	Performed - <i>Adequate LN</i> ve Other Cleanup Goal - <i>L</i>					
BENEFITS OF A	ADDITIONAL WORK						
Remove /	Reduce Source Ma	ass - Continue LNAPL reco	very.				
SENSITIVE REC	EPTORS LIKELY TO B	E IMPACTED AND TIME FRAME	FOR IMPACT				
SENSITIVE RECE Groundwater			FRAME FOR IMPACT ady Impacted		COMMENTS LNAPL remains at	one well	1

Review Conclusions T0603701041

- Review indicates:
 - The site is an active UST facility (airport)
 - Free product detected in MW-5A from 1999-2009 (i.e., free product appears to have remained localized)
 - GW sampling on Dec 2009: maximum TPH-d and TPH-g detected in GW at 470-ug/L and at 53-ug/L, respectively, in MW-4A (NDs for TPH-g, Benzene, MTBE and TBA)
- Discussion:
 - GWM trend is downward, but product remains
 - Cleanup closure timeline will be based on remediation of product

Potential closure candidate, appears to be on track, no closeable now.

MOBIL 18-LEG (T0603700608)

2121 ARLINGTON AVE S, JEFFERSON PARK, CA 90018



NOTE: Site is in EAOP

Case Age: 23 years
Primary COC: Gasoline

RP Identified by Regulator: Emily Anderson

(Exxon Mobil Refining & Supply)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Active 76 Station

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900180098 CASEWORKER: DAVID M. BJOSTAD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Offsite impacts undefined
- Active SVE still effectively removing hydrocarbons
- GW contamination above MCLs

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/15/2010
RESPONSE - REPORTS	Remedial Progress Report	1/15/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/15/2009
RESPONSE - REPORTS	Remedial Progress Report	10/15/2009	10/15/2009



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700608

Assessment last 5 years

- Qtrly GWM
- SVE pilot study
- Additional subsurface investigation
- CAP/RAP-feasibility study

Assessment older than 5 years

- Initial subsurface investigation
- Well installation
- CAP/RAP-feasibility study

Remediation last 5 years


- Active SVE
 - Not yet asymptotic

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603700608

as reported by regulatory agency



Review Conclusions T0603700608

- Review indicates:
 - Site has ongoing active SVE remediation → not yet asymptotic
 - Offsite plume boundary undefined remains undefined to the NE of site
 - Post SVE monitoring required i.e. rebound/SVE effectiveness monitoring
 - Primary COCs in groundwater include benzene and MTBE
 - Site is currently an active gas station
- Discussion:
 - Effectiveness of remediation should be evaluated
 - Cleanup closure timeline should be evaluated

<u>Potential for Closure Consideration</u> pending remedial results and offsite assessment, appears to be on track

LA CO FACILITIES MGM DEPT (T0603701679) 21356 AVALON BLVD S, CARSON, CA 90745



Possible Reasons Why This Case Is So Old

- Persistent free product in GW
- Persistent GW contamination
- Case was transferred between agencies
- · Effectiveness of remediation

Case Age: 22 years
Primary COC: Gasoline
RP Identified: LA County
Current Land Use: Commercial

Potential Media Effected: Aquifer used for

drinking water supply **Well Network:** 12

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 907450034
CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Site Conceptual Model	4/19/2010
OTHER REGULATORY ACTIONS	Site Visit / Inspection / Sampling	10/26/2009
RESPONSE - OTHER	Site Conceptual Model	10/15/2009
RESPONSE - OTHER	Site Conceptual Model	7/20/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - OTHER	Site Conceptual Model	4/15/2009
ENFORCEMENT/ORDERS	Staff Letter	2/25/2009
RESPONSE - OTHER	Site Conceptual Model	1/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

- Ongoing: GW monitoring
- 2007, 2008, 2009, 2010: SCMs
- 2006: Sensitive receptor survey
- 2004: Site conceptual model and plume model

Remediation last 5 years

- 2009-ongoing: TPE
- 2008-ongoing: Remedial progress
- 2006: Remove free product

Assessment older than 5 years

- 2004: Site conceptual model and plume model
- 2003-ongoing: GW monitoring
- 1992: Subsurface investigation and vapor extraction test

- 2005: CAP/RAP Final remediation
- 2000: Remove free product

IMPEDIMENTS TO CLOSURE (TO603701679)

as reported by regulatory agency



Review Conclusions T0603701679

- Review indicates:
 - Previous investigation confirmed no off-site sources.
 - Site has persistent GW contamination (free product) in spite of remediation. Results from January 2010:

Contaminant	Maximum Concentration	Sample ID
TPH-g	87,000 μg/1	MW19
TPH-d	39,000 μg/1	MW19
Benzene	23,000 μg/1	MW19
Ethylbenzene	1,700 μg/l	MW19
Toluene	18.000 μg/1	MW19
Total Xylenes	6,500 μg/l	MW19
MTBE	620 μg/l	MW31
TBA	380 μg/l	MW31

- Discussion:
 - Effectiveness of current remediation how long to reach Clean-Up Goals?
 - Concentrations indicative of significant remaining source consider more robust source-zone remediation e.g. excavation, injection, etc.
- Not a Potential Closure Candidate, appears to be on track

SHELL WIC 204-4190-0204 (T0603702922)

1031 HACIENDA BLVD S, HACIENDA HEIGHTS, CA 91745



Possible Reasons Why This Case Is So Old

- Little activity between 1989 and 2000
- Persistent GW contamination
- Remedial effectiveness
- Possible off-site source contribution

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 22 years

Primary COC: Solvents ←

RP Identified: Shell Oil Products US

Potential Media Effected: Aquifer used for

drinking water supply

Current Land Use: Auto Service

Well Network: 18

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-03526

CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Site Conceptual Model	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010
RESPONSE - OTHER	Site Conceptual Model	10/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009

Activities Conducted to Date Based on GeoTracker Info (T0603702922)

Assessment last 5 years

- Ongoing: GW monitoring
- 2006 2010: Site Conceptual Models

Remediation last 5 years

- 2006-ongoing: Dual phase extraction
- 2006: SVE with Other

Assessment older than 5 years

- 1988-ongoing: GW monitoring
- 2002 -- 2005: Site Conceptual Models
- 2003: Soil and water investigation, UST sampling, sensitive receptor report
- 1999: Phase II Site assessment
- 1988-1989: Site assessment

- 2003-ongoing: Remediation
- 2001: Initial site remediation
- 1988-1992: Separate phase HC removal

IMPEDIMENTS TO CLOSURE (T0603702922)

as reported by regulatory agency

SHELL	WIC 204-	4190-0204 (TC	603702922) -	· (MAP)			
HACIENDA LOS ANGE	ENDA BLVD S A HEIGHTS, CA ELES COUNTY ANUP SITE	91745				CASEWORKER LOS ANGELES COU	QCB (REGION 4) (LEAD) - CASE #: I-03526
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR GLOSURE AS O	DF 10/14/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
• Groundwa		ve Other Cleanup Goal - E	xceed AICLs.				
BENEFITS OF	ADDITIONAL WORK						
• Remove	/ Reduce Source Ma	ass - DPE system was beli	ng operated since June 2	2006.			
SENSITIVE RE	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAME	E FOR IMPACT				
Groundwate		TIME FRAME FOR Already Impa		COMMENTS significantly w	vith benzene, MTBE and TE	A.	

Review Conclusions T0603702922

- Review indicates:
 - Multiple phases of investigation
 - Active remediation (DPE), rebound test proposed
 - Benzene, MTBE, TBA still above MCLs, but exhibit a downward trend
 - Possible offsite source for MTBE
 - Adjacent site that is potential comingled plume source is not well defined, but active investigations are in progress
- Discussion:
 - Cleanup closure timeline needs to be looked at in a CSM report
 - Effectiveness of current remediation should be evaluated
 - Off-site source and other data gaps are possible for this site

Potential Closure Consideration pending GWM trend, appears on track

DRAFT: SEPT 3, 2010

SHELL STATION (T0603701203) 3500 CENTINELA AVE S, LOS ANGELES, CA 90066



Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Brad Boschetto (Equiva Services LLC)

Potential Media Affected: Drinking water

NOT UPDATED

supply well

Current Land Use: Chevron Station

(Google Map)
Well Network: 6

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900660052 CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears to have years of gap in oversight at the beginning of the case
- Offsite plume
- Near Charnock Well Field MTBE site
- 3 year gap in SVE operation (06-09)

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/15/2009
RESPONSE - REPORTS	Pilot Study Treatability Report	7/15/2009	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701203

Assessment last 5 years

- Quarterly GWM
- CAD
- Pilot/treatability study
- Well installation
- Apparent missing reports?

Assessment older than 5 years

- Initial investigation
- Apparent missing reports?

Remediation last 5 years

Active SVE

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603701203

as reported by regulatory agency

Management of the Parket		I (T060370120	3) - (MAP)				
OS ANGE	TINELA AVE S ELES, CA 9006 ELES COUNTY ANUP SITE	6				CLEANUP OVERSIGHT LOS ANGELES RWQCI CASEWORKER: U LOS ANGELES, CITY O CASEWORKER: el	B (REGION 4) <i>(LEAD) - CASE #: 90066005</i> A <i>Y HUANG</i> DF
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
							VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
	SOURCE CONTROL ng Source Poses Th	nreat to Groundwater - The	e RP is conducting SVE to	o clean up the vadose zone			
BENEFITS OF A	ADDITIONAL WORK						
• Remove /	/ Reduce Source M	ass - clean up the vadose	zone to reduct the three	at to Charnock wellfield			
SENSITIVE REC	CEPTORS LIKELY TO E	BE IMPACTED AND TIME FRAME	FOR IMPACT				
Municipal W Groundwater	rell	1-10	FRAME FOR IMPACT) Years adv Impacted		COMMENTS 4019 ft. to product since 1998	ion wells	
			,,		5///C 1770		
# OF WELL REASONS F	.S MONITORED FOR QUARTERL	MONITORING I - QUARTERLY : 5, SE Y OR MONTHLY OR roack MITBE PRP site	MI-ANNUALLY : 1 OTHER GROUNDWA				

Review Conclusions T0603701203

- Review indicates:
 - Appears to have missing reports in GeoTracker
 - Site has ongoing active SVE after 3-years of gap in SVE operations (2006-2009)
 - Source to groundwater reportedly still present
 - Site is an active gas station
 - Near Charnock Well Field MTBE site
 - Well field approximately 4,000 feet from site
 - Groundwater plume offsite
- Discussion:
 - Cleanup closure timeline

Potential Closure Candidate pending remediation results, on track

G I TRUCKING CO (T0603701540) 14727 ALONDRA BLVD, LA MIRADA, CA 90638



Case Age: 22 years
Primary COC: Gasoline

RP Identified by Regulator: Estes Terminal

of California, LLC

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Commercial Lot

Well Network: 16

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 906380116 CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Multiple USTs removals/sources
- Potential offsite contamination
- NAPL case
- GW plume not fully delineated
- Large industrial site, almost all paved
- Free product in GW

NOTE: Data queried from GeoTracker and reviewed in August 2010





Activities Conducted to Date Based on GeoTracker Info T0603701540

Assessment last 5 years

- Ongoing: GW monitoring (16 wells)
- 2008: Proposed soil-gas (WP)
- 2007: Potential off-site source assessment

Remediation last 5 years


- 2007-2008: Free product removal
- 2007: Interim soil remediation at shallow zone (1,998-gal HC removed)

Assessment older than 5 years

- 2002-2008: Multiple SCMs
- 1999, 2001-2003: GW well installation

- 2006:-2007 Free product recovery— 13,409-gal recovered
- 2006-2007: SVE system (5,245-gal removed)
- 2000-2005: Free phase petroleum HC (product recovery) operations – vacuum truck

IMPEDIMENTS TO CLOSURE T0603701540 as reported by regulatory agency



Review Conclusions T0603701540

- Review indicates:
 - Site was a shipping terminal and has operated as a fuel dispensing system since 1976. Site is almost all pavement or concrete.
 - Shallow GW at, or near, the site is not being used as a source of drinking water, irrigation water, or for other beneficial uses.
 - Site location is within industrial use area with other UST cases.
 - Model indicated that GW plume beneath site has reached steady-state conditions.
 - Report indicated off-site source and ASTs on-site may have contributed to the contamination.
- Discussion:
 - Review SCM and long term goals against current remedial approach
 - Review indoor air risk (now and future)
 - Continue to remove and monitor product levels
- Not a Potential Closure Candidate, appears on track

GOOD SAMARITAN HOSPITAL (T0603700594) 1102 6TH ST W, LOS ANGELES, CA 90017



Case Age: 20 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon

RP Identified by Regulator: Andrew

M.Taylor (Pacific Bell)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Hospital Building

Well Network: 12

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900170143

CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old • Limited oversight and RP involvement at

- the beginning of case
- No active remediation has been implemented
- GW contamination issue remains

		The same of the sa	
ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	♥ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010	7/13/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	11/16/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	10/15/2009	8/10/2009
ENFORCEMENT/ORDERS	Staff Letter	9/18/2009	9/18/2009
RESPONSE - REPORTS	Pilot Study/ Treatability Report	7/30/2009	7/30/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	6/23/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700594

Assessment last 5 years

- Semi-annual GWM
- Monitoring well installations
- Pilot/treatability study
- Few investigation reports in GeoTracker
- Risk assessment in progress
- Vapor intrusion evaluation in progress

Remediation last 5 years

- Multiphase pilot test
- Few investigation reports in GeoTracker

Assessment older than 5 years


- Initial subsurface investigation
- Monitoring well installations
- Few investigation reports in GeoTracker

- None
- Few investigation reports in GeoTracker

DRAFT: SEPT 3, 2010

IMPEDIMENTS TO CLOSURE T0603700594

as reported by regulatory agency



Review Conclusions T0603700594

- Review indicates:
 - Very high dissolved phase concentrations remaining → e.g. 17,000 ppb benzene in groundwater. Concentrations indicative of a (former?)
 NAPL site.
 - Active remediation still in development/testing stage
 - RP has reportedly proposed to perform the following tasks:
 - conduct risk assessment
 - conduct vapor intrusion evaluation
 - RP has also reported that site redevelopment (RD) is pending; to include underground parking i.e. large scale source removal with GW P&T
- Discussion:
 - Cleanup closure timeline should be evaluated, including next steps.

Potential for case closure dependent on remedial efforts, but not soon

SHELL #204-1944-0100 (T0603703277)3801 SEPULVEDA BLVD S, CULVER CITY, CA 90232



 Part of Charnock Well Field MTBE investigation area, monitoring as potential contributor

Possible Reasons Why This Case Is So Old

- Missing earlier reports
- GW contamination persists, but going down

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 19 years
Primary COC: Gasoline

RP Identified by Regulator: Joe Lentini (Equiva

Services)

Potential Media Affected: Drinking water supply

wel

Current Land Use: Shell Gas Station

Well Network: 22

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-07099 CASEWORKER: WEIXING TONG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2010
RESPONSE - REPORTS	Remedial Progress Report	5/3/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Remedial Progress Report	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009
ENFORCEMENT/ORDERS	Staff Letter	8/20/2009
OTHER REGULATORY ACTIONS	Site Visit / Inspection / Sampling	8/3/2009

Activities Conducted to Date Based on GeoTracker Info T0603703277

Assessment last 5 years

- Semi-annual GWM on 22 wells and Qrtly GWM on 15 wells
 - Remedial effectiveness monitoring
 - Address Charnock MTBE site
- MTBE investigation

Assessment older than 5 years

- Initial subsurface investigation
- Well installations
- No historical data in GeoTracker


Remediation last 5 years

- GWP&T
 - Not reached asymptotic state

Remediation older than 5 years

GWP&T

IMPEDIMENTS TO CLOSURE τ0603703277 as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY: 15, SEMI-ANNUALLY: 22

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

• Well Being Sampled During Remedial Action for Progress Assessment - groundwater pump and treat system is operating at the site

• Other - The site is within Charnock Well Field MTBE Investigation area

Review Conclusions T0603703277

- Review indicates:
 - Site is currently an active gas station
 - Older reports apparently missing from GeoTracker
 - Ongoing GWP&T from large well network → not asymptotic yet
 - Near by Charnock Well Field wells impacted with MTBE
 - Monitoring to determine if a source to this site now or in future
 - Unclear at this time if Shell has been identified as RP for Charnock site
- Discussion:
 - Latest GW monitoring results
 - Consider cleanup closure and timeline, what will be necessary to get case to closure?

Potential closure candidate (pending GWM results and trend)

MOBIL #18-E45 (FORMER #11-E45) (T0603702878) 14206 MULBERRY DR, WHITTIER, CA 90604



Primary COC: Gasoline
RP Identified by Regula

Case Age: 19 years

RP Identified by Regulator: Andrea Gray (Exxon

Mobil Oil Corp)

Potential Media Affected: Drinking water supply

aquifer

Current Land Use: Hannah Mobil/U-Haul

Well Network: 14

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-02988 CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old GW contamination (elevated benzene)

- Site conditions changed (i.e., GW elevations)
- No active remediation has occurred since 2002



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities Go	
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Site Conceptual Model	10/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	10/15/2010
RESPONSE - OTHER	Site Conceptual Model	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702878

Assessment last 5 years

- Semi-annual GWM
- Site conceptual model

Remediation last 5 years


- Groundwater pump outs only
 - Due to inability to negotiate access and subsequent reduction in overall concentrations, agency agreed that active remediation is not required

Assessment older than 5 years

- Initial subsurface investigation
- Monitoring well installations
 - Including SVE & offsite wells
- Soil gas survey investigation
- Vacuum extract test
- CPT/ROST/AS/GWP&T pilot tests

- UST system replacement
- Groundwater "pump outs"
- Dual phase extraction
 - Shut down due to change in groundwater elevations i.e. submerged screens

as reported by regulatory agency



Review Conclusions T0603702878

- Review indicates:
 - Site is currently an active gas station
 - Robust investigations and pilot tests have been conducted
 - Initial active remediation was ceased due to significant change in groundwater elevations, i.e. submerged screens
 - Lack of access agreements and a decreasing trend in COC concentrations in groundwater led to agency not requiring remediation to resume, utilizing pumpouts only
 - Benzene primary concern; residual still in the 3,000 ug/L range
- Discussion:
 - Need and benefit of remediation, or continue GW monitoring
 - Cleanup closure timeline to be evaluated

Not a Potential Closure Candidate, appears to be on track

SHELL (T0603701109)6101 OLYMPIC BLVD, LOS ANGELES, CA 90048



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Shell Oil

Company

Potential Media Affected: Soil Current Land Use: Shell Gas Station

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RIVOCB (REGION 4) (LEAD) - CASE #: 900480098

CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF - CASE #: 30466

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Case was transferred between agencies (LAFD and LA-RWQCB), limited oversight activities
- No case/site historical information
- Extent of contamination unknown site assessment (GWM) has only began

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/13/2010
RESPONSE - OTHER	4th Status Report	1/15/2010	1/13/2010
RESPONSE - OTHER	Other Report / Document	10/15/2009	10/15/2009
RESPONSE - OTHER	Other Report / Document	7/13/2009	7/13/2009
RESPONSE - OTHER	1st status 2009 report	4/15/2009	4/7/2009
RESPONSE - OTHER	Other Report / Document	1/15/2009	12/7/2009
ENFORCEMENT/ORDERS	Staff Letter	11/13/2008	11/13/2008
LEAK ACTION	Leak Reported	10/25/1991	
LEAK ACTION	Leak Discovery	9/7/1988	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701109

Assessment last 5 years

2008-ongoing: Quarterly status report

Remediation last 5 years

• None


Assessment older than 5 years

 2003: 4 soil samples taken during dispenser upgrade

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603701109

- Review indicates:
 - Limited reports/documents in GeoTracker. No historical case information.
 - In 2008, case was transferred from LA Fire Dept to LA-RWQCB.
 - The site is currently an operating gas station → if existing sensitive receptors are at risk from this site, they may have already been impacted.
- Discussion:
 - Next step → cleanup closure timeline, next steps, detailed site conceptual model?

Not a Potential Closure Candidate

TARGET STORE #T-292 (T0603701871)

950 33RD ST E, SIGNAL HILL, CA 90807



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Marilyn Guthrie

(Tesoro Refining Marketing Supp)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Target – no street view

Wells Network: 18

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-11132 CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF - CASE #: UNK

Possible Reasons Why This Case Is So Old

- Extent of GW plume remains undefined
- Free product in GW
- Source of contamination may still be on-site

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All A	Activities 🔻 Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2011	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010	4/19/2010
RESPONSE - REPORTS	Soil and Water Investigation Report	7/15/2010	
ENFORCEMENT/ORDERS	Staff Letter	6/9/2010	6/9/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	4/19/2010
RESPONSE - WORKPLANS	Pilot Study / Treatability Workplan	7/15/2009	7/7/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	10/21/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	4/15/2009	4/13/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	10/15/2008	10/15/2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701871

Assessment last 5 years

- Ongoing: GW monitoring (18 wells)
- 2009: Additional GW borings
- 2008: Static soil gas survey

• 2007-2009: SVF (soil

- 2007-2009: SVE (soil)
- 2005: Free product removal
- Unknown: In-situ bioremediation


Assessment older than 5 years

None

Remediation older than 5 years

• None

IMPEDIMENTS TO CLOSURE T0603701871 as reported by regulatory agency



Review Conclusions T0603701871

- Review indicates:
 - Free product has decreased steadily in GW remediation (SVE).
 - Extent of GW plume south of the site remains undefined.
 - On June 2010, regulator sent a directive letter to RP to take corrective action and concurring with the proposed remediation and activities to (1) assess the lateral extent of LNAPL in vicinity of MW-1A, and (2) to evaluate the effectiveness and feasibility of DPE as a source area remedial technology.
- Discussion:
 - Complete GW plume assessment
 - Evaluate remediation effectiveness to move case towards cleanup closure

Not a Potential Closure Candidate, appears to be on track

MOBIL #18-GP9 (FORMER #11-GP9) (T0603702870) 17122 PIONEER BLVD S, ARTESIA, CA 90701



Case Age: 18 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon – GeoTracker appears incorrect RP Identified by Regulator: Gene Ortega (Exxon

Mobil Oil Corp)

Potential Media Affected: Drinking water supply

aquifer

Current Land Use: Mobile Station/Nader Foodmart Well Network: ? - GeoTracker is not up to date

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-02871

CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT ACTION TYPE ACTION ACTION TYPE RESPONSE - REPORTS RESPONSE - REPORTS

Possible Reasons Why This Case Is So Old

- Lack historical data in GeoTracker
- Investigations ongoing → extent of contamination undefined
- Elevated GW contamination

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702870

Assessment last 5 years

- MTBE investigations
- Vapor sampling
- CAP/RAP
- Site conceptual model
- Additional offsite investigation proposed for 2010

Assessment older than 5 years

- Initial investigation reportedly "lost"
- VEW/MW well installation
- SVE pilot test
- Observation well installation

Remediation last 5 years

- Groundwater extraction
- Dual-phase extraction

- Over-excavation of UST pit
- Groundwater extraction
- Dual-phase extraction

as reported by regulatory agency

MOBIL #18-GP9	(FORMER #1	1-GP9) (T060	3702870) - <u>(M</u> A	NP)		
17122 PIONEER BLVD S ARTESIA, CA 90701 LOS ANGELES COUNTY LUST CLEANUP SITE					CLEANUP OVERSIGHT AGENCIES LOS ANGELES RIVIGUES (REGION 4) (LEAD) - CASE #: I-O; CASEWORKER: NIAN BAO LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO	
Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE REVIEW - THIS	CASE IS NOT READY					VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS TO CLOSURE						
SITE ASSESSMENT INCOMPLETE Extent of Contamination H	las Not Been Determined -	The extent of the groun	dwater contamination has i	not been fully defined.		
BENEFITS OF ADDITIONAL WORK						
Remove / Reduce Source A	hass - Need to reduce the o	contamination in the gro	undwater.			
SENSITIVE RECEPTORS LIKELY TO	BE IMPACTED AND TIME FRAM	E FOR IMPACT				
SENSITIVE RECEPTOR Groundwater	TIME FRAME FOR II Already Impact		COMMENTS High MTBE conce	ntration in the groundwat	er.	
Access of the second control of the second c				**************************************		

Review Conclusions T0603702870

- Review indicates:
 - Site is currently an active gas station
 - Lack historical site information in GeoTracker
 - Site has ongoing active remediation (Groundwater Pump and Treat)
 - Additional offsite subsurface investigation proposed for 2010
 - Fuel oxygenate case → inverse concentration relationship with TBA indicates MTBE degradation is occurring
- Discussion:
 - Review latest GWM results and trend
 - Cleanup closure consideration and timeline should be evaluated

<u>Potential closure candidate in a few years (pending GWM trend), appears</u> to be on track

EXXON #7-3591 (T0603702884)

1377 IMPERIAL HWY W, ATHENS, CA 90044



Possible Reasons Why This Case Is So Old

- GW contamination → current levels still exceeds MCLs
- Site was redeveloped into commercial use

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 19 years Primary COC: Gasoline

RP Identified by Regulator: Felicia Jones (Exxon

Mobil Oil Corp)

Potential Media Affected: Drinking water

supply Aquifer

Current Land Use: Commercial Complex

Well Network: 15

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-03027
CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - WORKPLANS	Interim Remedial Action Plan	2/11/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009

Activities Conducted to Date Based on GeoTracker Info T0603702884

Assessment last 5 years

Multiple well installation phases

- On- and offsite locations
- Well reinstallation post site redevelopment
- Interim RAP
- Semi-annual GWM

Assessment older than 5 years

- System removal
- Initial subsurface investigation
- Monitoring & DPE well installation
- Historical data missing from GeoTracker

Remediation last 5 years

- HIT DPE pilot test
 - High intensity test
- 2009 HIT 7-day DPE operations

- Passive NAPL bailing
- Dual-phase extraction pilot test

as reported by regulatory agency

1377 IMPERIAL HWY W ATHENS, CA 90044 LOS ANGELES COUNTY LUST CLEANUP SITE				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWGCB (REGION 4) (LEAD) - CASE #: 1-030; CASEWORKER: MAGDY BAIADY LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO		
Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	0F 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
	CASE IS NOT READY	FOR CLOSURE AS C	DF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
			PF, 8720/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
BENEFITS OF ADDITIONAL WORK Verify Remedial Action Effe	ctiveness - Cleanup in pro	gress	0F 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
BENEFITS OF ADDITIONAL WORK	ctiveness - Cleanup in pro	gress			COMMENTS	YIEW ALL POSSIBLE CLOSURE REVIEW VALUE

Review Conclusions T0603702884

- Review indicates:
 - Site has been redeveloped into a commercial center
 - Residual NAPL is an ongoing source to groundwater
 - Ongoing active remediation, i.e. HIT DPE completed late 2009
 - Two groundwater zones → shallow zone often dry; reduction in trend data/clarity
 - Redeveloped site; additional delay → many wells damaged requiring reinstallation at a later date
- Discussion:
 - Effectiveness of current remediation needs to be evaluated
 - Cleanup closure timeline and projections should be made in CSM

<u>Potential closure candidate pending post remediation effectiveness,</u> <u>appears to be on track</u>

EXXON #7-9477 (FORMER) (T0603703278) 11284 VENICE BLVD, CULVER CITY, CA 90230



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Andrew Gray (Exxon

Mobil Environmental Service)

Potential Media Affected: Drinking water supply

wells

Well used for Current Land Use: Venice Super

Petrol

Well Network: 19

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-07100
CASEWORKER: WEIXING TONG - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - REPORTS	Remedial Progress Report	*11/15/2009



Possible Reasons Why This Case Is So Old

- Part of Charnock Well Field MTBE investigation area with monitoring for potential contributors
- GW contamination → MTBE and TBA levels

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603703278

Assessment last 5 years

- Quarterly GWM
 - review includes adjacent
 Charnock Well Field MTBE
 Investigation area
- Shallow aquifer investigation

Remediation last 5 years

In-Situ Chemical Oxidation


Assessment older than 5 years

 Apparent missing files in GeoTracker?

Remediation older than 5 years

Apparent missing files in GeoTracker?

IMPEDIMENTS TO CLOSURE τ0603703278 as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY: 19

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

Other - The site is within Charnock Well Field MTBE Investigation area

Review Conclusions T0603703278

- Review indicates:
 - Site is currently an operating gas station
 - Primarily a MTBE/TBA case
 - Site is monitored as a potential contributor to the Charnock well
 - Older reports apparently missing from GeoTracker
 - Unclear if any earlier active remediation had occurred
 - Near Charnock Well Field wells impacted with MTBE
- Discussion:
 - Effectiveness of remediation -> current results and trend needs to be evaluated
 - Cleanup closure timeline should be evaluated in CSM

Not a Potential Closure Candidate, but appears to be on track

MOBIL #18-GG4 (T0603704589) 11009 ROSECRANS AVE E, NORWALK, CA 90650



Case Age: 17 years
Primary COC: Aviation

RP Identified by Regulator: Felicia F.Jones (Exxon

Mobil Oil Corp)

Potential Media Affected: Drinking water supply

aguifer/ production well

Current Land Use: Norwalk Mobil

Well Network: 15

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-02210

CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 002133-002210

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- GW contamination levels too high, especially for TBA
- Production well potentially at risk



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Site Conceptual Model	4/15/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
RESPONSE - REPORTS	Remedial Progress Report	7/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704589

Assessment last 5 years

- Semi-annual GWM
- Site conceptual model
- Apparent missing reports?

Remediation last 5 years

- Soil vapor extraction
- Groundwater P&T
- Apparent missing reports?

Assessment older than 5 years

- Initial subsurface investigation
- Monitoring well installation
- SVE well installation
- SVE pilot test
- CAP/RAP-finial remedial plan
- Apparent missing reports?

- System upgrade
- System removal
- Soil excavation
- Apparent missing reports?

IMPEDIMENTS TO CLOSURE T0603704589 as reported by regulatory agency

MOBIL	18-GG4 (Г0603704589)	- (MAP)				
NORWALK, LOS ANGE	OR ROSECRANS AVE E. RWALK, CA 90650 LOS ANGELES RWOCB (REGION 4) (LEAD) - CAS CASEWORKER: HA D. NIGHYEN LOS ANGELES COUNTY LOS ANGELES COUNTY LOS ANGELES COUNTY CASE WORKER: JOHN AWALKO CASEWORKER: JOHN AWALKO				DCB (REGION 4) (LEAD) - CASE #: R-02210 HA D. NGUYEN NTY - CASE #: 002133-002210		
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
IMPEDIMENTS T	TO CLOSURE ER IMPACTS	CASE IS NOT READY		DF 10/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
BENEFITS OF A	ADDITIONAL WORK						
Remove /	Reduce Source Ma	ass - SVEI GWPT system w	as being operated at th	e site since May 06 and has	removed 115 lbs of HC to	o date.	
SENSITIVE REC	EPTORS LIKELY TO B	E IMPACTED AND TIME FRAME	FOR IMPACT				
Groundwater			TIME FRAME FOR IMPACT Already Impacted			MENTS h MTBE and TBA.	

Review Conclusions T0603704589

- Review indicates:
 - Site is currently an active gas station.
 - Apparent missing historical reports
 - Offsite plume access issues
 - Active remediation, SVE/GWP&T, began in 2006 → residual TBA in groundwater is primary COC (~24,000 ppb, 1999)
 - Production well 1,320 feet from site → potential to impact this well requires additional monitoring
- Discussion:
 - Effectiveness of remediation need to continue to be evaluated
 - Cleanup closure timeline to be evaluated.

Not a potential closure candidate, on track

FAST GAS #538/TARGET T-290 (T0603705396) 2029 REDONDO BEACH BLVD W, GARDENA, CA 90247



Case Age: 19 years Primary COC: Gasoline

RP Identified by Regulator: Tesoro Petroleum Co. Potential Media Affected: Drinking water supply

Current Land Use: Parking Lot?

Well Network: 19

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-23243

CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- High source-area concentrations remain
- Currently undergoing remediation
- Site might have been redeveloped
- Does not appear to have much site activities at the beginning of case

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All	Activities 💌
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Soil and Water Investigation Report	8/25/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Remedial Progress Report	7/15/2010
ENFORCEMENT/ORDERS	Staff Letter	5/25/2010
RESPONSE -	Soil and Water Investigation Workplan	4/21/2010
RESPONSE - REPORTS	Risk Assessment Report	4/19/2010

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603705396

Assessment last 5 years

Additional monitoring wells (19 wells in total)

Remediation last 5 years


- In situ treatment
- Chemical bioremediation
- Oxidant injection points
- Additional DPE

Assessment older than 5 years

- No investigation reports available on GeoTracker
- Corrective Action Plan
- Remedial Action Plan

- No remediation reports available on GeoTracker
- **Dual Phase Extraction**
- Soil Vapor Extraction

IMPEDIMENTS TO CLOSURE TO603705396 as reported by regulatory agency



Review Conclusions T0603705396

- Review indicates:
 - Limited investigation reports available in GeoTracker
 - Elevated residual concentrations in source area
 - Active remediation currently being refocused
 - Potential for offsite municipal wells becoming impacted
 - Site appears to have been redeveloped currently vacant
- Discussion:
 - GeoTracker report compliance is an issue
 - Effectiveness of remediation cleanup closure timeline needs to be evaluated

Not a Potential Closure Candidate, on track

SHELL BRANDED SERV. STATION (FORMER) (T0603701215) 3151 CAHUENGA BLVD W, LOS ANGELES, CA 90068



Possible Reasons Why This Case Is So Old

- Lack of oversight apparent 8 years between leak discovery and oversight
- Continuous detections of MTBE, TPH-g, benzene and TBA in GW

NOTE: Data queried from GeoTracker and reviewed in August 2010

NOTE: Site is in EAOP

Case Age: 17 years Primary COC: Gasoline

RP Identified by Regulator: Ms. Deborah Pryor

(Shell Oil Product US)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Commercial Complex

Well Network: 10

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900680016

CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010	7/14/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/12/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/19/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/16/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/16/2009

Activities Conducted to Date Based on GeoTracker Info T0603701215

Assessment last 5 years

Ongoing: GW monitoring

Remediation last 5 years

Aug/Sept 2009: Ozone sparging remediation scheduled

Assessment older than 5 years

2002-ongoing: GW monitoring

Remediation older than 5 years

2002: Remedial (according to "Activities Report" in GeoT, but no reports)

IMPEDIMENTS TO CLOSURE τ0603701215 as reported by regulatory agency

SHELL	BRANDE	D SERVICE S	TATION (FO	RMER) (T0603	701215) - <u>(M</u> A	·P)	
LOS ANGE LOS ANGE	JENGA BLVD W LES, CA 90068 LES COUNTY ANUP SITE					CLEANUP OVERSIGHT LOS ANGELES RWQCE CASEWORKER: DE LOS ANGELES, CITY O CASEWORKER: 260	REGION 4) (LEAD) - CASE #: 900680016 ANIEL PIROTTON F
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
IMPEDIMENTS GROUNDWAT	TO CLOSURE	CASE IS NOT READY	FOR CLOSURE AS C	DF 8/19/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
		ve Other Cleanup Goal - E	levated TPHG, benzene,	MTBE, and TBA concentrat	tions.		
	ADDITIONAL WORK esignated Beneficia	al Uses - Elevated TPHG,	benzene. MTRF. and TRA	1 concentrations			
		E IMPACTED AND TIME FRAMI		CONCENTRACIONS.			
SENSITIVE REC	EPTOR	TIME	FRAME FOR IMPACT Idy Impacted		COMMENTS Concentrations above	ve MCLs.	

Review Conclusions T0603701215

- Review indicates:
 - Detections in MW8 is on the site of an active ARCO Gas Station – contamination could be from other current operation.
 - Contamination localized around MW-8 (across the site).
 - Given the age of the release (pre-1980s) and MTBE was not known to be used then, it is unlikely that MTBE impacted GW is a result of the release from this site.
 - Site appears to have been redeveloped.
- Discussion:
 - Effectiveness of GW remedial activity needs to be evaluated.
 - Cleanup closure timeline should be studied and mapped.

Potential closure candidate pending remedial results, on track

MOBIL #18-MAP (T0603704674) 20802 VERMONT AVE S, TORRANCE, CA 90502



Possible Reasons Why This Case Is So Old

- Multiple phases of UST removals and investigations
- Multiple phases of active remediation; ongoing
- •NOTE: Site has an open environmental case (Case #R-5290)

NOTE: Data queried from GeoTracker and reviewed in August 2010

NOTE: Site is in the EAOP

Case Age: 17 years
Primary COC: Gasoline

RP Identified by Regulator: Exxon Mobil Oil Corp

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Gas Station

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-05290 CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED

TORRANCE, CITY OF

CASEWORKER: RICHARD V. BONGARD - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go	•
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	4/30/2010
RESPONSE - REPORTS	Well Installation Report	7/15/2009	11/23/2009
RESPONSE - REPORTS	Remedial Progress Report	7/15/2009	7/20/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	7/20/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
ENFORCEMENT/ORDERS	Waste Discharge Requirements	4/20/2009	4/20/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/23/2009



Activities Conducted to Date Based on GeoTracker Info T0603704674

Assessment last 5 years

- Ongoing: GW monitoring
- 2009: Compliance soil sampling for USTs removal
- 2005: Three borings and soil sampling

Remediation last 5 years

- 2009: "Hot spot" excavation
- 2009: Chemical oxidation
- 2007-2008: SVE


Assessment older than 5 years

- 1996: Seven soil borings
- 1997: Three GW MWs
- 2000: Three GW MWs

Remediation older than 5 years

1998: Free product removal

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY : 7

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

WDR Permit Requirement - WDR for chemical injection requires quarterly monitoring and reporting.

Review Conclusions T0603704674

- Review indicates:
 - Site is an active gas station
 - Multiple phases of UST removals
 - Multiple phases of investigations and active remediation
 - Source removal and active remediation still occurring
 - Case appears to be on right track, but not ready to close until remediation effectiveness has been evaluated and any rebound monitored, especially benzene concentrations
- Discussion:
 - Cleanup closure timeline --> consider SCM or closure summary to pull together all current site info
 - Unclear if indoor air assessment has been completed
- Potential closure candidate in a couple of years, on track

MOBIL OIL CORP S.S #18-LKA (T0603704754) 6100 SEPULVEDA BLVD, CULVER CITY, CA 90230



Possible Reasons Why This Case Is So Old

- Little activity between 1994 and 2003
- No active remediation until 2003/05
- Still have elevated MTBE and TBA concentrations in groundwater

Case Age: 17 years
Primary COC: Gasoline

RP Identified by Regulator: Exxon Mobil Oil

Corp

Potential Media Affected: Aguifer used for

drinking water supply

Current Land Use: Gas Station

Well Network: 18

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-07139
CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 006907-007139
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	→ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Remedial Progress Report	4/1/2010
ENFORCEMENT/ORDERS	Staff Letter	3/30/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010
RESPONSE - REPORTS	Remedial Progress Report	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009
RESPONSE - REPORTS	Remedial Progress Report	7/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
RESPONSE - REPORTS	Remedial Progress Report	7/3/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - OTHER	Site Conceptual Model	4/15/2009



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704754

Assessment last 5 years

- Ongoing: GW monitoring (18 wells)
- 2006: Delineate extent of MTBE and TBA plume

Remediation last 5 years

- 2005-ongoing: SVE
- 2006: GW Pump and Treat
- As of April 2009, removed 1,087lbs of hydrocarbon vapors and 4.9-million gals of GW

Assessment older than 5 years

 2002-2006: Multiple phases of assessment, including three soil borings and installation of 18 GW monitoring

Remediation older than 5 years

 2003: 3-days interim remedial event and feasibility test using multiphase extraction system (MxT) – removed 175-lbs of hydrocarbon vapor and 14,900-gal GW

as reported by regulatory agency

OS ANGE	ULVEDA BLVD CITY, CA 90230 ELES COUNTY EANUP SITE					CASEWORKER:	CB (REGION 4) (<i>LEAD</i>) - CASE #: R-07139 JAY HUANG ITY - CASE #: 006907-007139
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	OF 7/27/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
	TER IMPACTS vater Impacted Abo	ve Other Cleanup Goal - e	levated MTBE and TBA c	oncentrations			
BENEFITS OF	ADDITIONAL WORK						
		ass - SVE and groundwate	r extraction ongoing				
Remove	/ Reduce Source Mi	ass - SVE and groundwate					

GROUNDWATER MONITORING FREQUENCY

F OF WELLS MONITORED - SEMI-ANNUALLY : 18

Review Conclusions T0603704754

- Review indicates:
 - Multiple phases of assessment
 - Site well characterized and undergoing remediation
 - Current remediation appears appropriate
 - Rebound testing to confirm efficiency and future operational needs
- Discussion:
 - Effectiveness of active remediation
 - Post remedial monitoring schedule
 - Other data gaps
 - Closure timeline

Potential Closure Candidate (pending monitoring results), on track

76 PRODUCTS STATION #4682 (T0603702399) 23706 VICTORY BLVD, WOODLAND HILLS, CA 91367



Possible Reasons Why This Case Is So Old

- Groundwater impacted (still have detections in 2009)
- No active remediation implemented
- Limited site activities at the beginning
- Site assessment incomplete

Case Age: 16 years EAOP Site

RP Identified by Regulator: Liz Sewell (Tosco/76

Products Team)

Primary COC: Gasoline

Media of Concern: Drinking Water Supply Aquifer

Current Land Use: Union 76 Gas Station

Well Network: 12

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913670634 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	0
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Pilot Study/ Treatability Report	6/22/2010
RESPONSE - REPORTS	Well Installation Report	2/11/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010
RESPONSE - WORKPLANS	Corrective Action Plan / Remedial Action Plan	10/12/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702399

Assessment last 5 years

- Semi-annual GWM
- Additional investigations
- On-and offsite well installations
- 2010 Follow-up investigation pending

Remediation last 5 years

None

Assessment older than 5 years

- Initial subsurface investigation
- Well installation
- Missing data in GeoTracker

- Excavation and removal of hydrocarbon-impacted cesspool
- Missing data in GeoTracker

IMPEDIMENTS TO CLOSURE T0603702399

as reported by regulatory agency



Review Conclusions T0603702399

- Review indicates:
 - Slow initial activity by RP; current activities indicate more responsive RP
 - Site is currently an active gas station
 - No active remediation has been implemented, despite being warranted
 - Future, offsite assessments proposed → plume not adequately defined offsite
 - Municipal wells 26,000 ft away → not likely a considerable threat once plume is well defined and is stable
 - Agency is requiring "hot spot" remediation according to GeoTracker
- Discussion:
 - Complete assessment, and evaluate need and benefit of remediation
 - Cleanup closure timeline seems on track as part of EAOP

Not a potential closure candidate

MOBIL #11-FXV (T0603702424) 4528 SEPULVEDA BLVD, SHERMAN OAKS, CA 91403



Possible Reasons Why This Case Is So Old

- Little activity at the beginning of the case
- GW plume not fully defined offsite
- Onsite vadose soils remediated
- Persistent GW contamination

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 15 years (appears to be 20 years)

Primary COC: Gasoline

RP Identified: Lee Hanley (Mobil Oil Corp)
Potential Media Effected: Aquifer used for

drinking water supply

Current Land Use: Gas Station

Well Network: 12

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 914030316 CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Remedial Progress Report	10/5/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
RESPONSE - REPORTS	Remedial Progress Report	7/2/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Remedial Progress Report	2/23/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	9/26/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2008

Activities Conducted to Date Based on GeoTracker Info (T0603702424)

Assessment last 5 years

- Ongoing: GW monitoring
- 2008: Soil and water investigation

Remediation last 5 years

- 2009: Remedial progress report
- Ongoing SVE


Assessment older than 5 years

- 2002: Soil and water investigation
- 1992-ongoing: GW monitoring
- 1992-2002: Multi phases of assessment
- 1990: Soil borings and vapor extraction wells installed

- 2005: SVE with Other, MxT system
- 1996-1997: ORC
- 1995: Vapor extraction test

IMPEDIMENTS TO CLOSURE (T0603702424)

as reported by regulatory agency




GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - SEMI-ANNUALLY : 12

Review Conclusions T0603702424

- Review indicates:
 - Onsite conditions have been well assessed
 - Offsite plume extents not completely defined
 - Source area remediation appears effective and has been shut down, leaving P&T system on for Groundwater
- Discussion:
 - Offsite plume definition, address "hot" offsite well → offsite "hot" well's data appears somewhat anomalous
 - Offsite indoor air risk potential?
 - Based on completing site contaminant characterization and effects of rebound on GW concentrations, closure potential high
 - Cleanup closure timeline should be addressed in a CSM
- Potential Closure Consideration in a few years, on track

TOSCO – 76 STATION #2021 (T0603701110) 8755 3rd ST W, LOS ANGELES, CA 90048



Case Age: 15 years
Primary COC: Gasoline

RP Identified by Regulator: Shari London

(Conoco Phillips Company)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: 76 Station Robertson

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900480107
CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES, CITY OF - CASE #: 3377

CASEWORKER: ELOY LUNA - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Multiple tank and associated parts removed over different periods since 1989
- Lateral extent of GW contamination not fully defined
- GW contamination (TPH-g and MTBE) above cleanup goals
- Transferred between agencies

NOTE: Data queried from GeoTracker and reviewed in August 2010



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009
RESPONSE - REPORTS	Site Assessment Report	9/3/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009

Activities Conducted to Date Based on GeoTracker Info T0603701110

Assessment last 5 years

- 2006-current; GWM
- 2006: Site assessment and GWM
- Assessment performed 2009

Remediation last 5 years

2005: 550-gal UST removed

Assessment older than 5 years


2004: Six soil borings and GW samples

Remediation older than 5 years

 1999: 185-tons contaminated soil removed

IMPEDIMENTS TO CLOSURE T0603701110

as reported by regulatory agency



Review Conclusions T0603701110

- Review indicates:
 - Site was transferred from LA City to LA-RWQCB (2006)
 - Current GWM indicates high levels of TPH-g, MTBE and TBA → localized around MW-8
 - Overall GWM showed decreasing trends
 - Site is an active gas station
 - Report indicates GW contamination extent is not fully defined at southeast portion of the site
- Discussion:
 - Groundwater monitoring trend → evaluate any benefits of remediation
 - Closure consideration a possibility? Location of sensitive receptors threatened by the site?

Closure consideration in a few years (pending GWM trend), I on track

ARCO #0166 (T0603701007) 105 AVENUE 52N, LOS ANGELES, CA 90042



Case Age: 26 years Primary COC: Gasoline

RP Identified: Ms. Vesta Slayman (ARCO

Products Corp)

Media of Concern: Aquifer used for

drinking water supply

Current Land Use: 76 Gas Station

Well Network: 3

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900420089 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



MTBE, TBA and benzene, and free product in GW

• Potential co-mingle plume from gas station across (Shell) -> T0603701002 (Shell #204-4531-5409)



6/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701007

Assessment last 5 years

- Ongoing: GW monitoring (3 wells)
- Additional assessment proposed early 2010

Assessment older than 5 years

2003-2009: GW monitoring

Remediation last 5 years


2004-2006: SVE with Other (approximately 300-lbs HC removed)

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE TO603701007

as reported by regulatory agency



Review Conclusions T0603701007

- Review indicates:
 - Site is currently an active gas station.
 - Persistent free product in GW.
 - Site might have commingle plume issue from adjacent gas station.
 - On March 2010, RP proposed investigation to determine residual petroleum HC mass remaining beneath suspected source area.
- Discussion:
 - Appropriate remediation (free product in GW)
 - Adjacent gas station case (T0603701002 Shell #204-4531-5409)
 - Cleanup closure timeline should be evaluated in Site Conceptual Model

Not a Potential Closure Candidate, appears to not be on track

SHELL (T0603702223) 6761 RESEDA BLVD, RESEDA, CA 91335



Possible Reasons Why This Case Is So Old

- Appears no activity between 1985 to 2002
- NAPL case
- Site redeveloped, now and EZ Lube
- Residual source material left in place
- Effectiveness of remediation unclear

Case Age: 25 years

RP Identified by Regulator: Equiva Services,

LLC (Shell)

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking

Current Land Use: EZ Lube

Well Network: 23

CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913350716 CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF CASEWORKER: elo

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Preliminary Site Assessment Report	6/30/2008
ENFORCEMENT/ORDERS	Staff Letter	4/28/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	*6/30/2008
RESPONSE - REPORTS	Preliminary Site Assessment Report	*6/30/2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702223

Assessment last 5 years

Ongoing: GW monitoring (23 wells)

Remediation last 5 years

2008: DPE


Assessment older than 5 years

- 2004: Received AQMD and industrial wastewater discharge permits
- 2002: Additional site assessments, and extraction wells installation
- 1999: Phase II site assessment
- 1998: Soil samples

- 2004-2008: DPE system start-up (interrupted in 2006)
- 2002: Dual-phase extraction (DPE) test

IMPEDIMENTS TO CLOSURE T0603702223

as reported by regulatory agency



Review Conclusions T0603702223

- Review indicates:
 - Site has been adequately assessed and the plume defined.
 - Remediation history not clear based on available info in GeoTracker.
 - In July 2009, RP proposed enhanced biodegradation, followed by monitored natural attenuation (MNA) as a supplemental corrective action.
 - Historical trends indicate natural attenuation is occurring, but at a slow rate.
 - NAPL and benzene concentrations in groundwater are primary issues.
- Discussion:
 - Remediation effectiveness, other alternatives for moving case along
 - Residual NAPL potential long term source
 - Closure evaluation should be discussed in a detailed SCM for this site.
- Not a Potential Closure Candidate, appears to not be on track

MOBIL #18-KCM (T0603702983)

18501 SOLEDAD CANYON RD, SANTA CLARITA, CA 91351



Case Age: 24 years

RP Identified by Regulator: Lee Hanley (Mobil Oil

Corp)

Primary COC: Gasoline

Media of Concern: Drinking water supply aquifer

Current Land Use: Mobil Gas Station

Well Network: Undefined in GT; 13 in 09 GWM rpt

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-04508

CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- GW contamination \rightarrow elevated levels
- Case was transferred between agencies

		ALC: NOT THE	The second	X EX
				esilai.
	Month	STATISTICS TO		
River of		A SPECIAL	- a 100	PER
	*50	20 B		
THE PERSON NAMED IN COLUMN		1		
3,000,000	Marketo A.	And the second	- 4 45 17 14	

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Site Conceptual Model	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - OTHER	Site Conceptual Model	1/21/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702983

Assessment last 5 years

- Well installation
- Plume travel time assessment
- Site conceptual model
- CAP/RAP
- Apparent missing documents?

Remediation last 5 years

- GWP&T
 - Recent moratorium by SCAQMD i.e. no permit reissues being allowed as of 2009
 - Temporarily shut down

Assessment older than 5 years

- Initial subsurface investigation
- Apparent missing documents?

Remediation older than 5 years

 Apparent missing reports, i.e. not clear when GWP&T began or if other remediation occurred

IMPEDIMENTS TO CLOSURE T0603702983 as reported by regulatory agency

MOBIL	#18-KCM	(T060370298	3) - (MAP)				
18501 SOLEDAD CANYON RD SANTA CLARITA, CA 91351 LOS ANGELES COUNTY LUST CLEANUP SITE					CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. I-045 CASEWORKER: JAY HUANG LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO		
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS O	OF 7/23/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE				THE COLUMN TWO IS NOT THE OWNER.		
GROUNDWAT • Groundw		ve Other Cleanup Goal - e	levated MTBE concentra	tions in groundwater			
BENEFITS OF	ADDITIONAL WORK						
Remove	/ Reduce Source M	ass - groundwater extract	ion system operational				
SENSITIVE RE	CEPTORS LIKELY TO I	BE IMPACTED AND TIME FRAME	E FOR IMPACT				
SENSITIVE REC	EPTOR	TIM	NE FRAME FOR IMPACT	***************************************	COMMENTS		
Municipal W	/ell	1-1	10 Years		1372 ft. to produ	uction well	
Groundwate			eady Impacted				

Review Conclusions T0603702983

- Review indicates:
 - Site is currently an active gas station
 - GW Pump & Treat only remediation → currently shut down due to moratorium by SCAQMD
 - Municipal well located 1372 feet from site → potential to impact this well; future monitoring required
 - Persistent MTBE and TBA → ratio of MTBE to TBA suggests that biodegradation has been effective in reducing MTBE concentrations
- Discussion:
 - Effectiveness of current remediation should be evaluated
 - Groundwater cleanup timeline should be addressed

Not a Potential closure candidate, appears to not be on track

MOBIL #11-LM9 (T0603700727) 2608 TEMPLE ST, LOS ANGELES, CA 90026



Case Age: 23 years

Primary COC: Aviation (GeoT) -> Gasoline RP Identified by Regulator: Lee Hanley

(Exxon Mobil Oil Corp)

Potential Media Affected: Aquifer used

for drinking water supply

Current Land Use: Isaac Mobil Gas

Station (Google Map)

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900260243 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF - CASE #: 15441

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- TPH-g, benzene, MTBE and TBA still detected in GW as of June 2009
- Potential vapor intrusion issues
- Extent of contamination undefined
- •Multiple releases over different periods (1987, 2000)

ACTIVITIES REPORT ACTION TYPE ACTION DATE RESPONSE - REPORTS RESPONSE - REPORTS Monitoring Report - Semi-Annu 4/15/2010 4/12/2010 RESPONSE - REPORTS RESPONSE - REPORTS Monitoring Report - Quarterly 1/25/2010 Monitoring Report - Quarterly 10/15/2009 10/19/2009 RESPONSE - REPORTS 7/16/2009 6/15/2009 6/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700727

Assessment last 5 years

- 2007: 3 soil gas sampling
- 2006: Post-remediation soil gas sampling
- 2005: Additional MWs installed and soil sampled
- 2003-ongoing: GW monitoring (12 wells)

Assessment older than 5 years

 2003-2004: Multiple phases of assessment (including installation of 6 MWs)


Remediation last 5 years

- 2006: Interim remedial action using MxT (removed and oxidized 1,005-lbs HC vapor)
- 2005-2006: Interim remedial action using MxT system (removed and oxidized 2,561-lbs HC vapor)
- 2005: Multiphase extraction feasibility test performed (MxT system removed and oxidized 647-lbs of HC vapor and extracted 2,043-gal GW); SVE w/Other

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603700727 as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - SEMI-ANNUALLY : 12

Review Conclusions T0603700727

- Review indicates:
 - Site is currently an active gas station.
 - Incomplete off-site assessment due to access issue to the south (residential).
 - Interim remedial actions were performed in 2005 to reduce residual soil gas concentrations in the southern portion and mitigate potential migration of soil gas to off-site property.
 - Case was under EAOP, but RB withdrew it from the program due to <u>indoor air vapor intrusion concern</u>.
- Discussion:
 - VI potential/issue (active gas station)
 - Must complete site assessment and/or remediation to move case toward cleanup closure

Not a Potential Closure Candidate, appears not on track

MOBIL 18-MLT (T0603701878) 1990 WARDLOW RD E, LONG BEACH, CA 90807



Case Age: 23 years

Primary COC: Waste/Motor/Hydraulic/Lube oils **RP Identified by Regulator:** Andrew Gray (Exxon

Mobil Environmental Service)

Potential Media Affected: Drinking water supply

aquifer

Current Land Use: Mobil Gas Station

Well Network: 6

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: 908070307

CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Investigation activities did not begin until 2004
- Elevated benzene and MTBE in GW
- Extent of contamination undefined (off-site)

		AND DESCRIPTION OF THE PARTY OF	
ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	1/25/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	11/23/2009
RESPONSE - OTHER	Site Conceptual Model	7/15/2009	7/20/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/20/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701878

Assessment last 5 years

- Semi-annual GWM
- Well installations
- Site conceptual model
- Interim RAP
- No investigation reports in GeoTracker

Assessment older than 5 years

- Initial subsurface investigation
- No investigation reports in GeoTracker


Remediation last 5 years

- None
- No reports in GeoTracker

- None
- No reports in GeoTracker

IMPEDIMENTS TO CLOSURE T0603701878

as reported by regulatory agency



Review Conclusions T0603701878

- Review indicates:
 - Active investigations did not begin until 2004
 - Site is currently an active gas station
 - Current groundwater samples contain high concentrations of benzene and MTBE
 - No investigation reports in GeoTracker (only QMR's)
 - RP reportedly proposes to conduct the following:
 - Offsite well installation
 - SCM for offsite plume extent
 - Install and operate onsite SVE/AS system
- Discussion:
 - Benefits of remediation
 - Investigation approach and cleanup closure timeline to be evaluated

Not a Potential Closure Candidate, appears not on track

CHEVRON #9-6594 (T0603704837)2600 MANCHESTER BLVD W, INGLEWOOD, CA 90305



Case Age: 23 years

Primary COC: Gasoline, motor/hydraulic oil RP Identified by Regulator: Chevron USA Potential Media Affected: Drinking water

supply aquifer/ production wells

Current Land Use: Fenced and Paved Vacant

Corner Lot
Well Network: 3

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-09600

CASEWORKER: JIMMIE WOO - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009

Possible Reasons Why This Case Is So Old

- Extent of contamination undefined
- Source to groundwater not removed (NAPL)
- Limited site activities at the beginning of case

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704837

Assessment last 5 years

- Ongoing: GW monitoring (3 wells)
- Multiple soil and groundwater investigations
- Closure request
- Site Conceptual Model
- Feasibility Study
- Interim Remedial Action Plan

Assessment older than 5 years

No reports with background sections in GeoTracker

Remediation last 5 years

 No reports with background sections in GeoTracker

Remediation older than 5 years


No reports with background sections in GeoTracker

DRAFT: SEPT 3, 2010

IMPEDIMENTS TO CLOSURE T0603704837

NOT UPDATED

as reported by regulatory agency



Review Conclusions T0603704837

- Review indicates:
 - Site is currently vacant
 - Evaluation of potential for case closure requires access to remediation data which is currently not available.
 - Site contamination and extent is inadequately defined.
 - Source for continued impacts to groundwater not controlled,
 i.e., mobile NAPL present.
 - Multiple documents with pertinent information not in GeoTracker.
 - Consultant requested case closure in 2006
- Discussion:
 - Need for additional assessment and benefit of remediation described in detailed CSM Report
 - Cleanup closure timeline needs to be evaluated

Not a Potential closure consideration, appears to not be on track

MOBIL #11-MKK (T0603704802)

11861 PARAMOUNT BLVD, DOWNEY, CA 90241



Case Age: 23 years Primary COC: Gasoline

RP Identified by Regulator: Felicia Jones

(Exxon Mobil Oil Corp)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Gas Station

Well Network: 8

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RIWCOS (REGION 4) (LEAD) - CASE #: R-09348

CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 09530-09348

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



Possible Reasons Why This Case Is So Old

- Little activity between 1987 and 2004?
- No active remediation conducted, dual phase testing performed
- Offsite plume extent not defined

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	→ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Site Conceptual Model	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - OTHER	Site Conceptual Model	4/15/2010
RESPONSE - REPORTS	Remedial Progress Report	2/27/2010
RESPONSE - REPORTS	Well Installation Report	2/11/2010
RESPONSE - OTHER	Site Conceptual Model	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
CLEANUP ACTION	Dual Phase Extraction	11/9/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	10/15/2009

Activities Conducted to Date Based on GeoTracker Info T0603704802

Assessment last 5 years

- Semi-annual GWM
- Sensitive receptor survey
- Soil borings/monitoring wells
- Interim RAP
- Site conceptual model

Remediation last 5 years

- Over purge (MW-5)
- AS/SVE pilot test
- Not known if full system operation has been implemented
- **Dual Phase test performed**


Assessment older than 5 years

- None
- Apparent missing reports?

- None
- **Apparent missing reports?**

IMPEDIMENTS TO CLOSURE T0603704802

as reported by regulatory agency



Review Conclusions T0603704802

- Review indicates:
 - Active site investigation appears to have begun in 2004/2005
 - Unclear if all historical documents were uploaded to GeoTracker
 - Unclear if full time system operation will be implemented for the recent AS/SVE pilot test
 - Offsite groundwater plume
 - Access issues has slowed this investigation
- Discussion
 - System start up and operation → effectiveness of remediation
 - Data gaps needed for closure criteria
 - Cleanup closure timeline needs to be evaluated

Not a potential closure candidate, does not appear to be on track

SOUTHWEST STREET MAINT YARD (T0603701091) 5860 WILTON PL S, LOS ANGELES, CA 90047



Case Age: 23 years
Primary COC: Kerosene

RP Identified by Regulator: Mike Mulhern

(Bureau of Engineering)

Potential Media Affected: Aquifer used for drinking

water

Current Land Use: Site is behind the residential

homes – no street view **Well Network:** 8 wells

Possible Reasons Why This Case Is So Old

- Appears to have limited oversight at the beginning of the case
- Free product in GW

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900470061 CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	Go	*1
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - OTHER	Site Conceptual Model	8/5/2009	8/5/2009
RESPONSE - REPORTS	Remedial Progress Report	8/5/2009	8/5/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	8/5/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/20/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701091

Assessment last 5 years

 Ongoing: GW monitoring (8 wells)

Remediation last 5 years

 2009: Multi-phase extraction (soil vapor, free product and GW)

Assessment older than 5 years

- 2003: GW wells installation
- 1990s-ongoing: GW monitoring
- 1992-1998: Various site assessments
- 1988: Site assessments
- 1987: Soil samples during removal

- 2003: Multi-phase extraction and treatment system
- 1990s: Vacuum enhanced free product recovery

IMPEDIMENTS TO CLOSURE T0603701091 as reported by regulatory agency

SOUTHWEST ST	REET MAINT	YARD (T060	3701091) - <u>(M</u> /	AP)		
5860 WILTON PL S LOS ANGELES, CA 90047 LOS ANGELES COUNTY LUST CLEANUP SITE					CLEANUP OVERSIGHT LOS ANGELES RWQCI CASEWORKER: DI LOS ANGELES, CITY O CASEWORKER: ph	B (REGION 4) (LEAD) - CASE #: 900470061 ANIEL PIROTTON F
Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	DF 8/19/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS TO CLOSURE						
GROUNDWATER IMPACTS • Groundwater Impacted Above	e Other Cleanup Goal - F	ree product.				
BENEFITS OF ADDITIONAL WORK						
Protect Designated Beneficial	al Uses - Free product.					
SENSITIVE RECEPTORS LIKELY TO B	E IMPACTED AND TIME FRAM	E FOR IMPACT				
SENSITIVE RECEPTOR Groundwater		TIME FRAME FOR Already Impac			COMMENTS	

Review Conclusions T0603701091

- Review indicates:
 - Activities Report in GeoTracker indicates many activities conducted on the site (e.g., multiple SCM reports produced between 2004-2009)
 - Site is located adjacent to residential homes
 - July 2009 GWM report indicates no free product, and NDs for TPH-g, TPH-d and BTEX. MTBE was detected at 15-ug/L.
- Discussion:
 - Need for additional GWM → review recent report/results trend for closure consideration

Potential Closure Consideration. Appears not to be on track

MOBIL #18-LLR (T0603700620) 989 SOUTH WESTERN AVE, LOS ANGELES, CA 90019



Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Greg Barton (Exxon Mobil Refining and Supply Co)
Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Bank Well Network: 19

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (*LEAD*) - CASE #: 900190107

CASEWORKER: <u>DANIEL PIROTTON</u> - SUPERVISOR: NONE SPECIFIED
LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Offsite NAPL plume
- Only periodic remediation (onsite only)
- Both active and passive
- Free product in GW

			Anno Anno Maria Con Angelona
ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - OTHER	Site Conceptual Model	4/15/2010	4/20/2010
RESPONSE - REPORTS	Remedial Progress Report	1/21/2010	1/21/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	1/21/2010
RESPONSE - OTHER	Site Conceptual Model	10/15/2009	10/19/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700620

Assessment last 5 years

- Semi-annual GWM
- No investigation reports in GeoTracker

Remediation last 5 years

- Dual phase extraction/Air sparge
 - Periodic application


Assessment older than 5 years

- Initial subsurface investigation
- Monitoring well installations
 - Including extraction wells
- No investigation reports in GeoTracker

- Dual phase extraction
 - Periodic application

IMPEDIMENTS TO CLOSURE T0603700620

as reported by regulatory agency



Review Conclusions T0603700620

- Review indicates:
 - Offsite NAPL plume
 - Only periodic remediation efforts
 - Active DPE and air sparge
 - Passive NAPL bailing
- Discussion:
 - Remediation (free product in GW)
 - Cleanup closure timeline

Not a closure candidate consideration, appears to not be on track

NOTE: Address in GeoTracker is incorrect

Shows: 989 Western Ave W

- Correct: 989 South Western Ave

LA DPW WESTERN DISTRICT-H.Q (T0603700617)5898 VENICE BLVD, MID CITY, CA 90019



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Mr. Dat Quach

(LADWP)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: LADPW Building

Well Network: 32 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900190070

CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

n nother

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Large mass released on site
- Still has free product in GW
- MTBE issue in GW

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	∨ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	2/23/2010
RESPONSE - OTHER	Site Conceptual Model	7/15/2009	7/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - OTHER	Site Conceptual Model	4/15/2009	4/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/15/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700617

Assessment last 5 years

- Ongoing: GW monitoring (32 wells)
- 2004: Additional GW wells

Remediation last 5 years

- 2004-2009: Pump-and-Treat (~7 million gal treated)
- 2008: Catalytic Oxidizer at PSC Yard
- 2004: SVE/GW remediation, and pump-and-treat

Assessment older than 5 years


- 2001: Pilot study for remediation and additional GW wells
- 1990: Characterize extent of soil and GW contamination
- 1989: 2 MWs and test for free product recovery
- 1987: Soil and GW investigation (Phase I and II) including 10 soil borings, soil vapor and 12 GW wells

- 1997: SVE at WDH Yard
- 1988-1996: Free product recovery (12,881-gal removed)
- 1989: Product-recovery pump at EW5
- 1988-1989: Auto skimmer at MW1

DRAFT: SEPT 3, 2010

NOT UPDATED

IMPEDIMENTS TO CLOSURE τ0603700617 as reported by regulatory agency



Review Conclusions T0603700617

- Review indicates:
 - Only monitoring reports available in GeoTracker.
 - Large amount of mass (estimated 51,627-gal) was released at the Site.
 - Active remediation on-site since late 1980s, however GW
 contamination remains high any active release source on-site?
- Discussion:
 - Effectiveness of remediation needs to be evaluated
 - Any active release source on-site should be investigated
 - Cleanup closure timeline needs to be addressed

Not a Potential Closure Candidate, not on track for closure soon

CHEVRON #9-9266 (T0603701393) 1732 LINCOLN BLVD, SANTA MONICA, CA 90404



Case Age: 17 years
Primary COC: Gasoline

RP Identified by Regulator: Y.M. Tuan (Chevron) **Potential Media Affected:** Drinking water supply

aquifer

Current Land Use: Chevron Station

Well Network: 11

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: 904040125A CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED SANTA MONICA, CITY OF

CASEWORKER: MONICA HANLEY - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Site has unstable plume migrating offsite
- Elevated GW contamination (TBA)
- Limited remediation performed



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2010	6/3/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	11/16/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	5/18/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	2/26/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701393

Assessment last 5 years

- Semi-Annual GWM
- Interim RAP
- Apparent missing reports?

Remediation last 5 years

MNA is current approach

Assessment older than 5 years

- Soil and groundwater investigation
- Interim RAP
- Apparent missing reports?

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE TO603701393

as reported by regulatory agency

CHEVR	ON #9-92	66 (T06037013	393) - <u>(MAP)</u>				
SANTA MONICA, CA 90404 OS ANGELES COUNTY				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 9040407 CASEWORKER: JAY HUANG SANTA MONICA, CITY OF CASEWORKER: MONICA HANLEY			
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS	OF 7/27/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
GROUNDWAT	vater Contamination	n Plume Not Stable or Dec ve Other Cleanup Goal - e		0 0 77			
BENEFITS OF A	ADDITIONAL WORK						
• Remove	/ Reduce Source Ma	ass - monitor natural atte	nuation				
CENCITIVE DE	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAMI	E FOR IMPACT				
SEMPILIAE KE							

Review Conclusions T0603701393

- Review indicates:
 - Site is currently an active gas station
 - Unstable plume; lateral migration apparently occurring
 - Offsite plume; unsure if extent is defined?
 - Current approach is MNA (monitored natural attenuation)
 - Apparent missing reports in GeoTracker
 - GWM Report (Nov 2009) indicates high to relatively high detections for TPH-g, MTBE, TBA and BTEX
- Discussion:
 - Consider benefits of incorporating other remediation

Not a Potential Closure Candidate, Not on track

PETRO DIAMOND TERMINAL COMPANY (T0603701940) 1920 LUGGER WY, LONG BEACH, CA 90813



Possible Reasons Why This Case Is So Old

- Bulk terminal plant
- Extensive impacts to soil and GW
- Widespread NAPL
- Site use to remain similar
- Effectiveness of remediation
- Free product

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 17 years
Primary COC: Gasoline

RP Identified: James J. Keating (Petro-

Diamond Terminal Company)

Current Land Use: Petro-Diamond Inc **Potential Media Effected:** Aguifer used for

drinking water supply **Well Network:** 19

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130261
CASEWORKER: MERCEDES HSU - SUPERVISOR: NONE SPECIFIED
LONG BEACH/SIGNAL HILL, CITIES OF
CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi- Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi- Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi- Annually	5/15/2009
RESPONSE - REPORTS	Monitoring Report - Semi-	12/16/2008

Activities Conducted to Date Based on GeoTracker Info (T0603701940)

Assessment last 5 years

Ongoing: GW monitoring

Remediation last 5 years

 Ongoing: Remediation (free product recovery)


Assessment older than 5 years

- 2002-ongoing: GW monitoring
- 1986, 1992, 1999: Site assessment

- 2004: Dual-phase extraction
- 2001-2004: Vapor extraction system
- Free product recovery

IMPEDIMENTS TO CLOSURE (T0603701940)

as reported by regulatory agency



Review Conclusions T0603701940

- Review indicates:
 - Bulk Terminal site large, complex, inaccessible
 - Extensive impacts to soil and groundwater over time
 - Site use to remain the same for foreseeable future
 - Widespread NAPL
 - Sensitive receptors identified
 - All source identified, stopped
 - Plume boundary monitoring
- Discussion:
 - SCM/FS/RAP submittals/updates
 - Effectiveness of remediation needs to be evaluated
 - Long term monitoring plan
- Not a Potential Closure Candidate, not on track

TEXACO (T0603702476)

14344 VENTURA BLVD, SHERMAN OAKS, CA 91423



Case Age: 17 years Primary COC: Gasoline

RP Identified by Regulator: Y.M. Tuan (Chevron) Potential Media Affected: Drinking water supply

aquifer

Current Land Use: Commercial retail complex

Well Network: 16

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 914230207 CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Limited remediation and effectiveness of remediation
- Elevated residual benzene
- Potential for offsite source

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Quartedy	3/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702476

Assessment last 5 years

1992-ongoing: GWM

Remediation last 5 years

- < 1 year of SVE/AS
 - Reportedly stopped due to low influent concentrations in 2006
- No other info in GeoTracker

Assessment older than 5 years


1986, 1991, 1992, 1993, 1994, 2000: Site assessment (according to a report)

Remediation older than 5 years

No info in GeoTracker

IMPEDIMENTS TO CLOSURE T0603702476

as reported by regulatory agency



Review Conclusions T0603702476

- Review indicates:
 - No reports/document/letter available in GeoTracker.
 - Appears to have a few active remediation → seems to have many missing reports/data in GeoTracker
 - TPH-g and benzene remain elevated at 27,000 ppb and 1,600 ppb, respectively
 - GWM report suggest potential of offsite source adding to benzene concentrations
 - Site appears to have been redeveloped
- Discussion:
 - Effectiveness of remediation needs to be evaluated
 - Potential source of contamination from off-site

Not a Potential Closure Candidate, not on track

TOSCO – 76 STATION #7426 (T0603704600) 28203 DOROTHY DR W, AGOURA, CA 91301



Possible Reasons Why This Case Is So Old

- Residual COC concentrations remain elevated in hot spot well
- GW contamination
- Closure request denied in 2009

Case Age: 16 years
Primary COC: Gasoline

RP Identified by Regulator: Ms. Shari London

(Conoco Phillips Company)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Seventy six and Unocal

Well Network: 21

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-02634
CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

OS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - OTHER	Other Report / Document	6/2/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704600

Assessment last 5 years

- Semi-annual GWM
- Additional subsurface investigation
- CAP
- Well installation

Remediation last 5 years

 Unclear if any active or passive remediation has occurred

Assessment older than 5 years

- Well installation
- Initial subsurface investigation
- Interim RAP
- Apparent reports missing?


Remediation older than 5 years

- Unclear if any active or passive remediation has occurred
- Apparent reports missing?

DRAFT: SEPT 3, 2010

NOT UPDATED

as reported by regulatory agency



Review Conclusions T0603704600

- Review indicates:
 - Site is currently an active gas station.
 - Apparent historical reports are missing in GeoTracker → unclear if any active or passive remediation has occurred.
 - Residual concentrations of COCs remain elevated → TPHg, benzene,
 MTBE/TBA.
 - Main area of concern reportedly focused on one hot spot well.
 - Relationship between DTW and concentration fluctuation suggest that source to groundwater still present near hot spot well.
 - RP requested low-risk closure in 2008, and LA-RWQCB denied closure in 2009 due to elevated contamination levels in GW.
- Discussion:
 - Recent GWM results and trend
 - Cleanup closure timeline → effectiveness of current remediation

Not a Potential Closure Candidate (pending GWM trend), no clear track for finish

TERM-X CHEMICAL & OIL CO (T0603759597) 2454 55TH ST E, HUNTINGTON PARK, CA 90058



Possible Reasons Why This Case Is So Old

- Appears no assessment conducted
- Case was transferred between agencies
- Limited RP involvement
- Extent of contamination undefined
- Recently had work plan approved

Case Age: 17 years
Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

RP Identified by Regulator: Martin Furhman

(Term-X Chemical & Oil Co)

Potential Media Affected: Soil

Current Land Use: Gaviotas Distributors/Therm-X

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-21186
CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Soil and Water Investigation Report	5/10/2010
ENFORCEMENT/ORDERS	Staff Letter	3/10/2010
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	11/30/2009
ENFORCEMENT/ORDERS	Staff Letter	10/30/2009
RESPONSE - OTHER	Other Report / Document	7/6/2009
ENFORCEMENT/ORDERS	Staff Letter	6/5/2009
CLEANUP ACTION	Excavate and Dispose	1/4/1996
LEAK ACTION	Leak Reported	10/14/1993
LEAK ACTION	Leak Discovery	9/22/1993
LEAK ACTION	Leak Stopped	9/20/1993
LEAK ACTION	Leak Began	1/1/1965



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603759597

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

- 1993: Soil samples collected during tank removal
- 1994: 6 borings drilled

Remediation older than 5 years

 1996: Excavate and dispose (URF) DRAFT: SEPT 3, 2010

IMPEDIMENTS TO CLOSURE τ0603759597 as reported by regulatory agency



Review Conclusions T0603759597

- Review indicates:
 - Very limited report/document/letter available in GeoTracker.
 - LA-RWQCB sent a letter to the RP in Oct 2009 as a directive to take corrective action.
 - In April 2009, case was transferred from LA County to LA-RWQCB with "UST Removal Report" (1993) and "Site Assessment Report" (1994).
 - Sampling in 1990s indicated high concentrations of fuel constituents and chlorinated VOCs in soil.
 - LA-RWQCB recently (March 2010) approved a workplan to conduct site assessment.
- Discussion:
 - RP and GeoTracker compliance, site now claimed with work plan submittal
 - Site must be assessed before timeline for cleanup can be projected

Not a Potential Closure Candidate, was stuck for a long time, now may be getting on track. Although an "old" case, it is only now being regulated. Client applying to cleanup fund.

LA CITY DEPT WATER & POWER (T0603700406)

8627 Fir Ave, Watts, CA 90002



Case Age: 26 years
Primary COC: Gasoline

RP Identified by Regulator: Robert D. Freeman

(LA City Dept of Water & Power)

Media of Concern: Drinking water supply

auifer

Current Land Use: Commercial (Google Maps)

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900020016

CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears to have limited oversight at the beginning of the case
- Mobile NAPL present in several wells (free product)
- Complex, multi-zone groundwater site

NOTE: Data queried from GeoTracker and reviewed in August 2010



Activities Conducted to Date Based on GeoTracker Info T0603700406

RESPONSE - OTHER

Assessment last 5 years

- Semi-annual GWM
- Interim RAP
- CAP/RAP-Final design
- Site conceptual model
- No investigation reports in GeoTracker

Remediation last 5 years

- NAPL recovery 1997 to 2008
- No remediation reports in GeoTracker

Assessment older than 5 years

- Initial subsurface investigation
- Monitoring well installations
 - Shallow & deep
- Sensitive receptor survey
- No investigation reports in GeoTracker

Remediation older than 5 years

- NAPL recovery 1984-1991
- No remediation reports in GeoTracker

DRAFT: SEPT 3, 2010

IMPEDIMENTS TO CLOSURE T0603700406

as reported by regulatory agency



Review Conclusions T0603700406

- Review indicates:
 - No investigation reports are in GeoTracker
 - Multiple zones of impacted groundwater
 - Ongoing mobile NAPL site
 - Continuing to remove large volumes of NAPL from multiple wells
 - Apparent large residual source to groundwater
- Discussion:
 - Remediation efforts planned for future?
 - RP and GeoTracker compliance issues, no uploads since 2008
 - Cleanup closure timeline should be discussed/evaluated

Not a potential closure candidate, appears stuck

DRAFT: SEPT 3, 2010

ARCO #3018 (T0603702627) 11958 Ramona St, El Monte, CA 91732



Possible Reasons Why This Case Is So Old

- Limited activity between 1985 and 2007
- Initial assessment soil only, incomplete
- GW plume not fully defined
- In 2007, case was transferred from LA County to LA-RWQCB due to GW concern
- No remediation

Case Age: 26 years
Primary COC: Gasoline

RP Identified by Regulator: John Batchelder

(ARCO)

Potential Media Affected: Soil Current Land Use: Gas Station

Well Network: 0

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-09016
CASEWORKER: NIHAN BAQ - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 9221-09016
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	7/15/2010	
ENFORCEMENT/ORDERS	Staff Letter	5/26/2010	5/26/2010
RESPONSE - OTHER	Other Report / Document	1/15/2010	1/19/2010
RESPONSE - OTHER	2nd Status Report	7/15/2009	7/16/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/16/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009	1/16/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702627

Assessment last 5 years

- 2007: Site assessment report discovered significant GW contamination
- 2009: Installed five (5) GW MWs

Remediation last 5 years

• None


Assessment older than 5 years

2004: Initial site investigation

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603702627

- Review indicates:
 - Long delay in beginning initial assessments
 - Data indicates significant impacts to soil and GW
 - Soil and GW contamination not fully defined
 - No remediation has occurred
 - Missing data/reports in GeoTracker
- Discussion:
 - RP and GeoTracker compliance
 - Complete site characterization
 - Consider remediation → timeline to reach Clean-Up Goals
 - Closure timeline
- Not a Potential Closure Candidate

TOSCO – 76 STATION #5096 (T0603701506) 25905 ROLLING HILLS ROAD, TORRANCE, CA 90505



Case Age: 25 years
Primary COC: Gasoline
RP Identified: Tosco/76

RP Identified: Tosco/76 Products Current Land Use: Gas Station

Potential Media Effected: Aguifer used for

drinking water supply Well Network: 11

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. 905050061

CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED
TOPPDANCE CITY OF

CASEWORKER: RICHARD V. BONGARD - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Transferred between agencies
- Multiple sources (offsite potential too)
- Comingled plume
- No active remediation
- · GW plume not fully delineated

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities ACTION TYPE RESPONSE - REPORTS ENFORCEMENT/ORDERS RESPONSE - REPORTS Monitoring Report - Semi-Annually 7/15/2009 Staff batter 6/15/2009 Monitoring Report - Quarterly 4/15/2009 RESPONSE - REPORTS RESPONSE - REPORTS Monitoring Report - Quarterly 1/15/2009 Monitoring Report - Quarterly 1/15/2008 RESPONSE - REPORTS Monitoring Report - Quarterly 1/15/2008 Monitoring Report - Quarterly 7/15/2008 RESPONSE - REPORTS Monitoring Report - Quarterly 7/15/2008 RESPONSE - REPORTS Site Conceptual Model Report RESPONSE - REPORTS RESPONSE - REPORTS Monitoring Report - Quarterly 4/15/2008 RESPONSE - REPORTS Monitoring Report - Quarterly 4/15/2008

Monitoring Report - Quarterly

1/15/2008 10/15/2007

Activities Conducted to Date Based on GeoTracker Info (T0603701506)

Assessment last 5 years

- Ongoing: GW monitoring
- 2008: Site conceptual model
- 2005: Soil and water investigation

Remediation last 5 years

None

Assessment older than 5 years


- 1989, 1995, 2004: Site assessments
- 2002-ongoing: GW monitoring

Remediation older than 5 years

2004: Remediation

IMPEDIMENTS TO CLOSURE (T0603701506)

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - SEMI-ANNUALLY: 11

Review Conclusions T0603701506

- Review indicates:
 - At least two source areas
 - Potential for offsite source
 - Multiple phases of investigation
 - Chemical concentrations low, but persistent
 - Site is an active gas station
- Discussion:
 - GWM trends show low levels
 - Comingled plume may need to be further evaluated
 - Is active remediation warranted; complete feasibility study?
 - Status and benefits of indoor air assessment
 - Cleanup closure plan and timeline
- Potential closure candidate in a few years, appears stuck.

TEXACO (T0603700926)736 VINE ST, HOLLYWOOD, CA 90038



Possible Reasons Why This Case Is So Old

- Missing historical reports and documents
- No RP identified
- Appears to have no/limited assessment
- No oversight from 1986 till 2009

Case Age: 24 years

RP Identified by Regulator: None identified in

GeoTracker - Unclaimed in GeoTracker

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking

water

Current Land Use: Commercial Complex

Well Network: 17 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900380152
CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



1986 till 2009			To the
ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
LEAK ACTION	Leak Reported	4/4/1986	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700926

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years


None

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603700926

as reported by regulatory agency



Review Conclusions T0603700926

- Review indicates:
 - No reports/documents/letter savailable in GeoTracker appears nothing has been done at this site
 - No RP identified
 - Site might have been redeveloped
- Discussion:
 - RP and GeoTracker compliance issues to be addressed
 - Next step cleanup closure procedure and timeline?

Insufficient information to determine case status, stuck case

THE SOUTHLAND CORP (CHIEF/AUTO) (T0603701903) 2594 SANTA FE AVE, LONG BEACH, CA 90810



Possible Reasons Why This Case Is So Old

- Extent of GW and soil contamination still undefined
- Legal settlement between Auto Zone and 7-Eleven (former Southland Corp)
- Site redeveloped
- No active remediation conducted

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 24 years

RP Identified by Regulator: C/O Ms. Diana

Hull (RP Atty) (Auto Zone Parts)

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking

water

Current Land Use: Commercial /Retail

Well Network: 11

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908100061 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities GO		
ACTION TYPE	ACTION	ACTION DATE	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	
RESPONSE - OTHER	Site Conceptual Model	7/15/2009	
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	
RESPONSE - OTHER	Site Conceptual Model	1/14/2009	
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008	

Activities Conducted to Date Based on GeoTracker Info T0603701903

Assessment last 5 years

Ongoing: GW monitoring (11 wells)

Remediation last 5 years

None

Assessment older than 5 years


- 2000-2006: GW monitoring
- 2001, 2003: Additional GW wells installed
- 1986, 2000: Soil borings and GW monitoring wells installed
- 1986: GW monitoring

Remediation older than 5 years

- 1986: Excavation (285-yd³ of soil)
- 2005: Air sparge/vapor extraction test

IMPEDIMENTS TO CLOSURE T0603701903

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY
OF WELLS MONITORED - SEMI-ANNUALLY: 11

Review Conclusions T0603701903

- Review indicates:
 - Site was formerly occupied by gas stations (Mobil and Texaco) still has GW detections in 2009 sampling event.
 - Off-site assessment was conducted to determine potential for offsite contamination impacting the subject site – conclusion unknown.
 - Report indicated no sensitive receptors in the surrounding area, and it is unlikely wells for potable water would be located within the immediate vicinity of the site.
 - Benzene is the primary driver (2,900 ug/L).
- Discussion:
 - Complete plume definition and SCM/FS
 - Evaluate current and future indoor air risk
 - Consider active remediation options and closure timeline
- Not a Potential Closure Candidate, may be stuck as no remediation

MOBIL #11-FCG (T0603702451) 15303 SHERMAN WY, VAN NUYS, CA 91406



Case Age: 24 years **Primary COC:** Gasoline

RP Identified: Felicia Jones (Exxon Mobil Oil Corp)

Current Land Use: Gas Station Potential Media Effected: Soil

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 914061743
CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities ACTION **ACTION DATE** RESPONSE - OTHER

Possible Reasons Why This Case Is So Old

- Case transferred between agencies (2009)
- No document/report upload in GeoTracker
- Limited oversight and RP involvement
- Appears to have no site assessment conducted

LEAK ACTION LEAK ACTION LEAK ACTION

ACTION TYPE

RESPONSE - OTHER

ENFORCEMENT/ORDERS

Other Report / Document 7/16/2010 Other Report / Document 1/15/2010 Staff Letter 12/15/2009 Leak Reported 11/10/1986 Leak Discovery 10/29/1986 Leak Stopped 10/29/1986

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603702451)

Assessment last 5 years

- NONE DOCUMENTED
- 2008: Site assessment (?)

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


1986: Site assessment (?)

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603702451)

as reported by regulatory agency



Review Conclusions T0603702451

- Review indicates:
 - Limited reports/documents available in GeoTracker.
 - Case appears to have transferred from City of Los Angeles to RWQCB in 2009 with no historical information.
 - Site is currently an active gas station.
 - RP responded (March 2010) to regulator's letter (Dec 2009)
 requesting for additional information with data from 1998.
 - RWQCB's letter in 2009 indicated that this site is qualified under the UST's program's Expedited Agency Oversight Program (EAOP).
- Discussion:
 - Next step → site assessment for recent site data

Not a Potential Closure Candidate, appears to be stuck

ARCO #1361 (FORMER) (T0603702479)14311 VENTURA BLVD, SHERMAN OAKS, CA 91423



Possible Reasons Why This Case Is So Old

- Appears to have limited site activity between 1986 and 2006
- Case was transferred between agencies
- Limited report/document in GeoTracker
- Missing historical reports and documents
- Limited RP involvement

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 24 years

RP Identified by Regulator: Bryan Mashian (Haba Investments LLC/AYM Investments)

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking water Current Land Use: Handy J Car Wash/commercial

Well Network: 5

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: 914230307

CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Preliminary Site Assessment Report	6/30/2008
ENFORCEMENT/ORDERS	Staff Letter	4/28/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	*6/30/2008
RESPONSE - REPORTS	Preliminary Site Assessment Report	*6/30/2008
ENFORCEMENT/ORDERS	Staff Letter	10/26/2007

Activities Conducted to Date Based on GeoTracker Info T0603702479

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years


None

Remediation older than 5 years

1994: Excavation

IMPEDIMENTS TO CLOSURE T0603702479

as reported by regulatory agency



Review Conclusions T0603702479

- Review indicates:
 - Insufficient data to evaluate case status
 - Only one work-plan report in GeoTracker (2006) with data from 1994 → 3,800-mg/kg of TPH and 50,000-ug/kg of benzene in soil.
- Discussion:
 - RP and GeoTracker compliance issues should be addressed
 - Evaluate case status and develop path forward → cleanup closure timeline
 - Consider robust investigation schedule (soil and GW) to complete plume definition and GW characterization as needed to determine if active remediation is warranted
- Not a Potential Closure Candidate, case appears to be stuck

MOBIL #18-FOM (FORMER 11-FOM) (T0603700880) 9448 PICO BLVD, LOS ANGELES, CA 90035



Case Age: 23 years
Primary COC: Gasoline

RP Identified by Regulator: Felicia Jones (Mobil Oil

Corp)

Potential Media Affected: Drinking water supply

aguifer

Current Land Use: Service Station

Well Network: 17

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900350098

CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Site initially closed as low-risk soils only case; reopened 3-4 years later during upgrades.
- NAPL site (5 wells), and two groundwater zones.
- Free product in wells

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	→ Go	* tho
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2010	1/19/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/16/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/16/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700880

Assessment last 5 years

- Semi-annual GWM
- Soil borings
- IRAP
- Only 1 investigation report in GeoTracker; current status unclear

Assessment older than 5 years

- Initial subsurface investigation
- IRAP
- Monitoring well installations
- Soil-vapor survey
- Only 1 investigation report in GeoTracker

Remediation last 5 years

- Unclear if active remediation occurred due to lack of reports in GeoTracker
- NAPL bailing

Remediation older than 5 years

- UST system replacement
- Soil excavation
- NAPL bailing
- Mobil vapor/groundwater extraction
- Dual phase extraction

IMPEDIMENTS TO CLOSURE T0603700880

as reported by regulatory agency

MOBIL	#18-FOM	(FORMER 11	-FOM) (T060	3700880) - <u>(M</u> A	AP)		
LOS ANGE	BLVD LES, CA 90033 LES COUNTY ANUP SITE	5	i izalih			CLEANUP OVERSIGHT LOS ANGELES RWQC CASEWORKER: JL LOS ANGELES, CITY C CASEWORKER: 91	B (REGION 4) (<i>LEAD</i>) - <i>CASE</i> #: 900350098 <u>AY HUANG</u> DF
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	DF 7/27/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
GROUNDWAT Groundwa		ve Other Cleanup Goal - f	ree product in five wells				
BENEFITS OF A	ADDITIONAL WORK						
• Remove	Reduce Source Ma	ass - free product remova	I				
SENSITIVE REC	CEPTORS LIKELY TO E	E IMPACTED AND TIME FRAME	FOR IMPACT				
SENSITIVE RECO			TIME FRAME Already In	FOR IMPACT npacted			MENTS CE 1999
		And the second s					

Review Conclusions T0603700880

- Review indicates:
 - Site is currently an active gas station
 - Site initially closed as low-risk, soils-only case reopened 3-4 years later
 - Strong investigation efforts; weak ramp-up of remediation efforts >
 NAPL still present in several wells despite many years of bailing
 - Site underlain by two water-bearing zones; both zones impacted
 - Current groundwater concentrations remain elevated → consistent with NAPL source
 - Remediation (DPE) began in 2004; unclear if ongoing
- Discussion:
 - Active remediation and effectiveness needs to be evaluated
 - Cleanup closure approach and timeline should be addressed

Not a potential closure candidate, appears to be stuck

YELLOW FREIGHT SYSTEMS INC (T0603702685) 9933 BEVERLY BLVD E, PICO RIVERA, CA 90660



Possible Reasons Why This Case Is So Old

Lack of oversight and RP involvement
No reports/documents uploaded into

• RP has not reported since 2004

GeoTracker

Case Age: 23 years
Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

RP Identified by Regulator: Mr. Jack Staszower

(Jack's Texaco)

Potential Media Affected: Aquifer used for

drinking water

Current Land Use: Storage?

Well Network: 5

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-00185 CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT ACTION TYPE ACTION TYPE ACTION TRESPONSE - REPORTS RESPONSE - REPORTS Estimated Plumb Travel Time Estimated Plumb Travel Time 10/15/2004

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info
T0603702685 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

Ongoing: GW monitoring

Remediation last 5 years

None


Assessment older than 5 years

- 2002-ongoing: GW monitoring
- 2003: Estimated Plume Travel Time Report
- 2004: Site Conceptual Model

Remediation older than 5 years

None

IMPEDIMENTS TO CLOSURE T0603702685 as reported by regulatory agency



Review Conclusions T0603702884

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Based on "Activities Report", multiple site activities were conducted.
 - Appears that work-plans prepared included: CAP/RAP Final Remediation/Design Plan, Interim Remedial Action Plan, and MTBE Investigation Work-plan, but it is unclear if any of the proposed tasks were conducted.
 - Closure Review indicates that "RP has not reported since 2004."
 - Site appears to have been redeveloped.
- Discussion:
 - RP and GeoTracker compliance → recent reports/documents need to be uploaded
 - Next steps to move case along

Insufficient information to determine current case status, appears stuck

ARGO REALTY PROPERTY (T0603701383) 1661 LINCOLN BLVD, SANTA MONICA, CA 90404



NOTE: Site in EAOP since 2005

Case Age: 23 years Primary COC: Gasoline

RP Identified by Regulator: Deborah Pryor

(Shell Oil Product US)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Commercial Complex

Well Network: 18 wells

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 904040034 CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED SANTA MONICA, CITY OF

CASEWORKER: MONICA HANLEY - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears to have limited oversight at the beginning of the case
- Extent of soil and GW contamination undefined
- High GW contamination remains

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/7/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	7/14/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	6/9/2009	6/9/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/15/2009
DESDONSE - DEDODTS	Monitoring Report - Quarterly	1/15/2000	1/15/2000

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701383

Assessment last 5 years

- Ongoing: GW monitoring (18 wells)
- 2009: Additional site assessment proposed (WP)
- 2004: Site assessment

Remediation last 5 years

None


Assessment older than 5 years

- 2000-2004: Additional site assessment
- 1998: GW monitoring
- 1987-1988: Environmental audit (subsurface contamination)

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603701383

- Review indicates:
 - Site was a Shell Service Station, and from 1927-1972 → there was a bulk fuel storage facility on-site.
 - Site is currently an office building.
 - GW plume migrating off-site.
 - As of 2009, GW contamination levels still high.
- Discussion:
 - Consider remediation
 - Cleanup closure timeline should be developed
- Not a Potential Closure Candidate, appears stuck

TEXACO (T0603703087)

7515 ALONDRA BLVD E, PARAMOUNT, CA 90723



Case Age: 22 years
Primary COC: Gasoline

RP Identified by Regulator: Paramount Texaco Service Station (Notes indicated "Cannot locate

RP") - Unclaimed in GeoTracker

Potential Media Affected: Aquifer used for

drinking water

Current Land Use: Paramount Fuel

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-05588

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- No reports/documents in GeoTracker
- No RP identified
- Limited oversight
- Site not claimed

ACTIVITIES REPORT

ACTION TYPE

RESPONSE - REPORTS

Monitoring Report - Semi-A

Staff Letter

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
ENFORCEMENT/ORDERS	* Historical Enforcement	2/11/1998
ENFORCEMENT/ORDERS	13267 Requirement	2/11/1998
LEAK ACTION	Leak Reported	3/15/1988

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603703087

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only two letters from LA-RWQCB in GeoTracker: (1) Notice of Non-Compliance and (2) Reduction in GWM frequency.
 - Site is currently an active gas station.
 - Activities Report in GeoTracker indicates a Monitoring Report submittal on July 2009 (report is not in GeoTracker).
 - Closure Review indicates "Cannot locate RP."
- Discussion:
 - RP and GeoTracker compliance issues should be addressed
 - Next step → cleanup procedure and timeline to be evaluated

Insufficient information to determine case status, appears to be stuck

BIXBY LAND COMPANY (T0603774459)

4401-4409 LOS COYOTES DIAGONAL, LONG BEACH, CA 90815



Case Age: 22 years
Primary COC: Gasoline

RP Identified by Regulator: Berkeley Davis

(Bixby Land Company)

Potential Media Affected: Aquifer used for

drinking water

Current Land Use: Commercial Center

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908150307

CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF - CASE #: PR0022865

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Other Report / Document	10/15/2008
ENFORCEMENT/ORDERS	Notice to Comply	9/18/2008
ENFORCEMENT/ORDERS	Staff Letter	9/2/2008
LEAK ACTION	Leak Reported	7/7/1988
LEAK ACTION	Leak Discovery	6/24/1988
LEAK ACTION	Leak Began	1/1/1965

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- Contamination detected on-site (in 2007)
- Extent of contamination still undetermined
- Only grab GW collected, no monitoring wells at site

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603774459

Assessment last 5 years

 2007/08: Field investigation (soil vapor and GW)

Remediation last 5 years

None


Assessment older than 5 years

- 1988: Soil investigation (including soil vapor study) and grab GW
- 1990: Site characterization

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603774459

- Review indicates:
 - No QM reports/documents available in GeoTracker.
 - Only one site characterization report (2008) uploaded to GeoTracker.
 - Site might have been transferred from City of Long Beach.
 - Site does not have monitoring wells installed.
- Discussion:
 - RP and GeoTracker compliance issues to be addressed
 - Next step → Benefit of GW monitoring for cleanup closure and timeline

<u>Insufficient information to determine case status, Case appears to</u> be stuck

PRUDENTIAL OVERALL SUPPLY (T0603702803) 17641 FABRICA WY E, CERRITOS, CA 90703



Case Age: 22 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon ____

RP Identified by Regulator: Lee Terry

(Prudential Overall Supply)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Commercial

Well Network: 9

Possible Reasons Why This Case Is So Old

- Little activity between 1989 and 2002
- Limited investigation/site characterization
- Limited oversight for years
- NAPL/Floating Product present
- Is this a petroleum LUST Site?

NOTE: Data queried from GeoTracker and reviewed in August 2010



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-01827
CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	→ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009

Activities Conducted to Date Based on GeoTracker Info T0603702803

Assessment last 5 years

 Ongoing: GW monitoring (9 wells)

Remediation last 5 years

None


Assessment older than 5 years

2002-ongoing: GW monitoring

Remediation older than 5 years

 1999: Product removal program (estimated 204.6gal removed)


as reported by regulatory agency



Review Conclusions T0603702803

- Review indicates:
 - Limited work performed and no apparent enforcement.
 - NAPL present in wells (in 2009 free product thickness ~ 0.03-0.6').
 - Last report (GW Monitoring) uploaded into GeoTracker on June 2009.
 - Based on the last GWM Report, consultant recommended to "continue free product removal from wells B-3, B-4, B-5, B-7, and B-8; and continue TRPH and VOCs analysis for wells B-6, B-9 and B-10 on semi-annual basis."
- Discussion:
 - GWM results in June 2009 → low to NDs for TRPH, MTBE and VOCs detections (any recent results?)
 - Cleanup closure timeline should be evaluated
- <u>Potential Closure Consideration for Petroleum? What is nature of the FP at site? Is this a Petroleum LUST Site? Appears Stuck!</u>

CERRITOS COMMUNITY COLLEGE (T0603703264) 11110 ALONDRA BLVD E, NORWALK, CA 90650



Case Age: 22 years
Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

RP Identified by Regulator: Michael D.Sebak

(Cerritos Community College)

Potential Media Affected: Drinking water

aquifer

Current Land Use: Community College

Well Network: ? - GeoTracker needs updating

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. I-06888 CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED LOS ANGELES COLUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Multiple UST sites/plumes across site (see figure above for UST locations)
- Appears to have years of gaps in between site activities

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities **ACTION TYPE ACTION DATE** RESPONSE - REPORTS Monitoring Report - Semi-Annually 7/15/2009 ENFORCEMENT/ORDERS 6/15/2009 RESPONSE - REPORTS Monitoring Report - Quarterly 10/15/2008 ENFORCEMENT/ORDERS 9/16/2008 Notice to Comply RESPONSE - REPORTS RESPONSE - REPORTS 7/15/2008 Monitoring Report - Quarterly 7/15/2008 OTHER REGULATORY ACTIONS Site Visit / Inspection / Sampling 6/11/2007 ENFORCEMENT/ORDERS Staff Letter 1/31/2000 LEAK ACTION Leak Reported 12/5/1988 LEAK ACTION Leak Discovery 11/3/1987

Activities Conducted to Date Based on GeoTracker Info T0603703264

Assessment last 5 years

- GWM (frequency unclear)
- Additional investigation and well installations
- Apparent missing reports?

Remediation last 5 years

Over-excavation post UST removal

Assessment older than 5 years

- Initial subsurface investigation
- Well installation
- Multiple UST removal events

Remediation older than 5 years

Minor over-excavation post UST removal

IMPEDIMENTS TO CLOSURE T0603703264

as reported by regulatory agency

CERRITOS CON	IMUNITY COL	LEGE (T0603	703264) - <u>(</u> MA	P)			
11110 ALONDRA BLVD E NORWALK, CA 90650 LOS ANGELES COUNTY LUST CLEANUP SITE					CLEANUP OVERSIGHT AGENCIES LOS ANGELES RIVOCB (REGION 4) (LEAD) - CASE #: 1-06888 CASEWORKER: AHMAD J. LAMMA LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO		
Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement		
CLOSURE REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS O	OF 9/15/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES	
IMPEDIMENTS TO CLOSURE							
Other - Additional ground	water monitoring required.						
BENEFITS OF ADDITIONAL WORK				7.4.1.500.0000000000000000000000000000000			
Other - Additional grounds	vater monitoring required						
SENSITIVE RECEPTORS LIKELY TO	BE IMPACTED AND TIME FRAME	E FOR IMPACT					
SENSITIVE RECEPTOR	TIME FRAME FOR		COMMENTS				
Groundwater	Already Impac	ted	Additional grou	ndwater monitoring requir	ed		
NOTES / COMMENTS							
Additional groundwater monitoring	required						

Review Conclusions T0603703264

- Review indicates:
 - Multiple UST sites/plumes with leak detection/reporting spread over time -> contents: Gasoline, diesel, waste oil, cutting oil
 - Various investigations appear to have occurred → adequacy of previous work is unclear, i.e. are all plumes defined & stable?
 - Additional monitoring is being requested by agency
 - Case closure has been requested by current RP (2008)
- Discussion:
 - Benefit of additional monitoring and remediation?
 - Potential for case closure dependent on review of current monitoring data, if available, to determine if plumes are defined and stable

Potential closure consideration (pending current monitoring data), Case appears stuck at present

FOUA D N DAGHER (T0603700808)

3130 BROADWAY N, MONTECITO HEIGHTS, CA 90031



Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Deborah Pryor

(Shell Oil Product US)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Valero Gas Station

Well Network: 7

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900310270 CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



Possible Reasons Why This Case Is So Old

- Free product in GW
- NAPL case/Offsite plume
- No active remediation
- Access problems

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010	7/13/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010	4/12/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/14/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2009	10/15/2009
RESPONSE - REPORTS	Well Installation Report	9/17/2009	9/17/2009

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700808

Assessment last 5 years

- Semi-Annual GWM
- Well installation
- 2009 SVE pilot test

Remediation last 5 years

- Vacuum extraction
- NAPL removal

Assessment older than 5 years

- Well installation
- Initial subsurface investigation

Remediation older than 5 years

• None

IMPEDIMENTS TO CLOSURE T0603700808

as reported by regulatory agency

FUUA	D N DAGH	ER (T0603700	0808) - <u>(MAP</u>)			
3130 BROADWAY N MONTECITO HEIGHTS, CA 90031 LOS ANGELES COUNTY LUST CLEANUP SITE				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 9003102 CASEWORKER: MAGIOY BAIADY LOS ANGELES. CITY OF CASEWORKER: eloy luna			
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	OF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS (OF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
	ADDITIONAL WORK	CASE IS NOT READY	FOR CLOSURE AS O	DF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
Other - f	ADDITIONAL WORK	CASE IS NOT READY		DF 8/20/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE

Review Conclusions T0603700808

- Review indicates:
 - Offsite plume → offsite access agreements pending
 - NAPL present
 - No active remediation occurring
 - Recent SVE implementation pilot-test results pending
 - Site is currently an active gas station
- Discussion:
 - Remediation efforts
 - Cleanup closure timeline to be evaluated

Not a Potential Closure Candidate (pending post-remedial effectiveness monitoring) Appears stuck

CITY OF LA VERNE, CITY HALL (T0603792929)3660 D ST, LA VERNE, CA 91750



Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Mr. Dan Keesey (City of La Verne) – Unclaimed in GeoTracker

Potential Media Affected: Soil

Current Land Use: City Business Building

CLEANUP OVERSIGHT AGENCIES

OS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-13153
CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 12913-13153
CASEWORKER: GILLIAN MINTIER - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Limited oversight -- no follow-up from regulator after 2 letters sent in 2008
- Appears no assessment conducted
- No RP involvement
- Extent of contamination undefined
- Government entity site, funding issues?

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All	Activities Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Other Report / Document	1/15/2009
ENFORCEMENT/ORDERS	Staff Letter	11/13/2008
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
LEAK ACTION	Leak Reported	5/19/1989

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603792929

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

None

as reported by regulatory agency



Review Conclusions T0603792929

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Regulator sent out letters (Notice of Non-Compliance and Additional Information Report) in 2008, and no follow-up activities since.
- Discussion:
 - RP and GeoTracker compliance issues to be addressed
 - Next step → site assessment for cleanup/closure and timeline
 - Government entity site, lack of enforcement, possible funding issues?

<u>Insufficient information to determine case status, Case appears to be stuck</u>

P&M #936 (T0603704036)

1144 HACIENDA BLVD, HACINEDA HEIGHTS, CA 91745



Case Age: 19 years
Primary COC: Gasoline

RP Identified by Regulator: Morteza Kohan **Potential Media Affected:** Aguifer used for

drinking water supply

Current Land Use: Used car lot

Well Network: 0

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-13117
CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 12884-13117

Mary or the state of the state

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	→ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	4/15/2010
ENFORCEMENT/ORDERS	Staff Letter	2/25/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010
RESPONSE - REPORTS	Soil and Water Investigation Report	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
ENFORCEMENT/ORDERS	Staff Letter	4/8/2009
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	2/13/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008

Possible Reasons Why This Case Is So Old

- Little activity between 1991 and 2006
- RP reportedly does not have adequate funds to do cleanup
- Site just recently completed phase II
- Extent of soil and groundwater contamination not delineated

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704036

Assessment last 5 years

2007/09: Site Assessment

Remediation last 5 years


None

Assessment older than 5 years

- 1990: 4 exploratory borings (soil and GW sampling)
- 1999: Subsurface sampling

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603704036

- Review indicates:
 - Little activity during initial site history
 - Phase II assessment (2009) indicated soil and groundwater contamination
 - Agency's letter to RP in February 2010 requested follow up investigation to complete delineation of impacted soil and groundwater
- Discussion:
 - Data gaps that may need to be filled
 - Cleanup closure timeline → consider robust investigation schedule and program to complete site characterization and determine remedial needs

Not a Potential Closure Candidate, appears stuck

> Case Age: 19 years Primary COC: Gasoline

TEMPLE SHERIFF STATION (T0603704593) 8838 LAS TUNAS DR E, TEMPLE CITY, CA 91780



Possible Reasons Why This Case Is So Old

- Limited oversight/limited assessment
- Government entity site, funding issues?
- No reports/documents in GeoTracker
- Extent of contamination undetermined
- Years with no letters sent by agency

ACTIVITIES REPORT ACTION TYPE RESPONSE - REPORTS ACTION DATE Monitoring Report - Semi-Annually 7/15/2010 RESPONSE - WORKPLANS Corrective Action Plan / Remedial Action Plan ENFORCEMENT/ORDERS Staff Letter 4/28/2010 LEAK ACTION Leak Reported 5/23/1991 LEAK ACTION Leak Discovery 5/17/1991

RP Identified by Regulator: County of LA Facility

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-02444

CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 002363 002444

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Management - Unclaimed in GeoTracker

Potential Media Affected: Soil Current Land Use: Police Dept **CLEANUP OVERSIGHT AGENCIES**

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704593

Assessment last 5 years

In GeoTracker (??)

GROUNDWATER MONITORING FREQUENCY OF WELLS MONITORED - SEMI-ANNUALLY: 12

Assessment older than 5 years

Several phases, including one by US EPA in which evidence of an upgradient source of PCE was found.


Remediation last 5 years

None

Remediation older than 5 years

- SVE?
- Letter from agency to RP mentions SVE performed at site in 1993 and 1994

as reported by regulatory agency



Review Conclusions T0603704593

- Review indicates:
 - No reports/documents available in GeoTracker, but work has been performed at this site, including remediation.
 - Only one letter from LA-RWQCB (April 2010) informing RP to take corrective action → letter listed many earlier site activities
 - Remedial action plan due June 1, 2010, but do not see it in GeoTracker.
- Discussion:
 - Any current data or site assessment and/or remediation?
 - Is enforcement the next step to make government entity comply with directive letters?

Case appears stuck due to non compliant RP

WEST COAST CHOPPERS (T0603701939) 718 ANAHEIM ST W, LONG BEACH, CA 90813



Possible Reasons Why This Case Is So Old

- Recalcitrant RP
- Six year gap between enforcement letters
- No data/reports available
- Appears no assessment conducted

Case Age: 15 years

Primary COC: Stoddard Solvent/Mineral

Spirits/Distillates ____

RP Identified by Regulator: Gordon

(Mr. Robinson) – Unclaimed in GeoTracker Potential Media Affected: Aguifer used for

drinking water supply

Current Land Use: West Coast Choppers

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130252

CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities	❤ Go
ACTION TYPE	ACTION		ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Sem	i-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter		6/15/2009
RESPONSE - REPORTS	Other Report / Documen	<u>t</u>	4/15/2009
ENFORCEMENT/ORDERS	Staff Letter		3/10/2009
ENFORCEMENT/ORDERS	Notice to Comply		9/16/2008
ENFORCEMENT/ORDERS	Staff Letter		6/24/2002
ENFORCEMENT/ORDERS	13267 Requirement		2/2/2001
LEAK ACTION	Leak Reported		5/15/1995
LEAK ACTION	Leak Discovery		3/28/1995



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701939

Assessment last 5 years

APPEARS NONE

Remediation last 5 years

APPEARS NONE


Assessment older than 5 years

APPEARS NONE

Remediation older than 5 years

APPEARS NONE

IMPEDIMENTS TO CLOSURE τ0603701939 as reported by regulatory agency



Review Conclusions T0603701939

- Review indicates:
 - DOES NOT APPEAR TO HAVE ANY WORK PERFORMED AT THIS SITE.
 - NO report/document available in GeoTracker to review to provide complete assessment.
 - Recalcitrant RP (did not respond to RWQCB letter in 2009).
- Discussion:
 - RP and GeoTracker compliance
 - Enforcement appears to be next step
- Not a Potential Closure Candidate, no data

LONG BEACH CITY TOW YARD (T0603701960) 901 ANAHEIM ST W, LONG BEACH, CA 90813



Possible Reasons Why This Case Is So Old

- Gaps in oversight and RP involvement
- Data gaps, Site assessment incomplete
- GW contamination
- Government Entity (funding/oversight issues?)

Case Age: 15 years Primary COC: Gasoline

RP Identified: Frank Neely (City of Long

Beach, Fleet Service Bureau) **Current Land Use:** Undetermined

Potential Media Effected: Aquifer used for

drinking water supply

Wells Network: 3

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130498
CASEWORKER: DAVID M. BJOSTAD
LONG BEACH/SIGNAL HILL, CITIES OF
CASEWORKER: CARMEN PIRO

ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	AB681	4/15/2010
RESPONSE - OTHER	Electronic Reporting Submittal Due	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	4/15/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2010
ENFORCEMENT/ORDERS	Staff Letter	12/28/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2007
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2006
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2006
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2006
RESPONSE - REPORTS	Soil and Water Investigation Report	4/19/2002
ENFORCEMENT/ORDERS	Staff Letter	2/19/2002
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	11/19/2001
ENFORCEMENT/ORDERS	Staff Letter	6/22/2001
LEAK ACTION	Leak Reported	8/30/1995
LEAK ACTION	Leak Discovery	8/30/1995



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on Geotracker Info (T0603701960)

Assessment last 5 years

- Assessments in 2005 and 2006
- Monitoring in 2010

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


- Tank removed 1995
- Assessments performed in 1996 and 2001

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (TO603701960)

as reported by regulatory agency



GROUNDWATER MONITORING FREQUENCY # OF WELLS MONITORED - SEMI-ANNUALLY : 3

Review Conclusions T0603701960

- Review indicates:
 - Limited report/document/letters available in GeoTracker.
 - Only 2 letters (2009) in GT from RWQCB: (1) requesting reduction in GW monitoring, and (2) requesting soil and GW investigation.
 - RWQCB's letter in 2009 indicates reports/documents available regarding assessments conducted at this site between 1995-2006, should be uploaded into GeoTracker.
 - GW Investigation Report from 2005 and monitoring report of 2010 indicate low levels of GW contamination.
- Discussion:
 - RP is Government Entity, which may indicate funding and or compliance/enforcement issues
 - Next step → cleanup closure timeline, placing RP into enforcement

PUBLIC SERVICE YARD (T0603701971) 1725 SAN FRANCISCO AVE, LONG BEACH, CA 90813



Possible Reasons Why This Case Is So Old

- No document/reports/letters uploaded in GeoTracker
- Case was transferred between agencies
- Appears to have limited oversight and RP involvement
- Government entity RP, which may signify funding/oversight issues

Case Age: 15 years
Primary COC: Diesel

RP Identified: Tom Leary (City of Long Beach)

Unclaimed in GeoTracker
 Potential Media Effected: Soil
 Current Land Use: Undetermined

NOTE: No street-view

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130607
CASEWORKER: NOMAN CHOWDHURY
LONG BEACH/SIGNAL HILL, CITIES OF
CASEWORKER: CARMEN PIRO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show A	All Activities Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	1/15/2009
ENFORCEMENT/ORDERS	Staff Letter	11/24/2008
LEAK ACTION	Leak Reported	8/4/1995
LEAK ACTION	Leak Discovery	8/4/1995
LEAK ACTION	Leak Stopped	8/4/1995

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603701971)

Assessment last 5 years

NONE DOCUMENTED

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


NONE DOCUMENTED

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603701971)

as reported by regulatory agency



Review Conclusions T0603701971

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - URF indicates source of discharge is "product piping" and cause of discharge is "structural failure"
 - Site appears to be an industrial area
- Discussion:
 - Cleanup closure timeline? Commence enforcement?
 - Government entity RP, may signify lack of funding and unwillingness to initiate enforcement

DIAMOND OIL COMPANY (T0603721214) 1553 Bluff Rd. S. Montebello, CA 90640



Case Age: 15 years **Primary COC:** Gasoline

RP Identified: Diamond Oil Co.

- Unclaimed in GeoTracker

Potential Media Affected: Drinking Water

Supply Aquifer

Current Land Use: Commercial

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-12651
CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 012496-012651
CASEWORKER: PHILLIP GHARIBIANS-TABRIZI - SUPERVISOR: MANUEL R REGALADO
CASEWORKER: TIM SMITH - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Appears no work conducted since release in 1995
- Transferred between agencies referred to RWQCB in 2009
- Non-responsive RP, had due date of 12-2009 for submittal of information, no record of submittal or follow-up.

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTION DATE RECEIVED / ISSUE DATE RESPONSE - OTHER 12/15/2009 Other Report / Document 10/14/2009 Request for Additional Information 10/1/2009 ENFORCEMENT/ORDERS Staff Letter 10/1/2009 New Referral Case LEAK ACTION Leak Reported 11/2/1995 LEAK ACTION 10/27/1995



Activities Conducted to Date Based on GeoTracker Info T0603721214

Assessment last 5 years

No data or reports in GT to review

Remediation last 5 years

No data or reports in GT to review


Assessment older than 5 years

No data or reports in GT to review

Remediation older than 5 years

No data or reports in GT to review

as reported by regulatory agency



Review Conclusions T0603721214

- Review indicates:
 - No data available in GeoTracker to review
 - Site transferred from LA Public Works to RWQCB
 - 2009 request to RP to submit data to GeoTracker has not been completed, due date was December 2009, over 7 months ago.
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

DOWNEY GLASS CO, INC (T0603758087) 5631 Ferguson Dr., Commerce, CA 90022



Case Age: 15 years (45 years since leak)

Primary COC: Gasoline

RP Identified: Downey Glass Company -

Unclaimed in GeoTracker

Potential Media Affected: Under Investigation **Current land use:** Commercial/manufacturing

Well Network: NA

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: 900220025A CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY - CASE #: 005648-005855

CASEWORKER: IHEANACHO OFO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- No reports in GeoTracker
- Appears to have no activity between 1995 and 2009
- Transferred between agencies
- First enforcement letter sent in 2009 following referral to RWQCB
- Additional enforcement appears necessary

NOTE: Data queried from GeoTracker and reviewed in August 2010





Activities Conducted to Date Based on GeoTracker Info T0603758087

Assessment last 5 years

No reports in GeoTracker to review

Remediation last 5 years

No reports in GeoTracker to review

Assessment older than 5 years


No reports in GeoTracker to review

Remediation older than 5 years

No reports in GeoTracker to review

IMPEDIMENTS TO CLOSURE T0603758087

as reported by regulatory agency



Review Conclusions T0603758087

- Review indicates:
 - Case recently (2009) was referred to RWQCB.
 - No data or reports available in GeoTracker to review.
 - Only one letter (December 2009) in GeoTracker → RWQCB requesting RP for additional information.
 - Due date for RP submittal of information was January, 2010
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

SHELL #204-0580-0200 (T0603704696) 6350 FLORENCE AVE, BELL GARDENS, CA 90201



Case Age: 26 years Primary COC: Gasoline

RP Identified: Shell Oil Co (Shell Oil Co. 507)

- Unclaimed in GeoTracker

Current Site Use: "Jack in the Box" Fast-food

Case Type: Soil

CLEANUP OVERSIGHT AGENCIES

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-05769
CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 005566-005769
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- No regulatory oversight, perhaps ever?
- No investigation information.
- Case was transferred between agencies.
- Appears no assessment conducted.
- Appears enforcement will be next tool for obtaining RP compliance.

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show	v All Activities
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	1/15/2010
ENFORCEMENT/ORDERS	Staff Letter	12/15/2009
LEAK ACTION	Leak Reported	4/6/1984
LEAK ACTION	Leak Discovery	4/4/1984
LEAK ACTION	Leak Stopped	4/4/1984



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704696

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE TO603704696

as reported by regulatory agency



Review Conclusions T0603704696

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - LA-RWQCB Comment: "No referral letter from Local Agency" (Los Angeles County).
 - Site appears to have been redeveloped (gas station to a fast food restaurant).
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

MOBIL (T0603701918)

1669 ANAHEIM ST W, LONG BEACH, CA 90813



Possible Reasons Why This Case Is So Old

- Appears to lack oversight and RP involvement, enforcement next?
- No reports/documents in GeoTracker
- GW contamination is the concern
- RP is Government entity, which may signify funding/oversight issues

Case Age: 26 years

RP Identified by Regulator: Barbara A. Kaiser

(Long Beach Redevelopment Agency)

Primary COC: Gasoline

Media of Concern: drinking water supply

Current Land Use: Industrial

Wells Network: 3

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130034
CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED
LONG BEACH/SIGNAL HILL, CITIES OF
CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Soil and Water Investigation Report	1/15/2004
OTHER REGULATORY ACTIONS	Site Visit / Inspection / Sampling	12/19/2003
ENFORCEMENT/ORDERS	Staff Letter	10/17/2003
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	7/15/2003
RESPONSE - REPORTS	Monitoring Report - Quarterly	*1/15/2004
ENFORCEMENT/ORDERS	Staff Letter	5/12/2003
RESPONSE - OTHER	Request for Closure	3/20/2003
RESPONSE - OTHER	Additional Information Report	7/31/2002



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701918

Assessment last 5 years

 2004 – 2009: Monitoring (no report in GeoTracker)

Remediation last 5 years

None

Assessment older than 5 years

 2004: Soil and water investigation (no reports in GeoTracker)

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701918

as reported by regulatory agency



Review Conclusions T0603701918

- Review indicates:
 - No reports/documents/letters available in GeoTracker
 - Only one RWQCB letter in GeoTracker informing RP to reduce GWM frequency to semi-annual (letter of June 2009)
 - Site appears to have been redeveloped
 - Closure Review indicates:
 - 1) Extent of contamination not determined
 - 2) No GW data since 1999
 - 3) GW has elevated TPH-g and benzene concentrations and free product
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful

GAS S/S (T0603700490) 5226 COMPTON AVE, LOS ANGELES, CA 90011



Possible Reasons Why This Case Is So Old

- Limited oversight
- No RP involvement not identified
- Appears to have no site activity/assessment
- no reports/documents in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 25 years
Primary COC: Gasoline

RP Identified by Regulator: None -

Unclaimed in GeoTracker

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: A&J Auto Tires & Repair

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900110016 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Other Report / Document	10/9/2008	
ENFORCEMENT/ORDERS	Staff Letter	9/17/2008	9/17/2008
OTHER REGULATORY ACTIONS	Site Visit / Inspection / Sampling	4/5/2007	4/5/2007
LEAK ACTION	Leak Reported	3/6/1985	

Activities Conducted to Date Based on GeoTracker Info T0603700490

Assessment last 5 years

2007: Site
 Visit/Inspection/Sampling

• 2009: Monitoring?

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603700490

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Recalcitrant RP → RP did not respond to regulator's letter (2008) requesting for additional information
 - Appears no assessment conducted at site
 - Case might have been transferred to Regional Board without site historical information
- Discussion:
 - RP and GeoTracker compliance needs to be addressed
 - Next step → Cleanup closure timeline

GEORGE MITCHEL (T0603701919) 1326 12th St W, Long Beach, CA 90813



Possible Reasons Why This Case Is So Old

- Appears to have limited oversight and RP involvement
- No reports/documents in GeoTracker
- No GW monitoring (no GWM wells installed)

Case Age: 25 years
Primary COC: Gasoline

RP Identified by Regulator: Bruce Harrison

(Bruce Harrison)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Beador Construction Co

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908130043
CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED
LONG BEACH/SIGNAL HILL, CITIES OF
CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Site Conceptual Model Report	1/15/2009	The Lat Vollage of
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - REPORTS	Interim Remedial Action Report	7/15/2008	Marie Marie 9
ENFORCEMENT/ORDERS	Staff Letter	5/27/2008	5/27/2008
RESPONSE - REPORTS	Site Conceptual Model Report	*1/15/2009	



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701919

Assessment last 5 years

- 2007: Site Visit for inspection of Sampling
- 2009: Monitoring referenced in regulator notes, but no data

Assessment older than 5 years


- Tank Removal Report in 2002, Assessment and Monitoring through 2005 noted in regulator notes, but no data
- Closure request 2005

Remediation last 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603701919

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Activities Report indicates multiple Quarterly Monitoring, Site Conceptual Model Reports, Request for Closure (2005 and 2007), and Soil and Water Investigation.
 - Activity Report recorded a "Request for Closure" in 2005.
 - Closure Review by regulator indicates no GWM wells installed.
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful

VENTURA MARKETING DIST PLANT (T0611100023) 3716 VENTURA AVENUE, VENTURA, CA 93001



Possible Reasons Why This Case Is So Old

- No regulatory oversight since leak discovery in 1987
- No RP involvement
- Case was transferred to LA-RWQCB with no report and referral letter
- Extent of contamination undefined

Case Age: 24 years Primary COC: Gasoline

RP Identified: No RP identified – unclaimed

in GeoTracker

Media of Concern: Aquifer used for Drinking

Water Supply

Current Land Use: Open Space?

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 930010343

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPOR	ACTIVITY TYPE	FILTER: Show All Activities	_
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	Leak Discovery	3/1/1987	
LEAK ACTION	Leak Reported	3/1/1987	
LEAK ACTION	Leak Stopped	3/1/1987	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on Geotracker Info T0611100023

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE TO611100023

as reported by regulatory agency



Review Conclusions T0611100023

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Closure Review indicates "Site was transferred from Local Agency."
 - No information available for this case.
 - Site is vacant.
- Discussion:
 - RP and GeoTracker compliance issues need to be addressed
 - Next step → Need for site assessment to determine cleanup closure and timeline

DRAFT: SEPT 3, 2010

FIRE STATION #3 (T0603700532)108 FREMONT AVE N, LOS ANGELES, CA 90012



Possible Reasons Why This Case Is So Old

- Appears to lack oversight and RP involvement
- No reports/documents in GeoTracker (although site activities conducted)
- Extent of contamination unknown
- RP needs to upload site data to GeoTracker

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 24 years

RP Identified by Regulator: Morton Price (City of LA DPW, Bureau of Engineer)

Primary COC: Diesel

Media of Concern: Aquifer for drinking water Current Land Use: Los Angeles Fire Dept

NOT UPDATED

Well Network: 7 wells

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900120361
CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES, CITY OF - CASE #: 3910
CASEWORKER: gloy lung - SUPERVISOR: NONE SPECIFIED

ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2010	7/1/2010
RESPONSE - OTHER	Other Report / Document	6/21/2010	6/21/2010
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	1/15/2010	1/14/2010
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2009	7/1/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	4/15/2009	4/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	1/15/2009	1/20/2009
RESPONSE - WORKPLANS	Corrective Action Plan/ Remedial Action Plan	10/29/2008	10/17/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008	10/15/2008
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	9/29/2008	10/6/2008
RESPONSE - WORKPLANS	Preliminary Site Assessment Workplan	9/25/2008	9/25/2008



Activities Conducted to Date Based on GeoTracker Info T0603700532

Assessment last 5 years

 2008- 2009: Monitoring (quarterly and semiannual) – according to Activities Report

Assessment older than 5 years

None


Remediation last 5 years

 None, but note of request to change remedial action in 2010 letter, no data in GeoTracker for us to see.

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700532


as reported by regulatory agency



Review Conclusions T0603700532

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Site Activity in GeoTracker indicates GW monitoring and other site assessment, possibly some remediation.
 - Given the age of release, potential existing receptors at risk from the release would likely already have been impacted.
- Discussion:
 - RP needs to become GeoTracker compliant, no data uploads for site
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful

PACIFIC VALVES (T0603703839)3201 WALNUT AVE, SIGNAL HILL, CA 90807



Possible Reasons Why This Case Is So Old

- No reports/documents uploaded into GeoTracker
- Limited oversight and RP involvement
- Case may have been transferred between agencies
- Appears no assessment conducted at site
- Enforcement may be next option

Case Age: 24 years

RP Identified by Regulator: Bruce Kusatsky (Pacific Valves) – **Unclaimed in GeoTracker**

Primary COC: Solvents

Media of Concern: Aquifer for drinking water

Current Land Use: Pacific Valves

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-11716 CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
LEAK ACTION	Leak Reported	9/12/1986



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603703839

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603703839

as reported by regulatory agency



Review Conclusions T0603703839

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only two letters from LA-RWQCB in GeoTracker: (1) Notice of Non-Compliance (Sept 2008) and (2) Reduction of GWM frequency (June 2009)
 - Closure Review indicates "No response from RP", Recalcitrant
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Case mentions being solvent case, is it a Petroleum LUFT Site?

DRAFT: SEPT 3, 2010

LUNADA BAY AUTOMOTIVE (T0603704996)

2133 PALOS VERDES DR W, PALOS VERDES ESTATES, CA 90274



Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- Case was transferred between agencies (2009)
- No documents/reports uploaded to GeoTracker
- Appears no assessment conducted
- Enforcement may be next step?

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 24 years **Primary COC:** Diesel

RP Identified: Jack Cierley (Unocal Corporation)

NOT UPDATED

Unclaimed in GeoTracker
 Current Land Use: Gas Station
 Potential Media Effected: Soil

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-11004

CASEWORKER: DANIEL PIROTTON - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 011017-011004

CASEWORKER: PHILLIP GHARIBIANS-TABRIZI - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	12/1/2009
ENFORCEMENT/ORDERS	Staff Letter	10/28/2009
REFERRAL TO OTHER AGENCY	Referral to Regional Board - #C611950	9/15/2009
LEAK ACTION	Leak Reported	3/27/1986
LEAK ACTION	Leak Stopped	3/26/1986
LEAK ACTION	Leak Discovery	2/1/1986



Activities Conducted to Date Based on GeoTracker Info (T0603704996)

Assessment last 5 years

NONE DOCUMENTED

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


NONE DOCUMENTED

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603704996)

as reported by regulatory agency



Review Conclusions T0603704996

- Review indicates:
 - No reports/documents in GeoTracker.
 - Only one letter from RWQCB (Oct 2009) requesting RP for additional information.
 - Case was transferred from Los Angeles County to LA-RWQCB in 2009 with no historical information.
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

KEY CENTERS, INC (T0603705023) 1325 HERMOSA AVE, HERMOSA BEACH, CA 90254



Possible Reasons Why This Case Is So Old

- Limited to none in oversight
- No RP involvement or responses noted
- Case was transferred (February 2009) from LA-County to LA-RWQCB due to groundwater
- No reports/documents upload to GeoTracker
- Lack of enforcement to date

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 24 years

RP Identified by Regulator: Key Centers, Inc (Key

Centers, Inc) - Unclaimed in GeoTracker

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking water

Current Land Use: Commercial Center

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-11141
CASEWORKER: MERCEDES HSU - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 011138-011141
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	5/29/2009
ENFORCEMENT/ORDERS	Staff Letter	3/20/2009
ENFORCEMENT/ORDERS	Staff Letter	3/20/2009
LEAK ACTION	Leak Reported	4/10/1986



Activities Conducted to Date Based on GeoTracker Info T0603705023

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603705023

as reported by regulatory agency



Review Conclusions T0603705023

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Only one letter from LA-RWQCB to RP requesting for additional information
 - Case was transferred (February 2009) from LA-County Dept of Public Works without historical information
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

HENDE'S STATION (T0603701826) 2990 PACIFIC AVE, LONG BEACH, CA 90806



Case Age: 24 years

RP Identified by Regulator: Tha C.Yin

(Keat & Tha Yin) - Unclaimed in GeoTracker

Primary COC: Gasoline

Media of Concern: Aquifer used for drinking

Current Land Use: Pacific Spring Market


CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908060070
CASEWORKER: HA D. NGUYEN - SUPERVISOR: NONE SPECIFIED
LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- No reports/documents in GeoTracker
- Transferred between agencies
- No site/case history
- Appears to have no assessment or has incomplete site characterization
- Enforcement next tool to obtain RP compliance?

NOTE: Data queried from GeoTracker and reviewed in August 2010





Activities Conducted to Date Based on GeoTracker Info T0603701826

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years


None

Remediation older than 5 years

1998: Excavate and Dispose (URF)

IMPEDIMENTS TO CLOSURE T0603701826

as reported by regulatory agency



Review Conclusions T0603701826

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Notice of Non-Compliance sent by regulator in September 2008 to RP.
 - Site is currently an active gas station (privately owned).
 - Closure review states, enforcement being considered.
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful to evaluate site status
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

LONG BEACH HOT MIX/ASPHALT (T0603701864) 1646 32ND ST E, LONG BEACH, CA 90807



Case Age: 23 years Primary COC: Diesel

RP Identified by Regulator: Mr. Jose

Guavalupe Chavez – Unclaimed GeoTracker

Potential Media Affected: Soil **Current Land Use:** Undetermined

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908070152 CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED ONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: SH	ow All Activities	Go
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
ENFORCEMENT/ORDERS	Staff Letter	11/16/2000	11/16/2000
LEAK ACTION	Leak Reported	8/1/1987	

Possible Reasons Why This Case Is So Old

- Limited oversight and no RP involvement
- No reports/documents in GeoTracker
- No assessment conducted to date
- No historical information to review
- Transferred between agencies
- Enforcement appears to be next option



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701864

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603701864

- Review indicates:
 - No reports/documents/letters available in GeoTracker
 - Site appears to be a vacant lot?
 - Only one Notice of Non-Compliance letter from regulator dated September 2008 (2 years ago)
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Any known historical and/or existing data uploaded into GeoTracker would be helpful
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

STABOND CORPORATION (T0603701290)

14010 WESTERN AVE S, GARDENA, CA 90249

Case Age: 22 years **Primary COC:** Toluene

drinking water



Current Land Use: Undetermined

RP Identified by Regulator: Don Martinson

Potential Media Affected: Aquifer used for

CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 902490152 CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

(Stabond Corporation) - Unclaimed in GeoTracker

ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - OTHER	Additional Information Report	8/15/2002	7/26/2005
ENFORCEMENT/ORDERS	Staff Letter	7/10/2002	7/10/2002
LEAK ACTION	Leak Reported	4/19/1988	
LEAK ACTION	Leak Stopped	4/19/1988	AND THE STATE OF T
LEAK ACTION	Leak Discovery	4/19/1988	

Possible Reasons Why This Case Is So Old

- Limited oversight and Recalcitrant RP
- No reports/documents in GeoTracker
- No assessment conducted
- Enforcement appears to be next avenue to gain information about this site

NOTE: Data queried from GeoTracker and reviewed in August 2010



Activities Conducted to Date Based on GeoTracker Info T0603701290

Assessment last 5 years

None Documented

Remediation last 5 years

None Documented


Assessment older than 5 years

None Documented

Remediation older than 5 years

None Documented

IMPEDIMENTS TO CLOSURE T0603701290 as reported by regulatory agency



Review Conclusions T0603701290

- Review indicates:
 - NO reports/documents available in GeoTracker.
 - Regulator sent RP a Notice of Non-Compliance in 2008 → no reply from RP
 - Activity Report in GeoTracker recorded notice sent regarding placing site on Semi-Annual Monitoring schedule in July 2009
 - In URF: "RP is contesting the need for a site investigation to determine the GW quality"
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - Assessment must be performed prior to being able to predict cleanup timeline (if any)

Not a potential closure candidate, no data

PEMACO INC (T0603704068)5050 SLAUSON AVE E, MAYWOOD, CA 90270



Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- Case was transferred between agencies
- No reports/documents/letters uploaded to GeoTracker
- Solvents listed as primary CoC, possibly not a petroleum LUFT case?
- Appears no assessment was conducted

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 22 years
Primary COC: Solvents

RP Identified by Regulator: L.S. Chemical

Corp – Unclaimed in GeoTracker Potential Media Affected: Soil Current Land Use: Golf Course?

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-13417
CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities	_
ACTION TYPE	ACTION	ACTION DATE	to a manual of
LEAK ACTION	Leak Reported	7/19/1988	
LEAK ACTION	Leak Discovery	5/20/1988	
LEAK ACTION	Leak Stopped	5/20/1988	



Activities Conducted to Date Based on GeoTracker Info T0603704068

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603704068

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - In 2009, case transferred from LA County to LA-RWQCB.
 - Site appears to be an open space or part of a golf course has site been redeveloped?
 - CoC listed in URF as Solvents, possibly not a petroleum LUFT
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - What and where are the sensitive receptors located? Closeable now without additional information?

Not a potential closure candidate, no data

RUBEN GONZALES GARAGE (T1000000531)

4201 CITY TERRACE DR, LOS ANGELES, CA 90063



Case Age: 22 years
Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

RP Identified by Regulator: Mr. Ruben Gonzales

(Land Owner) - Unclaimed in GeoTracker

Potential Media Affected: Soil **Current Land Use:** Storage?

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-01912
CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Limited oversight, No RP involvement
- No reports/documents uploaded to GeoTracker
- Appears to have no assessment conducted
- Is this a UST site or SLIC Case?

ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION	ACTION DATE
Site Visit / Inspection / Sampling	10/26/2009
Other Report / Document	7/13/2009
Staff Letter	6/11/2009
Leak Reported	3/10/1988
Leak Stopped	11/13/1987
Leak Discovery	11/13/1987
	ACTION Site Visit / Inspection / Sampling Other Report / Document Staff Letter Leak Reported Leak Stopped



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

None

Remediation last 5 years


• None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T10000000531

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter from LA-RWQCB (June 2009) request for additional information.
 - Activities Report indicated Report and Site Visit, Inspection, Sampling in 2009.
 - Is this a LUFT site or a SLIC site?
- Discussion:
 - Enforcement appears to be next tool to obtain RP compliance
 - What and where are the sensitive receptors located? Closeable now without additional information?

Not a potential closure candidate, no data

MOBIL (T0603701707)402 ATLANTIC AVE, LONG BEACH, CA 90802



Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- No assessment done on the site
- Transferred between agencies
- No reports/documents in GeoTracker
- No site/case historical information

Case Age: 22 years
Primary COC: Gasoline

RP Identified by Regulator: Nate Dakar -

Unclaimed in GeoTracker

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Rite Aid Express 1-Hour

Photo, Vacant Lot

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 908020234

CASEWORKER: MERCEDES HSU - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMEN PIRO - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Ad	ctivities 🔻 Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - OTHER	Other Report / Document	1/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	11/19/2008	11/19/2008
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - OTHER	Additional Information Report	7/31/2002	
ENFORCEMENT/ORDERS	Staff Letter	6/24/2002	6/24/2002
ENFORCEMENT/ORDERS	Staff Letter	3/22/2001	3/22/2001
LEAK ACTION	Leak Discovery	1/25/1989	
LEAK ACTION	Leak Reported	1/25/1989	



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

None Reported

Remediation last 5 years

None Reported


Assessment older than 5 years

None Reported

Remediation older than 5 years

None Reported

as reported by regulatory agency



Review Conclusions T0603701707

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Only one Notice of Non-Compliance letter in GeoTracker from regulator to RP (September 2008).
 - Site appears to be a vacant lot.
 - Consider: (1) the mobile portion of the release has likely attenuated due to the age of the release and (2) if existing receptors are at risk from this site, they are likely already impacted (22 years from release).
- Discussion:
 - Enforcement the next tool to obtain RP compliance
 - What and where are the sensitive receptors located? Closeable now without additional information?

Not a potential closure candidate, no data

OAKDALE MEMORIAL PARK (T0603707050) 1401 S GRAND AVE, GLENDORA, CA 91740



Possible Reasons Why This Case Is So Old

- Appears to have limited site activities at the beginning of the case
- Case was transferred between agencies
- No RP involvement
- No reports/documents in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 21 years
Primary COC: Gasoline

RP Identified by Regulator: Genny Delgado (Oakdale Memorial Park) – Unclaimed GeoTracker Potential Media Affected: Under Investigation Current Land Use: Cemetery and Mortuary

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-23243

CASEWORKER: CHANDRA CANSLER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO





Activities Conducted to Date Based on GeoTracker Info T0603707050

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

1999: UST removal sample results?

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603707050 as reported by regulatory agency

OAKDAI	LE MEMO	ORIAL PARK	(T060370705	0) - <u>(MAP)</u>			
1401 S GRAND AVE GLENDORA, CA 91740 LOS ANGELES COUNTY LUST CLEANUP SITE CLEANUP OVERSIGHT AGENC LOS ANGELES RIVIGER (REGILL CASEWORKER: NOMAN CLEANUP SITE		CB (REGION 4) (LEAD) - CASE #: R-09759					
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE R	EVIEW - THIS	CASE IS NOT READY	FOR GLOSURE AS (OF 10/22/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS TO	CLOSURE						
Other - Nev		removal samples results"	is available in file. Red	wested RP to provide addit	ional info.		
BENEFITS OF AD	DITIONAL WORK						
• Other - Req	guested for addit	ional info.					
SENSITIVE RECEI	PTORS LIKELY TO B	E IMPACTED AND TIME FRAME	FOR IMPACT				
SENSITIVE RECEPT	TOR	TU	ME FRAME FOR IMPACT		COMMENTS		
Groundwater		Ur	determined		No GW sample	e was taken	
and the second second second							

Review Conclusions T0603707050

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only a letter from LA-RWQCB to RP (July 2009) requesting addition information.
 - In May 2009, case was transferred from LA County to LA-RWQCB with "UST Removal Sample Results" (dated Jan 1999).
 - Site is a cemetery/mortuary. Low risk to sensitive receptors?
- Discussion:
 - What and where are the sensitive receptors located? Closeable now without additional information? Current land use may pose additional risk to receptors.

Potential closure candidate, without additional data?

> Case Age: 20 years Primary COC: Diesel

Unclaimed in GeoTracker Potential Media Affected: Soil

PARKER CENTER (T0603700531) 151 JUDGE JOHN AISO, LOS ANGELES, CA 90012



Possible Reasons Why This Case Is So Old

- Appears to have limited oversight
- No/limited RP involvement
- No reports/documents in GeoTracker → no site assessment?
- GW contamination?
- Government entity site, funding issues?
- Request for closure made.

Well Network: 16 wells CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900120352 CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED LOS ANGELES, CITY OF - CASE #: 2220 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

Current Land Use: Parking/Commercial Lot?

RP Identified by Regulator: Mr.Rene Villa-Agustin (Department of General Services) -

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activ	rities V Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Well Destruction Report	10/5/2009	10/5/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - OTHER	Additional Information Report	2/20/2004	3/30/2005
ENFORCEMENT/ORDERS	Staff Letter	12/23/2003	12/23/2003
LEAK ACTION	Leak Reported	7/2/1990	
LEAK ACTION	Leak Discovery	6/22/1990	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603700531

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

 No GW monitoring since 2003 (according to Closure Review)

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603700531

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Appears to have GW contamination issue.
 - Appears to have no site assessment conducted at this site.
 - Recalcitrant RP → regulator sent a "Notice of Non-Compliance" in 2008
 - Activity Report in GeoTracker indicated "Well Destruction Report" dated Oct 2009, Request for Closure, 8-12-2010, what is status?
- Discussion:
 - RP and GeoTracker compliance
 - Content of the "Well Destruction Report"
 - Next step → Status of Closure Request

ESSEX CHEMICAL CORP (T0603702989) 19451 SUSANA RD S, COMPTON, CA 90221



Possible Reasons Why This Case Is So Old

- No reports/documents in GeoTracker
- Case was transferred between agencies (LA County to LA-RWQCB)
- Limited oversight and RP involvement

Case Age: 20 years Primary COC: Toluene

RP Identified by Regulator: Peridot

Chemicals, Inc - Unclaimed in GeoTracker

Potential Media Affected: Soil

Current Land Use: Fleetwood Continental Inc.

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-04560 CASEWORKER: YI LU - SUPERVISOR: NONE SPECIFIED CASEWORKER: MAGDY BAIADY - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show	All Activities 🔻
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	1/15/2010
ENFORCEMENT/ORDERS	Staff Letter	12/15/2009
LEAK ACTION	Leak Reported	3/12/1990
LEAK ACTION	Leak Discovery	8/27/1986



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702989

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

 Confirmation sampling (according to URF)

Remediation older than 5 years

 Vacuum extraction (according to URF)

as reported by regulatory agency

	ANA DOC					CLEANUD OVEDCIO	CUT ACENCIES
OMPTON OS ANGE	SANA RD S I, CA 90221 ELES COUNTY FANUP SITE					LOS ANGELES COL	QCB (REGION 4) (LEAD) - CASE #: 1-0456
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
IMPEDIMENTS		CASE IS NOT READY	FOR GEOSORE AS I	JF 1977/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
Other - I	No referral letter f	om Local Agency					
BENEFITS OF	ADDITIONAL WORK						
• Other - /	No referral letter fr	om Local Agency					
SENSITIVE RE	CEPTORS LIKELY TO	BE IMPACTED AND TIME FRAMI	E FOR IMPACT				
	EPTOR	TIME FRAME	FOR IMPACT	CDMM	ENTS		



Review Conclusions T0603702989

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only letter (December 2009) from LA-RWQCB to RP request for additional information
 - URF indicated case was transferred from LA County to LA-RWQCB with no historical information.
- Discussion:
 - RP and GeoTracker compliance issues
 - Site historical information missing
 - Next step → cleanup procedure and timeline for moving case along

ALHAMBRA GENERAL MAIL FACILITY (T0603703168) 15421 GALE AVE E, INDUSTRY, CA 91745



Case Age: 20 years

RP Identified by Regulator: Mr. Joe Bellino (US Postal Service) - Unclaimed in GeoTracker

Primary COC: Gasoline Media of Concern: Soil

Current Land Use: Mail Facility?

Well Network: 4

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-06116 CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- No reports/documents uploaded to GeoTracker
- Extent of GW contamination undefined

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2008
RESPONSE - WORKPLANS	Other Workplan	10/15/2008
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
ENFORCEMENT/ORDERS	Staff Letter	8/5/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	7/15/2005

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603703168

Assessment last 5 years

• 2008-2009: Quarterly/Semi-Annual "Monitoring Report" (listed under "activities Report" in GeoT, but no reports in GeoT)

Remediation last 5 years

None

Assessment older than 5 years

2002-2005: Quarterly "Monitoring Report" (listed under "Activities Report" in GeoT, but no reports in GeoT)

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603703168

as reported by regulatory agency



Review Conclusions T0603703168

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only three letters from LA-RWQCB: (1) Delinquent Technical Reports (Aug 2008), (2) Notice of Non-Compliance (Sept 2008), and (3) Reduction in GWM frequency (June 2009).
 - Activities Report indicates multiple monitoring activities.
- Discussion:
 - RP and GeoTracker compliance issues need to be addressed
 - Missing reports
 - Next step → site assessment and cleanup timeline

NU-WAY INDUSTRIES (T0603702750) 400 LIVE OAK AVE E, IRWINDALE, CA 91706



Case Age: 20 years Primary COC: Gasoline

RP Identified: Nu-Way Industries – Unclaimed

in GeoTracker

Current Land Use: Industrial **Potential Media Effected:** Soil

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-01077

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 001077

CASEWORKER: |HEANACHO OFO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT AG	CTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
REFERRAL TO OTHER AGENCY	Referral to Regional Board	6/23/1994
LEAK ACTION	Leak Reported	8/14/1990
LEAK ACTION	Leak Discovery	7/12/1990
LEAK ACTION	Leak Stopped	7/12/1990
ENFORCEMENT/ORDERS	* Historical Enforcement	1/1/1965



Possible Reasons Why This Case Is So Old

- No reports/documents/letters uploaded to GeoTracker
- Case transferred between agencies (1994), nothing happened since (16 yrs).
- Very Limited oversight involvement by lead agency, no letters, no reports.

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

NONE DOCUMENTED

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


• 1990: Site assessment (?)

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603702750)

as reported by regulatory agency



Review Conclusions T0603702750

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Case was transferred from Los Angeles County to RWQCB in 1994.
 - Nothing happening with this case (stagnant) with "no file" referenced in closure review report
- Discussion:
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located? Closeable now without additional information?

E.C. CONSTRUCTION COMPANY (T0603704128) 2213 CHICO AVE N, LOS ANGELES, CA 91733



Possible Reasons Why This Case Is So Old

- Limited oversight (almost none)
- No RP identified, Unclaimed Site
- Case was transferred between agencies, no reports in GeoTracker

Case Age: 20 years Primary COC: Gasoline

RP Identified by Regulator: NO RP
IDENTIFIED - Unclaimed in GeoTracker

Potential Media Affected: Soil

Current Land Use: EC Construction Company

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-14000A
CASEWORKER: JOE F. LUERA - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: C-589209
LOS ANGELES COUNTY - CASE #: 13604-14000
LOS ANGELES RWQCB (REGION 4) - CASE #: I-14000
CASEWORKER: JOE F. LUERA - SUPERVISOR: NONE SPECIFIED

ACTION TYPE	ACTION DATE	ACTION
RESPONSE - OTHER	4/15/2009	Other Report / Document
ENFORCEMENT/ORDERS	1/20/2009	Staff Letter
REFERRAL TO OTHER AGENCY	10/22/2008	Referral to Regional Board - #CORR# 589209
LEAK ACTION	3/6/1990	Leak Reported

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Other Report / Document	4/15/2009
ENFORCEMENT/ORDERS	Staff Letter	1/20/2009
REFERRAL TO OTHER AGENCY	Referral to Regional Board - #CORR# 589209	10/22/2008
LEAK ACTION	Leak Reported	3/6/1990

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

None

Remediation older than 5 years

(URF) Excavate and dispose

IMPEDIMENTS TO CLOSURE T0603704128 as reported by regulatory agency

E C. CONSTRUCTION COM	PANY (T0603704128) - (MAP)	
2213 CHICO AVE N SOUTH EL MONTE, CA 91733 LOS ANGELES COUNTY LUST CLEANUP SITE		CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWOCB (REGION 1) (LEAD) - CASE #. I-14000A CASEWORKER: JOE F. LUERA LOS ANGELES COUNTY - CASE #. 13804-14000 LOS ANGELES COUNTY - CASE #. C-589209 LOS ANGELES RWOCB (REGION 4) - CASE #. I-14000 CASEWORKER: JOE F. LUERA
Summary Closure Review Cleanup Status Hist	Programment Regulatory Activities Environmental Data (ESI) Site Maps	/ Documents
CLOSURE REVIEW - THIS CASE IS NOT REA	DY FOR CLOSURE AS OF 10/1/2009	VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS TO CLOSURE		
	atified or Evaluated - New case - insufficient data to make closure d ed - New cose - insufficient data to make closure determination	etermination
BENEFITS OF ADDITIONAL WORK		
Fill-in RI Data Gaps - New case - insufficient data	to make closure determination	
SENSITIVE RECEPTORS LIKELY TO BE IMPACTED AND TIME F	RAME FOR IMPACT	
SENSITIVE RECEPTOR	TIME FRAME FOR IMPACT	COMMENTS

Review Conclusions T0603704128

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - URF indicated the case was closed by LA County in May 1992.
 - In 2008, case was transferred from LA County to LA-RWQCB with no historical information.
- Discussion:
 - RP and GeoTracker compliance
 - Next step → cleanup closure procedure and timeline

PIC A PART AUTO SALVAGE (T0603704166) 4414 LIVE OAK AVE E, MONROVIA, CA 91016



Possible Reasons Why This Case Is So Old

- Limited oversight
- No RP involvement, Unclaimed Site
- Case was transferred between agencies in 1991, No work has occurred since.
- No reports/documents in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 20 years Primary COC: Gasoline

RP Identified by Regulator: Pic A Part Auto

Salvage - Unclaimed in GeoTracker Potential Media Affected: Soil

Current Land Use: Undetermined (open space?)

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-14428
CASEWORKER: JOE F. LUERA - SUPERVISOR: NONE SPECIFIED
CASEWORKER: GREGG KWEY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 013956-014428

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	*5/1/2010
ENFORCEMENT/ORDERS	Staff Letter	12/31/2009
ENFORCEMENT/ORDERS	Staff Letter	12/31/2009
LEAK ACTION	Leak Stopped	5/6/1990
LEAK ACTION	Leak Reported	5/2/1990
LEAK ACTION	Leak Discovery	4/6/1990
ENFORCEMENT/ORDERS	* Historical Enforcement	1/1/1965

Activities Conducted to Date Based on GeoTracker Info T0603704166

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603704166 as reported by regulatory agency

PIC A PART AUT	O SALVAGE	(T060370416	6) - <u>(MAP)</u>		100	
414 LIVE OAK AVE E MONROVIA, CA 91016 .OS ANGELES COUNTY .UST CLEANUP SITE					LOS ANGELES CO	GHT AGENCIES 'QCB (REGION 4) (LEAD) - CASE #: I-14428 UNITY - CASE #: 013956-014428 R: JOHN AWUJQ
Summary Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS	OF 10/7/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS TO CLOSURE						
Other - No referral letter from	om Local Agency					
BENEFITS OF ADDITIONAL WORK						
Other - No referral letter fro	m Local Agency					
SENSITIVE RECEPTORS LIKELY TO BE	IMPACTED AND TIME FRAME	FOR IMPACT				
SENSITIVE RECEPTOR Other	TIME FRAME Undeterm	FOR IMPACT	COMM No re	ENTS ferral letter from Local Age	2004	

Review Conclusions T0603704166

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter from LA-RWQCB (Dec 2009) to RP requesting RP to take corrective action.
 - Case was transferred from LA County to LA-RWQCB (September 1991) with no historical information.
- Discussion:
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located?
 Closeable now without additional information?

ARCO CREDIT UNION (T0603704294) 1907 SEPULVEDA BLVD E, CARSON, CA 90810



Possible Reasons Why This Case Is So Old

- Limited oversight
- No RP involvement
- Case was transferred between agencies
- No reports/documents in GeoTracker
- Appears no assessment conducted

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 20 years
Primary COC: Gasoline

RP Identified by Regulator: ARCO Credit Union

Unclaimed in GeoTracker
 Potential Media Affected: Soil

Current Land Use: Pengo Complete Auto Serv.

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-15338

CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: S	now All Activities
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Other Report / Document	5/1/2009
ENFORCEMENT/ORDERS	Staff Letter	4/1/2009
LEAK ACTION	Leak Reported	3/13/1990

Activities Conducted to Date Based on GeoTracker Info T0603704294

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

1991: Soil investigation?

Remediation older than 5 years

as reported by regulatory agency

THE RESIDENCE OF THE PARTY OF T	CREDIT U		CONTRACTOR DESCRIPTION OF THE PERSON NAMED IN CONTRACTOR DESCRIPTION				
1907 SEPULVEDA BLVD E CARSON, CA 90810 LOS ANGELES COUNTY LUST CLEANUP SITE				CLEANUP OVERSIGHT AGENCIES LOS ANGELES RIVIGCE (REGION 4) (LEAD) - CASE #: I-153; CASEWORKER: MARYAM TAIED! LOS ANGELES COUNTY CASEWORKER: JOHN AWUJO			
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (E5I)	Site Maps / Documents	Community Involvement	
							VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	OF 8/4/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
IMPEDIMENTS SITE ASSESS	TO CLOSURE	CASE IS NOT READY		DF 8/4/2009			VIEW ALL POSSIBLE CLOSURE REVIEW YALUE
IMPEDIMENTS SITE ASSESS Other	TO CLOSURE			DF 8/4/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
SITE ASSESS Other -	TO CLOSURE MENT INCOMPLETE This case is new. A ADDITIONAL WORK		equired.	DF 8/4/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUE
SITE ASSESS Other- BENEFITS OF	MENT INCOMPLETE This case is new. Ac ADDITIONAL WORK This case is new. Ac	dditional information is re	equired. quired.	DF 8/4/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALU

Review Conclusions T0603704294

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter from LA-RWQCB (April 2009) to RP request for additional information.
 - In 2009, case was transferred from LA County to LA-RWQCB with "Tank Closure Reports" (1990), "Site Assessment Proposal" (1990) and "Results of Preliminary Soil Investigation" (1991).
- Discussion:
 - Review historical report and determine next steps
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located? Closeable now without additional information?

GOOD SAMARITAN HOSPITAL (2) (T0603772920)637 LUCAS AVE, LOS ANGELES, CA 90017



NOTE: Site has another case T0603700594

Case Age: 20 years

Primary COC: Other Solvent or Non-Petroleum HC **RP Identified by Regulator**: Barry L. Mangels –

Unclaimed in GeoTracker

Potential Media Affected: Aquifer used for drinking

water supply

Current Land Use: Building Complex

Well Network: 3

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900170216 CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED

OS ANGELES, CITY OF



Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- No reports/documents uploaded to GeoTracker
- Appears to have high GW contamination
- Might have nearby municipal wells, but closure report states 18,349' (3 ½ miles) away

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT ACTIVITY TYPE PILITER: Show All Activities ACTION DATE RESPONSE - REPORTS RESPONSE - WORKPLANS ENFORCEMENT / ORDERS LEAK ACTION LEAK ACTION LEAK ACTION Leak Began 1/1/1965 Leak Began 1/1/1965

Activities Conducted to Date Based on GeoTracker Info T0603772920

Assessment last 5 years

GW monitoring (3 wells)?

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603772920 as reported by regulatory agency





Review Conclusions T0603772920

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter (Notice of Non-Compliance) in GeoTracker (September 2008). Is this a duplicate site listing?
 - Closure Review indicates high petroleum and VOCs in GW.
 - Site is currently a hospital. Is there a risk?
- Discussion:
 - Review historical report and determine next steps
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located? Closeable now without additional information?

OLD FIVE INC. (T0603704357) 17321 CLARK AVE S, BELLFLOWER, CA 90706



Case Age: 20 years (Check the actual age of case)

Primary COC: Gasoline

RP Identified by Regulator: Vickie Throgmortor

(Prime Env.) - Unclaimed in GeoTracker

Potential Media Affected: Soil Current Land Use: Vacant Corner Lot

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-15840

CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- No reports/documents in GeoTracker
- Multiple releases/UST removals?



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go		* INDICATES A REVISED DUE DATE
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE	ACTION DESCRIPTION
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	11/21/2008		
ENFORCEMENT/ORDERS	Staff Letter	9/20/2008	9/20/2008	Directive to take Corrective Action
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008	Notice of Non-Compliance
RESPONSE - REPORTS	Sensitive Receptor Survey Report	10/15/2003		PLUME TRAVEL TIME
RESPONSE - WORKPLANS	Interim Remedial Action Plan	7/15/2003		
RESPONSE - REPORTS	Site Conceptual Model Report	7/15/2003		
RESPONSE - WORKPLANS	MTBE Investigation Workplan	7/15/2003		
ENFORCEMENT/ORDERS	13267 Requirement	3/10/2003	3/10/2003	
LEAK ACTION	Leak Reported	10/17/1990		
LEAK ACTION	Leak Discovery	10/1/1990		
LEAK ACTION	Leak Stopped	10/1/1990		

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

T0603704357 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

 2003: SCM and Sensitive Receptor Survey

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603704357

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Two letters in GeoTracker from LA-RWQCB: (1) Directive to take Corrective Action (Sept 2008), and (2) Notice of Non-Compliance (Sept 2008).
 - According to LA-RWQCB's letter:
 - Site was a former gasoline service station until ~1998. Currently a vacant lot.
 - Over-excavation sampling indicated a maximum of 444-mg/kg of TPH-g, 0.75-mg/kg of benzene, and 0.4-mg/kg of MTBE.
 - Total of 850 tons of impacted soil were removed and disposed of offsite.
 - Actual age of case in question: LA-RWQCB letter indicated USTs were excavated in 2000, but URF was dated 1990 – multiple UST removals?
- Discussion:
 - RP and GeoTracker compliance has not occurred
 - What and where are the sensitive receptors located? Closeable now without additional information?

RAYNE SOFTWATER OF THE VALLEY (T0603702091) 6953 CANOGA AVE, CANOGA PARK, CA 91303



Possible Reasons Why This Case Is So Old

- No reports/documents in GeoTracker
- No RP identified
- Case was transferred between agencies (LAFD and LA-RWQCB)

Case Age: 19 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon

RP Identified by Regulator: NO RP

IDENTIFIED – Unclaimed in GeoTracker

Potential Media Affected: Aguifer used for

drinking water supply

Current Land Use: Rayne Water Systems

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 913030852

CASEWORKER: MARYAM TAIDY - SUPERVISOR; NONE SPECIFIED

LOS ANGELES, CITY OF

CASEWORKER: eloy luna - SUPERVISOR; NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activitie	s 🔻 Go
ACTION TYPE	ACTION		ACTION DATE
RESPONSE - REPORTS	Monitoring Report - Semi-A	nnually	7/15/2009
ENFORCEMENT/ORDERS	Staff Letter		6/15/2009
ENFORCEMENT/ORDERS	Notice to Comply		9/16/2008
LEAK ACTION	Leak Discovery		8/29/2000
LEAK ACTION	Leak Reported		2/12/1991
LEAK ACTION	Leak Stopped		8/29/1990



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603702091

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603702091

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - One Notice on Non-Compliance letter (September 2008) from regulator.
- Discussion:
 - RP and GeoTracker compliance issues need to be addressed
 - Next step → cleanup closure approach and timeline to be evaluated

TEXACO (T0603703083)20858 ARROW HWY E, COVINA, CA 91724



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Texaco -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current Land Use: Penske Truck Rental and

Shell Gas Station

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWGCB (REGION 4) (LEAD) - CASE #: 1-05556

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

CASEWORKER: GREGG KWEY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 5556

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- Case was transferred between agencies
- No reports/documents in GeoTracker
- No historical site information

ACTIVITIES REPORT ACTIVITY TYPE FILTER: | Show All Activities ACTION TYPE **ACTION DATE** RESPONSE - OTHER Other Report / Document 12/31/2009 ENFORCEMENT/ORDERS Staff Letter 11/23/2009 LEAK ACTION 12/20/1991 Leak Reported LEAK ACTION Leak Discovery 10/24/1991

Leak Stopped

10/24/1991

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603703083

Assessment last 5 years

None

Remediation last 5 years

• None


LEAK ACTION

Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE τ0603703083 as reported by regulatory agency



Review Conclusions T0603703083

- Review indicates:
 - No reports/documents available in GeoTracker
 - Only one letter from LA-RWQCB (November 2009) to RP request for additional information
 - Site is currently an active gas station
 - Case was transferred (October 2009) from LA County to LA-RWQCB with no site historical information
- Discussion:
 - RP and GeoTracker compliance issues need to be resolved
 - Next step → assessment and cleanup timelines to be evaluated

LA CO SHERIFF STATION (T0603704904)

23740 MAGIC MOUNTAIN PKWY, SANTA CLARITA, CA 91355



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Bruce Kragen

(LA Co Sheriff Dept)

Potential Media Affected: Drinking water

supply aquifer

Current Land Use: Abco Bail Bonds

Well Network: 30

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: R-10092
CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



Possible Reasons Why This Case Is So Old

- High residual concentrations/LNAPL
- Site assessment appears to begin a few years after leak reported
- Unclear if remediation conducted or effective

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704904

Assessment last 5 years

- None
- GWM only (30 wells)
- Site Conceptual Model

Remediation last 5 years

 Apparently ongoing SVE according to GeoTracker; no reports available for review


Assessment older than 5 years

- UST removals
- Multiple soil borings and wells
- Corrective Action Plan
- Remedial Action Plan
- SVE pilot test

Remediation older than 5 years

- ORC injections
- Vapor extraction
- Soil vapor extraction

IMPEDIMENTS TO CLOSURE T0603704904 as reported by regulatory agency



Review Conclusions T0603704904

- Review indicates:
 - Few investigation, monitoring, or remediation reports available in GeoTracker.
 - Active remediation reportedly ongoing.
 - High residual concentrations (TPH-g, benzene, MTBE), and NAPL present.
 - Latest report in GeoTracker dated 2007.
- Discussion:
 - Effectiveness of current remediation needs to be evaluated
 - Cleanup closure timeline should be outlined in SCM

Not a Potential Closure Candidate, unable to determine status due to lack of recent reports in GeoTracker

BELMONT FIBERS (T0603704108)

1736 CHAPIN ROAD, MONTEBELLO, CA 90640



Possible Reasons Why This Case Is So Old

- No oversight and RP involvement
- Case was transferred between agencies
- No reports/documents uploaded to GeoTracker
- Case is shown as soil only, diesel

Case Age: 18 years
Primary COC: Diesel

RP Identified by Regulator: Belmont Fibers -

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current Land Use: Industrial

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-13835

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities	✓ Go
ACTION TYPE	ACTION		ACTION DATE
RESPONSE - REPORTS	Other Report / Doc	ument	5/15/2009
ENFORCEMENT/ORDERS	Staff Letter		4/15/2009
LEAK ACTION	Leak Reported		3/10/1992
LEAK ACTION	Leak Discovery		8/22/1991



NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704108

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603704108

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Case appears to have been transferred from LA County to LA-RWQCB with no historical information.
 - Little to zero follow up by lead agency, perhaps due to site being listed as soils-only, with diesel as COC?
- Discussion:
 - No data from which to draw any conclusions, closure review states groundwater already impacted, where is evidence?
 - What and where are the sensitive receptors located? Closeable now without additional information?

SMITH'S FOOD & DRUGS/MOSKOWITZ (T0603704432) 3440 SOUTH ST E, LAKEWOOD, CA 90712



Case Age: 18 years
Primary COC: Waste

Oil/Motor/Hydraulic/Lubricating

RP Identified by Regulator: Irving Moskowitz

- Unclaimed in GeoTracker

Potential Media Affected: Soil Current Land Use: 76 Gas Station

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-16734

CASEWORKER: MHAN BAO - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 003841 003972

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Limited oversight and no RP involvement
- Case was transferred between agencies
- No reports/documents in GeoTracker
- Appears no assessment conducted
- Letter dated November 2009 requested RP information by January 2010

NOTE: Data queried from GeoTracker and reviewed in August 2010



Activities Conducted to Date Based on GeoTracker Info T0603704432

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency

SMITH'	'S FOOD 8	DRUGS/MO	SKOWITZ (T	0603704432) -	(MAP)		
3440 SOUTH ST E LAKEWOOD, CA 90712 LOS ANGELES COUNTY LUST CLEANUP SITE			CLEANUP OVERSIGHT AGENCIES LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. 1-16; LOS ANGELES COUNTY - CASE #. 003841 003972 CASEWORKER: JOHN AWUJO				
Summary	Closure Review	Cleanup Status History	Regulatory Activities	Environmental Data (ESI)	Site Maps / Documents	Community Involvement	
CLOSURE	REVIEW - THIS	CASE IS NOT READY	FOR CLOSURE AS C	F 10/7/2009			VIEW ALL POSSIBLE CLOSURE REVIEW VALUES
IMPEDIMENTS	TO CLOSURE						
	. IMPEDIMENTS lo referral letter fr	om Local Agency					
BENEFITS OF A	ADDITIONAL WORK						
Other - N	o referral letter fro	om Local Agency					
SENSITIVE REC	CEPTORS LIKELY TO B	E IMPACTED AND TIME FRAMI	E FOR IMPACT				
Other	EPTOR	TIME FRAME Unde term	FOR IMPACT ined	<u>сомм</u> No re	ENTS ferral letter from Local Ag	ency	

Review Conclusions T0603704432

- Review indicates:
 - No reports/documents available in GeoTracker.
 - One letter from LA-RWQCB (November 2009) to RP requesting for additional information by January 2010, no record of compliance to this request.
 - Case was transferred from LA County to LA-RWQCB with no historical information.
 - Site is currently an active gas station.
- Discussion:
 - Review historical report and determine next steps
 - No data from which to draw any conclusions

SHELL GAS STATION (T0603760075)405 AVENUE 64 N, LOS ANGELES, CA 90042



Case Age: 18 years
Primary COC: Gasoline

RP Identified by Regulator: Deborah Pryor (Shell Oil products) and Wafica Megally (Megally Perry,

Inc) - Unclaimed in GeoTracker

Potential Media Affected: Under Investigation

Current Land Use: CA Gasoline, U-Haul

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 900420152

CASEWORKER: ARMAN TOUMARI - SUPERVISOR: NONE SPECIFIED

LOS ANGELES, CITY OF - CASE #: 4434

CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Lack of oversight
- No RP involvement
- Case was transferred between agencies, no activity for 15 year period
- Appears no assessment extent of contamination undefined

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - WORKPLANS	Soil and Water Investigation Workplan	8/16/2010
ENFORCEMENT/ORDERS	Staff Letter	7/14/2010
ENFORCEMENT/ORDERS	Staff Letter	6/24/2010
RESPONSE - OTHER	Other Report / Document	*7/15/2010
ENFORCEMENT/ORDERS	Staff Letter	6/29/2009
RESPONSE - OTHER	Other Report / Document	11/21/2008
ENFORCEMENT/ORDERS	Staff Letter	10/21/2008
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008
RESPONSE - OTHER	Additional Information Report	10/31/2007
ENFORCEMENT/ORDERS	Staff Letter	9/28/2007
LEAK ACTION	Leak Reported	3/31/1992
LEAK ACTION	Leak Discovery	3/31/1992
LEAK ACTION	Leak Began	1/1/1965

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603760075

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603760075

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Site is currently an active gas station.
 - LA-RWQCB sent a letters to the RP in October 2008 and June 2009 to request additional information, no record of reply received.
 - In August 2007, case was transferred from LA Fire Dept to LA-RWQCB with 'Result of Tank Exploration and Soils Test at Tank Closure Site 1992'
 - Closure Review indicates "Potential threat to nearby municipal well."
- Discussion:
 - Review historical report (if any) and determine next steps
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located? Closeable now without additional information?

KRATKA RIDGE SKI AREA (T0603700082)

STAR ROUTE 2 T3N R10W S14, LA CANADA-FLINTRIDGE, CA 91011



Possible Reasons Why This Case Is So Old

- No documents/reports/letters uploaded to GeoTracker.
- Case was transferred between agencies.
- Appears to have no oversight nor RP involvement to date.
- Listed as soils only case- solvent, non Petr.

NOTE: Location not found on map (check

address)

Case Age: 18 years

Primary COC: Other Solvent or Non-

Petroleum HC

RP Identified: Los Angeles Winter

Development - Unclaimed in GeoTracker

Potential Media Effected: Soil Current Land Use: Commercial

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 052493-10
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	12/16/1992
LEAK ACTION	Leak Discovery	10/10/1991

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603700082)

Assessment last 5 years

NONE DOCUMENTED

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


NONE DOCUMENTED

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (TO603700082)

as reported by regulatory agency



Review Conclusions T0603700082

- Review indicates:
 - No reports/documents/letters in GeoTracker.
 - Case was transferred from Los Angeles County (LIA) to RWQCB with apparently no case historical information nor referral letter.
- Discussion:
 - Verify if this is a Federal LUST case
 - RP and GeoTracker compliance issues
 - Cleanup closure plan and timeline?
 - What and where are the sensitive receptors located?
 Closeable now without additional information?

M C NOTTINGHAM (T0603772692) 3150 MAXSON ROAD N, EL MONTE, CA 91732



Possible Reasons Why Is This Case So Old

- Limited oversight
- No RP involvement
- No reports/documents/letters uploaded to GeoTracker
- Appears no site assessment conducted
- Case was transferred between agencies?

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 17 years

Primary COC: Trichloroethylene (TCE) RP Identified by Regulator: Lawrence Polzin (M C Nottingham of CA) - Unclaimed in

GeoTracker

Potential Media Affected: Soil

Current Land Use: Dixie Diesel & Electric Inc

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-13377

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: CLUP# 569528

CASEWORKER: TIM SMITH - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities ACTION TYPE **ACTION DATE** RESPONSE - REPORTS Other Report / Document 10/15/2008 ENFORCEMENT/ORDERS Staff Letter 9/5/2008 LEAK ACTION Leak Discovery 6/23/1993 LEAK ACTION Leak Reported 6/23/1993 LEAK ACTION 1/1/1965



Activities Conducted to Date Based on GeoTracker Info T0603772692

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE τ0603772692 as reported by regulatory agency



Review Conclusions T0603772692

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - The last and only oversight was in 2008.
 - Case might have been transferred from LA County without any historical information.
- Discussion:
 - RP and GeoTracker compliance issues need to be addressed
 - Next step → Cleanup closure procedure and timelines to be evaluated

ARCADIA FIRE STATION #2 (T0603703607) 630 BALDWIN AVE S, ARCADIA, CA 91007



Media of Concern: Soil

Case Age: 17 years

Primary COC: Diesel

Current Land Use: Fire Department

Arcadia) - Unclaimed in GeoTracker


CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-10328 CASEWORKER: NHAN BAO - SUPERVISOR: NONE SPECIFIED

RP Identified by Regulator: David Odell (City of

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show	v All Activities
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	6/30/2009
ENFORCEMENT/ORDERS	Staff_Letter	5/26/2009
LEAK ACTION	Leak Reported	1/4/1994
LEAK ACTION	Leak Discovery	1/4/1994





- No reports/documents in GeoTracker
- Case was transferred between agencies (LA County to LA-RWQCB)
- Appears to lack oversight and RP involvement

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603703607

as reported by regulatory agency



Review Conclusions T0603703607

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter from LA-RWQCB requesting RP for additional information.
 - RWQCB letter indicates Tank Closure Report (1993) and Addendum (1994) available – reports not in GeoTracker.
 - Case was transferred (Oct 2009) from LA County to LA-RWQCB → case was "revived" when County of LA Dept of Public Works raised concerns of GW impacts.
- Discussion:
 - RP and GeoTracker compliance issues need to be addressed
 - Next step → cleanup closure procedure and timelines to be evaluated

SHELL PIPELINE COMPANY (T0603703983) 2459 REDONDO AVE, SIGNAL HILL, CA 90806



Case Age: 17 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon

RP Identified by Regulator: Shell Oil Company

Potential Media Affected: Soil

Current Land Use: Crimson Pipeline LP and So

Cal Pump & Supply LLC

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-12597

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: IHEANACHO OFO - SUPERVISOR: MANUEL R REGALADO



Possible Reasons Why This Case Is So Old

- No reports/documents uploaded into GeoTracker
- Case was transferred between agencies
- Limited oversight and RP involvement
- Not clear this is a LUST site, pipeline leak?

NOTE: Data queried from GeoTracker and reviewed in August 2010

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities **ACTION TYPE** ACTION **ACTION DATE** RESPONSE - OTHER Other Report / Document 12/31/2009 ENFORCEMENT/ORDERS Staff Letter 11/23/2009 LEAK ACTION Leak Reported 6/17/1993 LEAK ACTION Leak Discovery 3/24/1993

Activities Conducted to Date Based on GeoTracker Info T0603703983

Assessment last 5 years

None

Remediation last 5 years

None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603703983

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter (Nov 2009) from LA-RWQCB to RP request for additional information.
 - Case was transferred from LA County to LA-RWQCB (October 2009) with no historical information.
- Discussion:
 - Review historical report and determine next steps
 - No data from which to draw any conclusions
 - Is this a Leaking UST case or leak from a pipeline?

RANCHO LOS AMIGOS HOSPITAL (T0603701265) 7601 IMPERIAL HWY E, DOWNEY, CA 90242



Case Age: 16 years
Primary COC: Gasoline

RP Identified by Regulator: Tony Billson

(Rancho Los Amigos Hospital)

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Parking Lot?

Wells Network: 9

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 902420016

CASEWORKER: NOMAN CHOWDHURY - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go		
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE	
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009		
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009	
RESPONSE - REPORTS	Site Conceptual Model Report	1/15/2008	2/13/2008	
RESPONSE - REPORTS	Remedial Progress Report	1/15/2008	2/13/2008	

Possible Reasons Why This Case Is So Old

- No reports/documents in GeoTracker
- Appears to have limited oversight and RP involvement
- Free product in GW?

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701265 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

- 2005: SCM, Soil and Water investigation
- 2006, 2007, 2008: SCMs

Remediation last 5 years

 2005, 2008: Remedial Progress Reports


Assessment older than 5 years

- 2000: GW well installation
- 2000-ongoing: Monitoring
- 2003: SCM and Estimated Plume Travel Time
- 2004: SCM

Remediation older than 5 years

2000: Excavate and dispose (URF)

IMPEDIMENTS TO CLOSURE T0603701265 as reported by regulatory agency



Review Conclusions T0603701265

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one regulator letter uploaded in GeoTracker informing RP to reduce GW sampling frequency.
 - Activities Report in GeoTracker indicates many activities conducted (no reports).
 - Last activity entry in GeoTracker dated July 2009.
 - Site is currently a hospital site.
- Discussion:
 - RP and GeoTracker compliance, No data from which to draw any conclusions
 - What and where are the sensitive receptors located?

PARAMOUNT ASSOCIATES (T0603704103) 14507 PARAMOUNT BLVD, PARAMOUNT, CA 90723



Case Age: 17 years
Primary COC: Gasoline

RP Identified by Regulator: Dwayne Butler (Paramount Associates) - Unclaimed in

GeoTracker

Potential Media Affected: Soil

Current Land Use: Paramount Unified

Community Day School

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-13817

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO

Possible Reasons Why This Case Is So Old

- Nothing was done on this site
- Limited oversight
- NO reports/documents uploaded to GeoTracker
- Recalcitrant RP (has not reported since 2000)
- Lack of enforcement

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities ACTION TYPE ACTION ACTION DATE ENFORCEMENT/ORDERS Notice to Comply 9/16/2008 ENFORCEMENT/ORDERS * Historical Enforcement 2/20/1998 ENFORCEMENT/ORDERS Staff Letter 2/20/1998 LEAK ACTION Leak Reported 11/29/1993

11/10/1987

11/10/1987

Leak Discovery

<u>Leak Stopped</u>

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker info T0603704103

Assessment last 5 years

None

Remediation last 5 years

None

LEAK ACTION


LEAK ACTION

Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE τ0603704103 as reported by regulatory agency



Review Conclusions T0603704103

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one Notice of Non-Compliance letter in GeoTracker from LA-RWQCB (September 2008) to RP.
 - Closure Review indicates "did not submit site conceptual model" and "RP has not reported since 2000 – need updated data to determine case status."
- Discussion:
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located?
 Closeable now without additional information?

CIRCUS AUTO SALES (T0603704149) 7416 FIRESTONE BLVD, DOWNEY, CA 90241



Possible Reasons Why This Case Is So Old

- Appears to have no oversight for the past
 16 years since leak was reported
- No RP identified/No RP involvement
- Case was transferred between agencies
- No reports/documents/letters uploaded into GeoTracker

Case Age: 16 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon

RP Identified by Regulator: Circus Auto

Sales – Unclaimed in GeoTracker
Potential Media Affected: Soil
Current Land Use: G&S Auto Sales

LEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: I-14271

CASEWORKER: AHMAD J. LAMMA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show	All Activities
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	12/31/2009
ENFORCEMENT/ORDERS	Staff Letter	11/23/2009
LEAK ACTION	Leak Reported	9/13/1994
LEAK ACTION	Leak Discovery	2/14/1989

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704149

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603704149

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one letter from LA-RWQCB (Nov 2009) to RP request for additional information.
 - In 2009, case was transferred from LA County to LA-RWQCB with no historical information.
- Discussion:
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located? Closeable now without additional information?

76 PRODUCTS STATION #3349 (T0603704888) 1430 LA BREA BLVD N, INGLEWOOD, CA 90302



Case Age: 16 years **Primary COC:** Waste

Current Land Use: Valero Gas Station (Inactive

RP Identified by Regulator: Tosco/76 Production

Potential Media Affected: Soil

Oil/Motor/Hydraulic/Lubricating

and Fenced according to report)

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-09979 CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED LOS ANGELES COUNTY - CASE #: 010113-024674

CASEWORKER: RANI IYER - SUPERVISOR: MANUEL R REGALADO CASEWORKER: MANUEL R REGALADO - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	✓ Go
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - OTHER	Other Report / Document	9/1/2010
ENFORCEMENT/ORDERS	Staff Letter	6/22/2010
REFERRAL TO OTHER AGENCY	Referral to Regional Board	6/3/2010
LEAK ACTION	Leak Reported	1/4/1995
LEAK ACTION	Leak Stopped	12/19/1994
LEAK ACTION	Leak Discovery	12/19/1994
ENFORCEMENT - OTHER	Unknown	

Possible Reasons Why This Case Is So Old

- Transferred between agencies in 2010
- Extent of GW contamination not fully assessed
- Limited oversight at the beginning of the case, now RWQCB lead

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704888

Assessment last 5 years

- 2008-ongoing: GWM
- 2008: Sensitive Receptor Survey
- 2005: Soil boring

Remediation last 5 years

None

Assessment older than 5 years


1997: Soil sampling

Remediation older than 5 years

1997: 845-tons contaminated soil removed

IMPEDIMENTS TO CLOSURE T0603704888

as reported by regulatory agency



Review Conclusions T0603704888

- Review indicates:
 - Site was transferred from LA County to LA-RWQCB (June 2010) with a "Tank Closure Report (Oct 1997)" → transfer was requested by RP in 2009
 - On June 2010, LA-RWQCB issued a letter to RP request for additional information
 - Report (Dec 2009) indicates site is currently inactive and fenced
 - Groundwater assessment only began in 2008 (*unable to open some of the GWM Reports in GeoTracker)
- Discussion:
 - Groundwater monitoring and benefit of remediation?
 - Cleanup procedure and timeline need to be established

Unable to determine overall status

SEALY MATTRESS CO (T0603704431) 8664 RHEEM ST, SOUTH GATE, CA 90280



Case Age: 15 years
Primary COC: Diesel

RP Identified: Kenneth Walker (Sealy Mattress

Manufacturing)

Current Land Use: Industrial

Potential Media Effected: Aguifer used for

drinking water supply

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: I-16710 CASEWORKER: JOE F. LUERA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY

CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO



ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities **ACTION ACTION DATE** RESPONSE - REPORTS RESPONSE - REPORTS Monitoring Rep 1/15/2010 Monitoring Report - Semi-Annually 7/15/2009 ENFORCEMENT/ORDERS Staff Letter 6/15/2009 RESPONSE - REPORTS Monitoring Report - Quarterly 4/15/2009 Monitoring Report - Quarterly 7/15/2003 ENFORCEMENT/ORDERS 13267 Requirement 1/14/2002 LEAK ACTION Leak Reported 6/14/1995 LEAK ACTION Leak Discovery 4/25/1994

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- No documents/reports uploaded into GeoTracker
- Case transferred between agencies

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603704431)

Assessment last 5 years

GW monitoring (?)

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


NONE DOCUMENTED

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603704431)

as reported by regulatory agency



Review Conclusions T0603704431

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only one RWQCB letter (June 2009) request for reduction in GW monitoring frequency, and a geo map.
 - Activities Report reference Monitoring Reports (2003, 2009 and 2010).
- Discussion:
 - RP and GeoTracker compliance, No data from which to draw any conclusions
 - What and where are the sensitive receptors located?

EASTERN AUTO REPAIR (T0603704611) 1711 EASTERN AVE, CITY TERRACE, CA 90063



Possible Reasons Why This Case Is So Old

- Limited oversight
- No RP involvement
- No reports/documents in GeoTracker appears no assessment conducted
- Case was transferred between agencies

Case Age: 15 years
Primary COC: Gasoline

RP Identified by Regulator: Mr. Luis Martinez (A&L Enterprises) – Unclaimed in GeoTracker

Potential Media Affected: Soil

Current Land Use: Casarez Used Tires?

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-03463

CASEWORKER: MARYAM TAIDY - SUPERVISOR: NONE SPECIFIED

LOS ANGELES COUNTY - CASE #: 003347-003463

CASEWORKER: ABIGAIL FLORES - SUPERVISOR: NONE SPECIFIED



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: 9	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
RESPONSE - REPORTS	Other Report / Documer	nt 7/31/2009
ENFORCEMENT/ORDERS	Staff Letter	6/11/2009
LEAK ACTION	Leak Reported	3/20/1995
LEAK ACTION	Leak Discovery	1/19/1995
LEAK ACTION	Leak Stopped	1/19/1995

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704611

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603704611 as reported by regulatory agency



Review Conclusions T0603704611

- Review indicates:
 - No reports/documents available in GeoTracker.
 - LA-RWQCB sent a letter to the RP in June 2009 to request additional information.
 - In March 2009, case was transferred from LA County to LA-RWQCB with no historical information.
- Discussion:
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located?
 Closeable now without additional information?

LOST HILLS SHERIFF'S STATION (T0603704776) 27050 AGOURA RD, CALABASAS, CA 91301



Possible Reasons Why This Case Is So Old

- Little activity between 1995 and 2005
- Case transferred between agencies (2009)
- Limited soil investigation, incomplete GW assessment
- No remediation
- Gov't entity site, possible funding issues?

NOTE: Data queried from GeoTracker and reviewed in August 2010

Case Age: 15 years

Primary COC: Diesel, Gasoline, Waste Oil/Motor/Hydraulic/Lubricating

RP Identified: Gary Tse and Tom Bellizia (LA

Co Sheriff's Dept/Facility Planning)

Potential Media Effected: Aquifer used for

drinking water supply

Current Land Use: Sheriff Dept

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-08531

CASEWORKER: DAVID M. BJOSTAD

LOS ANGELES COUNTY - CASE #: 008032-008531

CASEWORKER: RANI IYER

CASEWORKER: MANUEL R REGALADO



ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities Go		
ACTION TYPE	ACTION	ACTION DATE	
OTHER REGULATORY ACTIONS	Technical Correspondence / Assistance / Other	10/8/2009	
RESPONSE - OTHER	Other Report / Document	9/30/2009	
ENFORCEMENT/ORDERS	Staff Letter	8/31/2009	
REFERRAL TO OTHER AGENCY	Referral to Regional Board	7/2/2009	
CLEANUP ACTION	Excavate and Dispose	10/27/2005	
LEAK ACTION	Leak Reported	6/13/1995	
LEAK ACTION	Leak Discovery	1/18/1995	

Activities Conducted to Date Based on GeoTracker Info (T0603704776)

Assessment last 5 years

2005: Subsurface investigation

Remediation last 5 years

• NONE

Assessment older than 5 years


NONE

Remediation older than 5 years

2005: Excavate and dispose

IMPEDIMENTS TO CLOSURE (TO603704776)

as reported by regulatory agency



Review Conclusions T0603704776

- Review indicates:
 - Insufficient site characterization
 - Case was transferred between agencies in 2009
 - Agency has requested RP for additional information and data collection (2009 and 2010)
 - Subsurface investigation conducted in 2005 indicated soil samples collected from under dispensers and fuel lines were NDs
- Discussion:
 - Address data gaps → complete soil and groundwater investigation
 - What and where are the sensitive receptors located? Closeable now without additional information?

Unable to determine case status due to insufficient information

ARROWHEAD MTN SPRING WATER CO (T0603704649) 13109 BUDLONG AVE S, GARDENA, CA 90247



Case Age: 16 years Primary COC: Gasoline

RP Identified by Regulator: Ms. Kelly Mills (The Perrier Group) - Unclaimed in GeoTracker

Potential Media Affected: Soil

Current Land Use: Arrowhead Bottled Water

CLEANUP OVERSIGHT AGENCIES

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: R-04646
CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED
LOS ANGELES COUNTY - CASE #: 004477-004646
CASEWORKER: RANI IYER - SUPERVISOR: MANUEL R REGALADO



Possible Reasons Why This Case Is So Old

- No oversight apparent 14 years of **<u>delay</u>** between leak discovery and attempts at oversight by agency
- Case was transferred between agencies
- Lack of RP response

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities	→ Go
ACTION TYPE	ACTION	AC	TION DATE
RESPONSE - REPORTS	Additional Information	Report 8	3/7/2009
ENFORCEMENT/ORDERS	Staff Letter	6,	/10/2009
ENFORCEMENT/ORDERS	Staff Letter	6,	/10/2009
LEAK ACTION	Leak Reported	1	L/4/1995
LEAK ACTION	Leak Stopped		1/4/1995
LEAK ACTION	Leak Discovery	1	1/4/1995

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603704649

Assessment last 5 years

None

Remediation last 5 years


None

Assessment older than 5 years

- 1994: Site Closure Report?
- 2002: Site sampling report?

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603704649

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Only two letters from LA-RWQCB to RP in June 2009 to request addition information.
 - In April 2009, case was transferred from LA County to LA-RWQCB with "Site Closure Report" (1994) and "Soil Sampling Report" (2002).
- Discussion:
 - No data from which to draw any conclusions
 - What and where are the sensitive receptors located?
 Closeable now without additional information?

MENASCO AEROSYSTEM DIVISION (T0603702503) 100 CEDAR AVE E, BURBANK, CA 91502



THIS IS NOT A FEDERAL UST CASE (SLIC)

Case Age: 22 years
Primary COC: Solvents

RP Identified: Colt Industries Inc -

Unclaimed in GeoTracker

Current Land Use: Commercial Potential Media Effected: Soil

Well Network: 13

LEAK ACTION

900 100 P

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 109.0842
CASEWORKER: Larry Moore - SUPERVISOR: NONE SPECIFIED
CASEWORKER: LARRY MOORE - SUPERVISOR: JEFFREY HU
LOS ANGELES RWQCB (REGION 4) - CASE #: 915020098
CASEWORKER: Larry Moore - SUPERVISOR: NONE SPECIFIED

CASEWORKER: LARRY MOORE - SUPERVISOR: JEFFREY HU

1/15/1988

ACTIVITIES REPORT

ACTIVITY TYPE FILTER: Show All Activities

ACTION TYPE

LEAK ACTION

LEAK REPORT

LEAK ACTION

LEAK Discovery

LEAK ACTION

LEAK DISCOVERY

LEAK ACTION

LEAK DISCOVERY

Leak Stopped

Possible Reasons Why This Case Is So Old

- Limited oversight and RP involvement
- Limited information available in GeoTracker
 → no report/document

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info (T0603702503)

Assessment last 5 years

NONE DOCUMENTED

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years

NONE DOCUMENTED

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603702503)

as reported by regulatory agency

MENASCO AEROSYSTE	N DIVISION (106037028	JOS) - (INIALE)			
UST CIEANIIP SHE	GROUNDWATER MONITO FOR WELLS MONITORED - SEMI-ANNI		CASEWORKI CASEWORKI LOS ANGELES R CASEWORKI		LEAD) - CASE #: 109.08 CASE #: 915020098
Summary Closure Review Cleanup Status	s History Regulatory Activities Environment	mental Data (ESI) Site Maps / D	Occuments Community Involvem	ent	
CLOSURE REVIEW - THIS CASE IS NOT	READY FOR CLOSURE AS OF 1/7/2	010		VIEW ALL POSSIB	LE CLOSURE REVIEW VALU
BENEFITS OF ADDITIONAL WORK					
Other - VOC contamination (SLIC case)					
SENSITIVE RECEPTORS LIKELY TO BE IMPACTED AND T	TIME FRAME FOR IMPACT				
SENSITIVE RECEPTOR	TIME FRAME FOR IMPACT	COMMENTS			
Other	Undetermined	VOC contami	ination (SLIC case)		
e History e RWQCB issued a CAO to Coltec Indi undale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th	ustries, inc.'on July 5, 2002 This facil y, the USEPA has issued a General I le facility's former industrial activities	ity has been named a Resp Notice Letter and a 104E L involved machining, manufi	ponsible Party by the USEPA etter and the facility is considuation, metal plating, anod	dered a Principle fizing of parts and	Responsible Party for equipment used by
e History e RWQCB issued a CAO to Coltec Indu	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General I se facility's former industrial activities is aerospace applications. Volatile C ent chromium have been detected in ampled quarterly. The amended Genellent chromium in the soil and groundy I Vapor Extraction (GVE) system to re	ity has been named a Resp Notice Letter and a 104E Linvolved machining, manufi organic Compounds (VOCs the subsurface soil and in the real Waste Discharge Requater. The facility is now im emediate the VOCs. A risk	ponsible Party by the USEPA etter and the facility is consi- acturing, metal plating, anod i) including TCE, PCE, 1,1-E ne groundwater underlying the uirement (WDR) permit was plementing a site-wide progra assessment report was sub	dered a Principle I izing of parts and o Dichloroethylene (1 ne site.Recently co approved and the ram to remediate t	Responsible Party for equipment used by 1,1-DCE) 1,1,1- Instructed offsite facility has complete the hexavalent
e History RWQCB issued a CAO to Coltec Indundale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou chloroethane (1,1,1-TCA) and hexavale undwater monitoring wells are being seilot study for the remediation of hexaval omium. The facility has operated a Soil proved by OEHHA and the Regional Borroved Borrowed Borro	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General I te facility's former industrial activities as aerospace applications. Volatile Cent chromium have been detected in ampled quarterly. The amended Genelent chromium in the soil and groundy I Vapor Extraction (SVE) system to repard. Groundwater monitoring continuations.	ity has been named a Resp Notice Letter and a 104E Linvolved machining, manufi organic Compounds (VOCs the subsurface soil and in the real Waste Discharge Requater. The facility is now im emediate the VOCs. A risk	ponsible Party by the USEPA etter and the facility is consideraturing, metal plating, anod s) including TCE, PCE, 1,1-E he groundwater underlying the uirement (WDR) permit was plementing a site-wide prograssessment report was sub s.	dered a Principle I izing of parts and o izindloroethylene (1 ne site. Recently co approved and the ram to remediate i mitted, reviewed,	Responsible Party for equipment used by 1,1-DCE) 1,1,1- instructed offsite facility has complete the hexavalent and the results
RWQCB issued a CAO to Coltec Indi ndale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou hibroethane (1,1,1¬TCA) and hexavale undwater monitoring wells are being se lot study for the remediation of hexaval omium. The facility has operated a Soil roved by OEHHA and the Regional Bo	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General referring the facility's former industrial activities as aerospace applications. Volatile on the continum have been detected in ampled quarterly. The amended General formium in the soil and groundy I Vapor Extraction (SVE) system to repard. Groundwater monitoring continues.	ity has been named a Resp Notice Letter and a 104E L involved machining, manuf- organic Compounds (VOCs the subsurface soil and in it eral Waste Discharge Requester. The facility is now im- emediate the VOCs. A risk nues on a semi-annual basi	ponsible Party by the USEPA etter and the facility is consideraturing, metal plating, anod s) including TCE, PCE, 1,1-E he groundwater underlying the uirement (WDR) permit was plementing a site-wide prograssessment report was sub s.	dered a Principle I izing of parts and o Dichloroethylene (1 ne site.Recently co approved and the ram to remediate t	Responsible Party for equipment used by 1,1-DCE) 1,1,1- instructed offsite facility has complete the hexavalent and the results
RWQCB issued a CAO to Coltec Indundale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou. Holtocethane (1,1,1-TCA) and hexavale undwater monitoring wells are being sailot study for the remediation of hexaval mium. The facility has operated a Soil proved by OEHHA and the Regional Bo	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General I te facility's former industrial activities is aerospace applications. Volatile Oent chromium have been detected in: ampled quarterly. The amended General I vapor Extraction (SVE) system to repard. Groundwater monitoring continuation of the status History Regulatory Activities.	ity has been named a Resp Notice Letter and a 104E L involved machining, manuf- organic Compounds (VOCs the subsurface soil and in it eral Waste Discharge Requester. The facility is now im- emediate the VOCs. A risk nues on a semi-annual basi	ponsible Party by the USEPA etter and the facility is consideraturing, metal plating, anod s) including TCE, PCE, 1,1-E he groundwater underlying the uirement (WDR) permit was plementing a site-wide prograssessment report was sub s.	dered a Principle I izing of parts and o izindloroethylene (1 ne site. Recently co approved and the ram to remediate i mitted, reviewed,	Responsible Party for equipment used by 1,1-DCE) 1,1,1- instructed offsite facility has complete the hexavalent and the results
RWQCB issued a CAO to Coltec Indundale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou U.S. Department of Defense for variou highoreothane (1,1,1-TCA) and hexavale undwater monitoring wells are being sallot study for the remediation of hexaval onium. The facility has operated a Soil oroved by OEHHA and the Regional Borroved by OEHHA and the Regional Borroved by OEHHA and Borring Logs (GEO NO SITE MAPS JEMENTTALS FOUND FOR THIS SIGN OCCUMENTALS FOUND FOR THIS SIGN OCCUMENTALS	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General I te facility's former industrial activities is aerospace applications. Volatile Oent chromium have been detected in: ampled quarterly. The amended General I vapor Extraction (SVE) system to repard. Groundwater monitoring continuation of the status History Regulatory Activities.	ity has been named a Resp. Notice Letter and a 104E Linvolved machining, manufilinganic Compounds (VOCs the subsurface soil and in the rall Waste Discharge Requater. The facility is now immediate the VOCs. A risk nues on a semi-annual basi	ponsible Party by the USEPA etter and the facility is considered and the facility including TCE, PCE, 1,1-E. including TCE, PCE, 1,1-E. including a facility including a site wide programmenting a site wide programment for the facility is subject to the facility including a site wide programment. Including the facility is subject to the facility including the facility is considered and the facility is cons	dered a Principle I izing of parts and joichlorcettylene (1 ne site.Recently co approved and the ram to remediate imitted, reviewed,	Responsible Party for equipment used by 1,1-DCE) 1,1-1 instructed offsite facility has complete the hexavalent and the results
RIVOCE Issued a CAO to Coltec Ind. Indale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou hibroethane (1,1,1-TCA) and hexavale undwater monitoring wells are being se ilot study for the remediation of hexaval omium. The facility has operated a Soil proved by OEHHA and the Regional Bc Summary Closure Review Cleanu Site Mapo and Boring Logs (GEC NO SITE MAP SUBMITTALS FOUND FOR THIS SITE OCCUMENTS SITE OCCU	ustries, inc.'on July 5, 2002. This facility, the USEPA has issued a General It is facility's former industrial activities is aerospace applications. Volatile Cent chromium have been detected in ampled quarterly. The amended General It vapor Extraction (SVE) system to repar the system of the control of th	ity has been named a Resp. Notice Letter and a 104E Linvolved machining, manufirganic Compounds (VOCS the subsurface soil and in the real Waste Discharge Requater. The facility is now impredict the VOCs. A risk nues on a semi-annual basi	ponsible Party by the USEPA etter and the facility is consider acturing, metal plating, anod s) including TCE, POE, 1,1-E, he groundwater underlying th uirement (WDR) permit was plementing a site-wide programs sub scuments. Samuella land	dered a Principle izing of parts and objective the site Recently coapproved and the ram to remediate is mitted, reviewed,	Responsible Party fe equipment used by 1,1-DCE) 1,1,1- instructed offsite facility has complete the hexavalent and the results
e History R WOCB issued a CAO to Coltec Indu andale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou holtorethane (1,1,1=TCA) and hexavale undwater monitoring wells are being sa illot study for the remediation of hexaval orium. The facility has operated a Soil proved by OEHHA and the Regional Bo Summary. Closure Review. Cleanu Ster Mapp and Boring Logs (GEO NO SITE MAP SUBMITTALS FOUND FOR THIS SITE MAP SUBMITTALS FOUND FOR THIS SITE DOCUMENTS.	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General refacility's former industrial activities is aerospace applications. Volatile Oent chromium have been detected in ampled quarterly. The amended General reference in the soil and ground Vapor Extraction (SVE) system to repard. Groundwater monitoring continues the status History Regulatory Activities FAGUITY.	ity has been named a Resp. Notice Letter and a 104E Linvolved machining, manufalgranic Compounds (VOCs the subsurface soil and in the rall Waste Discharge Requater. The facility is now immediate the VOCs. A risk nues on a semi-annual basi	ponsible Party by the USEPA etter and the facility is considered and the facility including TCE, PCE, 1,1-E. including TCE, PCE, 1,1-E. including a facility including a site wide programmenting a site wide programment for the facility is subject to the facility including a site wide programment. Including the facility is subject to the facility including the facility is considered and the facility is cons	dered a Principle I izing of parts and joichlorcettylene (1 ne site.Recently co approved and the ram to remediate imitted, reviewed,	Responsible Party for equipment used by 1,1-DCE) 1,1-1 instructed offsite facility has complete the hexavalent and the results
e History a RWOCB issued a CAO to Coltec Indu endale North Operable Unit. Additionally Glendale Chromium Operable Unit. Th U.S. Department of Defense for variou holrocethane (1,1,1=TCA) and hexavale undwater monitoring wells are being sa ilot study for the remediation of hexaval omium. The facility has operated a Soil proved by OEHHA and the Regional Bo Summary. Closure Review. Cleanu Site Mappined Boring Eops (Gao NO SITE MAP SUBMITTALS FOUND FOR THIS SITE SITE OCCUPANTIALS FOUND FOR THIS SITE SITE GENERAL WORSE RA-2007-0019 SERIES	ustries, inc.'on July 5, 2002. This facily, the USEPA has issued a General refacility's former industrial activities is aerospace applications. Volatile Oent chromium have been detected in ampled quarterly. The amended General reference in the soil and ground Vapor Extraction (SVE) system to repard. Groundwater monitoring continues the status History Regulatory Activities FAGUITY.	ity has been named a Resp. Notice Letter and a 104E Linvolved machining, manufalgranic Compounds (VOCs the subsurface soil and in the rall Waste Discharge Requater. The facility is now immediate the VOCs. A risk nues on a semi-annual basi	consible Party by the USEPA etter and the facility is considered and the facility including TCE, PCE, 1,1-E. including TCE, PCE, 1,1-E. including a site-wide programment (WDR) permit was plementing a site-wide programment facility in the facility is seen and the facility is considered and the facility is seen and the facility is considered and	dered a Principle I lizing of parts and joichlorcettylene (1 ne site.Recently co approved and the ram to remediate imitted, reviewed,	Responsible Party for equipment used by equipment used by equipment used by the party of the par

Review Conclusions T0603702503

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Limited information in GeoTracker only two letters from RWQCB: (1) General Waste Discharge (2007) and (2) approval of workplan to collect additional soil and soil gas samples (2006).
 - THIS IS NOT A FEDERAL UST CASE Closure Review indicates this is a <u>SLIC case</u> (VOCs issue in subsurface soil and GW).
- Discussion:
 - Remove this case from the LUST program in GeoTracker

Not Federal UST case → SLIC Case

UCC/LINDE DIVISION (T0603701471) 19200 HAWTHORNE BLVD, TORRANCE, CA 90503



Possible Reasons Why This Case Is So Old

- Case was transferred between agencies
- Missing historical reports and documents
- No RP involvement
- No report/document in GeoTracker

NOTE: MIGHT NOT BE A FEDERAL UST CASE

Case Age: 24 years

RP Identified by Regulator: UCC/Linde

Division (UCC/Linde Division) - Unclaimed in

GeoTracker

Primary COC: Acetone Media of Concern: Soil

Current Land Use: Praxair Inc/Distribution

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #: 905030134

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

TORRANCE, CITY OF

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities	•
ACTION TYPE A	CTION	ACTION DATE	
LEAK ACTION L	eak Reported	12/18/1986	
LEAK ACTION L	eak Discovery	12/8/1986	

NOTE: Data queried from GeoTracker and reviewed in August 2010

Activities Conducted to Date Based on GeoTracker Info T0603701471

Assessment last 5 years

None

Remediation last 5 years

None


Assessment older than 5 years

None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701471

as reported by regulatory agency



Review Conclusions T0603701471

- Review indicates:
 - No report/document/letter available in GeoTracker.
 - Only one letter from City of Torrance (Sept 1995) in GeoTracker: This case might not be a Federal UST Case since letter indicated above-ground source of acetone
- Discussion:
 - Possibly remove this case from LUST in GeoTracker

Might not be a Federal UST Case

MARINE HARDWARE CO (T0603701962)

1322 17TH ST W, LONG BEACH, CA 90813



Case Age: 19 years

Primary COC: Other Solvent or Non-Petroleum

Hydrocarbon <- Federal UST case?

RP Identified by Regulator: Frank Brannen (Marine Hardware Co) - Unclaimed in

GeoTracker

Potential Media Affected: Aquifer used for

drinking water supply

Current Land Use: Complex/Parking Lot?

Wells Network: 6

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWOCB (REGION 4) (LEAD) - CASE #: 908130516

CASEWORKER: JAY HUANG - SUPERVISOR: NONE SPECIFIED

LONG BEACH/SIGNAL HILL, CITIES OF

CASEWORKER: CARMENIPIRO - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- Limited oversight
- Recalcitrant RP
- No reports/documents in GeoTracker

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	▼ Go	
ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE
RESPONSE - REPORTS	Monitoring Report - Semi-Annually	7/15/2009	
ENFORCEMENT/ORDERS	Staff Letter	6/15/2009	6/15/2009
RESPONSE - REPORTS	Soil and Water Investigation Report	6/1/2009	
ENFORCEMENT/ORDERS	Staff Letter	3/20/2009	3/20/2009
ENFORCEMENT/ORDERS	Notice to Comply	9/16/2008	9/16/2008
RESPONSE - REPORTS	Monitoring Report - Quarterly	10/15/2004	9/22/2004

NOTE: Data queried from GeoTracker and reviewed in August

Activities Conducted to Date Based on GeoTracker Info

T0603701962 (NOTE: Based on "Activities Report" in GeoTracker)

Assessment last 5 years

- 2002-2004: Quarterl monitoring
- 2009: Quarterly monitoring

Remediation last 5 years

None

Assessment older than 5 years

- 1997: GW monitoring (6 wells)
- 2002, 2009: Soil and water investigation

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603701962

- Review indicates:
 - No reports/documents available in GeoTracker.
 - Three letters from regulator: (1) Notice of Non-Compliance (Sept 2008), (2) Delinquent Site Assessment Report (March 2009), and (3) GWM Frequency Reduction (June 2009).
 - Closure Review indicates (1) Elevated benzene concentrations, and
 (2) No GW data since 2004.
 - Activities Report in GeoTracker indicates multiple site/case activities.
- Discussion:
 - Report/document associated with case placed in GeoTracker
 - RP and GeoTracker compliance
 - Cleanup closure timeline

CHARNOCK WELLS (T0603701212)

11375 WESTMINSTER, LOS ANGELES, CA 90066



Possible Reasons Why This Case Is So Old

- Not a UST Site case was opened for well head treatment purpose.
- Appears to have limited oversight and no RP involvement.

NOTE: Data queried from GeoTracker and reviewed in August 2010

NOTE: Not Federal UST case

Case Age: 15 years
Primary COC: Gasoline

RP Identified: BLANK - Unclaimed in

GeoTracker

Current Land Use: Residential

Potential Media Effected: Aguifer used for

drinking water supply

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES RWQCB (REGION 4) (LEAD) - CASE #. 900660143
CASEWORKER: WEIXING TONG
LOS ANGELES COUNTY
CASEWORKER: JOHN AWUJO

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
ENFORCEMENT/ORDERS	Staff Letter	4/10/2003
LEAK ACTION	Leak Stopped	10/30/1996
LEAK ACTION	Leak Reported	6/1/1995
LEAK ACTION	Leak Discovery	6/1/1995



Activities Conducted to Date Based on Geotracker Info (T0603701212)

Assessment last 5 years

NONE DOCUMENTED

Remediation last 5 years

NONE DOCUMENTED

Assessment older than 5 years


NONE DOCUMENTED

Remediation older than 5 years

NONE DOCUMENTED

IMPEDIMENTS TO CLOSURE (T0603701212)

as reported by regulatory agency



Review Conclusions T0603701212

- Review indicates:
 - No reports/documents/letters available in GeoTracker.
 - Case Closure Review indicates "<u>This is not a UST site</u>.
 The case was opened for well head treatment purpose."
- Discussion:
 - Remove case in GeoTracker from LUST site

Not a UST Case