



3N16 and Crab Creek, focusing on road delivery to crossing (Spring 2008, Erin Lutrick)



Same location as above, but shows more of south creek bank. Shows rill entering the creek from the road bed. (Fall 2008, Robert Taylor)





Less gravel seen - some likely buried. Road work removed rill entering the creek from the road. (June 2009, Robert Taylor)



More gravel seen; road has had maintenance work (October 2009, Mikaila Rimbenieks)