35600 Verdant View P.O. Box 16 The Sea Ranch, CA 95497-0016 CSA 41 Zone 2 On-Site Wastewater Disposal Zone

> tel: 707-785-2756 Fax: 707-785-9756

North Coast Regional Water Quality Control Board

RE: Draft Waste Discharge Requirements or Sonoma County Service Area 41, Zone 2, Sea Ranch Association Onsite Wastewater Management Zone Order Number R1-2017-0014

File: SC, Sea Ranch, #41, Zone 2, Sea Ranch, Sonoma County WDID No. 1B89051RSON

Comments to Draft Order of March 9, 2017:

- 1. Facility Address (Table 1. Discharger Information): 35600 Verdant View Drive/PO Box 16, The Sea Ranch, CA 95497
- 2. Page 3, Table 3, Facility Information: Facility Address, correct zip code: 95497, and Mailing address: PO Box 16, The Sea Ranch, CA 95497
- 3. Page 4, last paragraph number change from 1,189 to 1,201
- 4. Page 5, first paragraph number (s) change from 935 to 943, and 254 to 258
- 5. Page 5, add that the Onsite wastewater disposal zone currently consists of 1,539 total possible systems, barring any future lot consolidations or lot splits.
- 6. Attachment B-Monitoring and Reporting Program, II D: Suggest it should read "Ground water well water measurements and groundwater constituent sampling are to be the primary indicator of achievement of applicable water quality objectives. Supplemental and supportive surface water monitoring may be conducted on a regular basis to support findings of causative factors of contamination within groundwater monitoring wells. Surface waters that exhibit similar qualitative values of samples taken upstream and downstream of a study area nay be subject to deletion in reporting requirements."
 - And III.E added as "Ground water well sampling sites to be increased in number at locations shown in Exhibit B-2."
- 7. "SEA RANCH WASTE DISPOSAL ZONE NO.2, WATER QUALITY MONITORING AND SEPTIC SYSTEM INSPECTION PROGRAM date April 1989 should be labeled Attachment B-1.

Provided by Randy H. Burke, REHS, The Sea Ranch Water Company

And Richard Stover, Wastewater Grade II



