

# ANRESCO

INCORPORATED

ANALYSIS RESEARCH CONSULTING

## HEADQUARTERS

1370 Van Dyke Ave., San Francisco, CA 94124-3313

Tel: (415) 822-1100 Fax: (415) 822-6615

Toll Free: 800-359-0920

www.anresco.com

797 Channel Street  
San Pedro, California 90731-1411

Tel: (310) 833-4598

Fax: (310) 833-1585

2310 N. W. 55th Court #123 & 124

Fort Lauderdale, Florida 33309-2743

Tel: (954) 486-2233

Fax: (954) 486-2886

November 28, 2001

Mirant Corp.  
Potrero Power Plant  
Chemical Laboratory  
1201 A Illinois Street  
San Francisco, CA

File Number: 1101429

Attn: Brian Kuhn/Avtar Vivdee Phone: 695-2601 Fax: 695-2639/ (925) 875-0300

Re: Four oil samples for PCB analysis (rush) marked as:

(A) PO-01-320 (Date Sampled: 11/28/01 Time Sampled: 1025)

(B) PO-01-321 (Date Sampled: 11/28/01 Time Sampled: 1100)

(C) PO-01-322 (Date Sampled: 11/28/01 Time Sampled: 1030)

(D) PO-01-323 (Date Sampled: 11/28/01 Time Sampled: 1040)

(Purchase Order: PO-212413)

Received: 11/28/2001

## PCB RESULTS

<u>Lab Sample Number</u>	<u>Sample Description</u>	<u>Concentration (ppm)</u>	<u>Detection Limit (ppm)</u>
(A)PO-01-320	#9 Auxillary Transformer Bank	None Detected	1.0
(B)PO-01-321	#11 Main Transformer Bank	None Detected	1.0
(C)PO-01-322	#12 Main Transformer Bank	None Detected	1.0
(D)PO-01-323	#13 Startup Transformer Bank	None Detected	1.0

Method: Modification of EPA SW-846 8080A for waste oils (Sulfuric acid clean-up and packed column GC-ECD)

CA ELAP Certificate Number: 1523

Reported by:  
ANRESCO, INC.

  
Hing Man Mang  
Senior Chemist

HM:G/2001/November/1101429