

APR. 2, 2001

MELINDA BECKER  
CAL. REGIONAL WATER QUALITY CONTROL BOARD  
320 4TH STREET, STE 200  
LOS ANGELES CALIF. 90013

SUB: WHITE FOAM ON SURFACE OF DISCHARGE  
WATER, DOWN STREAM HILL CANYON WASTE  
WATER TREATMENT PLANT. CITY OF THOUSAND  
OAKS

DEAR MS. BECKER; PHONE  
PERHAPS YOU RECALL OUR CONVERSATION A SHORT  
TIME BACK RE: SURFACE FOAM AT OUR PROPERTY  
LOCATED APPROX 1 MILE DOWNSTREAM OF THE  
MOUTH OF HILL CANYON ON CODEJO CREEK. THE  
CONDITION OCCURS QUITE OFTEN. AS I RECALL, YOU  
SUGGESTED I SUBMIT PHOTOS SHOWING SAID CONDITION.

ENCLOSED PLEASE FIND EIGHT PHOTOS THAT SHOW THE  
FOAMING CONDITION - PLEASE NOTE SEVEN TAKEN  
ON 4/21/2001 AND ONE OF 2/24/2001. MAY I CALL YOUR  
ATTENTION TO THE SILT IN THE WATER, EROSION  
OF OUR LAND ON ITS WAY TO MUGU LAGOON.

IN THE PAST, I HAVE WRITTEN TO SEVERAL OFFICIALS  
IN YOUR OFFICE, I AM STILL WAITING FOR A SINGLE  
RESPONSE.

YOURS TRULY

Howard Jones Trustee  
LENA JONES TRUST  
4009 SUNSET LANE.  
OXFORD CA. 93035



