

[Home \(/go/site/7258/\)](#)

[/ Photo Gallery \(http://www.refugioresponse.com/go/doctype/7258/265622/Photo-Gallery\)](http://www.refugioresponse.com/go/doctype/7258/265622/Photo-Gallery)

[/ Before and After Images for Refugio Oil Spill Response](#)

DATE: June 24, 2015 11:48:43 AM PDT

Before and After Images for Refugio Oil Spill Response

Restoration of Pipeline Excavation Site, SSE View

Section



Left: May 25, 2015.

Right: June 3 2015.

Restoration of Pipeline Excavation Site, ENE View

Section



Left: May 24, 2015.

Right: June 3, 2015.

Restoration of Pipeline Excavation Site, NNE View

Section 1



Left: May 24, 2015.

Right: June 3, 2015.

Refugio State Beach During Cleanup



Left: May 29, 2015.

Right: June 3, 2015.

Kelp at Refugio State Beach During Cleanup



Left: May 22, 2015.

Right: June 3, 2015.


Cleanup teams between Refugio and El Capitan State Beach



Left: May 29, 2015.

Right: June 3, 2015.

Refugio State Beach During Cleanup



Left: May 29, 2015.

Right: June 3, 2015.

Bluff at Refugio State Beach During Cleanup, Pending Restoration



Left: June 2, 2015.

Right: June 17, 2015.

Section 4

Bluff at Refugio State Beach During Cleanup, Pending Restoration



Section 4

Left: June 2, 2015.

Right: June 17, 2015.

Drainage Culvert North of HWY 101



Section 2

Left: May 21, 2015.

Right: June 23, 2015.