

ATTACHMENT 3

REFERENCE EXHIBITS FOR UNCONTESTED TENTATIVE CDO NO. R3-2017-0016

Below is a list of reference Exhibits for the above-referenced matter. All Exhibits are provided by reference with a hyperlink. All Exhibits are available on the internet at:

http://www.waterboards.ca.gov/centralcoast/water_issues/programs/enforcement/index.shtml

- Exhibit 1:** [Waste Discharge Requirements Order No. R3-2014-0047 for Cambria Community Services District Class II Surface Impoundment](#)
- Exhibit 2:** [California Code of Regulations, title 27, section 20240](#)
- Exhibit 3:** [California Code of Regulations, title 27, section 20320 \(providing Table 4.1. Construction Standards for Units\)](#)
- Exhibit 4:** [Combined Notices of Violation dated February 9, 2017](#)
- Exhibit 5:** [Cambria CSD's Surface Impoundment Inspection Logs from January 1 to February 27, 2017](#)
- Exhibit 6:** [Email dated March 14, 2017, Reporting Monitoring Well Measurements and Distances from Surface Impoundment Liner to Groundwater Surface](#)
- Exhibit 7:** [Email dated April 11, 2017, Reporting Monitoring Wells Depths to Groundwater](#)
- Exhibit 8:** [Email dated May 2, 2017, Reporting Freeboard Measurement and Monitoring Well Depths to Groundwater](#)
- Exhibit 9:** [Water Board Staff Spreadsheet – Groundwater Distances to Liner](#)
- Exhibit 10:** [“Technical Memorandum 2: Physical Setting and Waste Characterization,” dated July 15, 2014, revised August 1, 2014 \(attachments excluded\)](#)
- Exhibit 11:** [“Technical Memorandum: Evaluation of Brine Evaporation Pond for Inundation from the 0.1-Percent Annual Exceedance Probability Storm Event,” dated November 11, 2014](#)
- Exhibit 12:** [Memorandum “Assessment of Depth to Groundwater at Van Gordon Reservoir”](#)
- Exhibit 13:** [Surface Impoundment Drawing](#)
- Exhibit 14:** [LCRS and VZMS Drawing](#)
- Exhibit 15:** [Cambria CSD's Responses to April 13, 2017 RWQCB Letter](#)