



Discharge to  
Morrison Creek  
Outfall 002


Admin Plume  
Treatment System



NO.	NAME
1	ADMINISTRATION
2	GRAND POND NO. 1
3	DATA BUILDING
4	DATA BUILDING
5	SHARPER SERVICE/STORAGE LABORATORY
6	LABORATORY
7	WAITING TANK
8	WAITING TANK
9	WAITING TANK
10	WAITING TANK
11	WAITING TANK
12	WAITING TANK
13	PLUMBER/MECHANIC WELLS
14	PLUMBER/MECHANIC WELLS
15	PLUMBER/MECHANIC WELLS
16	PLUMBER/MECHANIC WELLS
17	PLUMBER/MECHANIC WELLS
18	PLUMBER/MECHANIC WELLS
19	PLUMBER/MECHANIC WELLS
20	PLUMBER/MECHANIC WELLS
21	PLUMBER/MECHANIC WELLS
22	PLUMBER/MECHANIC WELLS



- EXPLANATION**
- IRCTS BOUNDARY
  - GROUNDWATER MONITORING WELL (STSM = SACRAMENTO TEST SITE WELL)
  - GROUNDWATER EXTRACTION WELL
  - INJECTION WELL
  - PERCHED GROUNDWATER MONITORING WELL
  - DOMESTIC WATER SUPPLY WELL
  - DRYWELL
  - CONCRETE
  - DIRT ROAD
  - MAINTENANCE
  - PLANTERS
  - POUND



Attachment E  
The Boeing Company  
Southern Groundwater Study Area Extraction and Treatment System  
Inactive Rancho Cordova Test Site  
Sacramento County