

Photo Log
April 20, 2011 inspection of the Red Ink Maid/Big Seam Mine
Page 1 of 2



Photo 1. Fresh soil erosion scar at toe of WD #5



Photo 2. Signs of recent traffic and rutting



Photo 3. Water bar needs maintenance



Photo 4. Sloughing of the cut slope on road



Photo Log
April 20, 2011 inspection of the Red Ink Maid/Big Seam Mine
Page 2 of 2

Photo 5. Pans under equipment and fuel tank



Photo 7. Head scarp/soil movement WD #4

Photo 6. Soil cracks at top of WD#4



Photo 8. Fresh earth flow scar at toe of WD #4