

Photo 1. Dolly Creek below WM-3. Blue-green color of the water is from discharge of acid mine drainage water containing copper and other metals from the Walker Mine.




Photo 3. Dolly Creek below WM-4. Blue-green color of the water is from discharge of acid mine drainage water containing copper and other metals from the Walker Mine.



Photo 2. Dolly Creek below WM-3. Blue-green color of the water is from discharge of acid mine drainage water containing copper and other metals from the Walker Mine.



Photo 4. Walker Mine Tailings, Circa 1986. Showing conditions similar to photo taken by Paul L. Henchey in September 1951.