

---

## Central Valley Regional Water Quality Control Board

3 August 2012

Kevin Hinman  
Cruiser Haven, Inc.  
1145 Second Street, #A202  
Brentwood, CA 94513

### **REPORT OF RECENT INSPECTION AND NOTICE OF VIOLATION, HOLLAND RIVERSIDE MARINA, CONTRA COSTA COUNTY**

The Holland Riverside Marina Wastewater Treatment Facility (WWTF) is regulated by Waste Discharge Requirements (WDR) Order 5-01-093 for a monthly average discharge not to exceed 7,500 gallons per day (gpd). The wastewater from the marina is discharged into two lined ponds and two percolation/evaporation ponds.

On 18 July 2012, Seylin Savy and myself conducted an inspection of the Holland Riverside Marina WWTF. John Trujillo accompanied us during the inspection. A site inspection photograph log is enclosed with this letter.

The following summarizes the observations made and information obtained from the Mr. Trujillo during the inspection:

- The Wastewater Treatment Plant was appropriately signed and fenced.
- The vegetation surrounding wastewater ponds 3 and 4 appeared to be freshly mowed.
- The freeboard in lined ponds 1 and 2 was approximately 3.5 feet.
- A mechanical aerator was observed in pond 1. At the time of the inspection, the aerator was not operating. John Trujillo indicated that the aerator typically runs approximately four hours per day.
- Abundant vegetation (duckweed) was observed in pond 2.
- Pond 3 was almost dry with a freeboard of approximately 4 feet. Pond 4 was dry.
- Freeboard staff gauges were not observed in any of the wastewater ponds.
- Slight odors were noted near the wastewater ponds.

#### **Inspection Violations**

The vegetation (duckweed) observed floating in pond 2 is a violation of Discharge Specification B.6 of the WDRs which states: *"Ponds shall be managed to prevent breeding of mosquitoes. In particular, ... Dead algae, vegetation, and debris shall not accumulate on the water surface..."*

By **15 September 2012**, please provide a report (with photos) showing that the vegetation has been removed from Pond 2. In addition, to accurately measure the freeboard in the ponds, a measuring device (i.e. staff gauge) needs to be installed in each of the ponds. Please include documentation along with photos of the staff gauges installed in each of the ponds.

If you have any questions about the inspection report or notice of violation please contact Guy Childs at (916) 464-4648

Original signed by

WENDY WYELS, Supervisor  
Compliance and Enforcement Section

Enc. Inspection photographs

cc: Randall Sawyer, Contra Costa Environmental Health Department, Concord

CIWQS Inspection No: 9099543

CWIQS Violation ID No: 931922

gjc: 3 Aug-12



Wet well with influent pump



Looking north at lined aeration pond no. 1



Close-up photo of pond no. 1



Mechanical aerator in pond no. 1 in operation.



Looking east at pond no. 2. Abundant duck weed observed on surface of the pond.



Looking north at pond 3 and 4. Minor amount of wastewater observed in pond 3.