

Holland Riverside Marina - Photographs received from the Discharger on 1 April 2016, following Board staff's 25 March 2016 site inspection.



Wooden fence surrounding the wet well.

Wooden fence surrounding the wet well.



Some debris and vegetation (blackberry bushes) removed near the pond areas

Blackberry bushes removed near the pond areas.

Holland Riverside Marina - Photographs received from the Discharger on 1 April 2016, following Board staff's 25 March 2016 site inspection.



Wastewater pond 1 that has been labeled.



Wastewater pond 2 that has been labeled.



Newly installed sign for pond 3.



Looking north at pond 3 showing that the blackberry bushes have been removed.

Holland Riverside Marina - Photographs received from the Discharger on 1 April 2016, following Board staff's 25 March 2016 site inspection.



Well cap installed in on the two groundwater monitoring wells.

Well cap installed in the other groundwater monitoring well.



West Monitoring Well that is freshly painted, labeled and locked.

East Monitoring Well that is freshly painted, labeled and locked.