



Linda S. Adams
Secretary for
Environmental Protection

California Regional Water Quality Control Board San Diego Region

Over 50 Years Serving San Diego, Orange, and Riverside Counties

Recipient of the 2004 Environmental Award for Outstanding Achievement from USEPA



Arnold Schwarzenegger
Governor

9174 Sky Park Court, Suite 100, San Diego, California 92123-4353
(858) 467-2952 • Fax (858) 571-6972
[http:// www.waterboards.ca.gov/sandiego](http://www.waterboards.ca.gov/sandiego)

July 22, 2010

In reply refer to:
642697:adai

Mr. Constantine Kontaxis
Department of Transportation
4050 Taylor Street
San Diego, CA 92110

Dear Mr. Kontaxis:

**SUBJECT: MONITORING REPORT REVIEW FOR THE
TECATE TRUCK INSPECTION STATION**

The California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) has reviewed the January–December 2009 annual monitoring report submitted by the California Department of Transportation in accordance with the Monitoring and Reporting Program (MRP) of Order No. R9-2007-0148.

The San Diego Water Board identified the following violations of the MRP of Order No. R9-2007-0148:

1. MRP Section D requires you to monitor the septic tanks and report the results listed in the table D.1. This information was missing in the submitted report.
2. MRP Section E requires you to submit a record of the type, quantity, manner, and location of disposal of all solids removed in the course of sewage treatment. This information was missing in the submitted report.

Please be aware these violations subject you to possible further enforcement action by the San Diego Water Board, including administrative enforcement orders requiring the you to cease and desist from violations, or to clean up waste and abate existing or threatened conditions of pollution or nuisance; administrative assessment of civil liability in amounts of up to \$5,000 per day per violation;¹ referral to the State Attorney General for injunctive relief; and referral to the District Attorney for criminal prosecution.

¹ Under authority of California Water Code section 13350.

Mr. Kontaxis
Tecate Truck Inspection Station

2

July 22, 2010

The next monitoring report required to be submitted is the January–December 2010 semiannual monitoring report, which is due by February 1, 2010.

In the subject line of any response, please include the requested "in reply refer to" information located in the heading of this letter. Please contact Amanda Dai at 858-627-3977 or via email at adai@waterboards.ca.gov if you have any questions on this matter.

Sincerely,

Robert Morris

Robert W. Morris, P.E.
Senior Water Resource Control Engineer
Groundwater Basins Branch

Regulatory Measure ID: 375121
Violation ID: 877417 and 877418