



California Regional Water Quality Control Board

San Diego Region



Linda S. Adams
Secretary for
Environmental Protection

Over 50 Years Serving San Diego, Orange, and Riverside Counties
Recipient of the 2004 Environmental Award for Outstanding Achievement from USEPA

Arnold Schwarzenegger
Governor

9174 Sky Park Court, Suite 100, San Diego, California 92123-4353
(858) 467-2952 • Fax (858) 571-6972
<http://www.waterboards.ca.gov/sandiego>

February 7, 2011

Michael Thornton
General Manager
San Elijo Joint Powers Authority
2695 Manchester Avenue
Cardiff by the Sea, CA, 92007

In reply refer to:

CRU:01-0125:jcofrancesco
WDID: 9 000000125

Dear Mr. Thornton:


SUBJECT: COMPLIANCE EVALUATION INSPECTION REPORTS FOR THE SAN ELIJO JOINT POWERS AUTHORITY, ORDER NO. R9-2005-0100, NPDES PERMIT NO. CA0107999

On July 15, 2009, a compliance evaluation inspection (CEI) was performed at the San Elijo Water Reclamation Facility, which discharges to the Pacific Ocean via the San Elijo Ocean Outfall (SEOO). The CEI was conducted by Danny O'Connell, Brenner Perryman, and James Ashby of PG Environmental, LLC, a contractor providing services for the San Diego Regional Water Quality Control Board (San Diego Water Board). The purpose of the inspection was to evaluate compliance with San Diego Water Board Order No. R9-2005-0101 (NPDES Permit No. CA0107999).

Please review the enclosed inspection report carefully. The report includes a summary of the inspector's findings and an evaluation of the effectiveness in complying with the permit requirements. The San Diego Water Board has completed review of the inspection report and has the following comment:

The report noted the following: The Discharger routinely failed to complete the number of exceedances field ("NO. EX") on their Discharge Monitoring Reports (DMRs) (refer to Exhibit 1). In the event of no exceedances, "0" should be entered for each parameter. Please ensure the DMRs are filled in correctly in future reports.

California Environmental Protection Agency



HONOLULU

Mr. Thornton,
San Elijo Joint Powers Authority
CEI Report

- 2 -

February 7, 2011

We appreciated you and your staff's assistance during the CEI. In the subject line of any response, please include the requested "In reply refer to:" information located in the heading of this letter. For questions pertaining to the subject matter, please contact Joann Cofrancesco at 858-637-5589 or jcofrancesco@waterboards.ca.gov.

Respectfully,

Robert Morris

Robert W. Morris
Senior WRC Engineer

RWM:bdk:jlc

Enclosure:

CEI Report for San Elijo Water Reclamation Facility

cc: (by email):

Mr. Ken Greenberg, USEPA Region 9, greenberg.ken@epa.gov

Craig Blett, PG Environmental, LLC, craig.blett@pgenv.com

Danny O'Connell, PG Environmental, LLC, danny.oconnell@pgenv.com

Order No.	R9-2005-0101
NPDES No.	CA0107999
CIWQS Place IDs	255265
WDID	9 000000125
CIWQS Reg. Measure No.	375641
CIWQS Inspection ID	1872940

California Environmental Protection Agency

 Recycled Paper

HPON\0\N