

Corrective Action Plans Submitted

Per Article 11, Section 2728 of the California Underground Storage Tank Regulations

Date Plan Received	Site Address	Proposed Remedial Actions - Soil	Proposed Remedial Actions - Groundwater
8/5/2011	Thrifty Oil Station #14 120 E. Imperial Hwy Brea	Soil Vacuum Extraction	Not Applicable
12/2/2010	Unocal/76 Station No. 5792 4002 Ball Road Cypress	In-situ Enhanced Bioremediation	In-situ Enhanced Bioremediation
2/7/2011	G&M Oil Company #34 15971 Goldenwest Huntington Beach	In-situ Chemical Oxidation	In-situ Chemical Oxidation
3/30/2011	Musick Branch Jail 13502 Musick Road Irvine	Soil Vacuum Extraction	No Action
1/21/2011	ARCO Station #3013 23742 El Toro Road Lake Forest	Monitored Natural Attenuation	Monitored Natural Attenuation
2/9/2011	G&K Petroleum 4975 Van Buren Blvd Riverside	Not Applicable	In-situ Chemical Oxidation
5/30/2011	Proposed In-N-Out Burger 795 W. Fifth Street San Bernardino	Soil Vacuum Extraction	Not Applicable
6/6/2011	INCO Service Station 796 W. Fifth Street San Bernardino	Soil Vacuum Extraction	Not Applicable

Monday, August 29, 2011

Page 1 of 2

Date Plan Received	Site Address	Proposed Remedial Actions - Soil	Proposed Remedial Actions - Groundwater
12/10/2010	ARCO Station #5082 605 N. H Sreet San Bernardino	Soil Vacuum Extraction	Not Applicable
8/23/2011	Shell Oil Company 3820 Fairview Road Santa Ana	No Action	Monitored Natural Attenuation
12/2/2010	Shell Station #1202 1202 E. Edinger Avenue Santa Ana	Dual Phase/Two-Phase Extraction	Dual Phase/Two Phase Extraction
10/7/2010	Former Gulf (Chevron) Station 1606 Standard Avenue Santa Ana	Dual Phase/Two-Phase Extraction	Dual Phase/Two-Phase Extraction
12/23/2010	ARCO Station #1977 2302 N. Grand Avenue Santa Ana	Soil Vacuum Extraction	Not Applicable
12/2/2010	Unocal/76 Station No. 7462 8472 Katella Avenue Stanton	In-situ Chemical Oxidation	In-situ Chemical Oxidation
6/1/2011	Thrifty #368 6311 Westminster Avenue Westminster	Dual Phase/Two-Phase Extraction	Dual Phase/Two-Phase Extraction
7/15/2011	Shell Oil Company 8990 Westminster Ave Westminster	No Action	Monitored Natural Attenuation