



# Electrical Conductivity at Clifton Court Forebay Nov 15 2013 – Nov 15 2014



[http://cdec.water.ca.gov/jspplot/jspPlotServlet.jsp?sensor\\_no=10433&end=11%2F15%2F2014+00%3A00&geom=huge&interval=365&cookies=cdec01](http://cdec.water.ca.gov/jspplot/jspPlotServlet.jsp?sensor_no=10433&end=11%2F15%2F2014+00%3A00&geom=huge&interval=365&cookies=cdec01)

# Pumping at Banks Nov 15 2013 – Nov 15 2014



[http://cdec.water.ca.gov/jsplot/jspPlotServlet.jsp?sensor\\_no=4447&end=11%2F15%2F2014+00%3A00&geom=huge&interval=365&cookies=cdec01](http://cdec.water.ca.gov/jsplot/jspPlotServlet.jsp?sensor_no=4447&end=11%2F15%2F2014+00%3A00&geom=huge&interval=365&cookies=cdec01)