Department of Environmental Heath

Hazardous Materials Management Division

Riverside County LOP Cases

MTBE Discharges and Groundwater Detection

Reporting period from 01/01/2005 through 03/31/2005

Region: San Diego

Site ID	Site Name	Address	City	MTBE Discharge	MTBE GW Detection	Max MTBE GW TBE Conc.
200218249	Thatcher's Market	45140 Hwy 79	Aguanga	Yes	NT	
92994	El Cariso Country Store	32692 Ortega Hwy	Lake Elsinore	Yes	Yes	1,900.00
200420960	Texaco Cal Oaks	40735 California Oaks	Murrieta	Y	NT	89,000.00
93232	Chevron #201241	40500 California Oaks Rd	Murrieta	Yes	Yes	5,500.00
9915188	Stan's Service	41991 Ivy St	Murrieta	Yes	ND	
200319346	Shell Murrieta	39614 Los Alamos	Murrieta	Yes	NT	
200521231	Mobil #18-BX6	39850 Los Alamos Rd	Murrieta	Yes	NT	
200521232	Mobil #18-HJ4	44520 Bedford Ct	Temecula	Yes	NT	
200016132	California Highway Patrol	27685 Commerce Ctr Dr #/	Temecula	Yes	Yes	1.30
200117527	Chevron #204029	31669 Hwy 79 S	Temecula	Yes	Yes	43.00
200319348	Rancho Car Wash	27278 Jefferson Ave	Temecula	Yes	ND	
200016646	Arco #5695	44239 Margarita Rd	Temecula	Yes	Yes	4,400.00
94144	CDF Station #12	28330 Mercedes St	Temecula	NT	NT	
200118093	Texaco	29750 Rancho California Rc	Temecula	Yes	Yes	16.00
200319683	Arco #5500	41555 Winchester Rd	Temecula	Yes	NT	
9915433	Inland Valley Reg Medica	36485 Inland Valley Dr	Wildomar	N	ND	
200319300	MWD Lake Skinner Work	33740 Borel Rd	Winchester			
200319665	MWD Lake Skinner LS - '	33740 Borel Rd	Winchester	N	N	
200319299	MWD Lake Skinner Work	33740 Borel Rd	Winchester			

*Data represents highest MTBE concentrations detected, may be from prior quarters.

Number of Sites: 19

ND = Not detected
NT = Not tested
NRQ = Not required. Used for soil only cases which have not been required to install gw wells.