


EXPLANATION

- Corrective Action Monitoring groundwater well
- Detection Monitoring groundwater well
- ⊙ Piezometer
- ▲ Surface water outfall and monitoring location
- △ Outfall location
- Private agricultural well
- ⊙ Vadoso zone/gas monitoring probe
- * Monthly methane gas inspection location
- ▨ Approximate fill area July 1, 2006 to September 30, 2006
- ▩ Approximate fill area October 1, 2006 to December 31, 2006



DATE	7/18/07
DWN	KMM
APP	TLV
REV	0
PROJECT NO.	063-7096

FIGURE A-1
CITY OF SANTA MARIA
SANTA MARIA LANDFILL
SANTA BARBARA COUNTY, CALIFORNIA
MONITORING LOCATIONS

Dimscale: 1 Lttscale: 1 Psttscale: 1=2
 C:\063-7096\FIGURES\MONITORING LOCATIONS.DWG 7/18/07