

SEE FIGURE 3

2003 REPAIR SITE

D2

WINDMILL WELL (INACTIVE)

D1

HOLLOWAY 1 (APPROXIMATE)

NIPOMO MESA





DANA ADOBE

40+00

30+00

NIPOMO CREEK

EXPLANATION

-  APPROXIMATE EXTENT OF TPH >100 mg/kg.
-  GROUNDWATER MONITORING WELL.
-  SOIL BORING
-  DOMESTIC WATER WELL.

NOTE:
LOCATIONS AND DIMENSIONS ARE APPROXIMATE




FIGURE 2

AERIAL PHOTOGRAPH OF SITE AND SURROUNDING AREA

NIPOMO CREEK PIPELINE
NIPOMO, CALIFORNIA

