

Rego Dairy #2 Inspection Photographs






Photo of a near overtopping lagoon with excess weeds and rodent holes on the embankments.



Photo of veterinary medical supplies strewn along the bank of the lagoon. Note the eroded discharge path from the lagoon towards the drain ditch located on the lagoon's south embankment.



Photo of leaking 6-inch PVC pipe plugged with concrete on the lagoon's south embankment. The leaking pipe was discharging wastewater from the lagoon directly into the off-property drain ditch.



Drain Ditch (Off-Property)

Dairy Lagoon

Photo of the drain ditch along the south production area perimeter full of manure wastewater.



Photo of deceased cows covered in manure.



Photo of a large area with cow carcasses in various stages of decomposition.



Photo of the illegal burial area.



Photo of cow carcasses in cow manure and cow bones next to the drain ditch.



Photo of wastewater ponding adjacent to the burial area.