



Picture 3



Picture 4







Snake Creek receiving water for storm water runoff from north side of Linkside Place


Picture 5



Picture 6

Dead vegetation matted down from storm water surface flows







Tree that is seen in Pictures 2, 5, 6 & 7

Picture 9



Picture 10



