

COUNTY OF LOS ANGELES

DEPARTMENT OF PUBLIC WORKS

"To Enrich Lives Through Effective and Caring Service"

900 SOUTH FREMONT AVENUE ALHAMBRA, CALIFORNIA 91803-1331 Telephone: (626) 458-5100 http://dpw.lacounty.gov

ADDRESS ALL CORRESPONDENCE TO: P.O. BOX 1460 ALHAMBRA, CALIFORNIA 91802-1460

IN REPLY PLEASE

REFER TO FILE:

FM-0

April 30, 2012

CERTIFIED MAIL

Mr. Samuel Unger, Executive Officer California Regional Water Quality Control Board 320 West 4th Street, Suite 200 Los Angeles, CA 90013

Attention Ms. L.B. Nye, Chief Section 401 Water Quality Certification Unit

Dear Mr. Unger:

2011-12 ANNUAL MAINTENANCE AND MONITORING REPORT SOFT-BOTTOM CHANNEL MAINTENANCE ACTIVITIES WASTE DISCHARGE REQUIREMENTS FILE NUMBER 99-011, CI 9580 ORDER NUMBER R4-2010-0021

In compliance with the annual monitoring and reporting conditions of our subject Waste Discharge Requirements permit, enclosed are three compact discs (CD) containing the necessary monitoring and reporting documentation, in PDF files, for the maintenance of our soft-bottom channel (SBC) reaches in 2011-12.

One CD contains the following documentation:

- > Final SBC maintenance clearing schedule.
- Pre- and Post-Clearing Mitigation Forms.
- ➤ Before and after Biological Resource Monitoring Reports and photos from BonTerra Consulting, the Los Angeles County Flood Control District's (LACFCD) biological consultants.
- Water quality monitoring plans and lab results.

Two CD's contain additional pre-, mid- and post-work photos taken by our field staff.

Mr. Samuel Unger April 30, 2012 Page 2

A total of 91 SBC reaches were maintained during the 2011-12 maintenance clearing period. All maintenance activities were performed outside the nesting bird season. Biologists performed both pre- and post-clearing biological surveys, including fish surveys for sensitive reaches. Work did not start until we received clearance from our Biologists. Onsite biological monitoring was conducted on specific sensitive reaches, as required in the permits. Water quality testing and monitoring were conducted as necessary, per the conditions of the permit.

This letter also serves as certification of no net loss of wetland habitat associated with this project:

"I declare under penalty of law that this document and all enclosures were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who managed the system or those directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Executed on the 30th day of April 2012, in Alhambra, California.

If you have any questions, please contact Ms. Jemellee Cruz of my staff at (626) 458-4170 or jcruz@dpw.lacounty.gov.

Very truly yours,

GAIL FARBER

Director of Public Works

RUDY LEE

Assistant Deputy Director Flood Maintenance Division

FA:sg

P:/DANIELL/MEMOS CRWQCB SBC MAINTENANCE

Enc.

bc: Flood Maintenance (Bordas, Sheridan, Vander Vis)



GAIL FARBER, Director

COUNTY OF LOS ANGELES

DEPARTMENT OF PUBLIC WORKS

"To Enrich Lives Through Effective and Caring Service"

900 SOUTH FREMONT AVENUE ALHAMBRA, CALIFORNIA 91803-1331 Telephone: (626) 458-5100 http://dpw.lacounty.gov

ADDRESS ALL CORRESPONDENCE TO: P.O. BOX 1460 ALHAMBRA, CALIFORNIA 91802-1460

IN REPLY PLEASE

REFER TO FILE:

FM-0

CERTIFIED MAIL

April 30, 2012

Mr. Dan Swenson, Chief Los Angeles and San Bernardino Sections North Coast Branch, Regulatory Division U.S. Army Corps of Engineers Los Angeles District 915 Wilshire Blvd., Suite 980 Los Angeles, CA 90017

Dear Mr. Swenson:

2011-12 ANNUAL MAINTENANCE AND MONITORING REPORT SOFT-BOTTOM CHANNEL CLEARING (FILE NUMBER SPL-2008-00851-KW)

In compliance with the annual monitoring and reporting conditions of our subject Nationwide Permit Number 3, enclosed are three compact discs (CD) containing the necessary monitoring and reporting documentation, in PDF files, for the maintenance of our soft-bottom channel (SBC) reaches in 2011-12.

One CD contains the following documentation:

- Final SBC maintenance clearing schedule.
- > Pre- and Post-Clearing Mitigation Forms.
- > Before and after Biological Resource Monitoring Reports and photos from BonTerra Consulting, the Los Angeles County's Flood Control District's (LACFCD) biological consultants.
- > Water quality monitoring plans and lab results.

Two CD's contain additional pre-, mid- and post-work photos taken by our field staff.

Mr. Dan Swenson April 30, 2012 Page 2

A total of 91 SBC reaches were maintained during the 2011-12 maintenance clearing period. All maintenance activities were performed outside the nesting bird season. Biologists performed both pre- and post-clearing biological surveys, including fish surveys for sensitive reaches. Work did not start until we received clearance from our Biologists. Onsite biological monitoring was conducted on specific sensitive reaches, as required in the permits. Water quality testing and monitoring were conducted as necessary, per the conditions of the Regional Water Quality Control Board's Section 401 Water Quality Certification permit.

If you have any questions, please contact Ms. Jemellee Cruz of my staff at (626) 458-4170 or jcruz@dpw.lacounty.gov.

Very truly yours,

GAIL FARBER

Director of Public Works

RUDY LEE

Assistant Deputy Director Flood Maintenance Division

FA:sa

H:/DANIELL/MEMO/SBC MAINTENANCE CRWQCB

Enc.

bc: Flood Maintenance (Bordas, Sheridan, Vander Vis)



GAIL FARBER, Director

COUNTY OF LOS ANGELES

DEPARTMENT OF PUBLIC WORKS

"To Enrich Lives Through Effective and Caring Service"

900 SOUTH FREMONT AVENUE ALHAMBRA, CALIFORNIA 91803-1331 Telephone: (626) 458-5100 http://dpw.lacounty.gov

ADDRESS ALL CORRESPONDENCE TO: P.O. BOX 1460 ALHAMBRA, CALIFORNIA 91802-1460

> IN REPLY PLEASE REFER TO FILE: FM-0

April 30, 2012

Ms. Geraldine Ruth California Department of Fish and Game Streambed Alteration Program South Coast Region 5 3883 Ruffin Road San Diego, CA 92123

Dear Ms. Ruth:

2011-12 ANNUAL MAINTENANCE AND MONITORING REPORT AND FEE STREAMBED ALTERATION AGREEMENT (SBAA NO. 1600-1999-0076-R5) SOFT-BOTTOM CHANNEL ANNUAL MAINTENANCE CLEARING

We are pleased to submit the following enclosed fee and monitoring/reporting documentation for the annual maintenance of our Soft-Bottom Channels (SBC) in 2011-12:

- Completion Fee in the amount of \$2400. (Warrant Number TS0015964717)
- Three Compact Discs (CD) containing the Annual Maintenance Report documentation, in PDF files, in compliance with current permit conditions associated with the 2011-12 Soft-Bottom Channels maintenance clearing activities:

One CD contains the following reports:

- Final SBC Maintenance Clearing schedule.
- Pre- and Post-Clearing Monitoring and Mitigation Forms.
- Biological Resource Monitoring Reports and photos prepared and taken by our contract Biologists.
- Water quality monitoring lab reports.
- Copy of the original 1999 SBAA 1600-1999-0076-R5 and its 2011-12 extension permit.

Two additional CDs contain photos taken by our field personnel.

Geraldine Ruth April 30, 2012 Page 2

A total of 91 SBC reaches were maintained during the 2011-12 maintenance clearing period. All maintenance activities were performed outside the nesting bird season. Biologists performed both pre- and post-clearing biological surveys, including fish surveys for sensitive reaches. Work did not start until we received clearance from our Biologists. Onsite biological monitoring was conducted on specific sensitive reaches, as required in the permits. Water quality testing and monitoring were conducted as necessary, per the conditions of the permit.

If you have any questions, please contact Ms. Jemellee Cruz of my staff at (626) 458-4170.

Very truly yours,

GAIL FARBER

Director of Public Works

RUDY/LEĚ

Assistant Deputy Director Flood Maintenance Division

FA:JQC

H:/DANIELL/MEMOS/SBC MAINTENANCE RUTH

Enc.

cc: Flood Maintenance (Bordas, Sheridan, Vander Vis)