

LOS ANGELES COUNTY DEPARTMENT OF PUBLIC WORKS



NOTES:

Figure 2: Internal sampling point (#2) located in center of Compton Creek at small
 crib structure with weir located about 1800' s/o Santa Fe Avenue Bridge over
 Compton Creek as measured along the access road on top of the west levee; access
 to levee through locked vehicle gate at southwest corner of bridge.



LOS ANGELES COUNTY
 DEPARTMENT OF PUBLIC WORKS
 900 S. Fremont Ave.
 Alhambra, CA 91803

Compton Creek SBC Cleanout Fall 2012-WQ Monit
 (Printed using View LA 17-Dec-12)



Data contained in this map is produced in whole or part from the Thomas Bros. Maps® digital database. This map is copyrighted, and reproduced with permission granted by Thomas Bros. Maps®. All rights reserved.

Data contained in this map was produced in whole or part from the Los Angeles County Department of Public Works.