Owner and/or Operator	Field Name	County	Sump Name/Description	Sump Location Latitude Longitude	Sump Volume in ft3	When was the Sump first excavated	How many years was the sump active	fluid discharged in	composition	was sump filled with soil or other material		what material was used to fill the sump	solidified	is yes, what was the ecomposition of those solids
Garner Engineering, Inc	Rosecrans	Los Angeles	Tank Farm Sump	33.918514 118.289389	590	UNK	10	170	Salt Water	No	N/A	N/A	N/A	N/A