

OJAI OIL COMPANY

400 W. VENTURA BOULEVARD, SUITE 100
CAMARILLO, CALIFORNIA 93010-9138

Tel: (805) 388-5858
Fax: (805) 388-8024

2016 FEB 17 PM 1:09
CALIFORNIA REGIONAL WATER
QUALITY CONTROL BOARD
LOS ANGELES REGION

February 11, 2016

Los Angeles Regional Water Quality Control Board
320 W. Fourth Street, Ste 200
Los Angeles, CA 90013

Attn: Joshua Cwikla

Dear Mr. Cwikla:


On December 31, 2015 we requested an extension to Section 13267 submittal time requirements in order to complete water testing. This extension was granted on January 15, 2016 to a deadline of February 29, 2016.

Enclosed is a second flash drive carrying four water analyses for irrigation farming wells that could have been contaminated by an abandoned sump:

Topa Lane Well	34° 26' 17.23"N 119° 08' 05.45W
Smith Well	34° 26' 11.73"N 119° 07' 46.88W
Sisar Grove Well	34° 26' 24.20"N 119° 07' 50.3W
Mexican Well	34° 26' 09.90"N 119° 07' 51.41W

We believe this completes our requirements for submittal of a technical report regarding information on how fluids associated with oil and gas production are managed with this field under investigative order R4-2015-0450.

Sincerely,



Douglas Off
Ojai Oil Company
Cell: 805 377 7713
Email: doug@ojaioil.com