



North Coast Regional Water Quality Control Board

June 25, 2021

Certified Mail 7016 2070 0000 6486 1893

Stephan K. Schnur PO Box 9911 Redlands, CA 92375

Dear Stephan K. Schnur:

Subject: Notice of Violation and Transmittal of Inspection Report for May 25,

2021 Inspection of Humboldt County Assessor's Parcel 216-393-019-000

File: Cannabis Program Inspections, Humboldt County, May 25,2021,

CIWQS Place ID

This letter is to notify you of observed violations of the requirements listed below, and cited in Attachment A, at the property identified as Humboldt County Assessor's Parcel Number: 216-393-019-000 (the Property):

- 1. Water Quality Control Plan for the North Coast Region (Basin Plan) Section 4.2.1
- 2. California Water Code (Water Code) Section 13260

On May 25, 2021, North Coast Regional Water Quality Control Board (Regional Water Board) staff (Staff) inspected the Property and observed active cannabis cultivation occurring in hoop-house style greenhouses. Accordingly, this letter directs you to address the violations noticed herein. Within 30 days, please contact Regional Water Board staff to discuss your plan to correct the observed violations.

Background

On May 25, 2021, staff from the Regional Water Board, accompanied by staff of California Department of Fish and Wildlife and personnel from the Humboldt County Sherriff's Office, inspected the Property. The purpose of the inspection was to evaluate onsite development and conditions, and to identify and assess any impacts or threatened impacts to the quality and beneficial uses of waters of the state.

Gregory A. Giusti, chair | Matthias St. John, executive officer

Attached is a copy of the water quality inspection report (Attachment B –Facilities Inspection Report and Attachment C – Inspection Map and Photolog). Please review the inspection report carefully and completely. The inspection report contains recommendations for correcting observed violations and advises you of the Regional Water Board permits necessary for instream work and projects/activities that result in discharges of waste to receiving waters.

Relevant Requirements

During the inspection, Regional Water Board staff identified several features and conditions on the Property that represent violations of water quality requirements and regulations. Attachment A – Regulatory Citations, provides references to these, and related, requirements and regulations.

Observed Violations

As documented in the May 25, 2021 inspection report, Regional Water Board staff observed violations of the California Water Code and the Basin Plan. Staff observed these violations at Property locations identified in the inspection report as CA1, CA2, MP1, and GREY.

Directive to Obtain Regulatory Coverage Prior to Future Activities Involving or Resulting in Discharges of Waste to Waters of the State

During the May 25, 2021, inspection, staff observed cannabis cultivation operations of sufficient size and scope to require regulatory coverage under the State Water Resources Control Board (State Water Board) Order No. WQ-2019-0001-DWQ, General Waste Discharge Requirements and Waiver of Waste Discharge Requirements for Discharges of Waste Associated with Cannabis Cultivation Activities (Statewide General Order).

Please be aware that, pursuant to Water Code sections 13260 and 13264, if you elect to resume/continue cannabis cultivation on the subject Property, you must either:

1) Enroll the property under the Statewide General Order by providing the information required in the online application process. The application can be accessed at: https://www.waterboards.ca.gov/water_issues/programs/cannabis/
Submit the application fee within 30 days of submitting the on-line application. Failure to submit the application fee within 30 days will result in the application being voided and authorization terminated. Payments shall be identified using the Fee Payment Application Number (found on the Notice of Receipt). All checks or money orders shall be made payable to: "State Water Resources Control Board," and shall be delivered to:

(By US Mail):

Accounting Office

Attn: Water Quality Fees – Cannabis General Order

P.O. Box 1888

Sacramento, CA 95812-1888

2) File a Report of Waste Discharge in order to obtain individual Waste Discharge Requirements (WDRs) specific to your property.

Please submit the appropriate documents and payments to:

North Coast Water Board Attn: Cannabis Permitting 5550 Skylane Boulevard, Suite A Santa Rosa, CA 95403

Water Code section 13260 states, in relevant part:

- (a) Each of the following persons shall file with the appropriate regional board a report of the discharge, containing the information which may be required by the regional board:
 - (1) Any person discharging waste, or proposing to discharge waste, within any region that could affect the quality of the waters of the state, other than into a community sewer system.

Water Code section 13264 states, in relevant part:

- (a) No person shall initiate any new discharge of waste or make any material changes in any discharge...prior to the filing of the report required by Section 13260 and no person shall take any of these actions after filing the report but before whichever of the following occurs first:
 - (1) The issuance of waste discharge requirements pursuant to Section 13263.

Failure to comply with Water Code sections 13260 and 13264 may result in an administrative civil liability under Water code sections 13261 and 13265 not to exceed \$1,000 per violation for each day in which each violation occurs.

Additional Potential Liabilities

The Regional Water Board is in the process of considering whether the violations of the Water Code and the Basin Plan warrant further enforcement. We encourage you to take steps, to correct the violations as soon as possible, securing any applicable permits from this and other agencies prior to conducting work. Please note that the existing

conditions, as observed and documented in the Inspection Report, may represent continuing violations of the Water Code and Basin Plan.

Please note that correcting the conditions of non-compliance at the Property does not preclude enforcement for the violations alleged in this notice. As noted above, the Regional Water Board reserves its right to fully enforce the law against any violation and threatened violation by taking enforcement actions such as a cleanup and abatement order, time schedule order, administrative civil liabilities, and referral to the California Attorney General's office. Administrative civil liabilities may be assessed on a daily basis in the amount up to \$5,000 for each day the violation occurs or up to \$10 per gallon, but not both pursuant to Water Code section 13350.

Inspection Report Recommendations

As mentioned above, the May 25, 2021 Inspection Report provides recommendations to correct the alleged violations, as well as to address features and conditions that threaten to impact water quality. **Within 30 days of this letter**, please advise Regional Water Board staff Shannon Utley of your intentions, plan, and schedule to implement recommendations in the inspection report. If you have questions about what is required of you to comply with the requirements outlined above, and to advise as to your plan and schedule to correct the alleged violations, please contact Regional Water Board staff Shannon Utley by email at Shannon.Utley@waterboards.ca.gov.

Future correspondence regarding this matter will be sent to you at this address unless an alternative address is provided to the Regional Water Board. Failure to accept mail from the Regional Water Board is not a valid excuse for non-compliance with any future enforcement orders, and a failure to respond or otherwise appear at a future enforcement proceeding could subject you to a default order and the imposition of administrative civil liability.

You may also contact me at Mona.Dougherty@waterboards.ca.gov or by phone at (707) 445-6129. Additionally, we are available to meet with you if you wish to discuss this letter or our waste discharge regulatory programs in further detail.

Sincerely,

Mona Dougherty, P.E. Senior Water Resource Control Engineer Northern Cannabis Permitting Unit 210625_Schnur_NOV

Attachments: Attachment A - Regulatory Citations

Attachment B – Facilities Inspection Report Attachment C – Inspection Map and Photolog

Certified Mail - Return Receipt requested

cc: North Coast Regional Water Quality Control Board

Northcoast.Cannabis@waterboards.ca.gov
Claudia Villacorta, Claudia.Villacorta@waterboards.ca.gov
Kason Grady, Kason.Grady@waterboards.ca.gov
Shannon Utley, Shannon.Utley@waterboards.ca.gov

Division of Water Rights

Stormer Feiler, <u>Stormer.Feiler@waterboards.ca.gov</u> Taro Murano, <u>Taro.Murano@waterboards.ca.gov</u>

Department of Fish and Wildlife

Ryan Bourque, <u>Ryan.Bourque@wildlife.ca.gov</u> Scott Bauer, Scott.Bauer@wildlife.ca.gov

Humboldt County Sheriff's Office

Sergeant Conan Moore, cmoore@co.humboldt.ca.us
Deputy Spellman Stallworth, stallworth@co.humboldt.ca.us

Attachment A – Regulatory Citations

Regulatory Section	Citation
Basin Plan Section	Prohibits "[t]he discharge of soil, silt, bark, slash, sawdust, or other organic and earthen material from
4.2.1, Prohibition 1	any logging, construction, or associated activity of whatever nature into any stream or watercourse in
	the basin in quantities deleterious to fish, wildlife, or other beneficial uses."
Basin Plan Section	Prohibits "[t]he placing or disposal of soil, silt, bark, slash, sawdust, or other organic and earthen
4.2.1, Prohibition 2	material from any logging, construction, or associated activity of whatever nature at locations where
	such material could pass into any stream or watercourse in the basin in quantities which could be
	deleterious to fish, wildlife, or other beneficial uses."
California Water Code	"(a) Each of the following persons shall file with the appropriate regional board a report of the
Section 13260	discharge, containing the information that may be required by the regional board:
	(1) A person discharging waste, or proposing to discharge waste, within any region that could affect the quality of the waters of the state, other than into a community sewer system.(2) A person who is a citizen, domiciliary, or political agency or entity of this state discharging waste, or proposing to discharge waste, outside the boundaries of the state in a manner that could affect the quality of the waters of the state within any region."
California Water Code	"A person who fails to furnish a report or pay a fee under Section 13260 when so requested by a
Section 13261(a)	regional board is guilty of a misdemeanor and may be liable civilly in accordance with subdivision (b)."

FACILITIES INSPECTION REPORT

Region/Office: 1	Status: Performed	Reg. Measure ID:	443739
Program Type: IRRICANNABIS	WDID:	Order Number:	
Scheduled Insp. Date:	Actual Insp. Dat	e: 05/25/2021	

Discharger Information

Party ID: 625306	Discharger Organization Name:	Stephan Schnur	
Address: Po Box 9911		City, State, Zip:	Redlands, CA 92375
Discharger Contact		Discharger	
Person:		Contact Phone:	
Discharger Contact Em	ail Address:		

Facility Information

Place ID 874702	Facility Name: Stephan Schnu	ır	
Address:		City, State, Zip	: CA
County: Humboldt	Latitude: Longi	tude:	Method:

Lead Inspector Information

Lead Inspector Part	y ID: 545131	Lead Inspector Name: Shannon Utley
Inspector Type:	■ State	☐ State Contractor ☐ EPA Contractor ☐ EPA (Regional)
	☐ EPA and St	tate (EPA Lead)

INSPECTION TYPE

Inspection Type: Miscellaneous inspection

VIOLATIONS


Were Violations noted during this inspection? $\ lacktriangledown$ Yes $\ \Box$ No

Violation ID	Violation Type	Occurrence Date	Rank	Description
1091291	Other Codes	05/25/2021	В	California Water Code Section 13260: cannabis cultivation operations of sufficient size and scope to require regulatory coverage under Order No. WQ 2019-0001-DWQ.
1091292	Basin Plan Prohibition	05/25/2021	В	Basin Plan Section 4.2.1, Prohibition 1 and Prohibition 2 at MP1 and GREY where fill and greywater can enter surface waters of the Class II watercourse.

Inspection ID: 44308115 Date Printed: 06/25/2021

Enroll in the State Water Resources Control Board Cannabis Policy and General Waste Discharge Requirement Order No. WQ 2019-0001-DWQ for cannabis cultivation and modify the cannabis cultivation activities and site conditions to comply with the General Order and Policy. Move the greywater discharge away from any surface waters and ensure waste and wastewater does not enter a	INSPECTION	I SUMMARY (REQUIRE	D) (500 character limit)	
GENERAL NOTES (OPTIONAL) (2000 character limit) Inspection Description: The May 25, 20121, inspection was associated with a criminal search warrant and only portions of the Property were viewed. Please see the attached Map and Appendices for locations and details about features of water quality concern. Active cannabis cultivation was occurring in two locations on the Humboldt County Accessor Parcel Number 216:393-019-000 (hereafter the Property), which requires enrollment under General Order No. WQ 2019-0001-DWQ for cannabis cultivation over 2,000 square feet. Active cannabis cultivation was occurring within hoop-house style greenhouses (CA1 on the Inspection Map) and within hoop-house style greenhouses (CA2) at a separate graded pad. Graded material from CA2 was pushed to the edge of the graded area and placed upslope of a Class II watercourse. Up stream of MP1 and near the residence a pipe discharging greywater (GREY) within 50 feet of the Class II watercourse located at MP2. For Internal Use (Optional) Reviewed By: (1) (2) (3) CIWOS Entry Regional Board CIWOS	Order No. WQ 2019-0001-DW0) for cannabis cultivation and modi		
Inspection Description: The May 25, 20121, inspection was associated with a criminal search warrant and only portions of the Property were viewed. Please see the attached Map and Appendices for locations and details about features of water quality concern. Active cannabis cultivation was occurring in two locations on the Humboldt County Accessor Parcel Number 216-393-019-000 (hereafter the Property), which requires enrollment under General Order No. WQ 2019-0001-DWO for cannabis cultivation over 2,000 square feet. Active cannabis cultivation was occurring within hoop-house style greenhouses (CA1 on the Inspection Map) and within hoop-house style greenhouses (CA2) at a separate graded pad. Graded material from CA2 was pushed to the edge of the graded area and placed upslope of a Class II watercourse (MP1) on a 44-degree slope where at least approximately 20 cubic yards of fill could deliver to the Class II watercourse. Up stream of MP1 and near the residence a pipe discharging greywater (GREY) within 50 feet of the Class II watercourse located at MP2. For Internal Use (Optional) Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS	Move the greywater discharge surface water.	away from any surface waters and	l ensure waste and wastewater does not	enter a
Inspection Description: The May 25, 20121, inspection was associated with a criminal search warrant and only portions of the Property were viewed. Please see the attached Map and Appendices for locations and details about features of water quality concern. Active cannabis cultivation was occurring in two locations on the Humboldt County Accessor Parcel Number 216-393-019-000 (hereafter the Property), which requires enrollment under General Order No. WQ 2019-0001-DWO for cannabis cultivation over 2,000 square feet. Active cannabis cultivation was occurring within hoop-house style greenhouses (CA1 on the Inspection Map) and within hoop-house style greenhouses (CA2) at a separate graded pad. Graded material from CA2 was pushed to the edge of the graded area and placed upslope of a Class II watercourse (MP1) on a 44-degree slope where at least approximately 20 cubic yards of fill could deliver to the Class II watercourse. Up stream of MP1 and near the residence a pipe discharging greywater (GREY) within 50 feet of the Class II watercourse located at MP2. For Internal Use (Optional) Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS				
Inspection Description: The May 25, 20121, inspection was associated with a criminal search warrant and only portions of the Property were viewed. Please see the attached Map and Appendices for locations and details about features of water quality concern. Active cannabis cultivation was occurring in two locations on the Humboldt County Accessor Parcel Number 216-393-019-000 (hereafter the Property), which requires enrollment under General Order No. WQ 2019-0001-DWO for cannabis cultivation over 2,000 square feet. Active cannabis cultivation was occurring within hoop-house style greenhouses (CA1 on the Inspection Map) and within hoop-house style greenhouses (CA2) at a separate graded pad. Graded material from CA2 was pushed to the edge of the graded area and placed upslope of a Class II watercourse (MP1) on a 44-degree slope where at least approximately 20 cubic yards of fill could deliver to the Class II watercourse. Up stream of MP1 and near the residence a pipe discharging greywater (GREY) within 50 feet of the Class II watercourse located at MP2. For Internal Use (Optional) Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS				
Inspection Description: The May 25, 20121, inspection was associated with a criminal search warrant and only portions of the Property were viewed. Please see the attached Map and Appendices for locations and details about features of water quality concern. Active cannabis cultivation was occurring in two locations on the Humboldt County Accessor Parcel Number 216-393-019-000 (hereafter the Property), which requires enrollment under General Order No. WQ 2019-0001-DWO for cannabis cultivation over 2,000 square feet. Active cannabis cultivation was occurring within hoop-house style greenhouses (CA1 on the Inspection Map) and within hoop-house style greenhouses (CA2) at a separate graded pad. Graded material from CA2 was pushed to the edge of the graded area and placed upslope of a Class II watercourse (MP1) on a 44-degree slope where at least approximately 20 cubic yards of fill could deliver to the Class II watercourse. Up stream of MP1 and near the residence a pipe discharging greywater (GREY) within 50 feet of the Class II watercourse located at MP2. For Internal Use (Optional) Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS				
The May 25, 20121, inspection was associated with a criminal search warrant and only portions of the Property were viewed. Please see the attached Map and Appendices for locations and details about features of water quality concern. Active cannabis cultivation was occurring in two locations on the Humboldt County Accessor Parcel Number 216-393-019-000 (hereafter the Property), which requires enrollment under General Order No. WQ 2019-0001-DWQ for cannabis cultivation over 2,000 square feet. Active cannabis cultivation was occurring within hoop-house style greenhouses (CA1 on the Inspection Map) and within hoop-house style greenhouses (CA2) at a separate graded pad. Graded material from CA2 was pushed to the edge of the graded area and placed upslope of a Class II watercourse (MP1) on a 44-degree slope where at least approximately 20 cubic yards of fill could deliver to the Class II watercourse. Up stream of MP1 and near the residence a pipe discharging greywater (GREY) within 50 feet of the Class II watercourse located at MP2. For Internal Use (Optional) Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS		NOTES (OPTIONAL) (2	2000 character limit)	
Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS	The May 25, 20121, inspecti were viewed. Please see the quality concern. Active cann Parcel Number 216-393-019 WQ 2019-0001-DWQ for can within hoop-house style gree (CA2) at a separate graded placed upslope of a Class II wards of fill could deliver to the content of the could deliver to the content of the could deliver to the could deliver to the content of the could deliver to the co	attached Map and Appendices for abis cultivation was occurring in two 000 (hereafter the Property), which nabis cultivation over 2,000 square anhouses (CA1 on the Inspection Mod. Graded material from CA2 was vatercourse (MP1) on a 44-degree he Class II watercourse. Up stream	locations and details about features of way locations on the Humboldt County Accept he requires enrollment under General Order feet. Active cannabis cultivation was occap) and within hoop-house style greenhouse pushed to the edge of the graded area as slope where at least approximately 20 cultions of MP1 and near the residence a pipe	ater essor er No. curring uses and
Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS				
Reviewed By: (1) (2) (3) CIWQS Entry Regional Board CIWQS	For Internal Use (Ontional)			
CIWQS Entry Regional Board CIWQS		(2)	(3)	
	CIWQS Entry	Regional Board	CIWQS	

Attachment C - Inspection Map and Photolog



All photographs and GPS locations were taken by Shannon Utley, North Coast Regional Water Quality Control Board

Photo 1: View of cultivation area CA1 looking towards the lower residence.



Photo 3: Active cannabis cultivation at CA2.



Photo 5: View of the well adjacent to the Class II watercourse and greywater pipe.



Photo 2: View of cultivation area CA1 propagation area next to hoop-houses.



Photo 4: View of cultivation area CA2 and adjacent hillside.



Photo 6: Closer view of the well located on the property.



Photo 7: View of the greywater pipe near the Class II watercourse.



Photo 9: Stream crossing XNG2 located off parcel upstream of MP2.



Photo 11: CA2 graded area fill material above the Class II watercourse and MP1.



Photo 8: Closer view of the grey water discharge with 50 feet of MP2.



Photo 10: View of XNG2 outlet located upstream of MP2.



Photo 12: Closer view of CA2 graded area fill material above MP1.



Photo 13: View of household garbage placed upslope of XNG1.



Photo 14: Closer view of garbage placed above XNG1.

